


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Greenethorpe Public School (2070)
Region : Riverina
State Electorate : Cootamundra
Local Government Area : Weddin

Initial Survey : Noel Arnold & Associates : 09 - May - 2008
Reviewed By : Greencap-NAA : 15 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1970 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Eaves Linings	Flat AC Sheeting 2070/B00A/Eaves Linings/S1					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 2070/B00A/Wall Cladding/S2					No Asbestos Detected
Wall Cladding	Compressed AC Sheet 2070/B00A/Wall Cladding/S3					No Asbestos Detected
Window In-fill-panel	Flat AC Sheeting 2070/B00A/Infill Panels below windows/S4					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Staff Room

No Asbestos

B00A - R0002 - Staff Toilet

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2070/B00A/R0004/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00A - R0005 - Entry Vestibule

No Asbestos

B00A - R0006 - Clerical Office

No Asbestos

B00A - R0007 - General Storeroom

No Asbestos

B00A - R0008 - Principal

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/General Learning - 1925 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction 4m height
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - Reading Area

No Asbestos

B00B - R0003 - Home Base

No Asbestos

B00B - R0004 - Duplicating Workroom

Floor Coverings Res/Textile	Adhesive					
	2070/B00B/R0005/Floor Coverings Res/Textile/S11					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00B/R0005/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)

B00B - R0005 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00B/R0005/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2070/B00B/R0005/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00B - R0006 - Withdrawal Space - 1hb

No Asbestos

B00B - R0007 - Movement


No Asbestos

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2070/B00B/R0009/Ceiling Structures/Linings/S6					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	2070/B00B/R0009/Ceiling Structures/Linings/S6					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	2070/B00B/R0009/Wall Linings Internal/S7					No Asbestos Detected



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/Staff Facilities - 1965 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
fascia	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00C/fascia/S8					Chrysotile (white asbestos)

Interior

B00C - R0001 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00C/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00C - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00C/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00C - R0003 - Canteen Covered Area

No Asbestos

B00C - R0004 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00C/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00C - R0005 - Canteen Covered Area

No Asbestos

B00C - R0006 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00C/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00C - R0007 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2070/B00C/R0002/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1970 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior

B00D - R0001 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Other - 1903 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00E - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Other - 1985 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other - 1985 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other - 1985 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00I - R0001 - Home Base

No Asbestos

B00I - R0002 - Home Base Store

No Asbestos

B00I - R0003 - Practical Activities

No Asbestos

B00I - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017