


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Green Valley Public School (2075)
Region : South Western Sydney
State Electorate : Liverpool
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 23 - Apr - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1928 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Other-Community Use

No Asbestos

B00C - R0003 - External Movement

No Asbestos

B00C - R0004 - Staff Kitchen

No Asbestos

B00C - R0005 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Movement

No Asbestos

B00G - R0003 - Practical Activities - 1hb

No Asbestos

B00G - R0004 - Practical Activities - 1hb

No Asbestos

B00G - R0005 - Movement

No Asbestos

B00G - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0009 - Outdoor Learning Area

No Asbestos

B00G - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0011 - Outdoor Learning Area

No Asbestos

B00G - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - Practical Activities - 1hb

No Asbestos

B00H - R0004 - Practical Activities - 1hb

No Asbestos

B00H - R0005 - Movement

No Asbestos

B00H - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0009 - Outdoor Learning Area

No Asbestos

B00H - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0011 - Outdoor Learning Area

No Asbestos

B00H - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2003 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Practical Activities - 1hb

No Asbestos

B00I - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0004 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0005 - Practical Activities - 1hb

No Asbestos

B00I - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0009 - External Movement

No Asbestos

B00I - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - Movement

No Asbestos

B00J - R0003 - Practical Activities - 1hb

No Asbestos

B00J - R0004 - Practical Activities - 1hb

No Asbestos

B00J - R0005 - Movement

No Asbestos

B00J - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0009 - Outdoor Learning Area

No Asbestos

B00J - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0011 - Outdoor Learning Area

No Asbestos

B00J - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2003 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Practical Activities - 1hb

No Asbestos

B00K - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0004 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0005 - Practical Activities - 1hb

No Asbestos

B00K - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0009 - External Movement

No Asbestos

B00K - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library - 2003 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0003 - Communications Room

No Asbestos

B00L - R0004 - K.L.A. Store

No Asbestos

B00L - R0005 - Movement

No Asbestos

B00L - R0006 - Toilets - Boys/Girls

No Asbestos

B00L - R0007 - Cleaning Supplies

No Asbestos

B00L - R0008 - External Movement

No Asbestos

B00L - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - External Movement

No Asbestos

B00M - R0002 - Practical Activities - 1hb

No Asbestos

B00M - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Administration - 2007 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - External Movement

No Asbestos

B00N - R0002 - Entry Vestibule

No Asbestos

B00N - R0003 - Clerical Office

No Asbestos

B00N - R0004 - Duplicating Workroom

No Asbestos

B00N - R0005 - Movement

No Asbestos

B00N - R0006 - Interview

No Asbestos

B00N - R0007 - Principal

No Asbestos

B00N - R0008 - Deputy Principal

No Asbestos

B00N - R0009 - Deputy Principal

No Asbestos

B00N - R0010 - Sick Bay

No Asbestos

B00N - R0011 - Disabled Shower/Toilet

No Asbestos

B00N - R0012 - Staff Kitchen

No Asbestos

B00N - R0013 - Staff Room

No Asbestos

B00N - R0014 - Staff Room

No Asbestos

B00N - R0015 - Cleaning Distributed Store

No Asbestos

B00N - R0016 - Staff Toilet

No Asbestos

B00N - R0017 - Staff Toilet

No Asbestos

B00N - R0018 - Staff Toilet

No Asbestos

B00N - R0019 - Interview

No Asbestos

B00N - R0020 - Security Store

No Asbestos

B00N - R0021 - External Stairs

No Asbestos

B00N - R0022 - External Movement

No Asbestos

B00N - R0023 - Main Switch Board

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Communal Facilities/Pupil Facilities - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B000 - R0001 - External Movement

No Asbestos

B000 - R0002 - Main Switch Board

No Asbestos

B000 - R0003 - Cleaning Distributed Store

No Asbestos

B000 - R0004 - Canteen Office/Store

No Asbestos

B000 - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B000 - R0006 - Canteen

No Asbestos

B000 - R0007 - Hall Chair Store

No Asbestos

B000 - R0008 - External Movement

No Asbestos

B000 - R0009 - External Movement

No Asbestos

B000 - R0010 - Covered Outdoor Learning Area

No Asbestos

B000 - R0011 - Communal Space

No Asbestos

B000 - R0012 - Raised Platform

No Asbestos

B000 - R0013 - Movement

No Asbestos

B000 - R0014 - Movement

No Asbestos

B000 - R0015 - Communal/Performance Store

No Asbestos

B000 - R0016 - P.E. Store

No Asbestos

B000 - R0017 - Sound Cupboard

No Asbestos

B000 - R0018 - Toilet - Lobby

No Asbestos

B000 - R0019 - Toilets - Boys/Disabled Cubicle

No Asbestos

B000 - R0020 - Toilet - Lobby

No Asbestos

B000 - R0021 - Toilet - Lobby

No Asbestos

B000 - R0022 - Toilets - Girls/Disabled Cubicle

No Asbestos

B000 - R0023 - Toilet - Lobby

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B000 - R0024 - Access Shower/Toilet

No Asbestos

B000 - R0025 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00P - R0001 - External Movement

No Asbestos

B00P - R0002 - Cleaning Distributed Store

No Asbestos

B00P - R0003 - Special Programs Store

No Asbestos

B00P - R0004 - Movement

No Asbestos

B00P - R0005 - Special Programs Room

No Asbestos

B00P - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0007 - Practical Activities - 1hb

No Asbestos

B00P - R0008 - Home Base Store

No Asbestos

B00P - R0009 - Home Base

No Asbestos

B00P - R0010 - Withdrawal Space - 2hb

No Asbestos

B00P - R0011 - Home Base

No Asbestos

B00P - R0012 - Practical Activities - 1hb

No Asbestos

B00P - R0013 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00Q - R0001 - Practical Activities - 1hb

No Asbestos

B00Q - R0002 - Home Base

No Asbestos

B00Q - R0003 - Home Base Store

No Asbestos

B00Q - R0004 - Withdrawal Space - 2hb

No Asbestos

B00Q - R0005 - Practical Activities - 1hb

No Asbestos

B00Q - R0006 - Home Base

No Asbestos

B00Q - R0007 - Home Base Store

No Asbestos

B00Q - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00Q - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00R - R0001 - External Movement

No Asbestos

B00R - R0002 - Practical Activities - 1hb

No Asbestos

B00R - R0003 - Home Base Store

No Asbestos

B00R - R0004 - Home Base

No Asbestos

B00R - R0005 - Withdrawal Space - 2hb

No Asbestos

B00R - R0006 - Home Base

No Asbestos

B00R - R0007 - Home Base Store

No Asbestos

B00R - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D11418 - Learning Unit - Standard/Withdrawal : Placement Date - 22/12/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D14952 - Learning Unit - Standard/Withdrawal : Placement Date - 24/12/2005

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017