


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Greenwich Public School (2076)
Region : Northern Sydney
State Electorate : Lane Cove
Local Government Area : Lane Cove

Initial Survey : Noel Arnold & Associates : 11 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 02 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1908 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction > 3m.					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Height Restriction > 3m.

Interior

B00A - R0001 - Cleaning Distributed Store

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles 2076/B00A/R0004/Floor Coverings Res/Textile/S2					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Staff Room

No Asbestos

B00A - R0008 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Clerical Office

No Asbestos

B00A - R0011 - Communal Space

No Asbestos

B00A - R0012 - Raised Platform

No Asbestos

B00A - R0013 - Duplicating Workroom

No Asbestos

B00A - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B00A/R0020/Ceiling Structures/Linings/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R0015 - Entry Vestibule

No Asbestos

B00A - R0016 - Principal

No Asbestos

B00A - R0017 - Home Base

No Asbestos

B00A - R0018 - Movement

No Asbestos

B00A - R0021 - Stairs

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2076/B00A/R1013/Ceiling Structures/Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0022 - Stairs

No Asbestos

B00A - R0023 - Movement

No Asbestos

B00A - R1001 - Practical Activities - 1hb

No Asbestos

B00A - R1002 - General Storeroom

No Asbestos

B00A - R1003 - Interview

No Asbestos

B00A - R1004 - K.L.A. Store

No Asbestos

B00A - R1005 - Reading Area

No Asbestos

B00A - R1007 - Personal Effects Storage

No Asbestos

B00A - R1008 - Staff Toilet

No Asbestos

B00A - R1009 - Personal Effects Storage

No Asbestos

B00A - R1010 - Staff Toilet

No Asbestos

B00A - R1011 - Home Base

No Asbestos

B00A - R1013 - Stairs

Ceiling Structures/Linings Flat AC Sheeting 7m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)

2076/B00A/R1013/Ceiling Structures/Linings/S3 Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R1014 - Stairs

No Asbestos

B00A - R1015 - General Storeroom

No Asbestos

B00A - R1016 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1967 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction > 3m.					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Ends	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction > 3m.						

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
2076/B00B/R0004/Floor Coverings Res/Textile/S4						

B00B - R0003 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	NA	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
2076/B00B/R0004/Floor Coverings Res/Textile/S4						

Electrical Mounting Board	Resinous Board	1Unit	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction > 3m.						

B00B - R0004 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
2076/B00B/R0004/Floor Coverings Res/Textile/S4						

B00B - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
2076/B00A/R0020/Ceiling Structures/Linings/S1						

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
2076/B00B/R0004/Floor Coverings Res/Textile/S4						

B00B - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
2076/B00A/R0020/Ceiling Structures/Linings/S1						

B00B - R9001 - Movement

No Asbestos

B00B - R9002 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
2076/B00A/R1013/Ceiling Structures/Linings/S3						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B00G/Eaves Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00F - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B00G/Eaves Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B00G/Eaves Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00G - R0003 - Toilets - Boys

No Asbestos

B00G - R0004 - Toilets - Girls

No Asbestos

B00G - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Administration/General Learning - 1909 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found				
Underfloor Voids - Packing to Floor Joists	No Asbestos Found				
Wall Cladding	Flat AC Sheeting				
	2076/B00H/R0008/Wall Linings Internal/S10				No Asbestos Detected

Interior

B00H - M0001 - Movement

No Asbestos

B00H - M0002 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet				
	2076/B00H/M0002/Floor Coverings Res/Textile/S8				No Asbestos Detected

B00H - M0003 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	3m2	West facing	Good Condition (1)	Low (1) Low Priority (2-3)
	2076/B00H/M0003/Wall Linings Internal/S9				Chrysotile (white asbestos)

B00H - M0004 - Stairs

No Asbestos

B00H - M0005 - Stairs

No Asbestos

B00H - R0001 - Home Base

No Asbestos

B00H - R0002 - Home Base

No Asbestos

B00H - R0003 - Movement

No Asbestos

B00H - R0004 - Movement

No Asbestos

B00H - R0005 - Personal Effects Storage

No Asbestos

B00H - R0006 - Deputy Principal

No Asbestos

B00H - R0009 - Movement

No Asbestos

B00H - R0010 - Cleaning Distributed Store

No Asbestos

B00H - R0011 - Staff Toilet

No Asbestos

B00H - R0012 - Staff Toilet

No Asbestos

B00H - R0013 - Practical Activities - 1hb

No Asbestos

B00H - R0014 - Home Base

No Asbestos

B00H - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1) Low Priority (2-3)
	2076/B00H/R0015/Ceiling Structures/Linings/S11				Chrysotile (white asbestos)

B00H - R0016 - Stairs

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R0017 - Clerical Office						
No Asbestos						
B00H - R0018 - Duplicating Workroom						
No Asbestos						
B00H - R0019 - Duplicating Workroom						
No Asbestos						
B00H - R1001 - Home Base						
No Asbestos						
B00H - R1002 - Staff Room						
No Asbestos						
B00H - R1003 - Movement						
No Asbestos						
B00H - R1004 - Home Base						
No Asbestos						
B00H - R1005 - Home Base						
No Asbestos						
B00H - R1006 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior

B001 - R0001 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B001/R0001/Partition Walls (Cubicles)/S12				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B00H/R0015/Ceiling Structures/Linings/S11				Chrysotile (white asbestos)	

B001 - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B001/R0001/Partition Walls (Cubicles)/S12				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	NA	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B00H/R0015/Ceiling Structures/Linings/S11				Chrysotile (white asbestos)	

B001 - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2076/B00H/R0015/Ceiling Structures/Linings/S11				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Building Services - 2006 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00L - R0001 - Communal Space

No Asbestos

B00L - R0002 - Raised Platform

No Asbestos

B00L - R0003 - Movement

No Asbestos

B00L - R0005 - Movement

No Asbestos

B00L - R0006 - Chair Storeroom

No Asbestos

B00L - R0007 - Communal/Performance Store

No Asbestos

B00L - R0008 - P.E. Store

No Asbestos

B00L - R0009 - Toilets - Girls

No Asbestos

B00L - R0010 - Toilet - Lobby

No Asbestos

B00L - R0011 - Sound Cupboard

No Asbestos

B00L - R0012 - Toilets - Boys

No Asbestos

B00L - R0013 - Toilet - Lobby

No Asbestos

B00L - R0014 - Cleaning Distributed Store

No Asbestos

B00L - R0015 - Other

No Asbestos

B00L - R0016 - Access Shower/Toilet/Change

No Asbestos

B00L - R0017 - Main Switch Board

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other-After School Care - 1995 - Steel (Steel)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Other-After School Care

No Asbestos

B00M - R0002 - Clerical Office

No Asbestos

B00M - R0003 - Other

No Asbestos

B00M - R0004 - General Storeroom

No Asbestos

B00M - R0005 - Toilet - Lobby

No Asbestos

B00M - R0006 - Toilets - Boys

No Asbestos

B00M - R0007 - Toilets - Girls

No Asbestos

B00M - R0008 - External Movement

No Asbestos

B00M - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00N - R0001 - Uniform Shop

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10138 - Learning Unit - Standard With P.A.A. : Placement Date - 25/02/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10339 - Learning Unit - Standard With P.A.A. : Placement Date - 1/02/2010

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11093 - Learning Unit - Standard With P.A.A. : Placement Date - 26/01/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D11360 - Learning Unit - Standard/Withdrawal : Placement Date - 7/02/2006

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 602 - D12758 - Learning Unit - Standard With P.A.A. : Placement Date - 29/12/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D12771 - Learning Unit - Standard With P.A.A. : Placement Date - 17/12/2012						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 603 - D12794 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 5/01/2006						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14209 - Learning Unit - Standard With P.A.A. : Placement Date - 9/01/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 601 - D14942 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

OS 601 - D14943 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
---------	---------------	------------------	--	--	--	-------

OS 601 - D14944 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
---------	---------------	------------------	--	--	--	-------

OS 523 - D15833 - Staff Study With Toilets : Placement Date - 23/07/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Staff Room

No Asbestos Found.

R3 - Staff Toilet

No Asbestos Found.

OS 603 - D16275 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 19/01/2009

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2076_ASB_010713_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017