

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Greta Public School (2084)
Region : Hunter/Central Coast
State Electorate : Cessnock
Local Government Area : Cessnock

Initial Survey : Noel Arnold & Associates : 16 - May - 2008
Reviewed By : AECOM : 18 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Library - 1878 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area					
	- low to ground no access point					
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Height Restriction 4.34m manhole in AR0004					

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - External Movement

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction 3.43m

B00A - R0005 - Home Base Store

No Asbestos

B00A - R0006 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	15m2	assumed to be under vinyl flooring	Good Condition (1)	Low (1)	Low Priority (2-3)
	2084/B00A/R0006/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00A - R0007 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction 3.4m

B00A - R0008 - Withdrawal Space - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2084/B00A/R0006/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00A - R0009 - Reading Area

Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction 3.4m

B00A - R0010 - K.L.A. Store

No Asbestos

B00A - R0011 - External Movement

No Asbestos

B00A - R0012 - Reading Area

Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction 3.4m

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - Staff Room Annexe

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2084/B00A/R0006/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00A - R0015 - Sports Store

No Asbestos

B00A - R0016 - Cleaning Distributed Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings
Res/Textile

Vinyl Sheet

2084/B00A/R0016/Floor Coverings Res/Textile/S7

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1913 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof Non Accessible Area
 - Area inaccessible no access hatch

Underfloor Voids - No Asbestos Found
 Packing to Floor Joists

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Canteen

No Asbestos

B00B - R0005 - Uniform Shop

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1913 - Timber (Timber)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2084/B00C/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown Asbestos)		
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2084/B00C/R0001/Wall Linings Internal/S2					

B00C - R0002 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2084/B00C/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown Asbestos)		
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2084/B00C/R0001/Wall Linings Internal/S2					

B00C - R0003 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2084/B00C/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown Asbestos)		
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2084/B00C/R0001/Wall Linings Internal/S2					

B00C - R0004 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2084/B00C/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown Asbestos)		
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2084/B00C/R0001/Wall Linings Internal/S2					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration/General Learning - 1950 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2084/B00D/Eaves Linings/S3					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00D - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2084/B00D/R0001/Ceiling Structures/Linings/S4					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 2084/B00D/R0001/Wall Linings Internal/S5					No Asbestos Detected

B00D - R0002 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting 2084/B00D/R0001/Ceiling Structures/Linings/S4					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 2084/B00D/R0001/Wall Linings Internal/S5					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration - 1970 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Slab on ground no access point					
Ceiling Voids - Flat Roof	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 2084/B00F/R0001/Wall Linings Internal/S9					No Asbestos Detected

Interior

B00E - R0001 - General Assistant/Bulk Store

No Asbestos

B00E - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1988 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Slab on ground no access point					
Eaves Linings	Flat AC Sheeting 2084/B00F/R0001/Ceiling Structures/Linings/S8					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior**B00F - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2084/B00F/R0001/Ceiling Structures/Linings/S8					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 2084/B00F/R0001/Wall Linings Internal/S9					No Asbestos Detected

B00F - R0003 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 2084/B00F/R0001/Ceiling Structures/Linings/S8					No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet 2084/B00F/R0003/Partition Walls (Cubicles)/S10					No Asbestos Detected

B00F - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 2084/B00F/R0001/Ceiling Structures/Linings/S8					No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet 2084/B00F/R0003/Partition Walls (Cubicles)/S10					No Asbestos Detected

B00F - R0005 - Disabled Toilet

Ceiling Structures/Linings	Flat AC Sheeting 2084/B00F/R0001/Ceiling Structures/Linings/S8					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0002 - Home Base Store

No Asbestos

B00G - R0003 - Practical Activities - 1hb

No Asbestos

B00G - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0006 - Practical Activities - 1hb

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Home Base Store

No Asbestos

B00G - R0009 - Practical Activities - 1hb

No Asbestos

B00G - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0013 - Home Base Store

No Asbestos

B00G - R0014 - Practical Activities - 1hb

No Asbestos

B00G - R0015 - External Movement

No Asbestos

B00G - R0016 - Ramp

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities/General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Covered Outdoor Learning Area

No Asbestos

B00H - R0002 - Communal Space

No Asbestos

B00H - R0003 - Movement

No Asbestos

B00H - R0004 - Movement

No Asbestos

B00H - R0005 - Raised Platform

No Asbestos

B00H - R0006 - Movement

No Asbestos

B00H - R0007 - Hall Chair Store

No Asbestos

B00H - R0008 - Communal/Performance Store

No Asbestos

B00H - R0009 - P.E. Store

No Asbestos

B00H - R0010 - Toilet - Lobby

No Asbestos

B00H - R0011 - Toilets - Girls

No Asbestos

B00H - R0012 - Sound Cupboard

No Asbestos

B00H - R0013 - Toilet - Lobby

No Asbestos

B00H - R0014 - Toilets - Boys

No Asbestos

B00H - R0015 - Cleaning Distributed Store

No Asbestos

B00H - R0016 - General Storeroom

No Asbestos

B00H - R0017 - Main Switch Board

No Asbestos

B00H - R0018 - Access Shower/Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D14138 - Learning Unit - Standard With P.A.A. : Placement Date - 22/04/2014

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos		70 m2
---------	---------------	------------------	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		3 m2

OS 502 - D14517 - Admin Staff/Principal/Clerk/Dup/Clinic : Placement Date - 1/09/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		23.04 m2

Interior

R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		16 m2

R10 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		12 m2
---------	---------------	------------------	--	-------

R2 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos		1 m2
---------	---------------	------------------	--	------

R3 - Duplicating Wookroom

Ceiling	Flat AC Sheet	Assumed Asbestos		12 m2
---------	---------------	------------------	--	-------

R4 - Clinic-Waiting

Ceiling	Flat AC Sheet	Assumed Asbestos		16 m2
---------	---------------	------------------	--	-------

R5 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos		36 m2
---------	---------------	------------------	--	-------

R6 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos		16 m2
---------	---------------	------------------	--	-------

R7 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos		2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		5 m2

R8 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos		2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		5 m2

R9 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		27 m2

OS 840 - D15397 - Girls Toilet : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
-------------	---------------------	------------------	--	---------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				2.88 m2
Interior						
R1 - Toilets-Girls						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017