


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Guildford Public School (2093)  
**Region :** South Western Sydney  
**State Electorate :** Granville  
**Local Government Area :** Holroyd

**Initial Survey :** Noel Arnold & Associates : 18 - Mar - 2008  
**Reviewed By :** AECOM : 26 - May - 2015



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00A - Administration - 1990 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00A - R0001 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0002 - Movement**

No Asbestos

**B00A - R0003 - Staff Toilet**

No Asbestos

**B00A - R0004 - Staff Toilet**

No Asbestos

**B00A - R0005 - Staff Toilet**

No Asbestos

**B00A - R0006 - General Storeroom**

No Asbestos

**B00A - R0007 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0008 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0009 - Duplicating Workroom**

No Asbestos

**B00A - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0011 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0012 - Cleaning Distributed Store**

No Asbestos

**B00A - R0013 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0014 - Sick Bay - Shower/Toilet**

No Asbestos

**B00A - R0015 - Sick Bay**

No Asbestos

**B00A - R0016 - Clerical Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0017 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0018 - Movement**

No Asbestos

**B00A - R0019 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0020 - Staff Room Annexe**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00A - R0021 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities/Pupil Facilities - 1990 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00B - R0001 - Movement**

No Asbestos

**B00B - R0002 - Community Clinic**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0003 - Community Clinic**

No Asbestos

**B00B - R0004 - Community Clinic**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0005 - Cleaning Supplies**

No Asbestos

**B00B - R0006 - P.E. Store**

No Asbestos

**B00B - R0007 - Plant**

No Asbestos

**B00B - R0008 - Hall Chair Store**

No Asbestos

**B00B - R0009 - Communal Space**

No Asbestos

**B00B - R0010 - Raised Platform**

No Asbestos

**B00B - R0011 - Movement**

No Asbestos

**B00B - R0012 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0013 - Staff Toilet**

No Asbestos

**B00B - R0014 - Movement**

No Asbestos

**B00B - R0015 - Canteen**

No Asbestos

**B00B - R0016 - Canteen Office/Store**

No Asbestos

**B00B - R0017 - Cleaning Supplies**

No Asbestos

**B00B - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0019 - Staff Shower/Change**

No Asbestos

**B00B - R0020 - Movement**

No Asbestos

**B00B - R0021 - Plant**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Pupil Facilities - 1990 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00C - R0001 - Movement**

No Asbestos

**B00C - R0002 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0003 - Kiln Room**

No Asbestos

**B00C - R0004 - Toilets - Girls**

No Asbestos

**B00C - R0005 - Toilets - Boys**

No Asbestos

**B00C - R0006 - Personal Effects Storage**

No Asbestos

**B00C - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0008 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0010 - Practical Activities - 1hb**

No Asbestos

**B00C - R0011 - Practical Activities - 1hb**

No Asbestos

**B00C - R0012 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0013 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0014 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0015 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0016 - Personal Effects Storage**

No Asbestos

**B00C - R0017 - Practical Activities - 1hb**

No Asbestos

**B00C - R0018 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0019 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0020 - Practical Activities - 1hb**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00C - R0021 - Personal Effects Storage**

No Asbestos

**B00C - R0022 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0023 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0024 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0025 - Practical Activities - 1hb**

No Asbestos

**B00C - R0026 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00C - R0027 - Cleaning Distributed Store**

No Asbestos

**B00C - R0028 - Disabled Toilet**

No Asbestos

**B00C - R0029 - Toilets - Girls**

No Asbestos

**B00C - R0030 - Toilets - Boys**

No Asbestos

**B00C - R0031 - Plant**

No Asbestos

**B00C - R0032 - Plant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library/Pupil Facilities - 1990 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00D - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0002 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0003 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0004 - Special Programs Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0005 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

**B00D - R0006 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0007 - Communications Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0008 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0009 - Movement**

No Asbestos

**B00D - R9001 - Main Switch Board**

No Asbestos

**B00D - R9002 - Toilets - Girls**

No Asbestos

**B00D - R9003 - General Assistant/Bulk Store**

No Asbestos

**B00D - R9004 - Sports Store**

No Asbestos

**B00D - R9005 - Garden Store**

No Asbestos

**B00D - R9006 - Toilets - Boys**

No Asbestos

**B00D - R9007 - Plant**

No Asbestos

**B00D - R9008 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
<b>B00E - General Learning - 1929 - Brick/Block (Brick/Block)</b>						
<b>Exterior</b>						
Ceiling Voids	Non Accessible Area - Area inaccessible - due to height.					
Underfloor Voids	No Asbestos Found					
<b>Interior</b>						
<b>B00E - R0001 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0002 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0003 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0004 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0005 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0006 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0007 - Staff Room Annexe</b>						
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0008 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0009 - Personal Effects Storage</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0010 - Toilets - Boys/Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0011 - Practical Activities - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	150m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0013 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00E/R0006/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0014 - Personal Effects Storage</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2093/B00E/R0006/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)	
<b>B00E - R0015 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2093/B00E/R0006/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)	
<b>B00E - R0016 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2093/B00E/R0006/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					
2093/B00E/R0016/Floor Coverings Res/Textile/S4					No Asbestos Detected	
<b>B00E - R0017 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2093/B00E/R0006/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)	
<b>B00E - R0018 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2093/B00E/R0006/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)	
<b>B00E - R0019 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2093/B00E/R0006/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)	
<b>B00E - R9001 - Drinking Facilities</b>						
No Asbestos						
<b>B00E - R9002 - Drinking Facilities</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1990 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00F/Eaves Linings/S5				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible - due to low clearance.					

**Interior**

**B00F - R0001 - Special Programs Room**

Panel behind heater	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00F/R0001/panel behind heater/S6				<b>Chrysotile (white asbestos)</b>	

**B00F - R0002 - Special Programs Room**

Panel behind heater	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00F/R0001/panel behind heater/S6				<b>Chrysotile (white asbestos)</b>	

**B00F - R0003 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00F/R0003/Ceiling Structures/Linings/S7				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00F - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00F/R0003/Ceiling Structures/Linings/S7				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	2m2	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00F/R0004/Wall Linings Internal/S8				<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1990 - Timber (Timber)**

**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible - due to low clearance.					

**Interior**

**B00G - R0001 - Movement**

No Asbestos

**B00G - R0002 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00G/R0002/Wall Linings Internal/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Wall Linings Internal	Flat AC Sheeting	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2093/B00G/R0002/Wall Linings Internal/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0003 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Pupil Facilities - 1950 - Timber (Timber)**

**Exterior**

Ceiling Voids - Raked Ceiling      No Asbestos Found

Underfloor Voids - Slab on Ground      No Asbestos Found

**Interior**

**B00H - R0001 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Pupil Facilities - 1950 - Timber (Timber)**

**Exterior**

Ceiling Voids - Raked Ceiling      No Asbestos Found

Underfloor Voids - Slab on Ground      No Asbestos Found

**Interior**

**B001 - R0001 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

### B00L - General Learning/Special Purpose Learning - 2010 - Brick/Veneer (Brick/Veneer)

#### Exterior

No Asbestos

#### Interior

##### B00L - R0001 - Practical Activities

No Asbestos

##### B00L - R0002 - Home Base

No Asbestos

##### B00L - R0003 - Home Base Store

No Asbestos

##### B00L - R0004 - Withdrawal Space - 1hb

No Asbestos

##### B00L - R0005 - Practical Activities - 2hb

No Asbestos

##### B00L - R0006 - Home Base

No Asbestos

##### B00L - R0007 - Home Base Store

No Asbestos

##### B00L - R0008 - Withdrawal Space - 2hb

No Asbestos

##### B00L - R0009 - Practical Activities - 3hb

No Asbestos

##### B00L - R0010 - Home Base

No Asbestos

##### B00L - R0011 - Home Base Store

No Asbestos

##### B00L - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

##### B00L - R0013 - External Movement

No Asbestos

##### B00L - R0014 - External Stairs

No Asbestos

##### B00L - R1001 - Home Base

No Asbestos

##### B00L - R1002 - Home Base Store

No Asbestos

##### B00L - R1003 - Withdrawal Space - 2hb

No Asbestos

##### B00L - R1004 - Practical Activities - 4hb

No Asbestos

##### B00L - R1005 - Home Base

No Asbestos

##### B00L - R1006 - Home Base Store

No Asbestos

##### B00L - R1007 - Withdrawal Space - 1hb

No Asbestos

##### B00L - R1008 - Practical Activities - 4hb

No Asbestos

##### B00L - R1009 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00L - R1010 - Home Base Store</b>						
No Asbestos						
<b>B00L - R1011 - Practical Activities - 4hb</b>						
No Asbestos						
<b>B00L - R1012 - External Movement</b>						
No Asbestos						
<b>B00L - R1013 - External Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 750 - D11601 - Learning Unit - ESL : Placement Date - 17/04/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Esl**

No Asbestos Found.

**OS 602 - D12532 - Learning Unit - Standard With P.A.A. : Placement Date - 4/09/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D12774 - Learning Unit - Standard With P.A.A. : Placement Date - 16/12/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 840 - D12816 - Girls Toilet : Placement Date - 9/08/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Toilets-Girls**

No Asbestos Found.

**OS 602 - D12958 - Learning Unit - Standard With P.A.A. : Placement Date - 6/12/2016**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 750 - D14042 - Learning Unit - ESL : Placement Date - 25/01/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Esl</b>						
No Asbestos Found.						
<b>OS 602 - D14275 - Learning Unit - Standard With P.A.A. : Placement Date - 29/09/2015</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D14442 - Learning Unit - Standard With P.A.A. : Placement Date - 20/03/2014</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D14585 - Learning Unit - Standard With P.A.A. : Placement Date - 3/01/2017</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017