



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Support Unit - 1965 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/Eaves Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Underfloor Voids	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					

**Interior****B00A - R0001 - Movement (13.01 m2)**

No Asbestos

**B00A - R0002 - Movement (13.53 m2)**

No Asbestos

**B00A - R0003 - Movement (60.51 m2)**

No Asbestos

**B00A - R0004 - Movement (13.58 m2)**

No Asbestos

**B00A - R0005 - Home Base (57.01 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

Floor Coverings Res/Textile	Vinyl Tiles	57.01m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0006 - Home Base Store (3.57 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

**B00A - R0007 - Home Base Store (3.57 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

**B00A - R0008 - Personal Effects Storage (9.59 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0009 - Movement (5.25 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0010 - Home Base (57.61 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

Floor Coverings Res/Textile	Vinyl Tiles	57.61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0011 - Home Base (56.97 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00A/R0005/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 2109/B00A/R0008/Floor Coverings Res/Textile/S4	56.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
<b>B00A - R0012 - Home Base Store (3.55 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00A/R0005/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0013 - Home Base Store (3.59 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00A/R0005/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0014 - Personal Effects Storage (9.46 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00A/R0005/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 2109/B00A/R0008/Floor Coverings Res/Textile/S4	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
<b>B00A - R0015 - Movement (5.33 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00A/R0005/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 2109/B00A/R0008/Floor Coverings Res/Textile/S4	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
<b>B00A - R0016 - Home Base (57.61 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00A/R0005/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 2109/B00A/R0008/Floor Coverings Res/Textile/S4	57.61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
<b>B00A - R0017 - Staff Room (52.89 m2)</b>						
No Asbestos						
<b>B00A - R0018 - Main Switch Board (2.92 m2)</b>						
Electrical Backing Board	Resinous Board 2109/B00A/R0018/Electrical Backing Board/S14	3m2	Southeast	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
<b>B00A - R0019 - Stairs (3.95 m2)</b>						
No Asbestos						
<b>B00A - R0020 - Stairs (4.06 m2)</b>						
No Asbestos						
<b>B00A - R1001 - Home Base Store - M (4.47 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00A/R0005/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R1003 - Movement (77.17 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 2109/B00A/R1003/Ceiling Structures/Linings/S16	78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1004 - Home Base (56.69 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	56.69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1005 - Home Base Store (3.6 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00A - R1006 - Home Base Store (3.6 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00A - R1007 - Personal Effects Storage (9.57 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1008 - Movement (5.14 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1009 - Home Base (57.31 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	57.31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1010 - Home Base (57.09 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	57.09m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00A/R0008/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1011 - Home Base Store (3.65 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00A - R1012 - Home Base Store (3.65 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00A - R1013 - Personal Effects Storage (9.46 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00A/R0005/Ceiling Structures/Linings/S13					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R0008/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)	
<b>B00A - R1014 - Movement (5.26 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
2109/B00A/R0005/Ceiling Structures/Linings/S13					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R0008/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)	
<b>B00A - R1015 - Home Base (57.26 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
2109/B00A/R0005/Ceiling Structures/Linings/S13					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	57.26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R0008/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)	
<b>B00A - R1016 - Distribution Board (0.38 m2)</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R1003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Electrical Backing Board	Resinous Board	1m2	Southeast	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R0018/Electrical Backing Board/S14					Chrysotile (white asbestos)	
<b>B00A - R1017 - Home Base - M (58.02 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
2109/B00A/R0005/Ceiling Structures/Linings/S13					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	58.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R0008/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)	
<b>B00A - R1021 - General Storeroom (6.68 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6.68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R0008/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
2109/B00A/R0005/Ceiling Structures/Linings/S13					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00A - R1022 - Stairs (11.72 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11.72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R1003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00A - R1023 - Stairs (11.8 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00A/R1003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00A - Room+1 - Movement</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration - 1965 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00B/Eaves Linings/S12				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0001 - Principal (17.5 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00B/R0009/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0002 - Movement (7.94 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00B/R0002/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00B - R0003 - Entry Vestibule (18.3 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00B/R0009/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0004 - Clerical Office (23.76 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00B/R0009/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0005 - Duplicating Workroom (10.74 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00B/R0009/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0006 - Movement (10.17 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00B/R0009/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0007 - Staff Toilet (4.06 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00B/R0009/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Incinerette	Millboard	1Unit(s)	inside toilet cubicle	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - item inaccessible</b>					

**B00B - R0008 - Distribution Board (0.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00B/R0008/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

Note: No inspection of live electrical installation.

**B00B - R0009 - Cleaning Distributed Store (3.14 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2109/B00B/R0009/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00B/R0009/Floor Coverings Res/Textile/S3				<b>Chrysotile (white asbestos)</b>	

**B00B - R0010 - Staff Toilet (4.91 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite		2109/B00B/R0009/Ceiling Structures/Linings/S2			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R0011 - Sick Bay (9.42 m2)</b>						
Ceiling Structures/Linings	Vermiculite		2109/B00B/R0009/Ceiling Structures/Linings/S2			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R0012 - Interview (9.06 m2)</b>						
Ceiling Structures/Linings	Vermiculite		2109/B00B/R0009/Ceiling Structures/Linings/S2			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R0013 - Deputy Principal (15.61 m2)</b>						
Ceiling Structures/Linings	Vermiculite		2109/B00B/R0009/Ceiling Structures/Linings/S2			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities/General Learning - 1965 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	25m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00C/Eaves Linings/S17				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Ground Surface	AC Fragments/Debris	10m2	Southwest & Southeast	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2109/B00C/Ground Surface/S31				<b>Chrysotile (white asbestos)</b>	

**Interior**

**B00C - R0001 - Movement (83.73 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Northwest	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00C/R0001/Ceiling Structures/Linings/S18				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting					
	2109/B00C/R0001/Ceiling Structures/Linings/S19				<b>No Asbestos Detected</b>	

**B00C - R0002 - Practical Activities - 1hb (11.19 m2)**

No Asbestos

**B00C - R0003 - Home Base (72.68 m2)**

No Asbestos

**B00C - R0004 - Sports Store (22.69 m2)**

No Asbestos

**B00C - R0005 - Toilets - Girls (43.65 m2)**

No Asbestos

**B00C - R0006 - General Assistant/Bulk Store (5.87 m2)**

No Asbestos

**B00C - R0007 - Cleaning Distributed Store (6.53 m2)**

No Asbestos

**B00C - R0008 - Toilets - Boys (48.22 m2)**

No Asbestos

**B00C - R0009 - Canteen (20.43 m2)**

No Asbestos

**B00C - R0010 - Uniform Shop (2.95 m2)**

No Asbestos

**B00C - R0011 - Canteen Office/Store (3.03 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning/Library - 1969 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/Eaves Linings/S24				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Movement (57.28 m2)**

No Asbestos

**B00D - R0002 - Personal Effects Storage (7.25 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00D/R0010/Ceiling Structures/Linings/S20				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21				<b>Chrysotile (white asbestos)</b>	

**B00D - R0003 - Home Base Store (6.26 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00D/R0010/Ceiling Structures/Linings/S20				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21				<b>Chrysotile (white asbestos)</b>	

**B00D - R0004 - Home Base (56.93 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00D/R0010/Ceiling Structures/Linings/S20				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	56.93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21				<b>Chrysotile (white asbestos)</b>	

**B00D - R0005 - Home Base (57.1 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00D/R0010/Ceiling Structures/Linings/S20				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57.1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21				<b>Chrysotile (white asbestos)</b>	

**B00D - R0006 - Home Base Store (6.65 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00D/R0010/Ceiling Structures/Linings/S20				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21				<b>Chrysotile (white asbestos)</b>	

**B00D - R0007 - Home Base Store (5.78 m2)**

Ceiling Structures/Linings	Vermiculite					
	2109/B00D/R0010/Ceiling Structures/Linings/S20				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21				<b>Chrysotile (white asbestos)</b>	

**B00D - R0008 - Distribution Board (0.72 m2)**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Backing Board	Resinous Board	0.2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0008/Electrical Backing Board/S22					<b>Chrysotile (white asbestos)</b>
Stored Sheeting	Flat AC Sheeting	1m2	Southeast	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2109/B00D/R0008/Stored Sheeting/S23					<b>Chrysotile (white asbestos)</b>
<b>B00D - R0009 - Personal Effects Storage (13.99 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	2109/B00D/R0010/Ceiling Structures/Linings/S20					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21					<b>Chrysotile (white asbestos)</b>
<b>B00D - R0010 - Home Base (57.1 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	2109/B00D/R0010/Ceiling Structures/Linings/S20					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57.1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21					<b>Chrysotile (white asbestos)</b>
<b>B00D - R0011 - Cleaning Distributed Store (5.51 m2)</b>						
No Asbestos						
<b>B00D - R0021 - Movement (2.84 m2)</b>						
No Asbestos						
<b>B00D - R0022 - Staff Toilet (3.16 m2)</b>						
No Asbestos						
<b>B00D - R0023 - Stairs (5.39 m2)</b>						
No Asbestos						
<b>B00D - R1001 - Movement (60.17 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R1001/Ceiling Structures/Linings/S25					<b>Chrysotile (white asbestos)</b>
<b>B00D - R1002 - K.L.A. Store (11.15 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	2109/B00D/R0010/Ceiling Structures/Linings/S20					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00D - R1003 - Library Office/Workroom (12.38 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	2109/B00D/R0010/Ceiling Structures/Linings/S20					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00D - R1004 - Reading Area (119.23 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	2109/B00D/R0010/Ceiling Structures/Linings/S20					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00D - R1005 - Home Base Store (5.66 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	2109/B00D/R0010/Ceiling Structures/Linings/S20					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0010/Floor Coverings Res/Textile/S21					<b>Chrysotile (white asbestos)</b>
<b>B00D - R1006 - Distribution Board (0.75 m2)</b>						
Note: No inspection of live electrical installation.						
Electrical Backing Board	Resinous Board	0.3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00D/R0008/Electrical Backing Board/S22					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R1007 - Personal Effects Storage (6.66 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00D/R0010/Ceiling Structures/Linings/S20					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 2109/B00D/R0010/Floor Coverings Res/Textile/S21	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1008 - Home Base (57.02 m2)</b>						
Ceiling Structures/Linings	Vermiculite 2109/B00D/R0010/Ceiling Structures/Linings/S20					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2109/B00D/R0010/Floor Coverings Res/Textile/S21	57.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1009 - Stairs (15.51 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 2109/B00D/R1001/Ceiling Structures/Linings/S25	15.51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Communal Facilities/Pupil Facilities - 1964 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Extreme Access Issue - No Access Point into underfloor voids identified					
Eaves Linings	Flat AC Sheeting 2109/B00F/Eaves Linings/S30	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Wall Cladding	Flat AC Sheeting 2109/B00F/Wall Cladding/S10					<b>No Asbestos Detected</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids	Non Accessible Area - Height Restriction					

**Interior**

**B00F - R0001 - Practical Activities - 1hb (51.9 m2)**

No Asbestos

**B00F - R0002 - Communal Space (296.75 m2)**

No Asbestos

**B00F - R0003 - Movement (8.19 m2)**

No Asbestos

**B00F - R0004 - Toilets - Girls (18.86 m2)**

Wall Linings Internal	Compressed AC Sheet 2109/B00F/R0007/Wall Linings Internal/S8	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles 2109/B00F/R0004/Floor Coverings Res/Textile/S9	9m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 2109/B00F/R0004/Floor Coverings Res/Textile/S27	18.86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**B00F - R0005 - Toilets - Boys (11.89 m2)**

Wall Linings Internal	Compressed AC Sheet 2109/B00F/R0007/Wall Linings Internal/S8	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	---	------	------------	--------------------	---------	--

**B00F - R0006 - Shower/Change (12.6 m2)**

Wall Linings Internal	Compressed AC Sheet 2109/B00F/R0007/Wall Linings Internal/S8	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	---	------	------------	--------------------	---------	--

**B00F - R0007 - Movement (2.2 m2)**

Wall Linings Internal	Compressed AC Sheet 2109/B00F/R0007/Wall Linings Internal/S8	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	---	-----	------------	--------------------	---------	--

**B00F - R0008 - Movement (11.3 m2)**

No Asbestos

**B00F - R0009 - Hall Chair Store (24.1 m2)**

Wall Linings Internal	Flat AC Sheeting 2109/B00F/R0009/Wall Linings Internal/S28	12m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	---	------	------	--------------------	---------	--

**B00F - R0010 - Staff Kitchen (17.8 m2)**

No Asbestos

**B00F - R0011 - Canteen (11.46 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Compressed AC Sheet	4m2	West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00F/R0007/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting					
2109/B00F/R0011/Ceiling Structures/Linings/S29					<b>No Asbestos Detected</b>	
<b>B00F - R0012 - General Storeroom (67.15 m2)</b>						
No Asbestos						
<b>B00F - R0013 - General Storeroom (13.72 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
2109/B00F/R0013/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>	
<b>B00F - R0014 - Movement (12.85 m2)</b>						
No Asbestos						
<b>B00F - R0015 - Movement (9.18 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2109/B00F/Eaves Linings/S30					<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Administration - 1978 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2109/B00G/Eaves Linings/S26					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00G - R0001 - Movement (9.01 m2)**

No Asbestos

**B00G - R0002 - Staff Room Annexe (6.04 m2)**

No Asbestos

**B00G - R0003 - Staff Kitchen (3.79 m2)**

No Asbestos

**B00G - R0004 - Cleaning Distributed Store (1.33 m2)**

No Asbestos

**B00G - R0005 - Interview (17.24 m2)**

No Asbestos

**B00G - R0006 - Staff Room Annexe (5.22 m2)**

No Asbestos

**B00G - R0007 - Staff - Toilet (3.38 m2)**

No Asbestos

**B00G - R0008 - Plant (1.77 m2)**

No Asbestos

**B00G - R0009 - Staff - Toilet (2.61 m2)**

No Asbestos

**B00G - R0010 - Movement (19.02 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00H - R0001 - External Movement (48.15 m2)**

No Asbestos

**B00H - R0002 - Home Base (67.58 m2)**

No Asbestos

**B00H - R0003 - Home Base Store (5.9 m2)**

No Asbestos

**B00H - R0004 - Access Shower/Toilet/Change (18.12 m2)**

No Asbestos

**B00H - R0005 - Laundry - S (5.12 m2)**

No Asbestos

**B00H - R0006 - Access Shower/Toilet/Change (6.12 m2)**

No Asbestos

**B00H - R0007 - Plant (0.43 m2)**

No Asbestos

**B00H - R0008 - Home Base (67.72 m2)**

No Asbestos

**B00H - R0009 - Home Base Store (5.9 m2)**

No Asbestos

**B00H - R0010 - Practical Activities - 2hb (38.77 m2)**

No Asbestos

**B00H - R0011 - Distribution Board (0.84 m2)**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017