


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Gunning Public School (2111)  
**Region :** Illawarra and South East  
**State Electorate :** Goulburn  
**Local Government Area :** Upper Lachlan

**Initial Survey :** Noel Arnold & Associates : 08 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 13 - Jul - 2015



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Pupil Facilities - 1966 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00A/Eaves Linings/S6				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids - Lining above corrugated metal	Flat AC Sheeting	64m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2111/B00A/Ceiling Voids - Lining above corrugated metal/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	5m2	North, south	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2111/B00A/Gable Verge Lining/S7				<b>Chrysotile (white asbestos)</b>	

**Interior**

**B00A - R0002 - Toilets - Boys**

No Asbestos

**B00A - R0003 - Cleaning Distributed Store**

No Asbestos

**B00A - R0004 - Toilets - Girls**

No Asbestos

**B00A - R0005 - Cleaning Distributed Store**

No Asbestos

**B00A - R0007 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00A/Eaves Linings/S6				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00A - R0010 - Toilet - Lobby**

No Asbestos

**B00A - R0011 - Toilets - Girls**

No Asbestos

**B00A - R0012 - Toilets - Boys**

No Asbestos

**B00A - R0013 - Toilet - Lobby**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1915 - Timber (Timber)**

**Exterior**

Ceiling Voids - Ceiling Access Cover	Flat AC Sheeting	1m2	BR0001	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2111/B00B/Ceiling Voids - Ceiling Access Cover/S8					<b>Chrysotile (white asbestos)</b>	
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00B - R0001 - Canteen**

Wall Linings Internal	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00B/R0007/Wall Linings Internal/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00B - R0003 - Home Base**

Wall Linings Internal	Flat AC Sheeting	60m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00B/R0007/Wall Linings Internal/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00B - R0004 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2111/B00B/R0004/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00B - R0005 - Movement**

No Asbestos

**B00B - R0006 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00B/R0006/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	

**B00B - R0007 - Special Programs Room**

Wall Linings Internal	Flat AC Sheeting	60m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00B/R0007/Wall Linings Internal/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00B - R0008 - Craft Store**

No Asbestos

**B00B - R0009 - Craft Store**

No Asbestos

**B00B - R0010 - Cleaning Supplies**

No Asbestos

**B00B - R0011 - Movement**

No Asbestos

**B00B - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0013 - Handwashing Facilities**

No Asbestos

**B00B - R0020 - Toilet - Lobby**

Wall Linings Internal	Flat AC Sheeting	7.5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00B/R0007/Wall Linings Internal/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00B - R0021 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting	7.5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00B/R0007/Wall Linings Internal/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1966 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00C/R0002/Ceiling Structures/Linings/S12				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Gable Verge Lining	Flat AC Sheeting	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No access due to height restrictions.</b>						
Underfloor Voids	Non Accessible Area - No key available during inspection					
Ceiling Voids - Ceiling Access Cover	Flat AC Sheeting	1m2	CR0005	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2111/B00C/Ceiling Voids - Ceiling Access Cover/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids - Packing to roof joists	Millboard	1m2	Above CR0005	Friable Asbestos (5)	Low (1)	High Priority (6-8)
2111/B00C/Ceiling Voids - Packing to roof joists/S13				<b>Chrysotile (white asbestos)</b>		

**Interior**

**B00C - R0001 - Distribution Board** Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00C/R0002/Ceiling Structures/Linings/S12				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0003 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0004 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0005 - Home Base Store**

No Asbestos

**B00C - R0006 - Home Base**

No Asbestos

**B00C - R0007 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2111/B00B/R0004/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>		

**B00C - R0009 - Home Base Store**

No Asbestos

**B00C - R0010 - Movement**

No Asbestos

**B00C - R0011 - Home Base**

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Adjacent to sink	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2111/B00B/R0004/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>		

**B00C - R0012 - Home Base Store**

No Asbestos

**B00C - R0013 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00C/R0002/Ceiling Structures/Linings/S12				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0014 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0015 - Sports Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00C/R0002/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities - 1915 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting 2111/B00D/Eaves Linings/S14					<b>No Asbestos Detected</b>
Ceiling Voids	Non Accessible Area - No ceiling access hatch to void					
Underfloor Voids	Non Accessible Area - Void is too small					

**Interior**

**B00D - R0001 - Communal Space**

Wall Linings Internal	Flat AC Sheeting	90m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00D/R0001/Wall Linings Internal/S15					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00D - R0002 - Movement**

No Asbestos

**B00D - R0003 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1955 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00E/R0003/Ceiling Structures/Linings/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	Non Accessible Area - No access to void. Access point is above 3.3 metres.					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00E - R0001 - Home Base**

Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00E/R0001/Electrical Backing Board/S17			<b>Chrysotile (white asbestos)</b>		
Electrical Cupboard Lining	Flat AC Sheeting	1m2	North	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2111/B00E/R0001/Electrical Cupboard Lining/S18			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		

**B00E - R0002 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00E/R0003/Ceiling Structures/Linings/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00E - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00E/R0003/Ceiling Structures/Linings/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Administration/Staff Facilities - 1871 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00F/Eaves Linings/S19				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Wall Cladding	Flat AC Sheeting	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00F/Wall Cladding/S4				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00F - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00F/Wall Cladding/S4				<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00F/Wall Cladding/S4				<b>Chrysotile (white asbestos)</b>	

**B00F - R0010 - External Movement**

No Asbestos

**B00F - R0011 - Principal**

No Asbestos

**B00F - R0012 - Movement**

No Asbestos

**B00F - R0013 - Clerical Office**

No Asbestos

**B00F - R0014 - Movement**

No Asbestos

**B00F - R0015 - Sick Bay**

No Asbestos

**B00F - R0016 - Staff Toilet**

No Asbestos

**B00F - R0017 - Staff Room**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1910 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting 2111/B00G/Eaves Linings/S20					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00G - R0001 - Withdrawal Space - 1hb**

No Asbestos

**B00G - R0002 - Home Base Store**

No Asbestos

**B00G - R0003 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00G/R0006/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00G - R0004 - Home Base**

No Asbestos

**B00G - R0005 - Special Programs Room**

No Asbestos

**B00G - R0006 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00G/R0006/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

Wall Linings Internal	Flat AC Sheeting 2111/B00G/R0007/Wall Linings Internal/S3					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

**B00G - R0007 - Movement**

Wall Linings Internal	Flat AC Sheeting 2111/B00G/R0007/Wall Linings Internal/S3					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00H - Administration - 1925 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/Eaves Linings/S21				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00H - R0001 - Movement**

Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0001/Electrical Backing Board/S22				<b>Chrysotile (white asbestos)</b>	

**B00H - R0002 - Entry Vestibule**

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Wall Linings Internal/S24				<b>Chrysotile (white asbestos)</b>	

**B00H - R0003 - Clerical Office/Workroom**

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Wall Linings Internal/S24				<b>Chrysotile (white asbestos)</b>	

**B00H - R0004 - Duplicating Workroom**

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Wall Linings Internal/S24				<b>Chrysotile (white asbestos)</b>	

**B00H - R0005 - Staff Shower/Change**

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Wall Linings Internal/S24				<b>Chrysotile (white asbestos)</b>	

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Ceiling Structures/Linings/S23				<b>Chrysotile (white asbestos)</b>	

**B00H - R0006 - Sick Bay**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Ceiling Structures/Linings/S23				<b>Chrysotile (white asbestos)</b>	

**B00H - R0007 - Movement**

No Asbestos

**B00H - R0008 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Wall Linings Internal/S24				<b>Chrysotile (white asbestos)</b>	

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Ceiling Structures/Linings/S23				<b>Chrysotile (white asbestos)</b>	

**B00H - R0009 - Uniform Shop**

Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Wall Linings Internal/S24				<b>Chrysotile (white asbestos)</b>	

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Ceiling Structures/Linings/S23				<b>Chrysotile (white asbestos)</b>	

**B00H - R0010 - Staff Room**

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B00H/R0008/Wall Linings Internal/S24				<b>Chrysotile (white asbestos)</b>	

**B00H - R0011 - Staff Room Annexe**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00H/R0008/Wall Linings Internal/S24					Chrysotile (white asbestos)	
<b>B00H - R0012 - Movement</b>						
Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2111/B00H/R0008/Wall Linings Internal/S24					Chrysotile (white asbestos)	
<b>B00H - R0013 - Principal</b>						
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2111/B00H/R0008/Wall Linings Internal/S24					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Building Services - 1960 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Wall Cladding	Flat AC Sheeting	40m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2111/B001/Wall Cladding/S25			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Ends	Flat AC Sheeting	3m2	North, south	Good Condition (1)	Low (1)	Low Priority (2-3)
	2111/B001/Wall Cladding/S25			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**Interior**

**B001 - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Building Services - 1955 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids                      Non Accessible Area  
 - No ceiling access hatch to void.

Underfloor Voids - Slab        No Asbestos Found  
 on Ground

**Interior**

**B00J - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Library - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00K - R0001 - External Movement**

No Asbestos

**B00K - R0002 - Library Office/Workroom**

No Asbestos

**B00K - R0003 - General Storeroom**

No Asbestos

**B00K - R0004 - Communications Room**

No Asbestos

**B00K - R0005 - Reading Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 837 - D14244 - Hcap Shower/Change/Toilet : Placement Date - 19/08/2016**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Disabled Shower/Toilet**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017