


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gymea Bay Public School (2116)
Region : Sydney
State Electorate : Cronulla
Local Government Area : Sutherland

Initial Survey : Noel Arnold & Associates : 13 - Jun - 2008
Reviewed By : AECOM : 29 - Oct - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1954 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Ends	Flat AC Sheeting	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Height Restriction					

Interior

B00A - R0001 - Home Base (67.57 m2)

No Asbestos

B00A - R0002 - Home Base Store (8.68 m2)

No Asbestos

B00A - R0003 - Personal Effects Storage (3.86 m2)

No Asbestos

B00A - R0004 - Movement (3.7 m2)

No Asbestos

B00A - R0005 - Movement (3.86 m2)

No Asbestos

B00A - R0006 - Home Base (67.42 m2)

No Asbestos

B00A - R0007 - Home Base Store (7.92 m2)

No Asbestos

B00A - R0008 - Personal Effects Storage (3.45 m2)

No Asbestos

B00A - R0009 - Movement (17.51 m2)

No Asbestos

B00A - R0011 - Special Programs Room (19.38 m2)

No Asbestos

B00A - R0012 - Cleaning Distributed Store (2.67 m2)

No Asbestos

B00A - R0013 - Personal Effects Storage (3.46 m2)

No Asbestos

B00A - R0014 - Home Base Store (8.03 m2)

No Asbestos

B00A - R0015 - Special Programs Room (67.43 m2)

No Asbestos

B00A - R0016 - Staff Room Annexe (13.21 m2)

No Asbestos

B00A - R0017 - Duplicating Workroom (13.14 m2)

No Asbestos

B00A - R0018 - Sick Bay (6.64 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0019 - Deputy Principal (18.98 m2)						
No Asbestos						
B00A - R0020 - Movement (3.48 m2)						
No Asbestos						
B00A - R0021 - Staff Toilet (2.08 m2)						
No Asbestos						
B00A - R0022 - Principal (18.05 m2)						
No Asbestos						
B00A - R0023 - Entry Vestibule (22.42 m2)						
No Asbestos						
B00A - R0025 - Clerical Office (14.42 m2)						
No Asbestos						
B00A - R0026 - Clerical Office/Workroom (17.32 m2)						
No Asbestos						
B00A - R0027 - Movement (5.81 m2)						
No Asbestos						
B00A - R0028 - External Movement (84.43 m2)						
No Asbestos						
B00A - R9001 - General Storeroom (63.55 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	64m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R9004/Ceiling Structures/Linings/S31			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	6m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R9001/Wall Linings Internal/S32			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9002 - General Assistant/Bulk Store (8.07 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R9004/Ceiling Structures/Linings/S31			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9003 - General Assistant/Bulk Store (7.57 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R9004/Ceiling Structures/Linings/S31			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9004 - General Assistant/Bulk Store (16.56 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R9004/Ceiling Structures/Linings/S31			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9005 - Craft Store (48.27 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/Tiered Learning - 1966 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Extreme Access Issue - Roof					
Wall Cladding	Flat AC Sheeting 2116/B00B/R0001/Wall cladding/S26					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00B - R0001 - Movement (73.68 m2)

Wall cladding	Flat AC Sheeting 2116/B00B/R0001/Wall cladding/S26					No Asbestos Detected
---------------	---	--	--	--	--	-----------------------------

B00B - R0002 - Special Programs Room (42.72 m2)

No Asbestos

B00B - R0003 - Special Programs Store (4.87 m2)

No Asbestos

B00B - R0004 - Distribution Board (0.58 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 2116/B00B/R0001/Wall cladding/S26					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 2116/B00B/R0001/Wall cladding/S26					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0005 - Cleaning Distributed Store (1.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting 2116/B00B/R0001/Wall cladding/S26					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0006 - Library Office/Workroom (25.95 m2)

No Asbestos

B00B - R0007 - K.L.A. Store (12.05 m2)

No Asbestos

B00B - R0008 - Reading Area (219.58 m2)

In-fill panel to door	Compressed AC Sheet 2116/B00B/R0008/In-fill panel to door/S25	5m2	South facing, East facing, West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------	--	-----	--	--------------------	---------	--

B00B - R0009 - Movement (13.99 m2)

Wall cladding	Flat AC Sheeting 2116/B00B/R0001/Wall cladding/S26					No Asbestos Detected
---------------	---	--	--	--	--	-----------------------------

B00B - R0010 - Movement (13.98 m2)

Wall cladding	Flat AC Sheeting 2116/B00B/R0001/Wall cladding/S26					No Asbestos Detected
---------------	---	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1961 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00C/R0005/Wall Linings Internal/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Flat AC Sheeting	NA	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
2116/B00E/R0001/Ceiling Structures/Linings/S16				Chrysotile (white asbestos)		

Interior

B00C - M0001 - Plant (18.18 m2)

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2116/B00C/R0005/Wall Linings Internal/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Wall Linings Internal	Flat AC Sheeting	2116/B00B/R0001/Wall cladding/S26				No Asbestos Detected
-----------------------	------------------	-----------------------------------	--	--	--	-----------------------------

B00C - R0001 - Movement (13.5 m2)

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Assumed to contain asbestos						

B00C - R0002 - Hall Chair Store (18.57 m2)

No Asbestos

B00C - R0005 - Staff Kitchen (15.47 m2)

Wall Linings Internal	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00C/R0005/Wall Linings Internal/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0006 - External Movement (6.92 m2)

No Asbestos

B00C - R0007 - Movement (18.08 m2)

No Asbestos

B00C - R0008 - Communal/Performance Store (23.04 m2)

No Asbestos

B00C - R0009 - Communal/Performance Store (22.82 m2)

No Asbestos

B00C - R0011 - Lift (1.2 m2)

No Asbestos

B00C - R0012 - Raised Platform (85.9 m2)

No Asbestos

B00C - R0013 - Disabled Toilet (13.51 m2)

No Asbestos

B00C - R0014 - External Movement (73.79 m2)

Ceiling Structures/Linings	Flat AC Sheeting	74m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00C/R0014/Ceiling Structures/Linings/S33				Chrysotile (white asbestos)		

B00C - R0015 - External Movement (14.23 m2)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00C/R0014/Ceiling Structures/Linings/S33				Chrysotile (white asbestos)		

B00C - R0016 - Communal Space (314.66 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Music/Staff Facilities - 1954 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m	East facing, West facing, All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement (4.28 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0002 - Staff Room Annexe (18.1 m2)

No Asbestos

B00D - R0003 - Staff Toilet (2.06 m2)

No Asbestos

B00D - R0004 - Uniform Shop (18.45 m2)

No Asbestos

B00D - R0005 - Movement (19.77 m2)

No Asbestos

B00D - R0006 - Personal Effects Storage (19.91 m2)

No Asbestos

B00D - R0007 - Home Base Store (8.81 m2)

No Asbestos

B00D - R0008 - Home Base (45.82 m2)

No Asbestos

B00D - R0009 - General Storeroom (3.09 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1954 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting	30m2	North facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00E/Wall Cladding/S14					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Withdrawal Space - 1hb (29.51 m2)

Wall Linings Internal	Flat AC Sheeting	30m2	North facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00E/R0001/Wall Linings Internal/S15					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00E/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

B00E - R0002 - Home Base Store (12.86 m2)

No Asbestos

B00E - R0003 - Home Base (83.25 m2)

No Asbestos

B00E - R0004 - Personal Effects Storage (7.12 m2)

Wall Linings Internal	Flat AC Sheeting	20m2	North facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00E/R0001/Wall Linings Internal/S15					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00E/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles					
	2116/B00E/R0004/Floor Coverings Res/Textile/S17					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00G - General Learning - 1954 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Fibre Cement Pipe	3m	Lower portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Redundant asbestos cement pipe					

Interior

B00G - R0001 - Home Base (57.08 m2)

No Asbestos

B00G - R0002 - Home Base Store (6.7 m2)

No Asbestos

B00G - R0003 - Personal Effects Storage (8.1 m2)

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2116/B00G/R0003/Wall Linings Internal/S8					

B00G - R0004 - Movement (5.02 m2)

No Asbestos

B00G - R0005 - Movement (4.77 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel above Door	Flat AC Sheeting	2m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0006 - Home Base Store (6.71 m2)

No Asbestos

B00G - R0007 - Home Base (56.38 m2)

No Asbestos

B00G - R0008 - Home Base (56.38 m2)

No Asbestos

B00G - R0009 - Home Base Store (6.76 m2)

No Asbestos

B00G - R0010 - Personal Effects Storage (7.36 m2)

No Asbestos

B00G - R0011 - Movement (4.81 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel above Door	Flat AC Sheeting	2m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1983 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	11m	East facing, West facing, All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Non Accessible Area - Area inaccessible. Access to ceiling could no be located.					
Underfloor Voids - Packing to Floor Joists	Packing	NA	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00H - R0001 - Home Base (66.03 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	2116/B00H/R0001/Floor Coverings Res/Textile/S10			No Asbestos Detected		

B00H - R0002 - Toilets - Boys/Girls (8.01 m2)

No Asbestos

B00H - R0003 - Toilets - Boys/Girls (3.53 m2)

No Asbestos

B00H - R0004 - Movement (17.6 m2)

No Asbestos

B00H - R0005 - Movement (5.18 m2)

No Asbestos

B00H - R0006 - General Storeroom (2.71 m2)

No Asbestos

B00H - R0007 - Withdrawal Space - 1hb (19.38 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	2116/B00H/R0007/Floor Coverings Res/Textile/S9			No Asbestos Detected		

B00H - R0008 - Toilets - Boys/Girls (3.49 m2)

No Asbestos

B00H - R0009 - Home Base Store (8.01 m2)

No Asbestos

B00H - R0010 - Home Base (65.85 m2)

No Asbestos

B00H - R0011 - Home Base (65.85 m2)

No Asbestos

B00H - R0012 - Home Base Store (8 m2)

No Asbestos

B00H - R0013 - Personal Effects Storage (3.47 m2)

No Asbestos

B00H - R0014 - Personal Effects Storage (3.47 m2)

No Asbestos

B00H - R0015 - Movement (7.86 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R0016 - Movement (5.22 m2)						
No Asbestos						
B00H - R0017 - Home Base Store (7.98 m2)						
No Asbestos						
B00H - R0018 - Home Base (67.33 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 1954 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00A/R0024/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B001 - R0001 - Home Base (55.41 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0002 - Home Base Store (6.72 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0003 - Personal Effects Storage (6.72 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0004 - Movement (19.44 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0005 - Movement (8.41 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0006 - Cleaning Supplies (8.14 m2)

Electrical Backing Board	Resinous Board	0.5m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Flat bituminous sheet in electrical						

B001 - R0007 - Sports Store (14.43 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0008 - Cleaning Distributed Store (2.92 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0009 - Personal Effects Storage (9.61 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0010 - Home Base Store (6.53 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0011 - Home Base (55.41 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2116/B001/R0002/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0012 - Stairs (4.35 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R1001 - Home Base (55.42 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B001 - R1002 - Home Base Store (6.73 m2)

Floor Coverings Res/Textile Vinyl Tiles 7m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 2116/B001/R1004/Floor Coverings Res/Textile/S13 **Chrysotile (white asbestos)**

B001 - R1003 - Personal Effects Storage (6.73 m2)

Floor Coverings Res/Textile Vinyl Tiles 7m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 2116/B001/R1004/Floor Coverings Res/Textile/S13 **Chrysotile (white asbestos)**

B001 - R1004 - Movement (19.15 m2)

Floor Coverings Res/Textile Vinyl Tiles 20m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 2116/B001/R1004/Floor Coverings Res/Textile/S13 **Chrysotile (white asbestos)**

B001 - R1005 - General Storeroom (14.69 m2)

Floor Coverings Res/Textile Vinyl Tiles 15m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 2116/B001/R1004/Floor Coverings Res/Textile/S13 **Chrysotile (white asbestos)**

B001 - R1006 - Cleaning Distributed Store (2.92 m2)

Floor Coverings Res/Textile Vinyl Tiles 5m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
Assumed Asbestos - Vinyl tiles assumed to contain

B001 - R1007 - Personal Effects Storage (9.7 m2)

Floor Coverings Res/Textile Vinyl Tiles 10m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 2116/B001/R1004/Floor Coverings Res/Textile/S13 **Chrysotile (white asbestos)**

B001 - R1008 - Home Base Store (6.54 m2)

Floor Coverings Res/Textile Vinyl Tiles 7m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 2116/B001/R1004/Floor Coverings Res/Textile/S13 **Chrysotile (white asbestos)**

B001 - R1009 - Home Base (55.42 m2)

No Asbestos

B001 - R1010 - Stairs (13.79 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00J - General Learning/Staff Facilities - 1954 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	180m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	50m	East facing, West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Ends	Flat AC Sheeting	100m2	East facing, West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	NA	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	Assumed Asbestos - Loose fragmented AC debris located					

Interior

B00J - R0001 - Outdoor Learning Area (31.95 m2)

No Asbestos

B00J - R0002 - Outdoor Learning Area (31.95 m2)

No Asbestos

B00J - R0003 - Home Base (66.8 m2)

Ceiling Structures/Linings	Flat AC Sheeting	66m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	25m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0004 - Toilets - Boys/Girls (3.92 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0005 - Personal Effects Storage (23.19 m2)

Ceiling Structures/Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Floor Coverings Res/Textile

Vinyl Tiles	2116/B00J/R0036/Floor Coverings Res/Textile/S18					No Asbestos Detected
-------------	---	--	--	--	--	-----------------------------

B00J - R0006 - Home Base (53.44 m2)

Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	25m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00J - R0007 - Personal Effects Storage (10.92 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0008 - Home Base (64.71 m2)						
Panel behind heater	Flat AC Sheeting	2m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0008/Panel behind heater/S21				Chrysotile (white asbestos)		
B00J - R0009 - Movement (4.64 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0010 - Movement (3.15 m2)						
No Asbestos						
B00J - R0011 - Personal Effects Storage (12.41 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
2116/B00J/R0029/Floor Coverings Res/Textile/S19				No Asbestos Detected		
B00J - R0012 - Home Base (53.59 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	25m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0013 - Home Base (53.59 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	25m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0014 - General Storeroom (6.37 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0015 - Personal Effects Storage (6.53 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
2116/B00J/R0029/Floor Coverings Res/Textile/S19				No Asbestos Detected		
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0016 - Home Base (53.59 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Wall Linings Internal	Flat AC Sheeting	25m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0017 - Staff Toilet (1.64 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0018 - Movement (4.43 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0019 - Movement (6.86 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0020 - Other-Community Use (23.72 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0021 - Cleaning Distributed Store (3.31 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0022 - Staff Room Annexe (13.95 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0023 - Staff Toilet (4.15 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0024 - Staff Room Annexe (14.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0025 - Movement (6.84 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
2116/B00J/R0029/Floor Coverings Res/Textile/S19				No Asbestos Detected		
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00J/R0040/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0026 - Movement (6.55 m2)						
No Asbestos						
B00J - R0027 - Home Base (53.59 m2)						
No Asbestos						
B00J - R0028 - Home Base (53.59 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00J - R0029 - Personal Effects Storage (13.32 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	2116/B00J/R0029/Floor Coverings Res/Textile/S19					No Asbestos Detected
Loft Hatch	Flat AC Sheeting	1Unit(s)	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0030 - Home Base (53.59 m2)						
No Asbestos						
B00J - R0031 - Home Base (53.59 m2)						
No Asbestos						
B00J - R0032 - General Storeroom (16.57 m2)						
No Asbestos						
B00J - R0033 - Craft Store (11.87 m2)						
Ceiling Space Access Panel	Flat AC Sheeting	1m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0034 - Personal Effects Storage (7.96 m2)						
No Asbestos						
B00J - R0035 - Home Base (65.27 m2)						
No Asbestos						
B00J - R0036 - Personal Effects Storage (11.8 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	2116/B00J/R0036/Floor Coverings Res/Textile/S18					No Asbestos Detected
B00J - R0037 - Movement (3.61 m2)						
No Asbestos						
B00J - R0040 - Movement (138.25 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Eastern Half	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0041 - Home Base (66.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	67m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	25m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00J/R0040/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0042 - Movement (260.4 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities/Building Services - 1954 - Concrete (Concrete)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting 2116/B00L/Gable Verge Lining/S34					No Asbestos Detected
Gable Ends	Flat AC Sheeting 2116/B00L/Gable Ends/S33					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 2116/B00L/Eaves Linings/S35					No Asbestos Detected

Interior

B00L - R0001 - Movement (19.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00L/R0001/In-fill over window/S30					Chrysotile (white asbestos)
In-fill-panel above Window	Flat AC Sheeting	2m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00L/R0001/In-fill over window/S30					Chrysotile (white asbestos)

B00L - R0002 - Canteen Office/Store (6.67 m2)

No Asbestos

B00L - R0003 - Staff Toilet (3.12 m2)

No Asbestos

B00L - R0004 - Canteen Office/Store (2.6 m2)

No Asbestos

B00L - R0005 - Canteen (51.4 m2)

No Asbestos

B00L - R0006 - Special Programs Room (23.71 m2)

No Asbestos

B00L - R0007 - Cleaning Supplies (5.44 m2)

No Asbestos

B00L - R0008 - Staff Toilet (5.49 m2)

No Asbestos

B00L - R0009 - Cleaning Supplies (7.95 m2)

No Asbestos

B00L - R0010 - Sports Store (5.06 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00L/R0001/In-fill over window/S30					Chrysotile (white asbestos)

B00L - R0011 - Toilets - Girls (30.42 m2)

Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00L/R0001/In-fill over window/S30					Chrysotile (white asbestos)

B00L - R0012 - Drinking Facilities (13.36 m2)

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00L/R0001/In-fill over window/S30					Chrysotile (white asbestos)

B00L - R0013 - Drinking Facilities (13.36 m2)

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00L/R0001/In-fill over window/S30					Chrysotile (white asbestos)

B00L - R0014 - Toilets - Boys (30.13 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00L/R0001/In-fill over window/S30					Chrysotile (white asbestos)	

B00L - R0015 - Movement (136.41 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00M - Staff Facilities - 1954 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Ends	Flat AC Sheeting	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00M - R0001 - General Storeroom (9.72 m2)

No Asbestos

B00M - R0002 - Movement (6.55 m2)

No Asbestos

B00M - R0003 - Movement (3.31 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00M - R0004 - No Access (134.96 m2)

No Asbestos

B00M - R0005 - Movement (1.91 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00M - R0006 - Movement (4.18 m2)

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2116/B00M/R0006/Wall Linings Internal/S27					

B00M - R0007 - Staff Toilet (2.16 m2)

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2116/B00M/R0006/Wall Linings Internal/S27					

B00M - R0008 - Staff Toilet (2.16 m2)

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2116/B00M/R0006/Wall Linings Internal/S27					

B00M - R0009 - Movement (7.34 m2)

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2116/B00M/R0006/Wall Linings Internal/S27					

B00M - R0010 - Movement (2.27 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00N - Pupil Facilities/Building Services - 1954 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Gable Verge Lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Ends	Flat AC Sheeting	30m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Height Restriction					

Interior

B00N - R0001 - Drinking Facilities (3.6 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00N - R0002 - Handwashing Facilities (29.14 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00N - R0003 - Toilets - Boys (39.03 m2)

Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00N - R0004 - Cleaning Distributed Store (2.7 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Upper portion	Good Condition (1)	Medium (2)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00N - R0005 - Movement (3.6 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Pupil Facilities/Building Services - 1954 - Concrete (Concrete)

Exterior

Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m	East facing, West facing, All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Height Restriction					

Interior

B000 - R0001 - Toilets - Girls (51.78 m2)

Ceiling Structures/Linings	Flat AC Sheeting	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B000 - R0002 - Cleaning Distributed Store (1.4 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B000 - R0003 - Drinking Facilities (18.19 m2)

Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2116/B00M/R0003/Ceiling Structures/Linings/S28			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Building Services - 1954 - Timber Shed (Timber Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0001 - General Assistant/Bulk Store (26.06 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Other-After School Care - 2004 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2116/B00Q/Eaves Linings/S3	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting 2116/B00Q/Wall Cladding/S2					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 2116/B00Q/Wall Cladding/S1					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00Q - R0001 - Out Of School Hours Care Centre (8.61 m2)

Wall Linings Internal	Flat AC Sheeting 2116/B00Q/R0001/Wall Linings Internal/S5	6m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 2116/B00Q/R0001/Ceiling Structures/Linings/S4					No Asbestos Detected

B00Q - R0002 - Out Of School Hours Care Centre (9.33 m2)

No Asbestos

B00Q - R0003 - Out Of School Hours Care Centre (13.12 m2)

No Asbestos

B00Q - R0004 - Out Of School Hours Care Centre (53.81 m2)

No Asbestos

B00Q - R0005 - Out Of School Hours Care Centre (37.21 m2)

Wall Linings Internal	Flat AC Sheeting 2116/B00Q/R0001/Wall Linings Internal/S5	4m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 2116/B00Q/R0001/Ceiling Structures/Linings/S4					No Asbestos Detected
In-fill-panel below Window	Flat AC Sheeting 2116/B00Q/Wall Cladding/S2					No Asbestos Detected

B00Q - R0006 - Out Of School Hours Care Centre (31.01 m2)

No Asbestos

B00Q - R0007 - Out Of School Hours Care Centre (21.99 m2)

No Asbestos

B00Q - R0008 - Out Of School Hours Care Centre (12.53 m2)

Floor Coverings Res/Textile	Vinyl Tiles 2116/B00Q/R0008/Floor Coverings Res/Textile/S6					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00Q - R0009 - Out Of School Hours Care Centre (5.39 m2)

Floor Coverings Res/Textile	Vinyl Tiles 2116/B00Q/R0009/Floor Coverings Res/Textile/S7					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00Q - R0010 - Toilets - Girls (2.25 m2)

No Asbestos

B00Q - R0011 - Movement (1.28 m2)

No Asbestos

B00Q - R0012 - Toilets - Boys (2.06 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	12m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
2116/B00Q/R0001/Wall Linings Internal/S5					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting					
2116/B00Q/R0001/Ceiling Structures/Linings/S4					No Asbestos Detected	

B00Q - R0013 - Movement (4.15 m2)

No Asbestos

B00Q - R0014 - Movement (1.3 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00R - R0001 - Movement (38.48 m2)

No Asbestos

B00R - R0002 - Practical Activities - 1hb (19.4 m2)

No Asbestos

B00R - R0003 - Home Base Store (6.02 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0004 - Home Base (59.19 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0005 - Withdrawal Space - 2hb (11.35 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0006 - Home Base (59.2 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0007 - Home Base Store (6.02 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0008 - Practical Activities - 1hb (19.4 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00S - R0001 - Home Base (59.8 m2)

No Asbestos

B00S - R0002 - Practical Activities - 1hb (18.64 m2)

No Asbestos

B00S - R0003 - Withdrawal Space - 1hb (8.95 m2)

No Asbestos

B00S - R0004 - Home Base Store (5.79 m2)

No Asbestos

B00S - R0005 - Home Base (60.53 m2)

No Asbestos

B00S - R0006 - Home Base Store (6.26 m2)

No Asbestos

B00S - R0007 - Practical Activities - 1hb (18.84 m2)

No Asbestos

B00S - R0008 - Withdrawal Space - 2hb (12.52 m2)

No Asbestos

B00S - R0009 - Home Base (60.46 m2)

No Asbestos

B00S - R0010 - Home Base Store (6.08 m2)

No Asbestos

B00S - R0011 - Practical Activities - 1hb (18.47 m2)

No Asbestos

B00S - R0012 - External Movement (77.68 m2)

No Asbestos

B00S - R0013 - External Stairs (20.64 m2)

No Asbestos

B00S - R0014 - External Stairs (20.68 m2)

No Asbestos

B00S - R1001 - Home Base (59.45 m2)

No Asbestos

B00S - R1002 - Practical Activities - 1hb (18.59 m2)

No Asbestos

B00S - R1003 - Withdrawal Space - 1hb (8.86 m2)

No Asbestos

B00S - R1004 - Home Base Store (5.77 m2)

No Asbestos

B00S - R1005 - Home Base (60.07 m2)

No Asbestos

B00S - R1006 - Home Base Store (6.29 m2)

No Asbestos

B00S - R1007 - Practical Activities - 1hb (18.85 m2)

No Asbestos

B00S - R1008 - Withdrawal Space - 2hb (12.52 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00S - R1009 - Home Base (60.17 m2)

No Asbestos

B00S - R1010 - Home Base Store (6.05 m2)

No Asbestos

B00S - R1011 - Practical Activities - 1hb (18.53 m2)

No Asbestos

B00S - R1012 - External Movement (53.16 m2)

No Asbestos

B00S - R1013 - External Stairs (31.02 m2)

No Asbestos

B00S - R1014 - External Stairs (30.97 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2116_ASB_150514_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017