


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Georges Hall Public School (3702)
Region : South Western Sydney
State Electorate : East Hills
Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 22 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 05 - Aug - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1976 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Deputy Principal (13.76 m2)**

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0002 - Interview (10.32 m2)

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0003 - Principal (22.79 m2)

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0004 - Clerical Office (13.33 m2)

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0005 - Entry Vestibule (14.3 m2)

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0006 - Deputy Principal (13.28 m2)

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0007 - Sick Bay (12.83 m2)

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0008 - Interview (13.12 m2)

Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0009 - Staff Toilet (8.94 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0010 - Staff Toilet (8.94 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0011 - Staff Toilet (3.02 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0012 - Distribution Board (0.74 m2) Note: No inspection of live electrical installation.						
Electrical Mounting Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0013 - Cleaning Supplies (12.15 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 3702/B00L/R1006/Floor Coverings Res/Textile/S5					No Asbestos Detected
B00A - R0014 - Staff Room (106.59 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0015 - Cleaning Distributed Store (6.48 m2)						
No Asbestos						
B00A - R0016 - Security Store (18.68 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 3702/B00L/R1006/Floor Coverings Res/Textile/S5					No Asbestos Detected
B00A - R0017 - Community Clinic (15.39 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0018 - Movement (25.17 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0019 - Movement (19.41 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0020 - Movement (28.52 m2)						
No Asbestos						
B00A - R1001 - K.L.A. Store (13.57 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1002 - K.L.A. Store (15.7 m2)						
Ceiling Structures/Linings	Vermiculite 3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1003 - Communications Room (12 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R1004 - Library Office/Workroom (9 m2)

Ceiling Structures/Linings Vermiculite
 3702/B00J/R0002/Ceiling Structures/Linings/S3 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R1005 - Library Office/Workroom (19.98 m2)

No Asbestos

B00A - R1006 - Distribution Board (1.89 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R1007 - Toilets - Girls (3.99 m2)

Partition Walls (Cubicles) Compressed AC Sheet 2m2 North Good Condition (1) Low (1) Low Priority (2-3)
 3702/B00B/R0003/Partition Walls (Cubicles)/S1 **Chrysotile (white asbestos)**

B00A - R1008 - Movement (11.02 m2)

Ceiling Structures/Linings Vermiculite
 3702/B00J/R0002/Ceiling Structures/Linings/S3 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R1009 - Toilets - Boys (3.48 m2)

Partition Walls (Cubicles) Compressed AC Sheet 2m2 South Good Condition (1) Low (1) Low Priority (2-3)
 3702/B00B/R0003/Partition Walls (Cubicles)/S1 **Chrysotile (white asbestos)**

B00A - R1010 - Cleaning Distributed Store (1.44 m2)

No Asbestos

B00A - R1011 - Reading Area (253.58 m2)

Ceiling Structures/Linings Vermiculite
 3702/B00J/R0002/Ceiling Structures/Linings/S3 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R1012 - Movement (28.52 m2)

Ceiling Structures/Linings Flat AC Sheeting 29m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
 3702/B00C/R0007/Ceiling Structures/Linings/S2 **Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities/Pupil Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	12m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Communal Space (271.56 m2)

No Asbestos

B00B - R0002 - Toilets - Girls (9.01 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1			Chrysotile (white asbestos)		

B00B - R0003 - Toilets - Boys (5.7 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1			Chrysotile (white asbestos)		

B00B - R0004 - Movement (7.33 m2)

No Asbestos

B00B - R0005 - Uniform Shop (4.51 m2)

No Asbestos

B00B - R0006 - Staff Toilet (4.51 m2)

No Asbestos

B00B - R0007 - Canteen Office/Store (7.09 m2)

No Asbestos

B00B - R0009 - Canteen (42.93 m2)

No Asbestos

B00B - R0010 - Raised Platform (49.48 m2)

No Asbestos

B00B - R0011 - Hall Chair Store (14.41 m2)

No Asbestos

B00B - R0012 - Movement (14.16 m2)

No Asbestos

B00B - R0013 - Main Switch Board (8.19 m2)

Electrical Mounting Board	Resinous Board	2Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0013/Electrical Mounting Board/S9			Chrysotile (white asbestos)		

B00B - R0014 - Cleaning Distributed Store (6 m2)

No Asbestos

B00B - R0016 - Movement (2.8 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Wall Linings Internal	Flat AC Sheeting	1m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0017 - Movement (2.8 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	1m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00B - R0018 - Movement (2.8 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	1m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00B - R0019 - Movement (98.36 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	3702/B00B/R0020/Ceiling Structures/Linings/S8			No Asbestos Detected		
B00B - R0020 - Movement (13.47 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	3702/B00B/R0020/Ceiling Structures/Linings/S8			No Asbestos Detected		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1976 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Vermiculite				Limited Samples Taken	
	3702/B00G/Ceiling Voids/S11				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Toilets - Girls (16.66 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00C - R0002 - General Storeroom (1.74 m2)

No Asbestos

B00C - R0003 - Toilets - Boys (16.72 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00C - R0004 - Practical Activities - 1hb (14.16 m2)

No Asbestos

B00C - R0005 - Toilets - Boys/Girls (2.89 m2)

No Asbestos

B00C - R0006 - Home Base (76.5 m2)

No Asbestos

B00C - R0007 - Movement (16.2 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0008 - Home Base (76.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0009 - Practical Activities - 1hb (14.16 m2)

No Asbestos

B00C - R0010 - Toilets - Boys/Girls (2.89 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	8m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Vermiculite					Limited Samples Taken
	3702/B00G/Ceiling Voids/S11				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0003 - Movement (11.34 m2)

No Asbestos

B00D - R0006 - Home Base (53.42 m2)

No Asbestos

B00D - R0007 - Home Base Store (4.32 m2)

No Asbestos

B00D - R0008 - Practical Activities (12.72 m2)

No Asbestos

B00D - R0009 - Practical Activities (53.26 m2)

No Asbestos

B00D - R0010 - Home Base Store (4.32 m2)

No Asbestos

B00D - R0011 - Practical Activities (12.72 m2)

No Asbestos

B00D - R1003 - Movement (11.34 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00D - R1005 - Home Base (53.42 m2)

No Asbestos

B00D - R1006 - Home Base Store (4.32 m2)

No Asbestos

B00D - R1007 - Practical Activities (12.72 m2)

No Asbestos

B00D - R1008 - Special Programs Room (66.26 m2)

No Asbestos

B00D - R1009 - Home Base Store (5.04 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Vermiculite					Limited Samples Taken
3702/B00G/Ceiling Voids/S11				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - General Storeroom (14.4 m2)

No Asbestos

B00E - R0002 - Toilets - Girls (15.81 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)		

B00E - R0003 - Cleaning Distributed Store (2.26 m2)

No Asbestos

B00E - R0004 - Distribution Board (1.21 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0013/Electrical Mounting Board/S9				Chrysotile (white asbestos)		

B00E - R0005 - Toilets - Boys (14.04 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)		

B00E - R0006 - Movement (20.25 m2)

No Asbestos

B00E - R0007 - General Storeroom (5.2 m2)

No Asbestos

B00E - R0008 - Stairs (10.99 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0009 - Handwashing Facilities (8.4 m2)

No Asbestos

B00E - R1001 - General Storeroom (14.4 m2)

No Asbestos

B00E - R1002 - Toilets - Girls (15.68 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)		

B00E - R1003 - Cleaning Distributed Store (2.28 m2)

No Asbestos

B00E - R1004 - Distribution Board (1.21 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0013/Electrical Mounting Board/S9				Chrysotile (white asbestos)		

B00E - R1005 - Toilets - Boys (14.04 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R1006 - Movement (20.25 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R1007 - Stairs (17.24 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Building Services - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	18m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Vermiculite					Limited Samples Taken
	3702/B00G/Ceiling Voids/S11				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0001 - General Storeroom (6.09 m2)

No Asbestos

B00F - R0002 - Hall Chair Store (25.22 m2)

No Asbestos

B00F - R0003 - General Assistant/Bulk Store (13.53 m2)

No Asbestos

B00F - R0004 - Cleaning Distributed Store (2.34 m2)

No Asbestos

B00F - R0005 - Movement (31.79 m2)

No Asbestos

B00F - R0006 - Toilets - Girls (18.67 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00F - R0007 - Toilets - Boys (18.24 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00F - R0008 - Cleaning Supplies (15.96 m2)

No Asbestos

B00F - R0009 - Movement (23.98 m2)

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0010 - Stairs (3.83 m2)

No Asbestos

B00F - R1003 - Movement (30.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R1004 - Stairs (6.54 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00F/R1004/Ceiling Structures/Linings/S10				Chrysotile (white asbestos)	

B00F - R1005 - Practical Activities (12.72 m2)

No Asbestos

B00F - R1006 - Home Base Store (4.32 m2)

No Asbestos

B00F - R1007 - Home Base (52.46 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Vermiculite					Limited Samples Taken
3702/B00G/Ceiling Voids/S11				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0005 - Distribution Board (0.57 m2) Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0013/Electrical Mounting Board/S9				Chrysotile (white asbestos)		

B00G - R0010 - Movement (67.45 m2)

Ceiling Structures/Linings	Flat AC Sheeting	68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0011 - Practical Activities (12.72 m2)

No Asbestos

B00G - R0012 - Home Base Store (4.32 m2)

No Asbestos

B00G - R0013 - Home Base (53.15 m2)

No Asbestos

B00G - R0014 - Home Base (50.67 m2)

No Asbestos

B00G - R0015 - Home Base Store (4.32 m2)

No Asbestos

B00G - R0016 - Practical Activities (12.52 m2)

No Asbestos

B00G - R0017 - Practical Activities (12.52 m2)

No Asbestos

B00G - R0018 - Home Base Store (4.32 m2)

No Asbestos

B00G - R0019 - Home Base (51.22 m2)

No Asbestos

B00G - R0020 - Home Base (52.31 m2)

No Asbestos

B00G - R0021 - Practical Activities (12.72 m2)

No Asbestos

B00G - R0022 - Home Base Store (4.32 m2)

No Asbestos

B00G - R1005 - Distribution Board (0.57 m2) Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0013/Electrical Mounting Board/S9				Chrysotile (white asbestos)		

B00G - R1010 - Movement (67.45 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		

- B00G - R1011 - Practical Activities (12.72 m2)**
No Asbestos
- B00G - R1012 - Home Base Store (4.32 m2)**
No Asbestos
- B00G - R1013 - Home Base (53.15 m2)**
No Asbestos
- B00G - R1014 - Home Base (50.67 m2)**
No Asbestos
- B00G - R1015 - Home Base Store (4.32 m2)**
No Asbestos
- B00G - R1016 - Practical Activities (12.52 m2)**
No Asbestos
- B00G - R1017 - Practical Activities (12.52 m2)**
No Asbestos
- B00G - R1018 - Home Base Store (4.32 m2)**
No Asbestos
- B00G - R1019 - Home Base (51.22 m2)**
No Asbestos
- B00G - R1020 - Home Base (52.31 m2)**
No Asbestos
- B00G - R1021 - Practical Activities (12.72 m2)**
No Asbestos
- B00G - R1022 - Home Base Store (4.32 m2)**
No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Vermiculite					Limited Samples Taken
	3702/B00H/Ceiling Voids/S15				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Toilets - Boys (13.83 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00H - R0002 - Cleaning Distributed Store (1.63 m2)

Wall Linings Internal	Flat AC Sheeting	3m2	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	3702/B00H/R1002/Infill panels on floor/S12				Chrysotile (white asbestos)	

B00H - R0003 - Toilets - Girls (15.91 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00H - R0008 - Distribution Board (0.59 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	2Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0013/Electrical Mounting Board/S9				Chrysotile (white asbestos)	

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00H - R0009 - Sports Store (14.86 m2)

No Asbestos

B00H - R0010 - General Storeroom (18.48 m2)

No Asbestos

B00H - R0011 - Movement (81.47 m2)

No Asbestos

B00H - R0012 - General Storeroom (6.15 m2)

No Asbestos

B00H - R0013 - Stairs (0.32 m2)

No Asbestos

B00H - R0014 - Practical Activities (12.72 m2)

No Asbestos

B00H - R0015 - Home Base Store (4.8 m2)

No Asbestos

B00H - R0016 - Home Base (51.7 m2)

No Asbestos

B00H - R0017 - Home Base (51.53 m2)

No Asbestos

B00H - R0018 - Practical Activities (12.72 m2)

No Asbestos

B00H - R0019 - Home Base Store (4.8 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R1001 - Toilets - Boys (13.76 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0003/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
B00H - R1002 - Cleaning Distributed Store (1.62 m2)						
Infill panels on floor	Flat AC Sheeting	3m2	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
3702/B00H/R1002/Infill panels on floor/S12					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	1m2	South (upper portion)	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
3702/B00H/R1002/Infill panels on floor/S12					Chrysotile (white asbestos)	
B00H - R1003 - Toilets - Girls (15.84 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0003/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
B00H - R1008 - Distribution Board (0.51 m2)						
Note: No inspection of live electrical installation.						
Electrical Mounting Board	Resinous Board	2Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00B/R0013/Electrical Mounting Board/S9					Chrysotile (white asbestos)	
B00H - R1009 - General Storeroom (14.92 m2)						
No Asbestos						
B00H - R1010 - General Storeroom (18.48 m2)						
Ceiling Structures/Linings	Vermiculite					
3702/B00J/R0002/Ceiling Structures/Linings/S3					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00H - R1011 - Movement (81.64 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00H - R1012 - Stairs (6.53 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00H - R1013 - Practical Activities (12.72 m2)						
No Asbestos						
B00H - R1014 - Home Base Store (4.32 m2)						
No Asbestos						
B00H - R1015 - Home Base (52.37 m2)						
No Asbestos						
B00H - R1016 - Home Base (52.34 m2)						
No Asbestos						
B00H - R1017 - Practical Activities (12.72 m2)						
No Asbestos						
B00H - R1018 - Home Base Store (4.32 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B001 - R0001 - Movement (38.47 m2)

No Asbestos

B001 - R0002 - Practical Activities - 1hb (19.39 m2)

No Asbestos

B001 - R0003 - Home Base Store (6.01 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0004 - Home Base (59.2 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0005 - Withdrawal Space - 2hb (11.36 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0006 - Home Base (59.19 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0007 - Home Base Store (6.02 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0008 - Practical Activities - 1hb (19.41 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1976 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Vermiculite					Limited Samples Taken
	3702/B00G/Ceiling Voids/S11			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Underfloor Voids	No Asbestos Found					

Interior**B00J - R0001 - Practical Activities - 1hb (13.87 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00J - R0002 - Toilets - Boys/Girls (3.24 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00J - R0003 - Home Base (87.83 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00J - R0004 - Home Base (87.83 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00J - R0005 - Practical Activities - 1hb (13.87 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00J - R0006 - Toilets - Boys/Girls (3.24 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00J - R0007 - Sports Store (4.35 m2)

No Asbestos

B00J - R0008 - Movement (71 m2)

No Asbestos

B00J - R0009 - Garden Store (12.3 m2)

No Asbestos

B00J - R0010 - Stairs (3.25 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0011 - Stairs (0.5 m2)

No Asbestos

B00J - R0012 - General Assistant/Bulk Store (15.96 m2)

No Asbestos

B00J - R1007 - Movement (72.54 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R1008 - Stairs (15.94 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R1009 - Stairs (4.87 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R1010 - Practical Activities (12.72 m2)						
No Asbestos						
B00J - R1011 - Home Base Store (4.56 m2)						
No Asbestos						
B00J - R1012 - Home Base (53.55 m2)						
No Asbestos						
B00J - R1013 - Practical Activities (12.72 m2)						
No Asbestos						
B00J - R1014 - Home Base Store (4.56 m2)						
No Asbestos						
B00J - R1015 - Home Base (51.98 m2)						
No Asbestos						
B00J - R1016 - Home Base (49.91 m2)						
No Asbestos						
B00J - R1017 - Practical Activities (12.72 m2)						
No Asbestos						
B00J - R1018 - Home Base Store (4.56 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities/Building Services - 1978 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Vermiculite 3702/B00G/Ceiling Voids/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Underfloor Voids	No Asbestos Found					

Interior**B00K - R0001 - Deputy Principal (10.85 m2)**

Ceiling Structures/Linings	Vermiculite 3702/B00K/R0001/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00K - R0002 - Distribution Board (0.44 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	2Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0013/Electrical Mounting Board/S9					Chrysotile (white asbestos)

B00K - R0003 - General Assistant/Bulk Store (13.92 m2)

No Asbestos

B00K - R0004 - General Assistant/Bulk Store (13.05 m2)

No Asbestos

B00K - R1001 - Toilets - Boys (14.86 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00K/R1001/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

Manhole

Flat AC Sheeting
3702/B00K/R1001/Manhole/S14

No Asbestos Detected

B00K - R1002 - Distribution Board (0.36 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0013/Electrical Mounting Board/S9					Chrysotile (white asbestos)

B00K - R1003 - Cleaning Distributed Store (2.79 m2)

No Asbestos

B00K - R1004 - Toilets - Girls (20.11 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00K/R1001/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning/Special Purpose Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Vermiculite					Limited Samples Taken
	3702/B00G/Ceiling Voids/S11				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Underfloor Voids	No Asbestos Found					

Interior

B00L - R0003 - Movement (42.02 m2)

No Asbestos

B00L - R0005 - Distribution Board (0.38 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	2Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00B/R0013/Electrical Mounting Board/S9				Chrysotile (white asbestos)	

B00L - R0006 - Duplicating Workroom (31.2 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00L - R0007 - Practical Activities (15.6 m2)

No Asbestos

B00L - R0008 - Home Base Store (4.32 m2)

No Asbestos

B00L - R0009 - Home Base (50.56 m2)

No Asbestos

B00L - R0010 - Home Base (52.12 m2)

No Asbestos

B00L - R0011 - Home Base Store (4.32 m2)

No Asbestos

B00L - R0012 - Practical Activities (12.84 m2)

No Asbestos

B00L - R1003 - Movement (41.93 m2)

Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3702/B00C/R0007/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00L - R1005 - Kiln Room (1.48 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	3702/B00L/R1006/Floor Coverings Res/Textile/S5					

B00L - R1006 - Craft Store (29.67 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3702/B00J/R0002/Ceiling Structures/Linings/S3				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	3702/B00L/R1006/Floor Coverings Res/Textile/S5					

B00L - R1007 - Practical Activities (15.6 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00L - R1008 - Home Base Store (4.32 m2)

No Asbestos

B00L - R1009 - Home Base (50.56 m2)

No Asbestos

B00L - R1010 - Home Base (52.12 m2)

No Asbestos

B00L - R1011 - Home Base Store (4.32 m2)

No Asbestos

B00L - R1012 - Practical Activities (12.84 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Communal Facilities - 1977 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Sports Store (23.8 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Pupil Facilities - 2008 - Concrete (Concrete)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0001 - Handwashing Facilities (8.93 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Other-After School Care - 2008 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00Q - R0001 - Other-After School Care (105.91 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10046 - Learning Unit - Standard With P.A.A. : Placement Date - 30/11/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D10177 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 3/11/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11757 - Learning Unit - Standard With P.A.A. : Placement Date - 16/04/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11977 - Learning Unit - Standard With P.A.A. : Placement Date - 10/01/2009

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 750 - D12007 - Learning Unit - ESL : Placement Date - 10/01/2009

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	5.76 m2

Interior

R1 - Esl

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
OS 750 - D13312 - Learning Unit - ESL : Placement Date - 25/11/2016						
Exterior						
No Asbestos Found.						
Interior						
R1 - Esl						
No Asbestos Found.						
OS 603 - D14915 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 13/11/2006						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

3702_ASB_261112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017