


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gwynneville Public School (3826)
Region : Illawarra and South East
State Electorate : Wollongong
Local Government Area : Wollongong

Initial Survey : Noel Arnold & Associates : 06 - May - 2008
Reviewed By : Grencap-NAA : 02 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1952 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/Eaves Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00B - R0001 - Seminar/Study

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0003/Floor Coverings Res/Textile/S1			Chrysotile (white asbestos)		

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0003/Floor Coverings Res/Textile/S1			Chrysotile (white asbestos)		

B00B - R0004 - Withdrawal Space - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0006/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0005 - Special Programs Room

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0005/Floor Coverings Res/Textile/S12			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3826/B00B/R0005/Floor Coverings Res/Textile/S13					

B00B - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0006/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1952 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00F/Wall Cladding/S6					Chrysotile (white asbestos)

Interior

B00C - R0001 - General Storeroom

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54.31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0005/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	3826/B00B/R0005/Floor Coverings Res/Textile/S13					No Asbestos Detected

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	3826/B00F/R0006/Ceiling Structures/Linings/S9					No Asbestos Detected

B00C - R9001 - Cleaning Supplies

No Asbestos

B00C - R9002 - Other-Vacant

Stored Sheeting	Flat AC Sheeting					
	3826/B00C/R9002/Stored Sheeting/S14					No Asbestos Detected

B00C - R9003 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1952 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
3826/B00F/Wall Cladding/S6					Chrysotile (white asbestos)	

Interior

B00D - R0001 - Kiln Room

No Asbestos

B00D - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54.47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3826/B00B/R0005/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
3826/B00B/R0005/Floor Coverings Res/Textile/S13					No Asbestos Detected	

B00D - R0003 - Movement

No Asbestos

B00D - R0004 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54.39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3826/B00B/R0005/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
3826/B00B/R0005/Floor Coverings Res/Textile/S13					No Asbestos Detected	

B00D - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
3826/B00F/R0006/Ceiling Structures/Linings/S9					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1952 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible No manhole					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00F/Wall Cladding/S6					Chrysotile (white asbestos)

Interior

B00E - R0001 - Movement

Wall Linings Internal	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00E/R0001/Wall Linings Internal/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0005/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3826/B00B/R0005/Floor Coverings Res/Textile/S13					

B00E - R0003 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00B/R0005/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	3826/B00B/R0005/Floor Coverings Res/Textile/S13					

B00E - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1952 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible No manhole					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00F/Wall Cladding/S6					Chrysotile (white asbestos)

Interior

B00F - R0001 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00F/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)

B00F - R0002 - Movement

Wall Linings Internal	Flat AC Sheeting	5m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00F/R0001/Wall Linings Internal/S7					Chrysotile (white asbestos)

B00F - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3826/B00F/R0003/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Withdrawal Space - 1hb

No Asbestos

B00F - R0007 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Shed - 1991 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00I - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Shed - 1951 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00J - R0001 - General Assistant/Bulk Store

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout, Upper portion	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
3826/B00J/R0001/Wall Linings Internal/S5					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Shed - 1951 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00K - R0001 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
		3826/B00K/R0001/Wall Linings Internal/S4				

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 1975 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00L - R0001 - Toilets - Girls

No Asbestos

B00L - R0002 - Cleaning Distributed Store

No Asbestos

B00L - R0003 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Pupil Facilities - 1951 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00M/Eaves Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00M - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00M/R0001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00M/R0001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0003 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00M/R0001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0004 - No Access

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3826/B00M/R0001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Communal Space

No Asbestos

B00N - R0002 - Raised Platform

No Asbestos

B00N - R0003 - Hall Chair Store

No Asbestos

B00N - R0004 - Communal/Performance Store

No Asbestos

B00N - R0005 - P.E. Store

No Asbestos

B00N - R0006 - Toilet - Lobby

No Asbestos

B00N - R0007 - Toilets - Girls

No Asbestos

B00N - R0008 - Sound Cupboard

No Asbestos

B00N - R0009 - Toilet - Lobby

No Asbestos

B00N - R0010 - Toilets - Boys

No Asbestos

B00N - R0011 - Cleaning Distributed Store

No Asbestos

B00N - R0012 - General Storeroom

No Asbestos

B00N - R0013 - Main Switch Board

No Asbestos

B00N - R0014 - Access Shower/Toilet/Change

No Asbestos

B00N - R0015 - Covered Outdoor Learning Area

No Asbestos

B00N - R0016 - Movement

No Asbestos

B00N - R0017 - Movement

No Asbestos

B00N - R0018 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Pupil Facilities - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B000 - R0001 - Access Shower/Toilet/Change

No Asbestos

B000 - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D12646 - Learning Unit - Standard With P.A.A. : Placement Date - 28/04/2011

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 502 - D13573 - Admin Staff/Principal/Clerk/Dup/Clinic : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	23.04 m2

Interior

R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2

R10 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	12 m2
---------	---------------	------------------	-------

R2 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos	1 m2
---------	---------------	------------------	------

R3 - Duplicating Wookroom

Ceiling	Flat AC Sheet	Assumed Asbestos	12 m2
---------	---------------	------------------	-------

R4 - Clinic-Waiting

Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2
---------	---------------	------------------	-------

R5 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2
---------	---------------	------------------	-------

R6 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2
---------	---------------	------------------	-------

R7 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

R8 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

R9 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	27 m2

OS 804 - D14317 - FSU : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior**R1 - Canteen**

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				54 m2

R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				19 m2

OS 602 - D14723 - Learning Unit - Standard With P.A.A. : Placement Date - 27/03/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14910 - Learning Unit - Standard With P.A.A. : Placement Date - 23/04/2014**Exterior**

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 534 - D15179 - Library/Group Study/Office/A V Store : Placement Date - 30/06/1995**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				23.04 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Clerical Office						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - Staff Room						
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
R3 - Security Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R4 - Principal						
Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
R5 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
R6 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
R7 - Reading Area						
Ceiling	Flat AC Sheet	Assumed Asbestos				54 m2
R8 - Entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				14 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017