


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Greenwell Point Public School (3872)
Region : Illawarra and South East
State Electorate : South Coast
Local Government Area : Shoalhaven

Initial Survey : Noel Arnold & Associates : 06 - May - 2008
Reviewed By : Grencap-NAA : 25 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Building Services/Communal Facilities - 1975 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00A - R0001 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

B00A - R0002 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

B00A - R0003 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities/General Learning - 1975 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00B/Eaves Linings/S6					Chrysotile (white asbestos)

Interior

B00B - R0001 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00B/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00B - R0003 - Main Switch Board

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00B/R0003/Electrical Backing Board/S5					Chrysotile (white asbestos)

B00B - R0004 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00B/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00B - R0005 - Kiln Room

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00B/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00B - R0006 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00B/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00B - R0007 - Canteen

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00B/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00B - R0008 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00B/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00B - R0013 - Covered Outdoor Learning Area

No Asbestos

B00B - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	102m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

B00B - R0015 - Canteen Covered Area

Ceiling Structures/Linings	Flat AC Sheeting	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1975 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior

B00C - R0001 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
3872/B00E/R0004/Floor Coverings Res/Textile/S3					No Asbestos Detected	

B00C - R0002 - Toilets - Boys/Girls

No Asbestos

B00C - R0003 - Home Base

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
3872/B00E/R0004/Floor Coverings Res/Textile/S3					No Asbestos Detected	

B00C - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)	

B00C - R0011 - Reading Area

No Asbestos

B00C - R0012 - Communications Room

No Asbestos

B00C - R0013 - K.L.A. Store

No Asbestos

B00C - R0014 - Library Office/Workroom

No Asbestos

B00C - R0015 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1893 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior

B00D - R0001 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00E/R0004/Floor Coverings Res/Textile/S3					No Asbestos Detected

B00D - R0002 - K.L.A. Store

No Asbestos

B00D - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

B00D - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1975 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior

B00E - R0001 - Toilets - Girls

No Asbestos

B00E - R0004 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
3872/B00E/R0004/Floor Coverings Res/Textile/S3					No Asbestos Detected	

B00E - R0005 - Home Base

No Asbestos

B00E - R0007 - Movement

Wall Linings Internal	Flat AC Sheeting	24m2	South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
3872/B00H/R0007/Wall Linings Internal/S2					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)	

B00E - R0008 - Disabled Shower/Toilet

No Asbestos

B00E - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00F - R0001 - Toilets - Boys

No Asbestos

B00F - R0002 - Staff Toilet

No Asbestos

B00F - R0003 - Movement

No Asbestos

B00F - R0004 - Cleaning Distributed Store

No Asbestos

B00F - R0005 - Toilets - Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 1975 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00G/Eaves Linings/S7					Chrysotile (white asbestos)

Interior

B00G - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Administration/Staff Facilities - 1975 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/Eaves Linings/S1					Chrysotile (white asbestos)

Interior

B00H - R0001 - Staff Room

Wall Linings Internal	Flat AC Sheeting	12m2	kitchen area	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/R0007/Wall Linings Internal/S2					Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl Tiles					
	3872/B00B/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00H - R0002 - Entry Vestibule

No Asbestos

B00H - R0003 - Clerical Office

No Asbestos

B00H - R0004 - Sick Bay

No Asbestos

B00H - R0005 - Clerical Office/Workroom

No Asbestos

B00H - R0006 - Principal

No Asbestos

B00H - R0007 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3872/B00H/R0007/Wall Linings Internal/S2					Chrysotile (white asbestos)

B00H - R0008 - General Storeroom

No Asbestos

B00H - R0009 - Movement

No Asbestos

B00H - R0010 - Movement

No Asbestos

B00H - R0011 - Movement

No Asbestos

B00H - R0012 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Communal Facilities - 2010 - Concrete (Concrete)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - Communal Space

No Asbestos

B00I - R0002 - Raised Platform

No Asbestos

B00I - R0003 - Movement

No Asbestos

B00I - R0004 - Stairs

No Asbestos

B00I - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Shed - 2011 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - Outdoor Learning Area

No Asbestos

B00J - R0002 - Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017