


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gordon East Public School (3985)
Region : Northern Sydney
State Electorate : Davidson
Local Government Area : Ku-Ring-Gai

Initial Survey : Noel Arnold & Associates : 11 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 13 - Jul - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - General Learning/Pupil Facilities - 1965 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Height Restriction					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction > 3m.					
Eaves Linings	Flat AC Sheeting	50m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction > 3m.					
Gable Ends	Flat AC Sheeting	5m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/Gable Ends/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00A - R0001 - Home Base**

Floor Coverings Res/Textile	Vinyl Tiles	58m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0002 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	0.6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0004 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0005 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

Electrical Mounting Board	Flat AC Sheeting	4Unit	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Electrical Mounting Board/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)

Electrical Mounting Board	Resinous Board	1Unit	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Electrical Mounting Board/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R0006 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles	58m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0007 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0008 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/R0005/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0009 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0010/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	
B00A - R0010 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0010/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	
B00A - R0011 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0012/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Corrugated AC Sheeting	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0013/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	
B00A - R0012 - Handwashing Facilities						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0012/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
B00A - R0013 - Handwashing Facilities						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0012/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
B00A - R0014 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0012/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
3985/B00A/R0014/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration - 1965 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	Non Accessible Area					
	- Height Restriction void is less than 0.4m.					
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Height Restriction > 3.					
Eaves Linings	Flat AC Sheeting	75m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00B/Eaves Linings/S11					Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting	5m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00A/Gable Ends/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00B - R0003 - Staff Toilet

No Asbestos

B00B - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3985/B00B/Eaves Linings/S11					Chrysotile (white asbestos)

B00B - R0005 - Movement

No Asbestos

B00B - R0009 - Movement

No Asbestos

B00B - R0010 - Clerical Office

No Asbestos

B00B - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0015 - Security Store

No Asbestos

B00B - R0019 - Clerical Office

No Asbestos

B00B - R0020 - Principal

No Asbestos

B00B - R0021 - Staff Toilet

No Asbestos

B00B - R0022 - Movement

No Asbestos

B00B - R0023 - Sick Bay

No Asbestos

B00B - R0024 - Clerical/Printing

No Asbestos

B00B - R0025 - Clerical Office

No Asbestos

B00B - R0026 - Movement

No Asbestos

B00B - R0027 - Staff Room

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library/Tiered Learning - 1957 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00C - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0007 - Plant

No Asbestos

B00C - R0008 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0009 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1965 - Concrete (Concrete)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction > 3m.					
Eaves Linings	Flat AC Sheeting 3985/B00D/Eaves Linings/S12	100m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting Assumed Asbestos - Height Restriction > 3m	5m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Underfloor Voids	AC Fragments/Debris 3985/B00D/Underfloor Voids/S14					No Asbestos Detected

Interior**B00D - R0001 - Personal Effects Storage**

Ceiling Structures/Linings	Flat AC Sheeting 3985/B00D/R0001/Ceiling Structures/Linings/S13	2m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------	--------------------	---------	--

B00D - R0002 - Home Base Store

No Asbestos

B00D - R0003 - Home Base

No Asbestos

B00D - R0004 - Home Base Store

No Asbestos

B00D - R0005 - Home Base

No Asbestos

B00D - R0006 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 3985/B00D/R0006/Floor Coverings Res/Textile/S4	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	---	-----	--------------	--------------------	---------	--

B00D - R0007 - Personal Effects Storage

No Asbestos

B00D - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3985/B00D/R0001/Ceiling Structures/Linings/S13	2m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------	--------------------	---------	--

B00D - R0012 - General Storeroom

No Asbestos

B00D - R0013 - Special Programs Room

No Asbestos

B00D - R0014 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 3985/B00D/R0014/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00D - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3985/B00D/Eaves Linings/S12	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00D - R0017 - Movement

No Asbestos

B00D - R0018 - Kitchen - Pre

No Asbestos

B00D - R0019 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - R0020 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Communal Facilities - 1991 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00G - M0001 - Communal Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0001 - Sports Store

No Asbestos

B00G - R0002 - Movement

No Asbestos

B00G - R0003 - Canteen

No Asbestos

B00G - R0004 - Staff Kitchen

No Asbestos

B00G - R0005 - Uniform Shop

No Asbestos

B00G - R0006 - Disabled Toilet

No Asbestos

B00G - R0007 - Cleaning Supplies

No Asbestos

B00G - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0009 - Out Of School Hours Care Centre

No Asbestos

B00G - R0010 - Out Of School Hours Care Centre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0011 - P.E. Store

No Asbestos

B00G - R0012 - Hall Chair Store

No Asbestos

B00G - R0013 - Communal Space

No Asbestos

B00G - R0014 - Plant

No Asbestos

B00G - R0015 - Communal/Performance Store

No Asbestos

B00G - R0016 - Toilets - Girls

No Asbestos

B00G - R0017 - Shower/Change

No Asbestos

B00G - R0018 - Movement

No Asbestos

B00G - R0019 - Toilets - Boys

No Asbestos

B00G - R0020 - Raised Platform

No Asbestos

B00G - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00G - R0022 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning/Pupil Facilities - 1965 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior

B00H - R0001 - Toilets - Girls

No Asbestos

B00H - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0005 - Practical Activities - 1hb

No Asbestos

B00H - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0007 - Practical Activities - 1hb

No Asbestos

B00H - R0008 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0010 - Toilets - Boys

No Asbestos

B00H - R0011 - Movement

No Asbestos

B00H - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R9001 - Garden Store

No Asbestos

B00H - R9002 - Sports Store

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Other-After School Care - 2007 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Packing to Floor Joists	No Asbestos Found

Interior

B001 - R0002 - General Storeroom

No Asbestos

B001 - R0003 - Staff Kitchen

No Asbestos

B001 - R0004 - Clerical Office

No Asbestos

B001 - R0005 - External Movement

No Asbestos

B001 - R0006 - Out Of School Hours Care Centre

No Asbestos

B001 - R0007 - Out Of School Hours Care Centre

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - Practical Activities

No Asbestos

B00J - R0003 - Home Base Store

No Asbestos

B00J - R0004 - Home Base

No Asbestos

B00J - R0005 - Withdrawal Space - 2hb

No Asbestos

B00J - R0006 - Practical Activities - 2hb

No Asbestos

B00J - R0007 - Home Base

No Asbestos

B00J - R0008 - Home Base Store

No Asbestos

B00J - R0009 - Practical Activities

No Asbestos

B00J - R0010 - Home Base Store

No Asbestos

B00J - R0011 - Home Base

No Asbestos

B00J - R0012 - Withdrawal Space - 2hb

No Asbestos

B00J - R0013 - Practical Activities

No Asbestos

B00J - R0014 - Home Base

No Asbestos

B00J - R0015 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10725 - Learning Unit - Standard With P.A.A. : Placement Date - 29/02/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D12512 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 17/01/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D12543 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 29/11/2004

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14230 - Learning Unit - Standard With P.A.A. : Placement Date - 21/04/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017