

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Support Unit - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00A/Eaves Linings/S15				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00A/Gable Verge Lining/S14				Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00A - R0001 - Home Base (55.38 m2)

No Asbestos

B00A - R0002 - Practical Activities - 1hb (13.44 m2)

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00B/R1006/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	

B00A - R0005 - Distribution Board (1.1 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0006 - Home Base - M (55.54 m2)

No Asbestos

B00A - R0007 - Practical Activities - M - 1hb (13.89 m2)

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00B/R1006/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	

B00A - R0008 - External Movement (72.42 m2)

No Asbestos

B00A - R0009 - External Stairs (11.58 m2)

No Asbestos

B00A - R0010 - External Stairs (16.48 m2)

No Asbestos

B00A - R0011 - External Stairs (2.21 m2)

No Asbestos

B00A - R0012 - Practical Activities (69.77 m2)

No Asbestos

B00A - R1001 - Home Base (55.38 m2)

No Asbestos

B00A - R1002 - Practical Activities - 1hb (13.42 m2)

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00B/R1006/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	

B00A - R1003 - Practical Activities - 1hb (13.42 m2)

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00B/R1006/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	

B00A - R1004 - Home Base (55.38 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R1005 - Distribution Board (1.12 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R1006 - Home Base (55.59 m2)

No Asbestos

B00A - R1007 - Practical Activities - 1hb (14.05 m2)

Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00B/R1006/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)	

B00A - R1008 - External Movement (72.19 m2)

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
4020/B00A/R1008/Ceiling Structures/Linings/S8						

B00A - R1009 - External Stairs (17.38 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction

B00A - R1010 - External Stairs (16.48 m2)

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Library - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
Gable Verge Lining	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
In-fill-panel	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00J/R0013/In-fill-panel/S1					Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Gable Verge Lining	Non Accessible Area - Extreme Access Issue - Height Restricted - Approx >6m High					

Interior

B00B - R0001 - Community Clinic (15.91 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0002 - Deputy Principal (14.2 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0003 - Interview (14.24 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0006 - Sick Bay (9.32 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0008 - Clerical Office/Workroom (14.69 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0011 - Principal (20.43 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0012 - Movement (11.02 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0013 - Duplicating Workroom (16.64 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00B - R0014 - General Storeroom (13.23 m2)

Ceiling Structures/Linings	Vermiculite	4020/B00B/R0012/Ceiling Structures/Linings/S10				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0015 - Plant (0.64 m2)						
No Asbestos						
B00B - R0016 - Distribution Board (2.32 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R0017 - Staff Room (67.38 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0019 - Movement (11.56 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0020 - Cleaning Distributed Store (10.46 m2)						
No Asbestos						
B00B - R0021 - External Movement (2.12 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0022 - Entry Vestibule (13.76 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0023 - Clerical Office (24.24 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0024 - Sick Bay (5.29 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0025 - Canteen Office/Store (10.37 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0026 - Movement (40.55 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0027 - Handwashing Facilities (2.99 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0028 - Staff Toilet (3.68 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0029 - Staff Toilet (3.7 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0030 - Handwashing Facilities (2.97 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		4020/B00B/R0012/Ceiling Structures/Linings/S10				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0031 - Stairs (4.45 m2)						
No Asbestos						
B00B - R1001 - Reading Area (219.74 m2)						
No Asbestos						
B00B - R1002 - Seminar/Study (14.66 m2)						
No Asbestos						
B00B - R1003 - Seminar/Study (14.63 m2)						
No Asbestos						
B00B - R1004 - K.L.A. Store (14.58 m2)						
No Asbestos						
B00B - R1005 - K.L.A. Store (10.6 m2)						
No Asbestos						
B00B - R1006 - Library Office/Workroom (18.81 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00B/R1006/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)	
B00B - R1007 - Movement (2.17 m2)						
No Asbestos						
B00B - R1008 - Toilets - Girls (2.97 m2)						
No Asbestos						
B00B - R1009 - Cleaning Distributed Store (5.82 m2)						
No Asbestos						
B00B - R1010 - Toilets - Boys (3.38 m2)						
No Asbestos						
B00B - R1011 - Distribution Board (1.6 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1012 - Movement (23.83 m2)						
No Asbestos						
B00B - R1013 - Stairs (15.72 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
Ceiling Structures/Linings	Non Accessible Area - Extreme Access Issue - Obstructed Area - To tight to access with ladder					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Building Services - 1960 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Gable Verge Lining	Flat AC Sheeting 4020/B00C/Gable Verge Lining/S11				No Asbestos Detected	
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00C - R0001 - General Storeroom (15.36 m2)

No Asbestos

B00C - R0002 - General Assistant/Bulk Store (15.39 m2)

No Asbestos

B00C - R0004 - Movement (32.18 m2)

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00J/R0008/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

B00C - R0005 - General Storeroom (12.27 m2)

n/a No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00D/Eaves Linings/S21					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00D/Gable Verge Lining/S20					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00D - R0001 - Communal Space (222.45 m2)

No Asbestos

B00D - R0002 - Movement (1.79 m2)

No Asbestos

B00D - R0003 - Movement (1.78 m2)

No Asbestos

B00D - R0004 - Movement (1.81 m2)

No Asbestos

B00D - R0005 - Movement (1.86 m2)

No Asbestos

B00D - R0006 - Toilets - Boys (7.16 m2)

No Asbestos

B00D - R0007 - P.E. Store (14.43 m2)

No Asbestos

B00D - R0008 - Canteen (28.4 m2)

No Asbestos

B00D - R0009 - Canteen Office/Store (2.96 m2)

No Asbestos

B00D - R0010 - Canteen Office/Store (4.58 m2)

No Asbestos

B00D - R0011 - Staff Toilet (2.57 m2)

No Asbestos

B00D - R0012 - Hall Chair Store (8.55 m2)

No Asbestos

B00D - R0013 - Toilets - Girls (7.27 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00E/Eaves Linings/S18			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Verge Lining	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00E - R0001 - Movement (67.13 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4020/B00A/R1008/Ceiling Structures/Linings/S8					No Asbestos Detected
B00E - R0003 - Personal Effects Storage (5.22 m2)						
No Asbestos						
B00E - R0004 - Movement (1.98 m2)						
No Asbestos						
B00E - R0005 - Home Base (57.82 m2)						
No Asbestos						
B00E - R0006 - Home Base (57.74 m2)						
No Asbestos						
B00E - R0007 - Home Base Store (4.37 m2)						
No Asbestos						
B00E - R0008 - Personal Effects Storage (5.23 m2)						
No Asbestos						
B00E - R0009 - Movement (2.01 m2)						
No Asbestos						
B00E - R0010 - Home Base (55.3 m2)						
No Asbestos						
B00E - R0011 - Practical Activities - 1hb (14.79 m2)						
No Asbestos						
B00E - R0012 - Home Base Store (4.33 m2)						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/Eaves Linings/S17				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	40m2	South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/Gable Verge Lining/S16				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/R0001/In-fill-panel/S9				Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00F - R0001 - Movement (102.6 m2)

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4020/B00A/R1008/Ceiling Structures/Linings/S8					
In-fill-panel	Flat AC Sheeting	20m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/R0001/In-fill-panel/S9				Chrysotile (white asbestos)	

B00F - R0002 - Home Base (56.73 m2)

In-fill-panel	Flat AC Sheeting	8m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/R0001/In-fill-panel/S9					Chrysotile (white asbestos)

B00F - R0003 - Home Base Store (6.23 m2)

No Asbestos

B00F - R0004 - Personal Effects Storage (7.11 m2)

No Asbestos

B00F - R0005 - Home Base (55.7 m2)

In-fill-panel	Flat AC Sheeting	8m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/R0001/In-fill-panel/S9					Chrysotile (white asbestos)

B00F - R0006 - Home Base (54.04 m2)

In-fill-panel	Flat AC Sheeting	4m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/R0001/In-fill-panel/S9					Chrysotile (white asbestos)

B00F - R0007 - Personal Effects Storage (7.25 m2)

No Asbestos

B00F - R0008 - Home Base (58.3 m2)

In-fill-panel	Flat AC Sheeting	8m	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00F/R0001/In-fill-panel/S9					Chrysotile (white asbestos)

B00F - R0009 - Home Base Store (6.18 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1952 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4020/B00G/Eaves Linings/S12	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 4020/B00G/Gable Verge Lining/S13	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00G - R0001 - Main Switch Board (6.29 m2)

Electrical Backing Board	Resinous Board	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B00G - R0002 - Cleaning Supplies (8.49 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4020/B00J/R0008/Ceiling Structures/Linings/S3	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00G - R0003 - Staff Toilet (3.88 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4020/B00J/R0008/Ceiling Structures/Linings/S3	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00G - R0004 - Toilets - Boys (50.77 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4020/B00J/R0008/Ceiling Structures/Linings/S3	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet 4020/B00J/R0005/Partition Walls (Cubicles)/S4	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00G - R0005 - Toilets - Girls (48.68 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4020/B00J/R0008/Ceiling Structures/Linings/S3	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet 4020/B00J/R0005/Partition Walls (Cubicles)/S4	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00G - R0006 - Staff Toilet (5.07 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4020/B00J/R0008/Ceiling Structures/Linings/S3	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------------	--------------------	---------	--

B00G - R0007 - Movement (63.83 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4020/B00J/R0008/Ceiling Structures/Linings/S3	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	------------	--------------------	---------	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Eaves Linings	Flat AC Sheeting 4020/B00H/Eaves Linings/S11					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Height Restriction

Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00H - R0001 - Home Base (58.13 m2)

No Asbestos

B00H - R0002 - Practical Activities - 1hb (14.67 m2)

No Asbestos

B00H - R0003 - Practical Activities - 1hb (14.43 m2)

No Asbestos

B00H - R0004 - Home Base (58.05 m2)

No Asbestos

B00H - R0005 - Movement (160.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting	161m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

In-fill-panel	Flat AC Sheeting	12m	Throughout, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0013/In-fill-panel/S1					Chrysotile (white asbestos)

B00H - R0006 - Home Base (56.65 m2)

No Asbestos

B00H - R0007 - Personal Effects Storage (14.08 m2)

No Asbestos

B00H - R0008 - Home Base Store (6.71 m2)

No Asbestos

B00H - R0009 - General Storeroom (6.81 m2)

No Asbestos

B00H - R0010 - Other-Community Use (56.72 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Support Unit/General Learning - 1960 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Eaves Linings	Flat AC Sheeting 4020/B00H/Eaves Linings/S11					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00I - R0001 - Home Base - M (41.78 m2)

No Asbestos

B00I - R0002 - Practical Activities - M - 1hb (2.53 m2)

No Asbestos

B00I - R0003 - Toilet - M (6.48 m2)

No Asbestos

B00I - R0004 - Home Base Store - M (5.47 m2)

No Asbestos

B00I - R0005 - Home Base (39.33 m2)

No Asbestos

B00I - R0006 - Practical Activities - 1hb (4.71 m2)

No Asbestos

B00I - R0007 - Home Base (44.33 m2)

No Asbestos

B00I - R0008 - Home Base (44.64 m2)

No Asbestos

B00I - R0009 - Movement (3.49 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4020/B00I/R0009/Floor Coverings Res/Textile/S6					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00I - R0010 - Movement (5.57 m2)

No Asbestos

B00I - R0011 - Staff Kitchen (16.05 m2)

No Asbestos

B00I - R0012 - Interview (17.99 m2)

No Asbestos

B00I - R0013 - General Storeroom (8.03 m2)

Wall Linings Internal	Flat AC Sheeting 4020/B00I/R0013/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00I - R0014 - Movement (62.37 m2)

No Asbestos

B00I - R0015 - Movement (5.19 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00J - General Learning/Support Unit - 1960 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Eaves Linings	Flat AC Sheeting 4020/B00H/Eaves Linings/S11				No Asbestos Detected	
Gable Verge Lining	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/Gable Verge Lining/S22				Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00J - R0001 - Movement (90.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00J - R0002 - General Storeroom (3.01 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00J - R0003 - Cleaning Distributed Store (3.06 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00J - R0004 - Toilets - Girls (36.64 m2)

Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0005/Partition Walls (Cubicles)/S4				Chrysotile (white asbestos)	

B00J - R0005 - Toilets - Boys (30.52 m2)

Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0005/Partition Walls (Cubicles)/S4				Chrysotile (white asbestos)	

B00J - R0006 - Staff Toilet (6.05 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00J - R0007 - Sports Store (5.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0008/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00J - R0008 - Movement (83.47 m2)

In-fill-panel	Flat AC Sheeting	14m	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4020/B00J/R0013/In-fill-panel/S1				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00J/R0008/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00J - R0009 - Movement (6.51 m2)						
No Asbestos						
B00J - R0010 - Home Base Store (4.49 m2)						
No Asbestos						
B00J - R0011 - Toilets - Boys/Girls (3.38 m2)						
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00J/R0011/Wall Linings Internal/S2					Chrysotile (white asbestos)	
B00J - R0012 - Home Base (85.8 m2)						
In-fill-panel	Flat AC Sheeting	14m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00J/R0013/In-fill-panel/S1					Chrysotile (white asbestos)	
B00J - R0013 - Home Base (85.8 m2)						
In-fill-panel	Flat AC Sheeting	14m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4020/B00J/R0013/In-fill-panel/S1					Chrysotile (white asbestos)	
B00J - R0014 - Toilets - Boys/Girls (3.37 m2)						
No Asbestos						
B00J - R0015 - Home Base Store (4.51 m2)						
No Asbestos						
B00J - R0016 - Movement (6.4 m2)						
No Asbestos						
B00J - R0019 - Toilet - E (9.52 m2)						
No Asbestos						
B00J - R0020 - Home Base Store - E (10.17 m2)						
No Asbestos						
B00J - R0021 - Home Base Store (3.32 m2)						
No Asbestos						
B00J - R0022 - Home Base - E (41.42 m2)						
No Asbestos						
B00J - R0023 - Practical Activities - E (28.48 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Storage - 2009 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - General Storeroom (34.52 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017