

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Glendale East Public School (4207)  
**Region :** Hunter/Central Coast  
**State Electorate :** Wallsend  
**Local Government Area :** Lake Macquarie

**Initial Survey :** Noel Arnold & Associates : 30 - Apr - 2008  
**Reviewed By :** Greencap-NAA : 24 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Library - 1960 - Brick/Veneer (Brick/Veneer)**

**Exterior**

In-fill-panel	Flat AC Sheeting	120m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00A/In-fill-panel/S1					<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting	8m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00A/Eaves Linings/S3					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Height Restriction					

**Interior**

**B00A - R0001 - Library Office/Workroom (9.1 m2)**

Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00A/R0003/Floor Coverings Res/Textile/S24					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00A/R0003/Floor Coverings Res/Textile/S23					<b>Chrysotile (white asbestos)</b>

**B00A - R0002 - Cleaning Supplies (4.81 m2)**

No Asbestos

**B00A - R0003 - Reading Area (187.22 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	188m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00A/R0003/Floor Coverings Res/Textile/S23					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00A/R0003/Floor Coverings Res/Textile/S24					

**B00A - R0004 - External Movement (6.36 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	4207/B00A/R0004/Ceiling Structures/Linings/S4					

**B00A - R0005 - External Movement (6.45 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00A/R0005/Ceiling Structures/Linings/S25					<b>Chrysotile (white asbestos)</b>

**B00A - R0006 - Entry Vestibule (21.86 m2)**

Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00A/R0003/Floor Coverings Res/Textile/S24					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00A/R0003/Floor Coverings Res/Textile/S23					<b>Chrysotile (white asbestos)</b>

**B00A - R0007 - Clerical Office (23.9 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00A/R0003/Floor Coverings Res/Textile/S23					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00A/R0003/Floor Coverings Res/Textile/S24					

**B00A - R0008 - Printing (17.17 m2)**

Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00A/R0003/Floor Coverings Res/Textile/S24					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4207/B00A/R0003/Floor Coverings Res/Textile/S23	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0009 - General Storeroom (3.26 m2)</b>						
No Asbestos						
<b>B00A - R0010 - Movement (9.94 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4207/B00A/R0003/Floor Coverings Res/Textile/S23	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 4207/B00A/R0003/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>
<b>B00A - R0011 - Principal (16.09 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4207/B00A/R0003/Floor Coverings Res/Textile/S23	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 4207/B00A/R0003/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>
<b>B00A - R0012 - Staff Toilet (3.04 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 4207/B00A/R0005/Ceiling Structures/Linings/S25	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0013 - Staff Toilet (2.71 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 4207/B00A/R0005/Ceiling Structures/Linings/S25	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Staff Facilities - 1960 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0001/Wall Linings Internal/S2					<b>Chrysotile (white asbestos)</b>
Wall Cladding	Flat AC Sheeting	100m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0001/Wall Linings Internal/S2					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0001 - General Assistant/Bulk Store (23.59 m2)**

Wall Linings Internal	Flat AC Sheeting	40m2	East, West & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0001/Wall Linings Internal/S2					<b>Chrysotile (white asbestos)</b>

**B00B - R0002 - Staff Room (57.96 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0002/Floor Coverings Res/Textile/S6					<b>Chrysotile (white asbestos)</b>
Heater backing	Compressed AC Sheet	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0002/Heater backing/S21					<b>Chrysotile (white asbestos)</b>

**B00B - R0003 - General Storeroom (4.21 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0002/Floor Coverings Res/Textile/S6					<b>Chrysotile (white asbestos)</b>

**B00B - R0004 - Movement (39.77 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0001/Wall Linings Internal/S2					<b>Chrysotile (white asbestos)</b>

**B00B - R0005 - Movement (7.56 m2)**

No Asbestos

**B00B - R0006 - General Storeroom (8.96 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0002/Floor Coverings Res/Textile/S6					<b>Chrysotile (white asbestos)</b>

**B00B - R0007 - Home Base Store (4.21 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0002/Floor Coverings Res/Textile/S6					<b>Chrysotile (white asbestos)</b>

**B00B - R0008 - Home Base (58.04 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0002/Floor Coverings Res/Textile/S6					<b>Chrysotile (white asbestos)</b>
Heater backing	Compressed AC Sheet	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0002/Heater backing/S21					<b>Chrysotile (white asbestos)</b>

**B00B - R0009 - Movement (1.25 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00B/R0001/Wall Linings Internal/S2					<b>Chrysotile (white asbestos)</b>

**B00B - R0010 - Movement (3.64 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00B/R0002/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
<b>B00B - R0011 - Personal Effects Storage (4.33 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00B/R0002/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
<b>B00B - R0012 - General Storeroom (4.27 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00B/R0002/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
<b>B00B - R0013 - Home Base (58.12 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00B/R0002/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
<b>B00B - R9001 - Toilets - Girls (51.4 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00B/R9002/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
<b>B00B - R9002 - Bulk Store (66.86 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00B/R9002/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00B/R0002/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Pupil Facilities - 1968 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4207/B00C/R0001/Ceiling Structures/Linings/S19					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00C - R0001 - Home Base (57.13 m2)**

Ceiling Structures/Linings	Vermiculite 4207/B00C/R0001/Ceiling Structures/Linings/S19					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Heater backing	Flat AC Sheeting 4207/B00C/R0001/Heater backing/S20	3m2	South west corner	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0002 - Home Base Store (4.2 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 4207/B00C/R0004/Floor Coverings Res/Textile/S9	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
-----------------------------	---	-----	------------	--------------------	---------	---

**B00C - R0003 - Movement (7.93 m2)**

Ceiling Structures/Linings	Vermiculite 4207/B00C/R0001/Ceiling Structures/Linings/S19					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4207/B00C/R0004/Floor Coverings Res/Textile/S9	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0004 - Personal Effects Storage (10.49 m2)**

Ceiling Structures/Linings	Vermiculite 4207/B00C/R0001/Ceiling Structures/Linings/S19					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4207/B00C/R0004/Floor Coverings Res/Textile/S9	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

Electrical Backing Board	Resinous Board	1Unit	North west corner	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Assumed Asbestos - Electrical Hazard</b>
--------------------------	----------------	-------	-------------------	--------------------	---------	---

**B00C - R0005 - Home Base Store (4.2 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 4207/B00C/R0004/Floor Coverings Res/Textile/S9	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
-----------------------------	---	-----	------------	--------------------	---------	---

**B00C - R0006 - Home Base (57.28 m2)**

Ceiling Structures/Linings	Vermiculite 4207/B00C/R0001/Ceiling Structures/Linings/S19					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Heater backing	Flat AC Sheeting 4207/B00C/R0001/Heater backing/S20	3m2	North west corner	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R9001 - Toilets - Boys (42.1 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 4207/B00C/R9001/Ceiling Structures/Linings/S18					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting		4207/B00C/R9001/Ceiling Structures/Linings/S18			<b>No Asbestos Detected</b>
<b>B00C - R9002 - Toilets - Boys (1.24 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting		4207/B00C/R9001/Ceiling Structures/Linings/S18			<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00D - Administration/General Learning - 1958 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00D/R0010/Ceiling Structures/Linings/S15			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Height Restriction					

**Interior**

**B00D - R0001 - Movement (6.22 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00D/R0010/Ceiling Structures/Linings/S15			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00D - R0002 - Movement (3.59 m2)**

Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Assumed Asbestos - Electrical Hazard</b>		

**B00D - R0003 - General Storeroom (9.88 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00D/R0003/Floor Coverings Res/Textile/S16			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00D/R0003/Floor Coverings Res/Textile/S17					

**B00D - R0004 - No Access (3.23 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00D/R0003/Floor Coverings Res/Textile/S16			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00D/R0003/Floor Coverings Res/Textile/S17					

**B00D - R0005 - Home Base (67.79 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00D/R0003/Floor Coverings Res/Textile/S16			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00D/R0003/Floor Coverings Res/Textile/S17					

**B00D - R0006 - Home Base (67.87 m2)**

Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00D/R0003/Floor Coverings Res/Textile/S17					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00D/R0003/Floor Coverings Res/Textile/S16			<b>Chrysotile (white asbestos)</b>		

**B00D - R0007 - General Storeroom (3.19 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00D/R0003/Floor Coverings Res/Textile/S16			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	4207/B00D/R0003/Floor Coverings Res/Textile/S17					

**B00D - R0008 - No Access (9.63 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00D/R0003/Floor Coverings Res/Textile/S16					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive					
4207/B00D/R0003/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>	
<b>B00D - R0009 - Movement (3.55 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00D/R0003/Floor Coverings Res/Textile/S16					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive					
4207/B00D/R0003/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>	
<b>B00D - R0010 - Movement (5.37 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00D/R0010/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00E - General Learning - 1960 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0001/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	Non Accessible Area - Height Restriction Area inaccessible					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00E - R0001 - Movement (5.2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0001/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00E - R0002 - Movement (3.38 m2)**

No Asbestos

**B00E - R0003 - General Storeroom (9.75 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13				<b>No Asbestos Detected</b>	

**B00E - R0004 - Home Base Store (3.7 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13				<b>No Asbestos Detected</b>	

**B00E - R0005 - Home Base (68.19 m2)**

Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	
Heater backing	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0005/Heater backing/S14				<b>Chrysotile (white asbestos)</b>	

**B00E - R0006 - Home Base (68.26 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13				<b>No Asbestos Detected</b>	
Heater backing	Flat AC Sheeting	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0005/Heater backing/S14				<b>Chrysotile (white asbestos)</b>	

**B00E - R0007 - Home Base Store (3.54 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>
<b>B00E - R0008 - Movement (5.31 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00E - R0009 - Movement (10.55 m2)</b>						
No Asbestos						
<b>B00E - R0010 - Personal Effects Storage (9.25 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>
<b>B00E - R0011 - Personal Effects Storage (9.35 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>
<b>B00E - R0012 - Home Base Store (3.34 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>
<b>B00E - R0013 - Toilets - Boys/Girls (3.39 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00E - R0014 - Home Base (95.53 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	96m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>
Heater backing	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0005/Heater backing/S14					<b>Chrysotile (white asbestos)</b>
<b>B00E - R0015 - Home Base (67.65 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>
Heater backing	Flat AC Sheeting	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0005/Heater backing/S14					<b>Chrysotile (white asbestos)</b>
<b>B00E - R0016 - Home Base Store (3.51 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					
<b>B00E - R0017 - Personal Effects Storage (9.26 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					
<b>B00E - R0018 - Movement (24.82 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					
<b>B00E - R0019 - Withdrawal Space - 1hb (16.35 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					
<b>B00E - R0020 - Cleaning Distributed Store (2.08 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					
<b>B00E - R0021 - Special Programs Room (18.86 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					
<b>B00E - R0022 - Craft Store (7.14 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					
<b>B00E - R0023 - Movement (5.31 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4207/B00E/R0001/Ceiling Structures/Linings/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00E - R0024 - General Storeroom (1.53 m2)</b>						
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4207/B00E/R0003/Floor Coverings Res/Textile/S13					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00E/R0003/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Pupil Facilities - 1958 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00F/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior**

**B00F - R0001 - Toilets - Boys (47.45 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00F/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0002 - Movement (16.44 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00F/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0003 - Movement (16.49 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00F/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0004 - Toilets - Girls (47.4 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00F/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0005 - Movement (8.32 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4207/B00F/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0006 - Movement (51.86 m2)**

No Asbestos

**B00F - R0007 - Canteen (27.9 m2)**

No Asbestos

**B00F - R0008 - Staff Toilet (3.61 m2)**

No Asbestos

**B00F - R0009 - Canteen Office/Store (7.19 m2)**

No Asbestos

**B00F - R0010 - Canteen Office/Store (4.61 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Communal Facilities/General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00G - R0001 - Covered Outdoor Learning Area (148.92 m2)**

No Asbestos

**B00G - R0002 - Communal Space (144.66 m2)**

No Asbestos

**B00G - R0003 - Movement (5.57 m2)**

No Asbestos

**B00G - R0004 - Raised Platform (60.98 m2)**

No Asbestos

**B00G - R0005 - Movement (11.1 m2)**

No Asbestos

**B00G - R0006 - Movement (13.54 m2)**

No Asbestos

**B00G - R0007 - Hall Chair Store (10.21 m2)**

No Asbestos

**B00G - R0008 - Communal/Performance Store (8.26 m2)**

No Asbestos

**B00G - R0009 - P.E. Store (13.13 m2)**

No Asbestos

**B00G - R0010 - Toilet - Lobby (2.37 m2)**

No Asbestos

**B00G - R0011 - Toilets - Girls (7.31 m2)**

No Asbestos

**B00G - R0012 - Sound Cupboard (2.06 m2)**

No Asbestos

**B00G - R0013 - Toilet - Lobby (3.3 m2)**

No Asbestos

**B00G - R0014 - Toilets - Boys (5.71 m2)**

No Asbestos

**B00G - R0015 - Cleaning Distributed Store (3.51 m2)**

No Asbestos

**B00G - R0016 - General Storeroom (1.6 m2)**

No Asbestos

**B00G - R0017 - Main Switch Board (3.3 m2)**

No Asbestos

**B00G - R0018 - Access Shower/Toilet (6.87 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**Available Asbestos Related Electronic Files**

4207\_ASB\_221112\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017