


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gwandalan Public School (4320)
Region : Hunter/Central Coast
State Electorate : Swansea
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1990 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Duplicating Workroom

No Asbestos

B00A - R0003 - Cleaning Distributed Store

No Asbestos

B00A - R0004 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Security Store

No Asbestos

B00A - R0006 - External Movement

No Asbestos

B00A - R0007 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0008 - Shower/Change

No Asbestos

B00A - R0009 - Sick Bay

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0010 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0012 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - External Movement

No Asbestos

B00A - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration - 1990 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Staff Toilet

No Asbestos

B00B - R0002 - Staff Toilet

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0006 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Staff Room Annexe

No Asbestos

B00B - R0009 - Cleaning Supplies

No Asbestos

B00B - R0010 - General Assistant/Bulk Store

No Asbestos

B00B - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Communal Facilities - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Toilets - Girls

No Asbestos

B00C - R0002 - Shower/Change

No Asbestos

B00C - R0003 - Disabled Toilet

No Asbestos

B00C - R0004 - External Movement

No Asbestos

B00C - R0005 - Hall Chair Store

No Asbestos

B00C - R0006 - P.E. Store

No Asbestos

B00C - R0007 - Plant

No Asbestos

B00C - R0008 - Plant

No Asbestos

B00C - R0009 - Cleaning Distributed Store

No Asbestos

B00C - R0010 - Main Switch Board

No Asbestos

B00C - R0011 - Sports Store

No Asbestos

B00C - R0012 - External Movement

No Asbestos

B00C - R0013 - Shower/Change

No Asbestos

B00C - R0014 - Toilets - Boys

No Asbestos

B00C - R0016 - Movement

No Asbestos

B00C - R0017 - Raised Platform

No Asbestos

B00C - R0019 - Movement

No Asbestos

B00C - R0020 - Communal Space

No Asbestos

B00C - R0021 - External Movement

No Asbestos

B00C - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1990 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Canteen Office/Store

No Asbestos

B00D - R0002 - Canteen

No Asbestos

B00D - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Library - 1990 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0003 - Practical Activities - 1hb

No Asbestos

B00E - R0004 - Practical Activities - 1hb

No Asbestos

B00E - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0007 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0010 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0011 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0012 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0013 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0014 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0015 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0017 - Movement

No Asbestos

B00E - R0018 - External Movement

No Asbestos

B00E - R0019 - Uniform Shop

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R0020 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1990 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Toilets - Boys**

No Asbestos

B00F - R0002 - Toilets - Girls

No Asbestos

B00F - R0003 - Practical Activities - 1hb

No Asbestos

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Withdrawal Space - 1hbVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0006 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0007 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0008 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0009 - Practical Activities - 1hb**

No Asbestos

B00F - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0011 - Kiln Room

No Asbestos

B00F - R0012 - Practical Activities - 1hb

No Asbestos

B00F - R0013 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0014 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0015 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0016 - Practical Activities - 1hb**

No Asbestos

B00F - R0017 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0018 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0019 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-After School Care - 1990 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00G - R0001 - Withdrawal Space - 1hb	Non Accessible					
B00G - R0002 - Special Programs Room	Non Accessible					
B00G - R0003 - Toilets - Boys/Girls	Non Accessible					
B00G - R0004 - Cleaning Distributed Store	Non Accessible					
B00G - R0005 - Handwashing Facilities	Non Accessible					
B00G - R0006 - Movement	Non Accessible					
B00G - R0007 - Withdrawal Space - 1hb	Non Accessible					
B00G - R0008 - General Storeroom	Non Accessible					
B00G - R0009 - General Storeroom	Non Accessible					
B00G - R0010 - Laundry - Type 2	Non Accessible					
B00G - R0011 - Staff Kitchen	Non Accessible					
B00G - R0012 - Canteen Office/Store	Non Accessible					
B00G - R0013 - External Movement	Non Accessible					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-After School Care - 1990 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	15m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00H - R0001 - General Storeroom

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Movement

No Asbestos

B00J - R0002 - Practical Activities - 1hb

No Asbestos

B00J - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Other-Community Use/Music - 2008 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - External Movement

No Asbestos

B00K - R0002 - Other-Community Use

No Asbestos

B00K - R0003 - External Movement

No Asbestos

B00K - R0004 - Kitchen - Pre

No Asbestos

B00K - R0005 - Other-Community Use

No Asbestos

B00K - R0006 - Movement

No Asbestos

B00K - R0007 - General Storeroom

No Asbestos

B00K - R0008 - Toilets-Unisex

No Asbestos

B00K - R0009 - Toilets-Unisex

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Toilets - Boys

No Asbestos

B00L - R0002 - Toilets - Girls

No Asbestos

B00L - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - Practical Activities - 1hb

No Asbestos

B00M - R0003 - Withdrawal Space - 1hb

No Asbestos

B00M - R0004 - Home Base Store

No Asbestos

B00M - R0005 - Home Base

No Asbestos

B00M - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0007 - Practical Activities - 1hb

No Asbestos

B00M - R0009 - Withdrawal Space - 2hb

No Asbestos

B00M - R0010 - Home Base

No Asbestos

B00M - R0011 - Home Base Store

No Asbestos

B00M - R0012 - Practical Activities - 1hb

No Asbestos

B00M - R0014 - Home Base Store

No Asbestos

B00M - R0015 - Home Base

No Asbestos

B00M - R0016 - External Movement

No Asbestos

B00M - R0017 - General Storeroom

No Asbestos

B00M - R0018 - General Storeroom

No Asbestos

B00M - R0019 - External Stairs

No Asbestos

B00M - R0020 - External Stairs

No Asbestos

B00M - R1001 - Practical Activities - 1hb

No Asbestos

B00M - R1003 - Withdrawal Space - 2hb

No Asbestos

B00M - R1004 - Home Base

No Asbestos

B00M - R1005 - Home Base Store

No Asbestos

B00M - R1006 - Practical Activities - 1hb

No Asbestos

B00M - R1008 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00M - R1009 - Home Base Store					
	No Asbestos					
	B00M - R1010 - Practical Activities - 1hb					
	No Asbestos					
	B00M - R1012 - Home Base					
	No Asbestos					
	B00M - R1013 - Withdrawal Space - 1hb					
	No Asbestos					
	B00M - R1014 - Home Base Store					
	No Asbestos					
	B00M - R1015 - Distribution Board					Note: No inspection of live electrical installation.
	No Asbestos					
	B00M - R1016 - External Movement					
	No Asbestos					
	B00M - R1017 - External Stairs					
	No Asbestos					
	B00M - R1018 - External Stairs					
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Storage - 2014 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017