


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Governor Philip King Public School (4567)
Region : South Western Sydney
State Electorate : Cabramatta
Local Government Area : Fairfield

Initial Survey : Noel Arnold & Associates : 14 - May - 2008
Reviewed By : Parsons Brinckerhoff : 03 - Jan - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1987 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00A - R0001 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0002 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Duplicating Workroom

No Asbestos

B00A - R0004 - Staff Toilet

No Asbestos

B00A - R0005 - Staff Toilet

No Asbestos

B00A - R0006 - General Storeroom

No Asbestos

B00A - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0008 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0009 - Security Store

No Asbestos

B00A - R0010 - Security Store

No Asbestos

B00A - R0011 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0016 - Sick Bay

No Asbestos

B00A - R0017 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0018 - Clerical Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0019 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0020 - External Movement

No Asbestos

B00A - R0021 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1987 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00B - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00B - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - Communal/Performance Store

No Asbestos

B00B - R0009 - Cleaning Distributed Store

No Asbestos

B00B - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0012 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0015 - Practical Activities - 1hb

No Asbestos

B00B - R0016 - Security Store

No Asbestos

B00B - R0017 - Cleaning Distributed Store

No Asbestos

B00B - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0019 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0020 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0021 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0022 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0023 - Practical Activities - 1hb						
No Asbestos						
B00B - R0024 - Music Store						
No Asbestos						
B00B - R0025 - Communal/Performance Store						
No Asbestos						
B00B - R0026 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0027 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0028 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0029 - Special Programs Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0030 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0031 - Practical Activities - 1hb						
No Asbestos						
B00B - R0032 - Security Store						
No Asbestos						
B00B - R0033 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R0034 - Cleaning Distributed Store						
No Asbestos						
B00B - R0035 - Disabled Toilet						
No Asbestos						
B00B - R0036 - Disabled Shower/Toilet						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0037 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet					
	4567/B00B/R0037/Partition Walls (Cubicles)/S3					No Asbestos Detected
B00B - R0038 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet					
	4567/B00B/R0037/Partition Walls (Cubicles)/S3					No Asbestos Detected
B00B - R0040 - External Movement						
No Asbestos						
B00B - R0041 - External Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0042 - External Movement

No Asbestos

B00B - R0043 - External Movement

No Asbestos

B00B - R0044 - External Movement

No Asbestos

B00B - R0045 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/Communal Facilities - 1987 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior

B00C - R0001 - Canteen

No Asbestos

B00C - R0002 - Canteen Office/Store

No Asbestos

B00C - R0003 - Canteen Office/Store

No Asbestos

B00C - R0004 - Hall Chair Store

No Asbestos

B00C - R0005 - Communal Space

No Asbestos

B00C - R0006 - General Storeroom

No Asbestos

B00C - R0007 - Sports Store

No Asbestos

B00C - R0008 - Raised Platform

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Disabled Toilet

No Asbestos

B00C - R0011 - Movement

No Asbestos

B00C - R0012 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4567/B00C/R0014/Partition Walls (Cubicles)/S1	No Asbestos Detected
----------------------------	--	----------------------

B00C - R0013 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 4567/B00C/R0014/Partition Walls (Cubicles)/S1	No Asbestos Detected
----------------------------	--	----------------------

B00C - R0014 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 4567/B00C/R0014/Partition Walls (Cubicles)/S1	No Asbestos Detected
----------------------------	--	----------------------

B00C - R0015 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 4567/B00C/R0014/Partition Walls (Cubicles)/S1	No Asbestos Detected
----------------------------	--	----------------------

B00C - R0016 - Cleaning Supplies

No Asbestos

B00C - R0017 - General Assistant/Bulk Store

No Asbestos

B00C - R0018 - Cleaning Supplies

No Asbestos

B00C - R0019 - Main Switch Board

No Asbestos

B00C - R0020 - External Movement

No Asbestos

B00C - R0021 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1987 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00D - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00D - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Security Store

No Asbestos

B00D - R0007 - Practical Activities - 1hb

No Asbestos

B00D - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Cleaning Distributed Store

No Asbestos

B00D - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - Security Store

No Asbestos

B00D - R0015 - Practical Activities - 1hb

No Asbestos

B00D - R0016 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0017 - Cleaning Distributed Store

No Asbestos

B00D - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0019 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0020 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0021 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0022 - Security Store						
No Asbestos						
B00D - R0023 - Practical Activities - 1hb						
No Asbestos						
B00D - R0024 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0025 - Distribution Board						
No Asbestos					Note: No inspection of live electrical installation.	
B00D - R0027 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
		4567/B00D/R0033/Partition Walls (Cubicles)/S2				
B00D - R0028 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
		4567/B00D/R0033/Partition Walls (Cubicles)/S2				
B00D - R0029 - Staff Toilet						
No Asbestos						
B00D - R0030 - Staff Toilet						
No Asbestos						
B00D - R0031 - General Assistant/Bulk Store						
No Asbestos						
B00D - R0032 - P.E. Store						
No Asbestos						
B00D - R0033 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
		4567/B00D/R0033/Partition Walls (Cubicles)/S2				
B00D - R0034 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
		4567/B00D/R0033/Partition Walls (Cubicles)/S2				
B00D - R0036 - External Movement						
No Asbestos						
B00D - R0037 - Movement						
No Asbestos						
B00D - R0038 - External Movement						
No Asbestos						
B00D - R0039 - External Movement						
No Asbestos						
B00D - R0040 - External Movement						
No Asbestos						
B00D - R0041 - External Movement						
No Asbestos						
B00D - R0042 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 1987 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior

B00E - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0002 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0005 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0006 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0007 - Movement

No Asbestos

B00E - R0008 - Plant

No Asbestos

B00E - R0009 - External Movement

No Asbestos

B00E - R0012 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Administration - 1975 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Staff Toilet

No Asbestos

B00F - R0003 - Community Clinic

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0004 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0006 - Practical Activities - 1hb

No Asbestos

B00G - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0009 - Practical Activities - 1hb

No Asbestos

B00G - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0011 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0013 - Practical Activities - 1hb

No Asbestos

B00G - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0016 - External Movement

No Asbestos

B00G - R0017 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Movement

Ramp	Compressed AC Sheet 4567/B00H/R0001/Ramp/S4	No Asbestos Detected
------	--	-----------------------------

B00H - R0002 - Practical Activities - 1hb

No Asbestos

B00H - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - External Movement

No Asbestos

B00I - R0002 - Cleaning Distributed Store

No Asbestos

B00I - R0003 - Movement

No Asbestos

B00I - R0004 - Home Base Store

No Asbestos

B00I - R0005 - Special Programs Room

No Asbestos

B00I - R0006 - Practical Activities - 1hb

No Asbestos

B00I - R0007 - Home Base Store

No Asbestos

B00I - R0008 - Home Base

No Asbestos

B00I - R0009 - Withdrawal Space - 2hb

No Asbestos

B00I - R0010 - Home Base

No Asbestos

B00I - R0011 - Home Base Store

No Asbestos

B00I - R0012 - Practical Activities - 1hb

No Asbestos

B00I - R0013 - No Access

No Asbestos

B00I - R0014 - Practical Activities - 1hb

No Asbestos

B00I - R0015 - Withdrawal Space - 1hb

No Asbestos

B00I - R0016 - Home Base Store

No Asbestos

B00I - R0017 - Home Base

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - Practical Activities - 1hb

No Asbestos

B00J - R0003 - Home Base Store

No Asbestos

B00J - R0004 - Home Base

No Asbestos

B00J - R0005 - Withdrawal Space - 2hb

No Asbestos

B00J - R0006 - Home Base

No Asbestos

B00J - R0007 - Home Base Store

No Asbestos

B00J - R0008 - Practical Activities - 1hb

No Asbestos

B00J - R0009 - No Access

No Asbestos

B00J - R0010 - Practical Activities - 1hb

No Asbestos

B00J - R0011 - Withdrawal Space - 1hb

No Asbestos

B00J - R0012 - Home Base Store

No Asbestos

B00J - R0013 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 251 - D11262 - Learning Unit - Double E.S.L./Workroom : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

R2 - Esl

No Asbestos Found.

R3 - Entry

No Asbestos Found.

R4 - Work Space

No Asbestos Found.

NS 321 - D11263 - Toilets - Boys : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Toilets-Boys

No Asbestos Found.

NS 320 - D11264 - Toilets - Girls : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Toilets-Girls

No Asbestos Found.

NS 321 - D11371 - Toilets - Boys : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Toilets-Boys

No Asbestos Found.

NS 320 - D11372 - Toilets - Girls : Placement Date - 30/06/1995

Exterior

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - Toilets-Girls						
No Asbestos Found.						
OS 751 - D11662 - Learning Unit - ESL : Placement Date - 21/01/1996						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
R2 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 602 - D15979 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017