


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Glendore Public School (4620)  
**Region :** Hunter/Central Coast  
**State Electorate :** Wallsend  
**Local Government Area :** Newcastle

**Initial Survey :** Noel Arnold & Associates : 24 - Apr - 2008  
**Register Issue Date :** 23 - Mar - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration - 1997 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00A - R0002 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0003 - Duplicating Workroom**

No Asbestos

**B00A - R0004 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0005 - Security Store**

No Asbestos

**B00A - R0006 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0007 - Communications Cupboard**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0008 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0009 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0010 - Cleaning Distributed Store**

No Asbestos

**B00A - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0012 - Staff Toilet**

No Asbestos

**B00A - R0013 - Staff Toilet**

No Asbestos

**B00A - R0014 - Staff Toilet**

No Asbestos

**B00A - R0015 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0016 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0017 - Sick Bay - Shower/Toilet**

No Asbestos

**B00A - R0018 - Sick Bay**

No Asbestos

**B00A - R0019 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0021 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1997 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00B - R0001 - Movement**

No Asbestos

**B00B - R0002 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0003 - Sports Store**

No Asbestos

**B00B - R0004 - Garden Store**

No Asbestos

**B00B - R0005 - Cleaning Distributed Store**

No Asbestos

**B00B - R0006 - Cleaning Supplies**

No Asbestos

**B00B - R0007 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0009 - Practical Activities - 1hb**

No Asbestos

**B00B - R0010 - Personal Effects Storage**

No Asbestos

**B00B - R0011 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0012 - Personal Effects Storage**

No Asbestos

**B00B - R0013 - Practical Activities - 1hb**

No Asbestos

**B00B - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0015 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0016 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0017 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0018 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0019 - Practical Activities - 1hb**

No Asbestos

**B00B - R0020 - Personal Effects Storage**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0021 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00B - R0022 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00B - R0023 - Personal Effects Storage</b>						
No Asbestos						
<b>B00B - R0024 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R0025 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00B - R0026 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00B - R0027 - Distribution Board</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00B - R0028 - Toilets - Girls</b>						
No Asbestos						
<b>B00B - R0029 - Kiln Room</b>						
No Asbestos						
<b>B00B - R0030 - Toilets - Boys</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Library - 1997 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - Staff Toilet**

No Asbestos

**B00C - R0002 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0003 - Special Programs Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0004 - Cleaning Distributed Store**

No Asbestos

**B00C - R0005 - Plant**

No Asbestos

**B00C - R0006 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0007 - Communications Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0008 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0009 - Communications Cupboard**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0011 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities - 1997 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00D - R0001 - Cleaning Distributed Store**

No Asbestos

**B00D - R0002 - Toilet - P**

No Asbestos

**B00D - R0003 - P.E. Store**

No Asbestos

**B00D - R0004 - General Assistant/Bulk Store**

No Asbestos

**B00D - R0005 - Toilets - Boys**

No Asbestos

**B00D - R0006 - Sports Store**

No Asbestos

**B00D - R0007 - Main Switch Board**

No Asbestos

**B00D - R0008 - Movement**

No Asbestos

**B00D - R0009 - Communal Space**

No Asbestos

**B00D - R0010 - Raised Platform**

No Asbestos

**B00D - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0012 - Plant**

No Asbestos

**B00D - R0013 - Hall Chair Store**

No Asbestos

**B00D - R0014 - Sports Store**

No Asbestos

**B00D - R0015 - Sports Store**

No Asbestos

**B00D - R0016 - Movement**

No Asbestos

**B00D - R0017 - Toilets - Girls**

No Asbestos

**B00D - R0018 - Shower/Change**

No Asbestos

**B00D - R0019 - Staff Kitchen**

No Asbestos

**B00D - R0020 - Staff Kitchen**

No Asbestos

**B00D - R0021 - Movement**

No Asbestos

**B00D - R0022 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R0023 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0024 - Staff Room Annexe</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0025 - Security Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0026 - Interview</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0027 - Interview</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0028 - Security Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0029 - Disabled Toilet</b>						
No Asbestos						
<b>B00D - R0030 - Disabled Toilet</b>						
No Asbestos						
<b>B00D - R0031 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities - 1997 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00E - R0001 - Canteen**

No Asbestos

**B00E - R0002 - Canteen Office/Store**

No Asbestos

**B00E - R0003 - Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Pupil Facilities - 1997 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - Movement**

No Asbestos

**B00F - R0002 - Practical Activities - 1hb**

No Asbestos

**B00F - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0005 - Personal Effects Storage**

No Asbestos

**B00F - R0006 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0007 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0008 - Personal Effects Storage**

No Asbestos

**B00F - R0009 - Practical Activities - 1hb**

No Asbestos

**B00F - R0010 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0012 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0013 - Practical Activities - 1hb**

No Asbestos

**B00F - R0014 - Personal Effects Storage**

No Asbestos

**B00F - R0015 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0016 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0017 - Personal Effects Storage**

No Asbestos

**B00F - R0018 - Practical Activities - 1hb**

No Asbestos

**B00F - R0019 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0020 - Home Base Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0021 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0022 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00F - R0023 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00F - R0024 - Personal Effects Storage</b>						
No Asbestos						
<b>B00F - R0025 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0026 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0027 - Personal Effects Storage</b>						
No Asbestos						
<b>B00F - R0028 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00F - R0029 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0030 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00G - R0001 - Movement**

No Asbestos

**B00G - R0002 - Practical Activities - 1hb**

No Asbestos

**B00G - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00H - R0001 - External Movement**

No Asbestos

**B00H - R0002 - Practical Activities - 1hb**

No Asbestos

**B00H - R0003 - Home Base Store**

No Asbestos

**B00H - R0004 - Home Base**

No Asbestos

**B00H - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00H - R0006 - Practical Activities - 1hb**

No Asbestos

**B00H - R0007 - Home Base**

No Asbestos

**B00H - R0008 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00I - R0001 - External Movement**

No Asbestos

**B00I - R0002 - Practical Activities - 1hb**

No Asbestos

**B00I - R0003 - Home Base Store**

No Asbestos

**B00I - R0004 - Home Base**

No Asbestos

**B00I - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00I - R0006 - Practical Activities - 1hb**

No Asbestos

**B00I - R0007 - Home Base**

No Asbestos

**B00I - R0008 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning/Other - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00J - R0001 - External Movement**

No Asbestos

**B00J - R0002 - Toilets - Girls**

No Asbestos

**B00J - R0003 - Toilets - Boys**

No Asbestos

**B00J - R0004 - Disabled Toilet**

No Asbestos

**B00J - R0005 - Cleaning Distributed Store**

No Asbestos

**B00J - R0006 - Practical Activities - 1hb**

No Asbestos

**B00J - R0007 - Home Base Store**

No Asbestos

**B00J - R0008 - Home Base**

No Asbestos

**B00J - R0009 - Withdrawal Space - 2hb**

No Asbestos

**B00J - R0010 - Practical Activities - 1hb**

No Asbestos

**B00J - R0011 - Home Base**

No Asbestos

**B00J - R0012 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 841 - D11328 - Boys Toilet : Placement Date - 17/01/2009**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Toilets-Boys**

No Asbestos Found.

**OS 840 - D13770 - Girls Toilet : Placement Date - 19/08/2003**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

**Interior**

**R1 - Toilets-Girls**

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	4 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

**OS 602 - D14656 - Learning Unit - Standard With P.A.A. : Placement Date - 24/11/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D15289 - Learning Unit - Standard With P.A.A. : Placement Date - 26/11/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017