


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Greenway Park Public School (4624)
Region : South Western Sydney
State Electorate : Liverpool
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 22 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Communal Facilities/Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Sports Store

No Asbestos

B00A - R0003 - Cleaning Distributed Store

No Asbestos

B00A - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0005 - Movement

No Asbestos

B00A - R0006 - Raised Platform

No Asbestos

B00A - R0007 - Lift

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Communal Space

No Asbestos

B00A - R0010 - P.E. Store

No Asbestos

B00A - R0011 - Hall Chair Store

No Asbestos

B00A - R0012 - Toilets - Boys

No Asbestos

B00A - R0013 - Plant

No Asbestos

B00A - R0014 - Toilets - Girls

No Asbestos

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Garden Store

No Asbestos

B00A - R0017 - General Assistant/Bulk Store

No Asbestos

B00A - R0018 - Security Store

No Asbestos

B00A - R0019 - Cleaning Supplies

No Asbestos

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Canteen

No Asbestos

B00A - R0022 - Canteen Office/Store

No Asbestos

B00A - R0023 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0024 - Disabled Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Staff Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0003 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - Cleaning Distributed Store

No Asbestos

B00B - R0005 - Main Switch Board

No Asbestos

B00B - R0006 - Staff Toilet

No Asbestos

B00B - R0007 - Staff Toilet

No Asbestos

B00B - R0008 - Staff Toilet

No Asbestos

B00B - R0009 - Security Store

No Asbestos

B00B - R0010 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Duplicating Workroom

No Asbestos

B00B - R0012 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0014 - Sick Bay

No Asbestos

B00B - R0015 - Disabled Shower/Toilet

No Asbestos

B00B - R0016 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0017 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0018 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0019 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Staff Toilet

No Asbestos

B00C - R0004 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Cleaning Distributed Store

No Asbestos

B00C - R0006 - Practical Activities - 1hb

No Asbestos

B00C - R0007 - Home Base Store

No Asbestos

B00C - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Personal Effects Storage

No Asbestos

B00C - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Personal Effects Storage

No Asbestos

B00C - R0013 - Practical Activities - 1hb

No Asbestos

B00C - R0014 - Home Base Store

No Asbestos

B00C - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0016 - Home Base Store

No Asbestos

B00C - R0017 - Practical Activities - 1hb

No Asbestos

B00C - R0018 - Personal Effects Storage

No Asbestos

B00C - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0020 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0021 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0022 - Home Base Store						
No Asbestos						
B00C - R0023 - Practical Activities - 1hb						
No Asbestos						
B00C - R0024 - Personal Effects Storage						
No Asbestos						
B00C - R0025 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R0026 - Home Base Store						
No Asbestos						
B00C - R0027 - Home Base						
No Asbestos						
B00C - R0028 - Personal Effects Storage						
No Asbestos						
B00C - R0029 - Practical Activities - 1hb						
No Asbestos						
B00C - R0030 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0031 - Home Base						
No Asbestos						
B00C - R0032 - Home Base Store						
No Asbestos						
B00C - R0033 - Practical Activities - 1hb						
No Asbestos						
B00C - R0034 - Personal Effects Storage						
No Asbestos						
B00C - R0035 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0003 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Cleaning Distributed Store

No Asbestos

B00D - R0009 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Toilets - Boys

No Asbestos

B00E - R0003 - Disabled Toilet

No Asbestos

B00E - R0004 - Toilets - Girls

No Asbestos

B00E - R0005 - Home Base Store

No Asbestos

B00E - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Practical Activities - 1hb

No Asbestos

B00E - R0008 - Personal Effects Storage

No Asbestos

B00E - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0011 - Home Base Store

No Asbestos

B00E - R0012 - Practical Activities - 1hb

No Asbestos

B00E - R0013 - Personal Effects Storage

No Asbestos

B00E - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0015 - Home Base Store

No Asbestos

B00E - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0017 - Personal Effects Storage

No Asbestos

B00E - R0018 - Practical Activities - 1hb

No Asbestos

B00E - R0019 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0020 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0021 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R0022 - Practical Activities - 1hb

No Asbestos

B00E - R0023 - Personal Effects Storage

No Asbestos

B00E - R0024 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Toilets - Boys

No Asbestos

B00F - R0003 - Kiln Room

No Asbestos

B00F - R0004 - Toilets - Girls

No Asbestos

B00F - R0005 - Home Base Store

No Asbestos

B00F - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Personal Effects Storage

No Asbestos

B00F - R0008 - Practical Activities - 1hb

No Asbestos

B00F - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0011 - Home Base Store

No Asbestos

B00F - R0012 - Practical Activities - 1hb

No Asbestos

B00F - R0013 - Personal Effects Storage

No Asbestos

B00F - R0014 - Home Base Store

No Asbestos

B00F - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0016 - Personal Effects Storage

No Asbestos

B00F - R0017 - Practical Activities - 1hb

No Asbestos

B00F - R0018 - Withdrawal Space - 1hb

No Asbestos

B00F - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0020 - Home Base Store

No Asbestos

B00F - R0021 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0022 - Personal Effects Storage						
No Asbestos						
B00F - R0023 - Movement						
No Asbestos						
B00F - R0024 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Movement

No Asbestos

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Practical Activities - 1hb

No Asbestos

B00H - R0002 - Home Base

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Withdrawal Space - 2hb

No Asbestos

B00H - R0005 - Practical Activities - 1hb

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - Practical Activities - 1hb

No Asbestos

B00H - R0009 - Home Base

No Asbestos

B00H - R0010 - Home Base Store

No Asbestos

B00H - R0011 - Withdrawal Space - 2hb

No Asbestos

B00H - R0012 - Practical Activities - 1hb

No Asbestos

B00H - R0013 - Home Base

No Asbestos

B00H - R0014 - Home Base Store

No Asbestos

B00H - R0015 - External Movement

No Asbestos

B00H - R0016 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Practical Activities - 1hb

No Asbestos

B00I - R0002 - Home Base

No Asbestos

B00I - R0003 - Home Base Store

No Asbestos

B00I - R0004 - Withdrawal Space - 2hb

No Asbestos

B00I - R0005 - Practical Activities - 1hb

No Asbestos

B00I - R0006 - Home Base

No Asbestos

B00I - R0007 - Home Base Store

No Asbestos

B00I - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D11135 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 24/12/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11359 - Learning Unit - Standard With P.A.A. : Placement Date - 27/12/2000

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D12640 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 10/01/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13114 - Learning Unit - Standard With P.A.A. : Placement Date - 25/05/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D13579 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 7/12/2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13677 - Learning Unit - Standard With P.A.A. : Placement Date - 20/03/2001

Exterior

Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D14046 - Learning Unit - Standard With P.A.A. : Placement Date - 22/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14831 - Learning Unit - Standard With P.A.A. : Placement Date - 3/01/2009

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D15358 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 30/12/2003

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D16240 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 21/01/2005

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 750 - D17701 - Learning Unit - ESL : Placement Date - 28/05/2009						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Esl						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017