


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Green Square School (5460)
Region : Sydney
State Electorate : Heffron
Local Government Area : Sydney

Initial Survey : Noel Arnold & Associates : 10 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1884 - Brick/Block (Brick/Block)**Exterior**

Gable Verge Linings	Flat AC Sheeting	5m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------	------------------	----	-------------------------------	--------------------	---------	--------------------

Assumed Asbestos - Unable to sample due to height of

Underfloor Voids	No Asbestos Found
------------------	-------------------

Ceiling Void	Non Accessible Area - Limited access - Manhole > 5metres high - too dangerous to access safely
--------------	---

Interior**B00A - R0001 - Practical Activities - 1hb**

No Asbestos

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - Cleaning Distributed Store

Partition Walls (Cubicles)	Flat AC Sheeting	8m2	South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------------------------	--------------------	---------	--------------------

5460/B00A/R0003/Partition Walls (Cubicles)/S2

Chrysotile (white asbestos)

B00A - R0004 - Staff Kitchen

No Asbestos

B00A - R0005 - Movement

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Cleaning Distributed Store

No Asbestos

B00A - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	17m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------	--------------------	---------	--------------------

5460/B00A/R0009/Ceiling Structures/Linings/S5

Chrysotile (white asbestos)

B00A - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
----------------------------	------------------	------	------------	---	------------	---------------------

5460/B00A/R0009/Ceiling Structures/Linings/S5

Chrysotile (white asbestos)

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0013 - Canteen Office/Store

No Asbestos

B00A - R0014 - Staff Toilet

No Asbestos

B00A - R0015 - Staff Toilet

No Asbestos

B00A - R0016 - General Storeroom

No Asbestos

B00A - R0017 - Sick Bay

No Asbestos

B00A - R0018 - Principal

No Asbestos

B00A - R0019 - Clerical Office

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0020 - Security Store						
No Asbestos						
B00A - R0021 - Main Switch Board						
Wall Linings Internal	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5460/B00A/R0021/Wall Linings Internal/S4					Chrysotile (white asbestos)	
B00A - R0022 - Movement						
No Asbestos						
B00A - R0023 - Entry Vestibule						
No Asbestos						
B00A - R0024 - Movement						
No Asbestos						
B00A - R0025 - Staff Room						
No Asbestos						
B00A - R0026 - Practical Activities - 1hb						
No Asbestos						
B00A - R0027 - Sports Store						
No Asbestos						
B00A - R0028 - Stairs						
No Asbestos						
B00A - R0029 - Duplicating Workroom						
No Asbestos						
B00A - R0030 - Staff Kitchen						
No Asbestos						
B00A - R1001 - Practical Activities - 1hb						
No Asbestos						
B00A - R1002 - Home Base						
No Asbestos						
B00A - R1003 - Home Base						
No Asbestos						
B00A - R1004 - Practical Activities - 1hb						
No Asbestos						
B00A - R1005 - Movement						
No Asbestos						
B00A - R1006 - Home Base						
No Asbestos						
B00A - R1007 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R1008 - General Assistant/Bulk Store						
No Asbestos						
B00A - R1009 - K.L.A. Store						
No Asbestos						
B00A - R1010 - Home Base						
No Asbestos						
B00A - R1011 - Practical Activities - 1hb						
No Asbestos						
B00A - R1012 - Communal Space						
No Asbestos						
B00A - R1013 - Deputy Principal						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1014 - Staff Toilet						
No Asbestos						
B00A - R1015 - Toilets - Girls						
Partition Walls (Cubicles)	Flat AC Sheeting		5460/B00A/R1015/Partition Walls (Cubicles)/S1			No Asbestos Detected
B00A - R1016 - Toilets - Boys						
Partition Walls (Cubicles)	Flat AC Sheeting		5460/B00A/R0015/Partition Walls (Cubicles)/S1			No Asbestos Detected
B00A - R1017 - General Assistant/Bulk Store						
No Asbestos						
B00A - R1018 - Movement						
No Asbestos						
B00A - R1019 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Other-D.E.C. Admin/General Learning - 1884 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	Non Accessible Area - No access - Manhole to high to access

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Clerical Office

Ceiling Structures/Linings	Flat AC Sheeting 5460/B00B/R0002/Ceiling Structures/Linings/S6					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0003 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	4m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5460/B00B/R0003/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Staff Toilet

Partition Walls (Cubicles)	Flat AC Sheeting	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	5460/B00A/R0003/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	12m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5460/B00B/R0003/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00B - R0006 - General Assistant/Bulk Store

No Asbestos

B00B - R0007 - Special Programs Store

No Asbestos

B00B - R0008 - Special Programs Store

No Asbestos

B00B - R0009 - Special Programs Room

No Asbestos

B00B - R0010 - Practical Activities - 1hb

No Asbestos

B00B - R0011 - Home Base Store

No Asbestos

B00B - R0012 - Toilets - Boys/Girls

No Asbestos

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Movement

No Asbestos

B00B - R0015 - Clerical Office

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1950 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 5460/B00C/Eaves Linings/S7					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior**B00C - R0001 - Toilets - Boys**

Partition Walls (Cubicles)	Flat AC Sheeting 5460/B00A/R1015/Partition Walls (Cubicles)/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00C - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Flat AC Sheeting 5460/B00A/R1015/Partition Walls (Cubicles)/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D12234 - Learning Unit - Standard With P.A.A. : Placement Date - 5/01/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12488 - Learning Unit - Standard With P.A.A. : Placement Date - 11/11/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017