


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gralee School (5730)
Region : Riverina
State Electorate : Murray
Local Government Area : Leeton

Initial Survey : Noel Arnold & Associates : 07 - May - 2008
Reviewed By : Parsons Brinckerhoff : 12 - Jul - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1974 - Brick/Block (Brick/Block)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00A - R0002 - Cleaning Supplies**

Floor Coverings Res/Textile	Vinyl Sheet	7m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
5730/B00A/R0009/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00A - R0003 - Toilets - Boys

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0006 - Movement

Electrical Mounting Board	Resinous Board	1Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
5730/B00A/R0006/Electrical Mounting Board/S3					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
5730/B00A/R0006/Ceiling Structures/Linings/S2						

B00A - R0008 - Withdrawal - M

No Asbestos

B00A - R0009 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet	6m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
5730/B00A/R0009/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00A - R0010 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet	9m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
5730/B00A/R0009/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00A - R0011 - Staff Toilet

No Asbestos

B00A - R0012 - Home Base - M

No Asbestos

B00A - R0013 - General Storeroom

No Asbestos

B00A - R0014 - Laundry - P

No Asbestos

B00A - R0020 - Withdrawal - M

No Asbestos

B00A - R0021 - Withdrawal Space - 1hb

No Asbestos

B00A - R0022 - Withdrawal - M

No Asbestos

B00A - R0023 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
5730/B00A/R0006/Ceiling Structures/Linings/S2						

B00A - R0024 - Home Base - M

No Asbestos

B00A - R0025 - Toilets - Boys/Girls

No Asbestos

B00A - R0026 - Kitchen - Pre

No Asbestos

B00A - R0027 - Communications Cupboard

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0028 - Covered Outdoor Learning Area

No Asbestos

B00A - R0029 - Toilets - Girls/Disabled Cubicle

No Asbestos

B00A - R0030 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Shed - 1974 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D12414 - Learning Unit - Standard/Withdrawal : Placement Date - 18/01/2007

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

OS 505 - D16175 - Admin Staff/Principal/Secure Store : Placement Date - 22/09/2000

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos		16 m2
---------	---------------	------------------	--	-------

R3 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos		20 m2
---------	---------------	------------------	--	-------

R4 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2
---------	---------------	------------------	--	------

R5 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		18 m2

OS 837 - D16496 - Hcap Shower/Change/Toilet : Placement Date - 27/02/2013

Exterior

No Asbestos Found.

Interior

R1 - Disabled Shower/Toilet

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017