


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** George Bass School (5767)  
**Region :** South Western Sydney  
**State Electorate :** Bankstown  
**Local Government Area :** Bankstown

**Initial Survey :** :  
**Register Issue Date :** 23 - Mar - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration - 2013 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00A - R0001 - Entry Vestibule**

No Asbestos

**B00A - R0002 - Clerical/Printing**

No Asbestos

**B00A - R0003 - Security Store**

No Asbestos

**B00A - R0004 - Staff Toilet**

No Asbestos

**B00A - R0005 - Staff Toilet**

No Asbestos

**B00A - R0006 - Staff Toilet**

No Asbestos

**B00A - R0007 - Access Shower/Toilet**

No Asbestos

**B00A - R0008 - Sick Bay**

No Asbestos

**B00A - R0009 - Staff Room**

No Asbestos

**B00A - R0010 - Staff Room Annexe**

No Asbestos

**B00A - R0011 - General Storeroom**

No Asbestos

**B00A - R0012 - Main Switch Board**

No Asbestos

**B00A - R0013 - Library Office/Workroom**

No Asbestos

**B00A - R0014 - Staff Room**

No Asbestos

**B00A - R0015 - K.L.A. Store**

No Asbestos

**B00A - R0016 - Communications Room**

No Asbestos

**B00A - R0017 - Interview**

No Asbestos

**B00A - R0018 - Interview**

No Asbestos

**B00A - R0019 - Interview**

No Asbestos

**B00A - R0020 - Principal**

No Asbestos

**B00A - R0021 - Movement**

No Asbestos

**B00A - R0022 - External Movement**

No Asbestos

**B00A - R0023 - External Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00A - R0024 - Clerical/Printing**

No Asbestos

**B00A - R0025 - Staff Kitchen**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00B - Other - 2013 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00B - R0001 - Covered Outdoor Learning Area**

No Asbestos

**B00B - R0002 - Other**

No Asbestos

**B00B - R0003 - Staff Kitchen**

No Asbestos

**B00B - R0004 - Special Programs Room**

No Asbestos

**B00B - R0005 - General Storeroom**

No Asbestos

**B00B - R0006 - General Storeroom**

No Asbestos

**B00B - R0007 - Chair Storeroom**

No Asbestos

**B00B - R0008 - General Storeroom**

No Asbestos

**B00B - R0009 - General Storeroom**

No Asbestos

**B00B - R0010 - Garden Store**

No Asbestos

**B00B - R0011 - Sports Store**

No Asbestos

**B00B - R0012 - Disabled Shower/Toilet**

No Asbestos

**B00B - R0013 - Disabled Toilet**

No Asbestos

**B00B - R0014 - Interview**

No Asbestos

**B00B - R0015 - Cleaning Supplies**

No Asbestos

**B00B - R0016 - Plant**

No Asbestos

**B00B - R0017 - External Movement**

No Asbestos

**B00B - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0019 - External Movement**

No Asbestos

**B00B - R0020 - External Movement**

No Asbestos

**B00B - R0021 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00C - Other - 2013 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00C - R0001 - Practical Activities - S - 1hb**

No Asbestos

**B00C - R0002 - Home Base - S**

No Asbestos

**B00C - R0003 - Cleaning Distributed Store**

No Asbestos

**B00C - R0004 - Home Base Store - S**

No Asbestos

**B00C - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0006 - Breakout Area**

No Asbestos

**B00C - R0007 - Disabled Toilet**

No Asbestos

**B00C - R0008 - External Movement**

No Asbestos

**B00C - R0009 - Disabled Shower/Toilet**

No Asbestos

**B00C - R0010 - Practical Activities - S - 1hb**

No Asbestos

**B00C - R0011 - Home Base - S**

No Asbestos

**B00C - R0012 - Disabled Shower/Toilet**

No Asbestos

**B00C - R0013 - Home Base Store - S**

No Asbestos

**B00C - R0014 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0015 - Breakout Area**

No Asbestos

**B00C - R0016 - Laundry - S**

No Asbestos

**B00C - R0017 - Home Base Store - S**

No Asbestos

**B00C - R0018 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0019 - Breakout Area**

No Asbestos

**B00C - R0020 - Practical Activities - S - 1hb**

No Asbestos

**B00C - R0021 - Home Base - S**

No Asbestos

**B00C - R0022 - Disabled Toilet**

No Asbestos

**B00C - R0023 - Disabled Shower/Toilet**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00C - R0024 - Disabled Shower/Toilet</b>					
	No Asbestos					
	<b>B00C - R0025 - Practical Activities - S - 1hb</b>					
	No Asbestos					
	<b>B00C - R0026 - Home Base - S</b>					
	No Asbestos					
	<b>B00C - R0027 - Home Base Store - S</b>					
	No Asbestos					
	<b>B00C - R0028 - Withdrawal Space - 1hb</b>					
	No Asbestos					
	<b>B00C - R0029 - Breakout Area</b>					
	No Asbestos					
	<b>B00C - R0030 - Plant</b>					
	No Asbestos					
	<b>B00C - R0031 - Distribution Board</b>					Note: No inspection of live electrical installation.
	No Asbestos					
	<b>B00C - R0032 - Distribution Board</b>					Note: No inspection of live electrical installation.
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00D - Other - 2013 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00D - R0001 - Home Base - S**

No Asbestos

**B00D - R0002 - Practical Activities - S - 1hb**

No Asbestos

**B00D - R0003 - Laundry - S**

No Asbestos

**B00D - R0004 - Home Base Store - S**

No Asbestos

**B00D - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00D - R0006 - Breakout Area**

No Asbestos

**B00D - R0007 - Disabled Shower/Toilet**

No Asbestos

**B00D - R0008 - Other**

No Asbestos

**B00D - R0009 - Disabled Toilet**

No Asbestos

**B00D - R0010 - Home Base - S**

No Asbestos

**B00D - R0011 - Practical Activities - S - 1hb**

No Asbestos

**B00D - R0012 - Withdrawal Space - 1hb**

No Asbestos

**B00D - R0013 - Breakout Area**

No Asbestos

**B00D - R0014 - Home Base Store - S**

No Asbestos

**B00D - R0015 - Plant**

No Asbestos

**B00D - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0017 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Other - 2013 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00E - R0001 - Practical Activities - S - 1hb**

No Asbestos

**B00E - R0002 - Home Base - S**

No Asbestos

**B00E - R0003 - Cleaning Distributed Store**

No Asbestos

**B00E - R0004 - Home Base Store - S**

No Asbestos

**B00E - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0006 - Breakout Area**

No Asbestos

**B00E - R0007 - Disabled Toilet**

No Asbestos

**B00E - R0008 - Other**

No Asbestos

**B00E - R0009 - Disabled Shower/Toilet**

No Asbestos

**B00E - R0010 - Practical Activities - S - 1hb**

No Asbestos

**B00E - R0011 - Home Base - S**

No Asbestos

**B00E - R0012 - Disabled Shower/Toilet**

No Asbestos

**B00E - R0013 - Home Base Store - S**

No Asbestos

**B00E - R0014 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0015 - Breakout Area**

No Asbestos

**B00E - R0016 - Laundry - S**

No Asbestos

**B00E - R0017 - Home Base Store - S**

No Asbestos

**B00E - R0018 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0019 - Breakout Area**

No Asbestos

**B00E - R0020 - Practical Activities - S - 1hb**

No Asbestos

**B00E - R0021 - Home Base - S**

No Asbestos

**B00E - R0022 - Disabled Toilet**

No Asbestos

**B00E - R0023 - Other**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00E - R0024 - Access Shower/Toilet</b>					
	No Asbestos					
	<b>B00E - R0025 - Practical Activities - S - 1hb</b>					
	No Asbestos					
	<b>B00E - R0026 - Home Base - S</b>					
	No Asbestos					
	<b>B00E - R0027 - Home Base Store - P</b>					
	No Asbestos					
	<b>B00E - R0028 - Withdrawal Space - 1hb</b>					
	No Asbestos					
	<b>B00E - R0029 - Breakout Area</b>					
	No Asbestos					
	<b>B00E - R0030 - Plant</b>					
	No Asbestos					
	<b>B00E - R0031 - Distribution Board</b>					Note: No inspection of live electrical installation.
	No Asbestos					
	<b>B00E - R0032 - Distribution Board</b>					Note: No inspection of live electrical installation.
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Other - 2013 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - Movement**

No Asbestos

**B00F - R0002 - Isolation Space**

No Asbestos

**B00F - R0003 - External Movement**

No Asbestos

**B00F - R0004 - Hydrotherapy - Pool**

No Asbestos

**B00F - R0005 - General Storeroom**

No Asbestos

**B00F - R0006 - Change - Type 2**

No Asbestos

**B00F - R0007 - Disabled Shower/Toilet**

No Asbestos

**B00F - R0008 - Disabled Shower/Toilet**

No Asbestos

**B00F - R0009 - Other**

No Asbestos

**B00F - R0010 - Plant**

No Asbestos

**B00F - R0011 - External Movement**

No Asbestos

**B00F - R0012 - Plant**

No Asbestos

**B00F - R0013 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 621 - D12349 - Single Learning Unit - H/Cap : Placement Date - 28/04/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Home Base-I.O.**

No Asbestos Found.

**R2 - Toilets-Disabled**

No Asbestos Found.

**R3 - Laundry**

No Asbestos Found.

**OS 621 - D14743 - Single Learning Unit - H/Cap : Placement Date - 6/07/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Home Base-I.O.**

No Asbestos Found.

**R2 - Toilets-Disabled**

No Asbestos Found.

**R3 - Laundry**

No Asbestos Found.

**OS 621 - D15032 - Single Learning Unit - H/Cap : Placement Date - 30/03/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Home Base-I.O.**

No Asbestos Found.

**R2 - Toilets-Disabled**

No Asbestos Found.

**R3 - Laundry**

No Asbestos Found.

**OS 621 - D15594 - Single Learning Unit - H/Cap : Placement Date - 28/04/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Home Base-I.O.**

No Asbestos Found.

**R2 - Toilets-Disabled**

No Asbestos Found.

**R3 - Laundry**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**OS 621 - D16026 - Single Learning Unit - H/Cap : Placement Date - 2/12/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Home Base-I.O.**

No Asbestos Found.

**R2 - Toilets-Disabled**

No Asbestos Found.

**R3 - Laundry**

No Asbestos Found.

**OS 621 - D16029 - Single Learning Unit - H/Cap : Placement Date - 2/12/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Home Base-I.O.**

No Asbestos Found.

**R2 - Toilets-Disabled**

No Asbestos Found.

**R3 - Laundry**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017