

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Glebe Public School (7419)  
**Region :** Sydney  
**State Electorate :** Balmain  
**Local Government Area :** Sydney

**Initial Survey :** Noel Arnold & Associates : 20 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00A - General Learning - 1887 - Brick/Block (Brick/Block)****Exterior**

Ceiling Void Non Accessible Area  
- No Access - Not possible to reach Manhole >6m high in middle of room

Underfloor Void No Asbestos Found

**Interior****B00A - R0001 - Out Of School Hours Care Centre**

No Asbestos

**B00A - R0002 - Movement**

No Asbestos

**B00A - R0003 - Movement**

No Asbestos

**B00A - R0004 - Home Base**

No Asbestos

**B00A - R0005 - Practical Activities - 1hb**

No Asbestos

**B00A - R0006 - Home Base Store**

No Asbestos

**B00A - R0007 - Home Base Store**

No Asbestos

**B00A - R0008 - Practical Activities - 1hb**

No Asbestos

**B00A - R0009 - Home Base**

No Asbestos

**B00A - R0010 - Cleaning Distributed Store**

No Asbestos

**B00A - R0011 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0012 - Movement**

No Asbestos

**B00A - R0013 - General Storeroom**

Partition Walls (Cubicles) Compressed AC Sheet  
7419/B00A/R0013/Partition Walls (Cubicles)/S9

**No Asbestos Detected**

**B00A - R0014 - Movement**

No Asbestos

**B00A - R0015 - Movement**

No Asbestos

**B00A - R0016 - Stairs**

No Asbestos

**B00A - R0017 - Stairs**

No Asbestos

**B00A - R0018 - Stairs**

No Asbestos

**B00A - R0019 - General Storeroom**

No Asbestos

**B00A - R0020 - Stairs**

No Asbestos

**B00A - R0021 - Stairs**

No Asbestos

**B00A - R1001 - Practical Activities - 1hb**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R1002 - Home Base</b>						
No Asbestos						
<b>B00A - R1005 - Home Base</b>						
No Asbestos						
<b>B00A - R1006 - Home Base Store</b>						
No Asbestos						
<b>B00A - R1007 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R1008 - Home Base Store</b>						
No Asbestos						
<b>B00A - R1009 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R1010 - Home Base</b>						
No Asbestos						
<b>B00A - R1011 - General Storeroom</b>						
No Asbestos						
<b>B00A - R1012 - Staff Room</b>						
No Asbestos						
<b>B00A - R1013 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R1014 - Movement</b>						
No Asbestos						
<b>B00A - R1015 - Movement</b>						
No Asbestos						
<b>B00A - R1016 - Movement</b>						
Wall Linings Internal	Flat AC Sheeting					
	7419/B00A/R1016/Wall Linings Internal/S8					<b>No Asbestos Detected</b>
<b>B00A - R1017 - Stairs</b>						
Wall Linings Internal	Flat AC Sheeting					
	7419/B00A/R1016/Wall Linings Internal/S8					<b>No Asbestos Detected</b>
<b>B00A - R1018 - Stairs</b>						
Wall Linings Internal	Flat AC Sheeting					
	7419/B00A/R1016/Wall Linings Internal/S8					<b>No Asbestos Detected</b>
<b>B00A - R1019 - Stairs</b>						
No Asbestos						
<b>B00A - R1020 - Stairs</b>						
No Asbestos						
<b>B00A - R1021 - Stairs</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration/General Learning - 1862 - Brick/Block (Brick/Block)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00B - M0001 - Movement**

No Asbestos

**B00B - M0002 - General Storeroom**

No Asbestos

**B00B - R0001 - Home Base**

No Asbestos

**B00B - R0002 - Clerical Office**

No Asbestos

**B00B - R0003 - Movement**

No Asbestos

**B00B - R0004 - Principal**

No Asbestos

**B00B - R0005 - Staff Room**

No Asbestos

**B00B - R0006 - Duplicating Workroom**

No Asbestos

**B00B - R0007 - Sick Bay**

No Asbestos

**B00B - R0008 - Movement**

Floor Coverings Res/Textile	Vinyl Sheet	7419/B00B/R9002/Floor Coverings Res/Textile/S4	<b>No Asbestos Detected</b>
-----------------------------	-------------	--	-----------------------------

**B00B - R0009 - Movement**

No Asbestos

**B00B - R0010 - Staff Toilet**

No Asbestos

**B00B - R0011 - Staff Toilet**

No Asbestos

**B00B - R0012 - Movement**

No Asbestos

**B00B - R0013 - Stairs**

No Asbestos

**B00B - R0014 - Stairs**

No Asbestos

**B00B - R0015 - Stairs**

No Asbestos

**B00B - R0016 - Stairs**

No Asbestos

**B00B - R1001 - Home Base**

No Asbestos

**B00B - R1002 - Home Base**

No Asbestos

**B00B - R1003 - K.L.A. Store**

No Asbestos

**B00B - R1004 - Reading Area**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1005 - Movement</b>						
No Asbestos						
<b>B00B - R1006 - Darkroom Space</b>						
No Asbestos						
<b>B00B - R1007 - Deputy Principal</b>						
No Asbestos						
<b>B00B - R1008 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1009 - Stairs</b>						
No Asbestos						
<b>B00B - R1010 - Stairs</b>						
No Asbestos						
<b>B00B - R9001 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00B - R9002 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
	7419/B00B/R9002/Floor Coverings Res/Textile/S4				<b>No Asbestos Detected</b>	
Wall Linings Internal	Flat AC Sheeting	3m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7419/B00B/R9002/Wall Linings Internal/S5				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R9003 - Cleaning Distributed Store</b>						
Wall Linings Internal	Flat AC Sheeting	3m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7419/B00B/R9002/Wall Linings Internal/S5				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R9004 - Movement</b>						
No Asbestos						
<b>B00B - R9005 - Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Pupil Facilities - 1913 - Brick/Block (Brick/Block)****Exterior**

Ceiling Void	Non Accessible Area - No Access - Manhole >6m high in middle of room
Underfloor Voids	No Asbestos Found

**Interior****B00C - R0001 - Special Programs Room**

No Asbestos

**B00C - R0002 - Deputy Principal**

No Asbestos

**B00C - R0003 - Movement**

No Asbestos

**B00C - R0004 - Craft Store**

Floor Coverings Res/Textile	Vinyl Tiles	30m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7419/B00C/R0004/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00C - R0005 - Movement**

No Asbestos

**B00C - R0008 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7419/B00C/R1004/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	

**B00C - R0009 - General Storeroom**

No Asbestos

**B00C - R0010 - Movement**

No Asbestos

**B00C - R0011 - Home Base**

No Asbestos

**B00C - R0012 - Practical Activities - 1hb**

No Asbestos

**B00C - R0013 - Home Base**

No Asbestos

**B00C - R0014 - Practical Activities - 1hb**

No Asbestos

**B00C - R0015 - Staff Toilet**

No Asbestos

**B00C - R0016 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles	21m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7419/B00C/R0004/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00C - R0017 - Movement**

No Asbestos

**B00C - R0018 - Stairs**

No Asbestos

**B00C - R0019 - Stairs**

No Asbestos

**B00C - R0020 - Stairs**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7419/B00C/R1004/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	

**B00C - R0021 - Raised Platform**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0022 - Communal Space</b>						
No Asbestos						
<b>B00C - R1001 - Home Base</b>						
No Asbestos						
<b>B00C - R1002 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00C - R1003 - Movement</b>						
No Asbestos						
<b>B00C - R1004 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7419/B00C/R1004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00C - R1005 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
7419/B00C/R1005/Wall Linings Internal/S2						
<b>B00C - R1006 - Practical Activities - M - 1hb</b>						
No Asbestos						
<b>B00C - R1007 - Home Base - M</b>						
No Asbestos						
<b>B00C - R1008 - Home Base - M</b>						
No Asbestos						
<b>B00C - R1009 - Stairs</b>						
No Asbestos						
<b>B00C - R1010 - Stairs</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7419/B00C/R1004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00C - R9001 - Drinking Facilities</b>						
No Asbestos						
<b>B00C - R9002 - Toilets - Boys</b>						
No Asbestos						
<b>B00C - R9003 - Movement</b>						
No Asbestos						
<b>B00C - R9004 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00C - R9005 - Movement</b>						
No Asbestos						
<b>B00C - R9006 - Movement</b>						
No Asbestos						
<b>B00C - R9007 - Drinking Facilities</b>						
No Asbestos						
<b>B00C - R9008 - Toilets - Girls</b>						
No Asbestos						
<b>B00C - R9009 - Sports Store</b>						
No Asbestos						
<b>B00C - R9010 - Canteen</b>						
No Asbestos						
<b>B00C - R9011 - Canteen Office/Store</b>						
No Asbestos						
<b>B00C - R9012 - Staff Toilet</b>						
No Asbestos						
<b>B00C - R9013 - Canteen Office/Store</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00C - R9014 - Movement**

No Asbestos

**B00C - R9015 - Stairs**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1913 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 7419/B00D/Eaves Linings/S7					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					

**Interior****B00D - R0001 - Toilets - Boys**

No Asbestos

**B00D - R0002 - Toilets - Boys**

Wall Linings Internal	Compressed AC Sheet 7419/B00D/R0002/Wall Linings Internal/S6					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

**B00D - R0003 - Toilets - Girls**

Wall Linings Internal	Compressed AC Sheet 7419/B00D/R0002/Wall Linings Internal/S6					<b>No Asbestos Detected</b>
-----------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017