


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Glenwood High School (8268)
Region : Western Sydney
State Electorate : Riverstone
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Support Unit - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior**B00A - R0001 - G.L.S. Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0003 - Cleaning Store - Distributed

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Covered Vehicle Area/Porte Cochere

No Asbestos

B00A - R0006 - Stairs

No Asbestos

B00A - R0007 - Seminar - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - G.L.S. Store

No Asbestos

B00A - R0009 - Staff - Toilet

No Asbestos

B00A - R0010 - Toilets-Disabled

No Asbestos

B00A - R0011 - Student Laundry - Type 3

No Asbestos

B00A - R0012 - Toilets-Disabled

No Asbestos

B00A - R0013 - General Learning Space - S/P

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - General Learning Space - Type 2

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Stairs

No Asbestos

B00A - R0017 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0018 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0019 - General Storeroom						
No Asbestos						
B00A - R0020 - G.L.S. Store						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0021 - General Learning Space - S/P						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0022 - Movement						
No Asbestos						
B00A - R0023 - Practical Activity Area						
No Asbestos						
B00A - R0024 - Movement						
No Asbestos						
B00A - R0025 - General Learning Space - S/P						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1001 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1002 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R1003 - Movement						
No Asbestos						
B00A - R1004 - Stairs						
No Asbestos						
B00A - R1005 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1006 - Shared Learning Space						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1007 - General Learning Space - Type 2						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1008 - Movement						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1009 - Movement						
No Asbestos						
B00A - R1010 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1011 - Communications Cupboard						
No Asbestos						
B00A - R1012 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1013 - G.L.S. Store						
No Asbestos						
B00A - R1014 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1015 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1016 - Seminar - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1017 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior**B00B - R0001 - General Learning Space - Type 1**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0002 - Stairs

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0005 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Seminar - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0010 - G.L.S. Store

No Asbestos

B00B - R0011 - Movement

No Asbestos

B00B - R0012 - Lift

No Asbestos

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Stairs

No Asbestos

B00B - R0015 - Staff - Toilet

No Asbestos

B00B - R0016 - Cleaning Store - Distributed

No Asbestos

B00B - R0017 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0018 - General Learning Space - Type 2						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0019 - Shared Learning Space						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0020 - Movement						
No Asbestos						
B00B - R1001 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1002 - Stairs						
No Asbestos						
B00B - R1003 - Movement						
No Asbestos						
B00B - R1004 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1005 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1006 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1007 - Seminar - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1008 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1009 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1010 - G.L.S. Store						
No Asbestos						
B00B - R1011 - Movement						
No Asbestos						
B00B - R1012 - Lift						
No Asbestos						
B00B - R1013 - Plant						
No Asbestos						
B00B - R1014 - Cleaning Store - Distributed						
No Asbestos						
B00B - R1015 - Communications Cupboard						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R1016 - Movement

No Asbestos

B00B - R1017 - Stairs

No Asbestos

B00B - R1018 - Movement

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1019 - General Learning Space - Type 2

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1020 - Shared Learning Space

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Fitness Laboratory

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Toilets-Boys

No Asbestos

B00C - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0007 - Toilets-Girls

No Asbestos

B00C - R0008 - Change

No Asbestos

B00C - R0009 - Change

No Asbestos

B00C - R0010 - Seminar - Type 2

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0011 - Fitness Store

No Asbestos

B00C - R0012 - Stairs

No Asbestos

B00C - R1001 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R1003 - Movement

No Asbestos

B00C - R1004 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1005 - Shared Learning Space

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1006 - Movement						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1007 - Movement						
No Asbestos						
B00C - R1008 - Stairs						
No Asbestos						
B00C - R1009 - Communications Cupboard						
No Asbestos						
B00C - R1010 - Cleaning Store - Distributed						
No Asbestos						
B00C - R1011 - G.L.S. Store						
No Asbestos						
B00C - R1012 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1013 - Seminar - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1014 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration/General Learning - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Stairs

No Asbestos

B00D - R0003 - Interview/Office - Type 1

No Asbestos

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00D - R0004 - Interview/Office - Type 1

No Asbestos

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00D - R0005 - Staff - Toilet

No Asbestos

B00D - R0006 - Staff - Toilet

No Asbestos

B00D - R0007 - Security Store

No Asbestos

B00D - R0008 - Principal Office

No Asbestos

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00D - R0009 - Movement

No Asbestos

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00D - R0010 - Administration - Clerical

No Asbestos

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00D - R0011 - Deputy Principal Office

No Asbestos

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00D - R0012 - Deputy Principal Office

No Asbestos

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00D - R0013 - Clinic - Girls

No Asbestos

B00D - R0014 - Clinic-Toilets

No Asbestos

B00D - R0015 - Clinic - Boys

No Asbestos

B00D - R0016 - Interview/Office - Type 2

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0017 - Student Reception						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0018 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R0019 - Cleaning Store - Distributed						
No Asbestos						
B00D - R0020 - Tea Room						
No Asbestos						
B00D - R0021 - Communications Cupboard						
No Asbestos						
B00D - R0022 - Visitors Office						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0023 - Public Reception						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1001 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1002 - Stairs						
No Asbestos						
B00D - R1003 - Movement						
No Asbestos						
B00D - R1004 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R1005 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1006 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1007 - Seminar - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1008 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1009 - General Learning Space - Type 1						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1010 - Communications Cupboard						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1011 - Cleaning Store - Distributed						
No Asbestos						
B00D - R1012 - G.L.S. Store						
No Asbestos						
B00D - R1013 - Movement						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
B00D - R1014 - Movement						
No Asbestos						
B00D - R1015 - General Learning Space - Type 2						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
B00D - R1016 - Shared Learning Space						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library/Science Learning - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior**B00E - R0001 - Movement**

No Asbestos

B00E - R0002 - General Learning Space - Type 3

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Preparation - Science

No Asbestos

B00E - R0006 - General Learning Space - Type 3

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - General Learning Space - Type 3

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0009 - Cleaning Store - Distributed

No Asbestos

B00E - R0010 - Apparatus Store

No Asbestos

B00E - R0011 - Chemical Store

No Asbestos

B00E - R0012 - Seminar - Type 2

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0013 - Botany/Zoology

No Asbestos

B00E - R0014 - General Learning Space - Type 3

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0015 - Science Laboratory

No Asbestos

B00E - R0016 - Science Laboratory

No Asbestos

B00E - R0017 - General Learning Space - Type 10

No Asbestos

B00E - R0018 - General Learning Space - Type 10

No Asbestos

B00E - R1001 - Movement

No Asbestos

B00E - R1002 - Senior Study

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1003 - Library Administration						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1004 - Main Area						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1005 - Main Entry						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1006 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00E - R1007 - Staff - Toilet						
No Asbestos						
B00E - R1008 - Toilets-Disabled						
No Asbestos						
B00E - R1009 - Careers Advisers Office						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1010 - Seminar - Type 3						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1011 - Seminar - Type 3						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1012 - Seminar - Type 3						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1013 - System Administrators Office						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1014 - Communication Space						
No Asbestos						
B00E - R1015 - Computer Store						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1016 - Computer Learning Space						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Staff Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Main Switchroom

No Asbestos

B00F - R0003 - Archive Store

No Asbestos

B00F - R0004 - Interview/Meeting

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Interview/Meeting

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Preparation/Printing

No Asbestos

B00F - R0007 - Interview/Meeting

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Interview/Meeting

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Movement

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - Staff Study

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0011 - Movement

No Asbestos

B00F - R0012 - Staff Lounge

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0013 - Staff - Toilet

No Asbestos

B00F - R0014 - Staff - Toilet

No Asbestos

B00F - R0015 - Staff - Toilet

No Asbestos

B00F - R0016 - Staff - Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0017 - Cleaning Store - Distributed						
No Asbestos						
B00F - R0018 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00F - R0019 - Communications Cupboard						
No Asbestos						
B00F - R0020 - Access Staff Shower/Toilet						
No Asbestos						
B00F - R0021 - Staff Study						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Technological & Applied Studies - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00G - R0001 - Movement

No Asbestos

B00G - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0003 - Communications Cupboard

No Asbestos

B00G - R0004 - Materials Store - Type 1

No Asbestos

B00G - R0005 - General Learning Space - Type 7

No Asbestos

B00G - R0006 - General Learning Space - Type 6

No Asbestos

B00G - R0007 - Seminar - Type 2

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - General Learning Space - Type 6

No Asbestos

B00G - R0009 - General Learning Space - Type 7

No Asbestos

B00G - R0010 - Materials Store - Type 1

No Asbestos

B00G - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0012 - Kitchen - Type 1

No Asbestos

B00G - R0013 - Preparation - Materials

No Asbestos

B00G - R0014 - Laundry

No Asbestos

B00G - R0015 - Pantry

No Asbestos

B00G - R0016 - Cleaning Store - Distributed

No Asbestos

B00G - R0017 - Kitchen - Type 1

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Technological & Applied Studies/General Learning - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00H - R0001 - Movement

No Asbestos

B00H - R0002 - Project Store - Type 1

No Asbestos

B00H - R0003 - Staff - Toilet

No Asbestos

B00H - R0004 - General Learning Space - Type 8

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0005 - General Learning Space - Type 9

No Asbestos

B00H - R0006 - General Learning Space - Type 9

No Asbestos

B00H - R0007 - General Learning Space - Type 8

No Asbestos

B00H - R0008 - Materials Store - Type 2

No Asbestos

B00H - R0009 - Dust Extraction Space

No Asbestos

B00H - R0010 - L.P.G. Store

No Asbestos

B00H - R0011 - Welding/Hot Metals Area

No Asbestos

B00H - R0012 - Kiln Space

No Asbestos

B00H - R0013 - Pottery Store

No Asbestos

B00H - R0014 - Outdoor Workshop

No Asbestos

B00H - R0015 - Materials Workshop - Type 2

No Asbestos

B00H - R0016 - Project Store - Type 1

No Asbestos

B00H - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0018 - Materials Workshop - Type 2

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - Art/General Learning - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior**B00J - R0001 - Covered Outdoor Space**

No Asbestos

B00J - R0002 - Student Canteen

No Asbestos

B00J - R0003 - Office/Store

No Asbestos

B00J - R0004 - General Storeroom

No Asbestos

B00J - R0005 - Performance Workshop

No Asbestos

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00J - R0006 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0007 - Practice/Seminar

No Asbestos

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00J - R0008 - Performance Store**

No Asbestos

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00J - R0009 - Visual Arts Workshop**

No Asbestos

B00J - R0010 - Communications Cupboard

No Asbestos

B00J - R0011 - Project Store - Type 3

No Asbestos

B00J - R0012 - Visual Arts Store

No Asbestos

B00J - R0013 - Movement

No Asbestos

B00J - R0014 - Cleaning Store - Distributed

No Asbestos

B00J - R0015 - Dark Room

No Asbestos

B00J - R0016 - General Learning Space - Type 5

No Asbestos

B00J - R0017 - General Learning Space - Type 4

No Asbestos

Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00J - R0018 - General Learning Space - Type 1**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0019 - General Learning Space - Type 1

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Multi Purpose Facilities/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00K - R0001 - Movement

No Asbestos

B00K - R0002 - Change

No Asbestos

B00K - R0003 - Toilets-Boys

No Asbestos

B00K - R0004 - Staff Shower

No Asbestos

B00K - R0005 - Toilets-Girls

No Asbestos

B00K - R0006 - Change

No Asbestos

B00K - R0007 - Movement

No Asbestos

B00K - R0008 - Movement

No Asbestos

B00K - R0009 - Stage

No Asbestos

B00K - R0010 - Access Staff Shower/Toilet

No Asbestos

B00K - R0011 - Gymnasium

No Asbestos

B00K - R0012 - Plant

No Asbestos

B00K - R0013 - First Aid

No Asbestos

B00K - R0014 - Large Equipment Store

No Asbestos

B00K - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0016 - Cleaning Supplies Store

No Asbestos

B00K - R0017 - Cleaning Store - Distributed

No Asbestos

B00K - R0018 - Garden Store Room

No Asbestos

B00K - R0019 - Maintenance Bulk Store

No Asbestos

B00K - R0020 - General Assistants

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0021 - Sport Equipment Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R0022 - Sport Equipment Store						
No Asbestos						
B00K - R0023 - Control Room						
No Asbestos						
B00K - R0024 - Chair Store						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 701 - D10524 - Art Learning Space/Workshop/Store : Placement Date - 12/10/2011

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Art Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

NS 200 - D10950 - Art Learning Space/Workshop/Bulk Store : Placement Date - 15/01/2009

Exterior

No Asbestos Found.

Interior

R1 - Art Learning Space

No Asbestos Found.

R2 - Workshop

No Asbestos Found.

R3 - Bulk Store

No Asbestos Found.

OS 601 - D10958 - Learning Unit - Standard/Withdrawal : Placement Date - 12/10/2011

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D11706 - Learning Unit - Standard/Withdrawal : Placement Date - 12/10/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 710 - D11766 - Home Science/Pantry/Laundry : Placement Date - 14/01/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - Food Technology L.S.						
No Asbestos Found.						
R3 - Laundry						
No Asbestos Found.						
OS 601 - D12565 - Learning Unit - Standard/Withdrawal : Placement Date - 17/01/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D13027 - Learning Unit - Standard/Withdrawal : Placement Date - 17/01/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D13750 - Learning Unit - Standard/Withdrawal : Placement Date - 5/01/2012						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D13758 - Learning Unit - Standard/Withdrawal : Placement Date - 5/01/2012						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D14191 - Learning Unit - Standard/Withdrawal : Placement Date - 17/01/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 510 - D14295 - Staff Common Room : Placement Date - 18/01/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Commonroom/staff room						
No Asbestos Found.						
R2 - Staff Toilet						
No Asbestos Found.						
R3 - Staff Toilet						
No Asbestos Found.						
R4 - Lobby						
No Asbestos Found.						
OS 601 - D14606 - Learning Unit - Standard/Withdrawal : Placement Date - 17/01/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D14658 - Learning Unit - Standard/Withdrawal : Placement Date - 16/05/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
NS 220 - D14744 - Science Learning/Preparation Space : Placement Date - 15/01/2009						
Exterior						
No Asbestos Found.						
Interior						
R1 - Laboratory L.S.						
No Asbestos Found.						
R2 - Preparation						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
NS 111 - D15117 - Learning Unit - Double Secondary/Secure : Placement Date - 14/01/2009						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
R4 - Secure Storeroom						
No Asbestos Found.						
R5 - Secure Storeroom						
No Asbestos Found.						
R6 - Entry						
No Asbestos Found.						
OS 523 - D15343 - Staff Study With Toilets : Placement Date - 7/12/2009						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - Staff Room						
No Asbestos Found.						
R3 - Staff Toilet						
No Asbestos Found.						
NS 220 - D15723 - Science Learning/Preparation Space : Placement Date - 7/12/2009						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Exterior						
No Asbestos Found.						
Interior						
R1 - Laboratory L.S.						
No Asbestos Found.						
R2 - Preparation						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
NS 260 - D16221 - Wood Technics/Storage : Placement Date - 12/12/2009						
Exterior						
No Asbestos Found.						
Interior						
R1 - Materials Technology L.S.						
No Asbestos Found.						
R2 - Store						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
NS 111 - D16253 - Learning Unit - Double Secondary/Secure : Placement Date - 12/12/2009						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
R4 - Secure Storeroom						
No Asbestos Found.						
R5 - Secure Storeroom						
No Asbestos Found.						
R6 - Entry						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017