

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Glenmore Park High School (8276)
Region : Western Sydney
State Electorate : Mulgoa
Local Government Area : Penrith

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Movement**

No Asbestos

B00A - R0002 - Staff - Toilet

No Asbestos

B00A - R0003 - Staff - Toilet

No Asbestos

B00A - R0004 - Security StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0005 - Movement**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0006 - Communications Cupboard**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0007 - Interview/Office - Type 1**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0008 - Interview/Office - Type 1**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0009 - Public Entry**

No Asbestos

B00A - R0010 - Public EntryVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0011 - Interview/Office - Type 1**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0012 - Administration - Clerical**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0013 - Staff Kitchen**

No Asbestos

B00A - R0014 - Cleaning Store - Distributed

No Asbestos

B00A - R0015 - MovementVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0016 - Principal Office**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0017 - Leading Teacher**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0018 - Movement**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0019 - Deputy Principal Office**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0020 - Pupil Entry						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0021 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0022 - Clinic - Girls						
No Asbestos						
B00A - R0023 - Clinic-Toilets						
No Asbestos						
B00A - R0024 - Clinic-Toilets						
No Asbestos						
B00A - R0025 - Clinic - Boys						
No Asbestos						
B00A - R0026 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0027 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0028 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0029 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0030 - Plant						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0002 - Computer Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0003 - Duplicating Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0004 - Staff - Toilet

No Asbestos

B00B - R0005 - Communications Cupboard

No Asbestos

B00B - R0006 - Communication Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0007 - Entry

No Asbestos

B00B - R0008 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0009 - Toilets-Disabled

No Asbestos

B00B - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0011 - Communications Cupboard

No Asbestos

B00B - R0012 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0015 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0016 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0017 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0018 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00B - R0019 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Cleaning Store - Distributed

No Asbestos

B00C - R0003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Security Store

No Asbestos

B00C - R0011 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Movement

No Asbestos

B00C - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0017 - Stairs

No Asbestos

B00C - R0018 - Stairs

No Asbestos

B00C - R1001 - Movement

No Asbestos

B00C - R1002 - Cleaning Store - Distributed

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R1003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1004 - Movement						
No Asbestos						
B00C - R1005 - Communications Cupboard						
No Asbestos						
B00C - R1006 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1007 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1008 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1010 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1011 - Security Store						
No Asbestos						
B00C - R1012 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1013 - Shared Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00C - R1014 - Movement						
No Asbestos						
B00C - R1015 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R1016 - Stairs						
No Asbestos						
B00C - R1017 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Technological & Applied Studies - 1997 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Movement**

No Asbestos

B00D - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0003 - Communications Cupboard

No Asbestos

B00D - R0004 - Design L.S.

No Asbestos

B00D - R0005 - Design/Technology L.S.Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0006 - Materials Workshop - Type 3**

No Asbestos

B00D - R0007 - Materials Store

No Asbestos

B00D - R1001 - Movement

No Asbestos

B00D - R1002 - Design/Technology L.S.Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R1003 - Design/Technology L.S.**

No Asbestos

B00D - R1004 - Materials Store

No Asbestos

B00D - R1005 - Materials Workshop - Type 3

No Asbestos

B00D - R1006 - General Storeroom

No Asbestos

B00D - R1007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R1008 - Cleaning Store - Distributed

No Asbestos

B00D - R1009 - Kiln Space

No Asbestos

B00D - R1010 - Dust Extraction Space

No Asbestos

B00D - R1011 - Materials Store

No Asbestos

B00D - R1012 - Metal Technology Bay

No Asbestos

B00D - R1013 - L.P.G. Store

No Asbestos

B00D - R1014 - Materials Workshop - Type 3

No Asbestos

B00D - R1015 - Resource/Project Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1016 - Design/Technology L.S.						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1017 - Design/Technology L.S.						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1018 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Performing Arts/Pupil Facilities - 1997 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Main Switchroom

No Asbestos

B00E - R0003 - Movement

No Asbestos

B00E - R0004 - Cleaning Store - Distributed

No Asbestos

B00E - R0005 - Toilets-Boys

No Asbestos

B00E - R0006 - Student Drinking Facilities

No Asbestos

B00E - R0007 - Movement

No Asbestos

B00E - R0008 - Shower/Change

No Asbestos

B00E - R0009 - Shower/Change

No Asbestos

B00E - R0010 - Shower/Change

No Asbestos

B00E - R0011 - Shower/Change

No Asbestos

B00E - R0012 - Shower/Change

No Asbestos

B00E - R0013 - Shower/Change

No Asbestos

B00E - R0014 - Toilets-Girls

No Asbestos

B00E - R0015 - Movement

No Asbestos

B00E - R0016 - Student Drinking Facilities

No Asbestos

B00E - R0017 - Movement

No Asbestos

B00E - R0018 - Stairs

No Asbestos

B00E - R0019 - Stairs

No Asbestos

B00E - R1001 - Movement

No Asbestos

B00E - R1002 - Movement

No Asbestos

B00E - R1003 - Cleaning Store - Distributed

No Asbestos

B00E - R1004 - Toilets-Disabled

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R1005 - Movement

No Asbestos

B00E - R1006 - Performance Workshop

No Asbestos

B00E - R1007 - Chair Store

No Asbestos

B00E - R1008 - Control Room

No Asbestos

B00E - R1009 - Movement

No Asbestos

B00E - R1010 - Staff - Toilet

No Asbestos

B00E - R1011 - Staff - Toilet

No Asbestos

B00E - R1012 - Staff Shower

No Asbestos

B00E - R1013 - Performing Arts Store

No Asbestos

B00E - R1014 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00E - R1015 - Communications Cupboard

No Asbestos

B00E - R1016 - Stairs

No Asbestos

B00E - R1017 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Staff Facilities/Senior Learning Unit - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Lift

No Asbestos

B00F - R0002 - Plant

No Asbestos

B00F - R0003 - Movement

No Asbestos

B00F - R0007 - Preparation

No Asbestos

B00F - R0008 - Chemical Store

No Asbestos

B00F - R0009 - Growing/Breeding

No Asbestos

B00F - R0010 - Apparatus Store

No Asbestos

B00F - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0015 - Movement

No Asbestos

B00F - R0016 - Stairs

No Asbestos

B00F - R0017 - Stairs

No Asbestos

B00F - R0018 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0019 - Science Laboratory

No Asbestos

B00F - R0020 - Science Laboratory

No Asbestos

B00F - R0021 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0022 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0023 - Science Laboratory

No Asbestos

B00F - R0024 - Science Laboratory

No Asbestos

B00F - R0025 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0026 - General Assistants

No Asbestos

B00F - R1001 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R1002 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1003 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1004 - Duplicating Workroom						
No Asbestos						
B00F - R1005 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00F - R1006 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1007 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1008 - Movement						
No Asbestos						
B00F - R1009 - Cleaning Store - Distributed						
No Asbestos						
B00F - R1010 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1011 - Toilets-Disabled						
No Asbestos						
B00F - R1012 - Staff - Toilet						
No Asbestos						
B00F - R1013 - Staff - Toilet						
No Asbestos						
B00F - R1014 - Staff - Toilet						
No Asbestos						
B00F - R1015 - Staff - Toilet						
No Asbestos						
B00F - R1016 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1017 - Commonroom						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1018 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1019 - Communications Cupboard						
No Asbestos						
B00F - R1020 - Lift						
No Asbestos						
B00F - R1021 - Stairs						
No Asbestos						
B00F - R1022 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Support Unit/Senior Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Movement

No Asbestos

B00G - R0002 - Movement

No Asbestos

B00G - R0003 - Chair Store

No Asbestos

B00G - R0004 - Study Space

No Asbestos

B00G - R0005 - Outdoor Learning Area

No Asbestos

B00G - R0006 - Movement

No Asbestos

B00G - R0007 - Outdoor Learning Area

No Asbestos

B00G - R0008 - Toilets-Disabled

No Asbestos

B00G - R0009 - Student Laundry - Type 3

No Asbestos

B00G - R0010 - Toilets-Disabled

No Asbestos

B00G - R0011 - Movement

No Asbestos

B00G - R0012 - Cleaning Store - Distributed

No Asbestos

B00G - R0013 - General Storeroom

No Asbestos

B00G - R0014 - Staff - Toilet

No Asbestos

B00G - R0015 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0016 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0017 - General Storeroom

No Asbestos

B00G - R0018 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0019 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0020 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0021 - Study Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0022 - General Storeroom						
No Asbestos						
B00G - R0023 - Practical Activity Area						
No Asbestos						
B00G - R0024 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00G - R0025 - Stairs						
No Asbestos						
B00G - R0026 - Stairs						
No Asbestos						
B00G - R1001 - Movement						
No Asbestos						
B00G - R1002 - Cleaning Store - Distributed						
No Asbestos						
B00G - R1003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1004 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1005 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1007 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1008 - Security Store						
No Asbestos						
B00G - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1010 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1011 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1012 - Movement						
No Asbestos						
B00G - R1013 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00G - R1014 - Movement						
No Asbestos						
B00G - R1015 - Communications Cupboard						
No Asbestos						
B00G - R1016 - Stairs						
No Asbestos						
B00G - R1017 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0005 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0008 - General Storeroom

No Asbestos

B00H - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0010 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0012 - Movement

No Asbestos

B00H - R0013 - Movement

No Asbestos

B00H - R0014 - Movement

No Asbestos

B00H - R0015 - Stairs

No Asbestos

B00H - R1001 - Communications Cupboard

No Asbestos

B00H - R1002 - Movement

No Asbestos

B00H - R1003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R1004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00H - R1005 - Seminar

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1007 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1008 - Security Store						
No Asbestos						
B00H - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1010 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1011 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00H - R1012 - Movement						
No Asbestos						
B00H - R1013 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1014 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Technological & Applied Studies/Science Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Movement

No Asbestos

B00I - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0003 - Movement

No Asbestos

B00I - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0005 - General Learning Space

No Asbestos

B00I - R0006 - Security Store

No Asbestos

B00I - R0007 - Kitchen - Type 1

No Asbestos

B00I - R0008 - Food/Research Space

No Asbestos

B00I - R0009 - Pantry

No Asbestos

B00I - R0010 - Laundry

No Asbestos

B00I - R0011 - Movement

No Asbestos

B00I - R0012 - Plant

No Asbestos

B00I - R0013 - External Movement

No Asbestos

B00I - R1001 - Movement

No Asbestos

B00I - R1002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R1003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R1004 - Movement

No Asbestos

B00I - R1005 - Darkroom Space

No Asbestos

B00I - R1006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00I - R1007 - Communications Cupboard

No Asbestos

B00I - R1008 - Multi Media Workshop

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - R1009 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Physical Education/General Learning - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00J - R0001 - Movement**

No Asbestos

B00J - R0002 - Staff - Toilet

No Asbestos

B00J - R0003 - Staff - Toilet

No Asbestos

B00J - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0005 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0008 - Fitness Laboratory

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0009 - Security Store

No Asbestos

B00J - R0010 - Staff Change

No Asbestos

B00J - R0011 - Staff Change

No Asbestos

B00J - R0014 - General Storeroom

No Asbestos

B00J - R0015 - Movement

No Asbestos

B00J - R0016 - General Assistants

No Asbestos

B00J - R1001 - Movement

No Asbestos

B00J - R1002 - Student Drinking Facilities

No Asbestos

B00J - R1003 - Toilets-Girls

No Asbestos

B00J - R1004 - Cleaning Store - Distributed

No Asbestos

B00J - R1005 - Toilets-Boys

No Asbestos

B00J - R1006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1007 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1008 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00J - R1009 - Communications Cupboard						
No Asbestos						
B00J - R1010 - Practice/Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1011 - Music Entry/Display						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1012 - Performance Workshop						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1013 - Security Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1014 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Multi Purpose Facilities - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0002 - Movement

No Asbestos

B00K - R0003 - Sport Equipment Store

No Asbestos

B00K - R0005 - Chair Store

No Asbestos

B00K - R0006 - Gymnasium

No Asbestos

B00K - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0008 - Communications Cupboard

No Asbestos

B00K - R0009 - Stage

No Asbestos

B00K - R0010 - Movement

No Asbestos

B00K - R0011 - Movement

No Asbestos

B00K - R0012 - Lift

No Asbestos

B00K - R0013 - Plant

No Asbestos

B00K - R0014 - Movement

No Asbestos

B00K - R0015 - Movement

No Asbestos

B00K - R0016 - Movement

No Asbestos

B00K - R0017 - Chair Store

No Asbestos

B00K - R0018 - Control Room

No Asbestos

B00K - R0019 - Covered Area

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Covered Area

No Asbestos

B00L - R0002 - Student Canteen

No Asbestos

B00L - R0003 - Office/Store

No Asbestos

B00L - R0004 - Cleaning Supplies Store

No Asbestos

B00L - R0005 - Maintenance Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - General Assistants

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Technological & Applied Studies - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - Metal Technology Bay

No Asbestos

B00N - R0002 - Metal Technology Bay

No Asbestos

B00N - R0003 - Plant

No Asbestos

B00N - R0004 - General Storeroom

No Asbestos

B00N - R0005 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017