


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Great Lakes College Senior Campus (8281)  
**Region :** North Coast  
**State Electorate :** Myall Lakes  
**Local Government Area :** Great Lakes

**Initial Survey :** Noel Arnold & Associates : 16 - Apr - 2008  
**Register Issue Date :** 24 - Mar - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - General Learning - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00I - R0001 - General Learning Space - Type 2**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0002 - G.L.S. Store**

No Asbestos

**B00I - R0003 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0004 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0005 - Seminar - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0006 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0007 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0008 - Shared Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0009 - General Learning Space - Type 2**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0010 - Movement**

No Asbestos

**B00I - R0011 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0012 - External Movement**

No Asbestos

**B00I - R0013 - External Movement**

No Asbestos

**B00I - R0014 - External Stairs**

No Asbestos

**B00I - R0015 - External Stairs**

No Asbestos

**B00I - R1001 - General Learning Space - Type 2**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R1002 - G.L.S. Store**

No Asbestos

**B00I - R1003 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R1004 - General Learning Space - Type 1**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00I - R1005 - Seminar - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00I - R1006 - General Learning Space - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00I - R1007 - General Learning Space - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00I - R1008 - Shared Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00I - R1009 - General Learning Space - Type 2</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00I - R1010 - Movement</b>						
No Asbestos						
<b>B00I - R1011 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00I - R1012 - External Movement</b>						
No Asbestos						
<b>B00I - R1013 - External Movement</b>						
No Asbestos						
<b>B00I - R1014 - External Stairs</b>						
No Asbestos						
<b>B00I - R1015 - External Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00J - Art - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00J - R0001 - General Learning Space - Type 8**

No Asbestos

**B00J - R0002 - Cleaning Store - Distributed**

No Asbestos

**B00J - R0003 - Dust Extraction Space**

No Asbestos

**B00J - R0004 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00J - R0005 - Materials Workshop - Type 2**

No Asbestos

**B00J - R0006 - Materials Store - Type 2**

No Asbestos

**B00J - R0007 - Outdoor Workshop**

No Asbestos

**B00J - R0008 - Movement**

No Asbestos

**B00J - R0009 - Pottery Store**

No Asbestos

**B00J - R0010 - Kiln Space**

No Asbestos

**B00J - R0011 - Visual Arts Workshop**

No Asbestos

**B00J - R0012 - Visual Arts Store**

No Asbestos

**B00J - R0013 - Photographic Studio**

No Asbestos

**B00J - R0014 - Movement**

No Asbestos

**B00J - R0015 - Dark Room**

No Asbestos

**B00J - R0016 - Movement**

No Asbestos

**B00J - R0017 - General Learning Space - Type 5**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0018 - General Learning Space - Type 4**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0019 - Project Store - Type 3**

No Asbestos

**B00J - R0020 - General Learning Space - Type 9**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0021 - L.P.G. Store**

No Asbestos

**B00J - R0022 - General Storeroom**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00J - R0023 - Communications Cupboard**

No Asbestos

**B00J - R0024 - External Movement**

No Asbestos

**B00J - R0025 - Outdoor Workshop**

No Asbestos

**B00J - R0026 - Materials Store - Type 1**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00S - Technological & Applied Studies - 2012 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00S - R0001 - Project Store - Type 1**

No Asbestos

**B00S - R0002 - Materials Store - Type 1**

No Asbestos

**B00S - R0003 - Materials Workshop - Type 2**

No Asbestos

**B00S - R0004 - Welding Area**

No Asbestos

**B00S - R0005 - Welding Area**

No Asbestos

**B00S - R0006 - Welding Area**

No Asbestos

**B00S - R0007 - External Movement**

No Asbestos

**B00S - R0008 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B0AA - Administration - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B0AA - R0001 - Public Reception**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0002 - Visitors Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0003 - Administration - Clerical**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0004 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0005 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0006 - Deputy Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0007 - Interview/Meeting**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0008 - Interview/Meeting**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0009 - Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0010 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0011 - Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0012 - Clinic - Girls**

No Asbestos

**B0AA - R0013 - Clinic-Toilets**

No Asbestos

**B0AA - R0014 - Clinic-Toilets**

No Asbestos

**B0AA - R0015 - Clinic - Boys**

No Asbestos

**B0AA - R0016 - Secure Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0017 - Cleaning Store - Distributed**

No Asbestos

**B0AA - R0018 - Deputy Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0AA - R0019 - Principal Office**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R0020 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R0021 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R0022 - Archive Store</b>						
No Asbestos						
<b>B0AA - R0023 - Communications Cupboard</b>						
No Asbestos						
<b>B0AA - R0024 - System Administrators Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R0025 - Access Staff Shower/Toilet</b>						
No Asbestos						
<b>B0AA - R0026 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R0027 - Computer Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R0028 - Staff - Toilet</b>						
No Asbestos						
<b>B0AA - R0029 - Staff - Toilet</b>						
No Asbestos						
<b>B0AA - R0030 - Tea Room</b>						
No Asbestos						
<b>B0AA - R0031 - Communications Cupboard</b>						
No Asbestos						
<b>B0AA - R0032 - Distribution Board Cupboard</b>						Note: No inspection of live electrical installation.
No Asbestos						
<b>B0AA - R0033 - External Movement</b>						
No Asbestos						
<b>B0AA - R0034 - External Movement</b>						
No Asbestos						
<b>B0AA - R0035 - External Stairs</b>						
No Asbestos						
<b>B0AA - R1001 - Main Entry</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R1002 - Main Area</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R1003 - Seminar - Type 3</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R1004 - Seminar - Type 3</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0AA - R1005 - Seminar - Type 3</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0AA - R1006 - Seminar - Type 3</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B0AA - R1007 - Library Administration</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B0AA - R1008 - Senior Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B0AA - R1009 - Access Student Shower/Toilet/Change</b>						
No Asbestos						
<b>B0AA - R1010 - Careers Advisers Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B0AA - R1011 - Computer Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B0AA - R1012 - Computer Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B0AA - R1013 - Staff - Toilet</b>						
No Asbestos						
<b>B0AA - R1014 - Communications Cupboard</b>						
No Asbestos						
<b>B0AA - R1015 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B0AA - R1016 - External Movement</b>						
No Asbestos						
<b>B0AA - R1017 - External Movement</b>						
No Asbestos						
<b>B0AA - R1018 - External Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0BB - General Learning - 2002 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B0BB - R0001 - Lecture Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0BB - R0002 - Lecture Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0BB - R0003 - Toilets - Boys**

No Asbestos

**B0BB - R0004 - Toilets - Girls**

No Asbestos

**B0BB - R0005 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0BB - R0006 - Plant**

No Asbestos

**B0BB - R0007 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B0BB - R0008 - Toilets-Disabled**

No Asbestos

**B0BB - R0009 - Plant**

No Asbestos

**B0BB - R0010 - Lift**

No Asbestos

**B0BB - R0011 - External Movement**

No Asbestos

**B0BB - R1001 - Movement**

No Asbestos

**B0BB - R1002 - Lift**

No Asbestos

**B0BB - R1003 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0CC - Support Unit/Staff Facilities - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B0CC - R0001 - Access Student Shower/Toilet/Change**

No Asbestos

**B0CC - R0002 - Access Student Shower/Toilet/Change**

No Asbestos

**B0CC - R0003 - Movement**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0004 - Seminar - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0005 - Adjoining School**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0006 - Adjoining School**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0007 - Adjoining School**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0008 - Adjoining School**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0009 - Adjoining School**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0010 - Seminar - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0011 - Movement**

No Asbestos

**B0CC - R0012 - Adjoining School**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0013 - G.L.S. Store**

No Asbestos

**B0CC - R0014 - General Learning Space - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0015 - Staff Kitchen**

No Asbestos

**B0CC - R0016 - G.L.S. Store**

No Asbestos

**B0CC - R0017 - G.L.S. Store**

No Asbestos

**B0CC - R0018 - General Learning Space - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0CC - R0019 - Seminar - Type 1**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R0020 - Student Laundry - Type 2</b>						
No Asbestos						
<b>B0CC - R0021 - G.L.S. Store</b>						
No Asbestos						
<b>B0CC - R0022 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B0CC - R0023 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B0CC - R0024 - G.L.S. Store</b>						
No Asbestos						
<b>B0CC - R0025 - Communications Cupboard</b>						
No Asbestos						
<b>B0CC - R0026 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R0027 - Movement</b>						
No Asbestos						
<b>B0CC - R0028 - External Movement</b>						
No Asbestos						
<b>B0CC - R0029 - External Stairs</b>						
No Asbestos						
<b>B0CC - R0030 - External Stairs</b>						
No Asbestos						
<b>B0CC - R1001 - Interview/Meeting</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1002 - Interview/Meeting</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1003 - Staff - Toilet</b>						
No Asbestos						
<b>B0CC - R1004 - Staff - Toilet</b>						
No Asbestos						
<b>B0CC - R1005 - Staff - Toilet</b>						
No Asbestos						
<b>B0CC - R1006 - Access Staff Shower/Toilet</b>						
No Asbestos						
<b>B0CC - R1007 - Staff Lounge</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1008 - Preparation/Printing</b>						
No Asbestos						
<b>B0CC - R1009 - Staff - Toilet</b>						
No Asbestos						
<b>B0CC - R1010 - Staff - Toilet</b>						
No Asbestos						
<b>B0CC - R1011 - Interview/Meeting</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1012 - Interview/Meeting</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1013 - Staff Lounge</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1014 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1015 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1016 - Staff Lounge</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1017 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1018 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1019 - External Movement</b>						
No Asbestos						
<b>B0CC - R1020 - Staff Lounge</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1021 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1022 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1023 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B0CC - R1024 - External Movement</b>						
No Asbestos						
<b>B0CC - R1025 - External Stairs</b>						
No Asbestos						
<b>B0CC - R1026 - External Stairs</b>						
No Asbestos						
<b>B0CC - R1027 - External Movement</b>						
No Asbestos						
<b>B0CC - R1028 - External Movement</b>						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0DD - Science/Technological & Applied Studies - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B0DD - R0001 - Materials Store - Type 1**

No Asbestos

**B0DD - R0002 - Kitchen - Type 1**

No Asbestos

**B0DD - R0003 - Laundry**

No Asbestos

**B0DD - R0004 - Preparation - Materials**

No Asbestos

**B0DD - R0005 - Pantry**

No Asbestos

**B0DD - R0006 - Kitchen - Type 1**

No Asbestos

**B0DD - R0007 - Materials Store - Type 1**

No Asbestos

**B0DD - R0008 - General Learning Space - Type 6**

No Asbestos

**B0DD - R0009 - General Learning Space - Type 7**

No Asbestos

**B0DD - R0010 - Seminar - Type 2**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0DD - R0011 - Seminar - Type 2**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0DD - R0012 - Adjoining School**

No Asbestos

**B0DD - R0013 - Adjoining School**

No Asbestos

**B0DD - R0014 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B0DD - R0015 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B0DD - R0016 - Plant**

No Asbestos

**B0DD - R0017 - Lift**

No Asbestos

**B0DD - R0018 - External Movement**

No Asbestos

**B0DD - R0019 - External Movement**

No Asbestos

**B0DD - R0020 - External Stairs**

No Asbestos

**B0DD - R1001 - Science Laboratory**

No Asbestos

**B0DD - R1002 - Preparation - Science**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0DD - R1003 - Science Laboratory</b>						
No Asbestos						
<b>B0DD - R1004 - Botany/Zoology</b>						
No Asbestos						
<b>B0DD - R1005 - General Learning Space - Type 3</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0DD - R1006 - General Learning Space - Type 3</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0DD - R1007 - Apparatus Storage</b>						
No Asbestos						
<b>B0DD - R1008 - Seminar - Type 2</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0DD - R1009 - Chemical Store</b>						
No Asbestos						
<b>B0DD - R1010 - Apparatus Storage</b>						
No Asbestos						
<b>B0DD - R1011 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0DD - R1012 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0DD - R1013 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B0DD - R1014 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B0DD - R1015 - External Movement</b>						
No Asbestos						
<b>B0DD - R1016 - Lift</b>						
No Asbestos						
<b>B0DD - R1017 - Tafe Utilised</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B0EE - Technological & Applied Studies/General Learning - 2002 - Brick/Veneer (Brick/Veneer)

#### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

#### Interior

##### B0EE - R0001 - Project Store - Type 1

No Asbestos

##### B0EE - R0002 - Pottery Store

No Asbestos

##### B0EE - R0003 - Kiln Space

No Asbestos

##### B0EE - R0004 - Outdoor Workshop

No Asbestos

##### B0EE - R0005 - Materials Store - Type 2

No Asbestos

##### B0EE - R0006 - Visual Arts Workshop

No Asbestos

##### B0EE - R0007 - Visual Arts Store

No Asbestos

##### B0EE - R0008 - Dark Room

No Asbestos

##### B0EE - R0009 - Adjoining School

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

##### B0EE - R0010 - Adjoining School

No Asbestos

##### B0EE - R0011 - Project Store - Type 3

No Asbestos

##### B0EE - R0012 - Adjoining School

No Asbestos

##### B0EE - R0013 - Adjoining School

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

##### B0EE - R0014 - Cleaning Store - Distributed

No Asbestos

##### B0EE - R0015 - Dust Extraction Space

No Asbestos

##### B0EE - R0016 - Materials Workshop - Type 2

No Asbestos

##### B0EE - R0017 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

##### B0EE - R0018 - L.P.G. Store

No Asbestos

##### B0EE - R0019 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

##### B0EE - R0020 - Staff Study

No Asbestos

##### B0EE - R0021 - Welding/Hot Metals Area

No Asbestos

##### B0EE - R0022 - Welding/Hot Metals Area

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0EE - R0023 - Movement</b>						
No Asbestos						
<b>B0EE - R0024 - External Movement</b>						
No Asbestos						
<b>B0EE - R0025 - External Movement</b>						
No Asbestos						
<b>B0EE - R0026 - External Movement</b>						
No Asbestos						
<b>B0EE - R0027 - External Stairs</b>						
No Asbestos						
<b>B0EE - R0028 - External Stairs</b>						
No Asbestos						
<b>B0EE - R0029 - Welding/Hot Metals Area</b>						
No Asbestos						
<b>B0EE - R1001 - Shared Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1002 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1003 - G.L.S. Store</b>						
No Asbestos						
<b>B0EE - R1004 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1005 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1006 - Seminar - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1007 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1008 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1009 - Movement</b>						
No Asbestos						
<b>B0EE - R1010 - Adjoining School</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B0EE - R1011 - Distribution Board Cupboard</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found					Note: No inspection of live electrical installation.	
<b>B0EE - R1012 - External Stairs</b>						
No Asbestos						
<b>B0EE - R1013 - External Movement</b>						
No Asbestos						
<b>B0EE - R1014 - External Stairs</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0FF - Multi Purpose Facilities/Performing Arts - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B0FF - R0001 - Gymnasium**

No Asbestos

**B0FF - R0002 - Outdoor Equipment Store**

No Asbestos

**B0FF - R0003 - Sport Equipment Store**

No Asbestos

**B0FF - R0004 - Stage**

No Asbestos

**B0FF - R0005 - Large Equipment Store**

No Asbestos

**B0FF - R0006 - Movement**

No Asbestos

**B0FF - R0007 - First Aid**

No Asbestos

**B0FF - R0008 - Chair Store**

No Asbestos

**B0FF - R0009 - Control Room**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B0FF - R0010 - Chair Store**

No Asbestos

**B0FF - R0011 - Movement Studio**

No Asbestos

**B0FF - R0012 - Movement Studio Store**

No Asbestos

**B0FF - R0013 - Plant**

No Asbestos

**B0FF - R0014 - Plant**

No Asbestos

**B0FF - R0015 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B0FF - R0016 - Change**

No Asbestos

**B0FF - R0017 - Change**

No Asbestos

**B0FF - R0018 - Toilets - Girls**

No Asbestos

**B0FF - R0019 - Toilets - Boys**

No Asbestos

**B0FF - R0020 - Change**

No Asbestos

**B0FF - R0021 - Change**

No Asbestos

**B0FF - R0022 - Change**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0FF - R0023 - Change</b>						
No Asbestos						
<b>B0FF - R0024 - Access Student Shower/Toilet/Change</b>						
No Asbestos						
<b>B0FF - R0025 - Staff - Toilet</b>						
No Asbestos						
<b>B0FF - R0026 - Staff Shower</b>						
No Asbestos						
<b>B0FF - R0027 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B0FF - R0028 - Covered Outdoor Space</b>						
No Asbestos						
<b>B0FF - R0029 - External Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0GG - General Learning/Performing Arts - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B0GG - R0001 - Practice/Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0002 - Performing Arts Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0003 - Performance Workshop**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0004 - Change**

No Asbestos

**B0GG - R0005 - Change**

No Asbestos

**B0GG - R0006 - Fitness Laboratory**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0007 - Practice/Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0008 - Fitness Store**

No Asbestos

**B0GG - R0009 - Practice/Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0010 - Performing Arts Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0011 - Performance Workshop**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0012 - Toilets - Girls**

No Asbestos

**B0GG - R0013 - Toilets - Boys**

No Asbestos

**B0GG - R0014 - Access Student Shower/Toilet/Change**

No Asbestos

**B0GG - R0015 - Adjoining School**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0016 - Adjoining School**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0017 - Adjoining School**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0018 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B0GG - R0019 - General Learning Space - Type 1**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B0GG - R0020 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B0GG - R0021 - Toilets - Boys**

No Asbestos

**B0GG - R0022 - Toilets - Girls**

No Asbestos

**B0GG - R0023 - Access Student Shower/Toilet/Change**

No Asbestos

**B0GG - R0024 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B0GG - R0025 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B0GG - R0026 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B0HH - Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B0HH - R0001 - Student Canteen**

No Asbestos

**B0HH - R0002 - Office/Store**

No Asbestos

**B0HH - R0003 - Garden Store Room**

No Asbestos

**B0HH - R0004 - Bulk Store**

No Asbestos

**B0HH - R0005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B0HH - R0006 - Student Canteen**

No Asbestos

**B0HH - R0007 - Toilets - Boys**

No Asbestos

**B0HH - R0008 - Toilets - Girls**

No Asbestos

**B0HH - R0009 - Office/Store**

No Asbestos

**B0HH - R0010 - Cleaning Store - Distributed**

No Asbestos

**B0HH - R0011 - Store**

No Asbestos

**B0HH - R0012 - Toilets-Disabled**

No Asbestos

**B0HH - R0013 - Tafe Utilised**

No Asbestos

**B0HH - R0014 - Tafe Utilised**

No Asbestos

**B0HH - R0015 - Plant**

No Asbestos

**B0HH - R0016 - Covered Outdoor Space**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 601 - D14211 - Learning Unit - Standard/Withdrawal : Placement Date - 16/01/2012**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017