


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Great Lakes College Tuncurry Campus (8289)
Region : North Coast
State Electorate : Myall Lakes
Local Government Area : Great Lakes

Initial Survey : Noel Arnold & Associates : 16 - Apr - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - Technological & Applied Studies - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00S - R0001 - Project Store - Type 1

No Asbestos

B00S - R0002 - Materials Store - Type 1

No Asbestos

B00S - R0003 - Materials Workshop - Type 2

No Asbestos

B00S - R0004 - Welding Area

No Asbestos

B00S - R0005 - Welding Area

No Asbestos

B00S - R0006 - Welding Area

No Asbestos

B00S - R0007 - Welding Area

No Asbestos

B00S - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00T - Technological & Applied Studies - 2012 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00T - R0001 - Dust Extraction Space**

No Asbestos

B00T - R0002 - Project Store - Type 1

No Asbestos

B00T - R0003 - Toilets-Disabled

No Asbestos

B00T - R0004 - Materials Learning Space - Type 1

No Asbestos

B00T - R0005 - Wood Technology Bay

No Asbestos

B00T - R0006 - Materials Store - Type 1

No Asbestos

B00T - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00T - R0008 - External Movement

No Asbestos

B00T - R0009 - Outdoor Workshop

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0AA - Administration - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0AA - R0001 - Public Reception

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0002 - Visitors Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0003 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0004 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0005 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0006 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0007 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0008 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0009 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0010 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0011 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0012 - Clinic - Girls

No Asbestos

B0AA - R0013 - Clinic-Toilets

No Asbestos

B0AA - R0014 - Clinic-Toilets

No Asbestos

B0AA - R0015 - Clinic - Boys

No Asbestos

B0AA - R0016 - Secure Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0017 - Cleaning Store - Distributed

No Asbestos

B0AA - R0018 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0AA - R0019 - Principal Office

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R0020 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R0021 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R0022 - Archive Store						
No Asbestos						
B0AA - R0023 - Communications Cupboard						
No Asbestos						
B0AA - R0024 - System Administrators Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R0025 - Access Staff Shower/Toilet						
No Asbestos						
B0AA - R0026 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R0027 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R0028 - Staff - Toilet						
No Asbestos						
B0AA - R0029 - Staff - Toilet						
No Asbestos						
B0AA - R0030 - Tea Room						
No Asbestos						
B0AA - R0031 - Communications Cupboard						
No Asbestos						
B0AA - R0032 - Distribution Board Cupboard						
No Asbestos					Note: No inspection of live electrical installation.	
B0AA - R0033 - External Movement						
No Asbestos						
B0AA - R0034 - External Movement						
No Asbestos						
B0AA - R0035 - External Stairs						
No Asbestos						
B0AA - R1001 - Main Entry						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R1002 - Main Area						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R1003 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R1004 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0AA - R1005 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0AA - R1006 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B0AA - R1007 - Library Administration						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B0AA - R1008 - Tafe Utilised						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B0AA - R1009 - Access Student Shower/Toilet/Change						
No Asbestos						
B0AA - R1010 - Careers Advisers Office						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B0AA - R1011 - Adjoining School						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B0AA - R1012 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B0AA - R1013 - Staff - Toilet						
No Asbestos						
B0AA - R1014 - Communications Cupboard						
No Asbestos						
B0AA - R1015 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B0AA - R1016 - External Movement						
No Asbestos						
B0AA - R1017 - External Movement						
No Asbestos						
B0AA - R1018 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0BB - General Learning - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0BB - R0001 - Lecture Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0BB - R0002 - Lecture Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0BB - R0003 - Toilets - Boys

No Asbestos

B0BB - R0004 - Toilets - Girls

No Asbestos

B0BB - R0005 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0BB - R0006 - Plant

No Asbestos

B0BB - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0BB - R0008 - Toilets-Disabled

No Asbestos

B0BB - R0009 - Plant

No Asbestos

B0BB - R0010 - Lift

No Asbestos

B0BB - R0011 - External Movement

No Asbestos

B0BB - R1001 - Movement

No Asbestos

B0BB - R1002 - Lift

No Asbestos

B0BB - R1003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0CC - Support Unit/Staff Facilities - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0CC - R0001 - Access Student Shower/Toilet/Change

No Asbestos

B0CC - R0002 - Access Student Shower/Toilet/Change

No Asbestos

B0CC - R0003 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0004 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0005 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0006 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0007 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0008 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0009 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0010 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0011 - Movement

No Asbestos

B0CC - R0012 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0013 - G.L.S. Store

No Asbestos

B0CC - R0014 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0015 - Staff Kitchen

No Asbestos

B0CC - R0016 - G.L.S. Store

No Asbestos

B0CC - R0017 - G.L.S. Store

No Asbestos

B0CC - R0018 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0019 - Seminar - Type 1

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R0020 - Student Laundry - Type 2						
No Asbestos						
B0CC - R0021 - G.L.S. Store						
No Asbestos						
B0CC - R0022 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B0CC - R0023 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B0CC - R0024 - G.L.S. Store						
No Asbestos						
B0CC - R0025 - Communications Cupboard						
No Asbestos						
B0CC - R0026 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R0027 - Movement						
No Asbestos						
B0CC - R0028 - External Movement						
No Asbestos						
B0CC - R0029 - External Stairs						
No Asbestos						
B0CC - R0030 - External Stairs						
No Asbestos						
B0CC - R1001 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1002 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1003 - Staff - Toilet						
No Asbestos						
B0CC - R1004 - Staff - Toilet						
No Asbestos						
B0CC - R1005 - Staff - Toilet						
No Asbestos						
B0CC - R1006 - Access Staff Shower/Toilet						
No Asbestos						
B0CC - R1007 - Staff Lounge						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1008 - Preparation/Printing						
No Asbestos						
B0CC - R1009 - Staff - Toilet						
No Asbestos						
B0CC - R1010 - Staff - Toilet						
No Asbestos						
B0CC - R1011 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1012 - Interview/Meeting						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1013 - Staff Lounge						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1014 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1015 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1016 - Staff Lounge						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1017 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1018 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1019 - External Movement						
No Asbestos						
B0CC - R1020 - Staff Lounge						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1021 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1022 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1023 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0CC - R1024 - External Movement						
No Asbestos						
B0CC - R1025 - External Stairs						
No Asbestos						
B0CC - R1026 - External Stairs						
No Asbestos						
B0CC - R1027 - External Movement						
No Asbestos						
B0CC - R1028 - External Movement						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0DD - Science/Technological & Applied Studies - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0DD - R0001 - Materials Store - Type 1

No Asbestos

B0DD - R0002 - Kitchen - Type 1

No Asbestos

B0DD - R0003 - Laundry

No Asbestos

B0DD - R0004 - Preparation - Materials

No Asbestos

B0DD - R0005 - Pantry

No Asbestos

B0DD - R0006 - Kitchen - Type 1

No Asbestos

B0DD - R0007 - Materials Store - Type 1

No Asbestos

B0DD - R0008 - Adjoining School

No Asbestos

B0DD - R0009 - Adjoining School

No Asbestos

B0DD - R0010 - Seminar - Type 2

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0011 - Seminar - Type 2

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0012 - General Learning Space - Type 6

No Asbestos

B0DD - R0013 - General Learning Space - Type 7

No Asbestos

B0DD - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0DD - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0DD - R0016 - Plant

No Asbestos

B0DD - R0017 - Lift

No Asbestos

B0DD - R0018 - External Movement

No Asbestos

B0DD - R0019 - External Movement

No Asbestos

B0DD - R0020 - External Stairs

No Asbestos

B0DD - R1001 - Science Laboratory

No Asbestos

B0DD - R1002 - Preparation - Science

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0DD - R1003 - Science Laboratory						
No Asbestos						
B0DD - R1004 - Botany/Zoology						
No Asbestos						
B0DD - R1005 - Adjoining School						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0DD - R1006 - Adjoining School						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0DD - R1007 - Apparatus Storage						
No Asbestos						
B0DD - R1008 - Seminar - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0DD - R1009 - Chemical Store						
No Asbestos						
B0DD - R1010 - Apparatus Storage						
No Asbestos						
B0DD - R1011 - General Learning Space - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0DD - R1012 - General Learning Space - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0DD - R1013 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B0DD - R1014 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B0DD - R1015 - External Movement						
No Asbestos						
B0DD - R1016 - Lift						
No Asbestos						
B0DD - R1017 - Tafe Utilised						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0EE - Technological & Applied Studies/General Learning - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0EE - R0001 - Project Store - Type 1

No Asbestos

B0EE - R0002 - Pottery Store

No Asbestos

B0EE - R0003 - Kiln Space

No Asbestos

B0EE - R0004 - Outdoor Workshop

No Asbestos

B0EE - R0005 - Materials Store - Type 2

No Asbestos

B0EE - R0006 - Visual Arts Workshop

No Asbestos

B0EE - R0007 - Visual Arts Store

No Asbestos

B0EE - R0008 - Dark Room

No Asbestos

B0EE - R0009 - General Learning Space - Type 5

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0010 - General Learning Space - Type 4

No Asbestos

B0EE - R0011 - Project Store - Type 3

No Asbestos

B0EE - R0012 - General Learning Space - Type 9

No Asbestos

B0EE - R0013 - General Learning Space - Type 8

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0014 - Cleaning Store - Distributed

No Asbestos

B0EE - R0015 - Dust Extraction Space

No Asbestos

B0EE - R0016 - Materials Workshop - Type 2

No Asbestos

B0EE - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0018 - L.P.G. Store

No Asbestos

B0EE - R0019 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0020 - Staff Study

No Asbestos

B0EE - R0021 - Welding/Hot Metals Area

No Asbestos

B0EE - R0022 - Welding/Hot Metals Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0EE - R0023 - Movement						
No Asbestos						
B0EE - R0024 - External Movement						
No Asbestos						
B0EE - R0025 - External Movement						
No Asbestos						
B0EE - R0026 - External Movement						
No Asbestos						
B0EE - R0027 - External Stairs						
No Asbestos						
B0EE - R0028 - External Stairs						
No Asbestos						
B0EE - R0029 - Welding/Hot Metals Area						
No Asbestos						
B0EE - R1001 - Shared Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1002 - General Learning Space - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1003 - G.L.S. Store						
No Asbestos						
B0EE - R1004 - General Learning Space - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1005 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1006 - Seminar - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1007 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1008 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1009 - Movement						
No Asbestos						
B0EE - R1010 - General Learning Space - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0EE - R1011 - Distribution Board Cupboard						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found					Note: No inspection of live electrical installation.	
B0EE - R1012 - External Stairs						
No Asbestos						
B0EE - R1013 - External Movement						
No Asbestos						
B0EE - R1014 - External Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0FF - Multi Purpose Facilities/Performing Arts - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0FF - R0001 - Gymnasium

No Asbestos

B0FF - R0002 - Outdoor Equipment Store

No Asbestos

B0FF - R0003 - Sport Equipment Store

No Asbestos

B0FF - R0004 - Stage

No Asbestos

B0FF - R0005 - Large Equipment Store

No Asbestos

B0FF - R0006 - Movement

No Asbestos

B0FF - R0007 - First Aid

No Asbestos

B0FF - R0008 - Chair Store

No Asbestos

B0FF - R0009 - Control Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0FF - R0010 - Chair Store

No Asbestos

B0FF - R0011 - Movement Studio

No Asbestos

B0FF - R0012 - Movement Studio Store

No Asbestos

B0FF - R0013 - Plant

No Asbestos

B0FF - R0014 - Plant

No Asbestos

B0FF - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0FF - R0016 - Change

No Asbestos

B0FF - R0017 - Change

No Asbestos

B0FF - R0018 - Toilets - Girls

No Asbestos

B0FF - R0019 - Toilets - Boys

No Asbestos

B0FF - R0020 - Change

No Asbestos

B0FF - R0021 - Change

No Asbestos

B0FF - R0022 - Change

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0FF - R0023 - Change						
No Asbestos						
B0FF - R0024 - Access Student Shower/Toilet/Change						
No Asbestos						
B0FF - R0025 - Staff - Toilet						
No Asbestos						
B0FF - R0026 - Staff Shower						
No Asbestos						
B0FF - R0027 - Cleaning Store - Distributed						
No Asbestos						
B0FF - R0028 - Covered Outdoor Space						
No Asbestos						
B0FF - R0029 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0GG - General Learning/Performing Arts - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0GG - R0001 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0002 - Performing Arts Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0003 - Performance Workshop

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0004 - Change

No Asbestos

B0GG - R0005 - Change

No Asbestos

B0GG - R0006 - Fitness Laboratory

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0007 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0008 - Performing Arts Store

No Asbestos

B0GG - R0009 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0010 - Performing Arts Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0011 - Performance Workshop

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0012 - Toilets - Girls

No Asbestos

B0GG - R0013 - Toilets - Boys

No Asbestos

B0GG - R0014 - Access Student Shower/Toilet/Change

No Asbestos

B0GG - R0015 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0016 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0017 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0018 - Adjoining School

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B0GG - R0019 - Adjoining School

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0GG - R0020 - Adjoining School

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0GG - R0021 - Toilets - Boys

No Asbestos

B0GG - R0022 - Toilets - Girls

No Asbestos

B0GG - R0023 - Access Student Shower/Toilet/Change

No Asbestos

B0GG - R0024 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0GG - R0025 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0GG - R0026 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0HH - Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0HH - R0001 - Student Canteen

No Asbestos

B0HH - R0002 - Office/Store

No Asbestos

B0HH - R0003 - Garden Store Room

No Asbestos

B0HH - R0004 - Bulk Store

No Asbestos

B0HH - R0005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0HH - R0006 - Student Canteen

No Asbestos

B0HH - R0007 - Toilets - Boys

No Asbestos

B0HH - R0008 - Toilets - Girls

No Asbestos

B0HH - R0009 - Office/Store

No Asbestos

B0HH - R0010 - Cleaning Store - Distributed

No Asbestos

B0HH - R0011 - Store

No Asbestos

B0HH - R0012 - Toilets-Disabled

No Asbestos

B0HH - R0013 - Tafe Utilised

No Asbestos

B0HH - R0014 - Tafe Utilised

No Asbestos

B0HH - R0015 - Plant

No Asbestos

B0HH - R0016 - Covered Outdoor Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 621 - D16023 - Single Learning Unit - H/Cap : Placement Date - 8/07/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Laundry

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017