

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gilgandra High School (8349)
Region : Western NSW
State Electorate : Barwon
Local Government Area : Gilgandra

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Various - 1962 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - No manhole in building					
Underfloor Voids - Slab on Ground	No Asbestos Found					
In-fill-panel	Compressed AC Sheet	92m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00A/R0003/In-fill-panel/S2					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00A/Eaves Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior**B00A - R0001 - External Movement (2.69 m2)**

No Asbestos

B00A - R0002 - Cleaning Supplies Store (11.97 m2)

No Asbestos

B00A - R0003 - Seminar (32.09 m2)

Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

In-fill-panel	Compressed AC Sheet	1m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00A/R0003/In-fill-panel/S2					Chrysotile (white asbestos)

B00A - R0004 - Staff Study (14.82 m2)

No Asbestos

B00A - R0005 - Staff - Toilet (3.9 m2)

Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0006 - Clinic - Boys (14.82 m2)

No Asbestos

B00A - R0007 - Clinic-Toilets (3.9 m2)

No Asbestos

B00A - R0008 - Staff Study (11.62 m2)

Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0009 - General Storeroom (11.06 m2)

Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00B/R0004/Floor Coverings Res/Textile/S18					Chrysotile (white asbestos)

B00A - R0010 - Staff Study (11.32 m2)

Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00A - R0011 - Deputy Principal Office (14.98 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0012 - Staff Kitchen (3.06 m2)						
No Asbestos						
B00A - R0013 - General Storeroom (3.93 m2)						
No Asbestos						
B00A - R0014 - Staff - Toilet (3.62 m2)						
No Asbestos						
B00A - R0015 - Principal Office (14.98 m2)						
Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0018 - Staff - Toilet (5.49 m2)						
No Asbestos						
B00A - R0019 - Staff - Toilet (7.19 m2)						
No Asbestos						
B00A - R0020 - Main Switchroom (4.42 m2)						
Electrical Backing Board	Resinous Board					
	8349/B00A/R0020/Electrical Backing Board/S23					No Asbestos Detected
B00A - R0021 - Interview/Office - Type 1 (11.12 m2)						
Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0022 - Commonroom (73.07 m2)						
No Asbestos						
B00A - R0023 - Resources Store (5.38 m2)						
Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0024 - Interview/Office - Type 1 (11.5 m2)						
Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0025 - External Movement (13.59 m2)						
Ceiling Structures/Linings	Vermiculite					
	8349/B00A/R0041/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0026 - Cleaning Supplies Store (13.21 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00A/R0031/Ceiling Structures/Linings/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R0027 - Darkroom Space (13.14 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00A/R0031/Ceiling Structures/Linings/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R0028 - General Storeroom (34.45 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00A/R0031/Ceiling Structures/Linings/S21					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R0029 - External Movement (4.72 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0030 - Toilets-Boys (26.13 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0030/Partition Walls (Cubicles)/S3				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0031 - Movement (7.19 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0032 - Pantry (2.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0033 - Staff - Toilet (4.48 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0034 - Student Canteen (35.69 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0035 - Toilets-Girls (26.89 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0030/Partition Walls (Cubicles)/S3				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0036 - External Movement (4.84 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0038 - Ancillary Staff (13.29 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0039 - Garden Store Room (12.81 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0041 - Movement (47.19 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0042 - Public Entry (59.37 m2)						
No Asbestos						
B00A - R0043 - Administration - Clerical (39.38 m2)						
No Asbestos						
B00A - R0044 - External Movement (269.02 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	270m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0045 - Lift (2.24 m2)						
No Asbestos						
B00A - R0046 - Disabled Toilet (8.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R0047 - General Storeroom (24.7 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0031/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1002 - Movement (5.05 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1003 - General Storeroom (5.9 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1004 - General Storeroom (6.08 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1005 - General Learning Space (52.56 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1007 - General Learning Space (52.2 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1008 - Art Learning Space (52.92 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1009 - Kiln Space (9.54 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1010 - Bulk Store (9.72 m2)						
Ceiling Structures/Linings	Vermiculite					
8349/B00A/R0041/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1011 - Art Learning Space (52.92 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Vermiculite
 8349/B00A/R0041/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R1013 - Movement (95.84 m2)

Ceiling Structures/Linings Vermiculite
 8349/B00A/R1013/Ceiling Structures/Linings/S25 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Science Learning - 1962 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - No manhole in building					
In-fill-panel	Compressed AC Sheet	72m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00A/R0003/In-fill-panel/S2					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00B/Eaves Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor void	No Asbestos Found					

Interior**B00B - R0001 - Movement (10.1 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8349/B00B/R1002/Ceiling Structures/Linings/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00B - R0002 - External Movement (5.81 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8349/B00B/R1002/Ceiling Structures/Linings/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00B - R0003 - General Learning Space (52.78 m2)

No Asbestos

B00B - R0004 - Laboratory L.S. (65.88 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8349/B00B/R1002/Ceiling Structures/Linings/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00B/R0004/Floor Coverings Res/Textile/S18					Chrysotile (white asbestos)

B00B - R0005 - Resources Store (7.31 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00B/R0004/Floor Coverings Res/Textile/S18					Chrysotile (white asbestos)

B00B - R0006 - Preparation (16.48 m2)

No Asbestos

B00B - R0007 - Laboratory L.S. (93.19 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8349/B00B/R1002/Ceiling Structures/Linings/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00B - R0008 - Distribution Board Cupboard (0.48 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0009 - Cleaning Store - Distributed (3.34 m2)

No Asbestos

B00B - R0010 - L.P.G. Store (3.96 m2)

No Asbestos

B00B - R0011 - External Movement (83.14 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8349/B00B/R1002/Ceiling Structures/Linings/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00B - R1001 - Cleaning Store - Distributed (2.75 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00B/R1001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	

B00B - R1002 - Movement (5.04 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R1003 - Movement (9.7 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R1004 - General Learning Space (52.13 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R1005 - General Learning Space (51.98 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R1006 - General Learning Space (52.13 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R1007 - General Learning Space (38.67 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R1008 - General Learning Space (39.26 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R1009 - Movement (73.11 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8349/B00B/R1002/Ceiling Structures/Linings/S17						
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Technological & Applied Studies - 1962 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - No manhole to building					
Eaves Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00C/R0011/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0002 - Distribution Board Cupboard (0.79 m2)**

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0004 - Cleaning Store - Distributed (3.35 m2)

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00C/R0004/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)

B00C - R0007 - Staff Study (39.05 m2)

No Asbestos

B00C - R0008 - Computer Learning Space (79.35 m2)

No Asbestos

B00C - R0009 - General Storeroom (6.3 m2)

No Asbestos

B00C - R0010 - External Movement (4.39 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00C/R0011/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)

B00C - R0011 - External Movement (170.88 m2)

Ceiling Structures/Linings	Flat AC Sheeting	171m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00C/R0011/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)

B00C - R0012 - Class Tools Storage (14.24 m2)

No Asbestos

B00C - R0013 - Materials Technology L.S. (84.92 m2)

No Asbestos

B00C - R0014 - Wood Technology Bay (60.02 m2)

No Asbestos

B00C - R0015 - Materials Technology L.S. (92.93 m2)

No Asbestos

B00C - R0016 - Distribution Board Cupboard (1.63 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0017 - External Movement (27.44 m2)

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8349/B00C/R0011/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)

B00C - R0018 - Pantry (10.7 m2)

No Asbestos

B00C - R0019 - Preparation - Materials (14.22 m2)

No Asbestos

B00C - R0020 - Food Technology L.S. (78 m2)

No Asbestos

B00C - R0021 - Preparation - Materials (15.76 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0022 - Hospitality Space (19.81 m2)						
No Asbestos						
B00C - R9001 - General Storeroom (6.34 m2)						
No Asbestos						
B00C - R9002 - External Movement (4.54 m2)						
No Asbestos						
B00C - R9003 - General Storeroom (32.17 m2)						
No Asbestos						
B00C - R9004 - Dust Extraction Space (3.96 m2)						
No Asbestos						
B00C - R9005 - General Storeroom (82.38 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Various - 1979 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Flat Roof	Non Accessible Area - No manhole in building

Interior

B00D - R0001 - Design L.S. (50.92 m2)

No Asbestos

B00D - R0002 - Staff Study (24.53 m2)

No Asbestos

B00D - R0003 - Staff - Toilet (3.81 m2)

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00D/R0003/Wall Linings Internal/S14					Chrysotile (white asbestos)	

B00D - R0004 - Food/Research Space (14.6 m2)

No Asbestos

B00D - R0005 - Staff Change (3.71 m2)

No Asbestos

B00D - R0006 - Food Technology L.S. (102.74 m2)

No Asbestos

B00D - R0007 - Distribution Board Cupboard (0.87 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0008 - Resource/Project Store (7.73 m2)

No Asbestos

B00D - R0009 - Resource/Project Store (4.49 m2)

No Asbestos

B00D - R0010 - Materials Technology L.S. (63.82 m2)

No Asbestos

B00D - R0011 - External Movement (108.27 m2)

No Asbestos

B00D - R1001 - Staff Study (24.6 m2)

Floor Coverings Res/Textile	Vinyl Tiles	2m2	South, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00E/R1004/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00D - R1002 - General Learning Space (51.48 m2)

No Asbestos

B00D - R1003 - Cleaning Store - Distributed (2.07 m2)

No Asbestos

B00D - R1004 - Staff - Toilet (3.77 m2)

No Asbestos

B00D - R1005 - Music Learning Space (95.48 m2)

No Asbestos

B00D - R1006 - Distribution Board Cupboard (0.56 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R1007 - General Learning Space (55.07 m2)

No Asbestos

B00D - R1008 - General Learning Space (51.05 m2)

No Asbestos

B00D - R1009 - Movement (103.72 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1979 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Flat Roof	Non Accessible Area - No manhole in building

Interior**B00E - R0001 - Toilets-Boys (17.4 m2)**

Wall Linings Internal	Flat AC Sheeting	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00E/R0001/Wall Linings Internal/S4					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0030/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	

B00E - R0002 - General Storeroom (7.35 m2)

No Asbestos

B00E - R0003 - Staff Study (24.85 m2)

Floor Coverings Res/Textile	Vinyl Tiles	2m2	South, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00E/R1004/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00E - R0004 - General Learning Space (50.34 m2)

No Asbestos

B00E - R0005 - Staff Study (23.88 m2)

Floor Coverings Res/Textile	Vinyl Tiles	2m2	South, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00E/R1004/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00E - R0006 - General Storeroom (4.34 m2)

No Asbestos

B00E - R0007 - Toilets-Girls (20.24 m2)

Wall Linings Internal	Flat AC Sheeting	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00E/R0001/Wall Linings Internal/S4					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00A/R0030/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	

B00E - R0008 - General Storeroom (5.24 m2)

No Asbestos

B00E - R0009 - External Movement (56.51 m2)

No Asbestos

B00E - R1001 - General Learning Space (51.84 m2)

No Asbestos

B00E - R1002 - Staff Study (24.81 m2)

Floor Coverings Res/Textile	Vinyl Tiles	2m2	North, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00E/R1004/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00E - R1003 - Special Learning Space (24.84 m2)

No Asbestos

B00E - R1004 - Senior Study (49.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00E/R1004/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00E - R1005 - External Movement (59.3 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Technological & Applied Studies - 1979 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling voids No Asbestos Found

Interior

B00F - R0004 - Materials Technology L.S. (60.75 m2)

No Asbestos

B00F - R0005 - Metal Technology Bay (3.98 m2)

No Asbestos

B00F - R0006 - Metal Technology Bay (3.1 m2)

No Asbestos

B00F - R0007 - Metal Technology Bay (3.14 m2)

No Asbestos

B00F - R0008 - Materials Technology L.S. (74.04 m2)

No Asbestos

B00F - R0009 - Materials Technology L.S. (86.75 m2)

No Asbestos

B00F - R0010 - External Movement (7.84 m2)

No Asbestos

B00F - R0011 - Plant (2.85 m2)

No Asbestos

B00F - R0012 - Plant (1.8 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Multi Purpose Facilities - 1977 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00G - M0001 - General Storeroom (6.24 m2)**

No Asbestos

B00G - M0002 - Control Room (6.24 m2)

No Asbestos

B00G - R0001 - Shower/Change (32.38 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00G/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	

Wall Linings Internal	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00G/R0001/Wall Linings Internal/S6					Chrysotile (white asbestos)	

B00G - R0002 - Toilets-Girls (14.52 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00G/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00G/R0001/Wall Linings Internal/S6					Chrysotile (white asbestos)	

B00G - R0003 - Movement (2.85 m2)

No Asbestos

B00G - R0004 - Cleaning Store - Distributed (3.27 m2)

No Asbestos

B00G - R0005 - Staff Kitchen (13.68 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
8349/B00G/R0005/Floor Coverings Res/Textile/S7					No Asbestos Detected	

B00G - R0006 - Staff Study (8.58 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
8349/B00G/R0005/Floor Coverings Res/Textile/S7					No Asbestos Detected	

B00G - R0007 - Staff Study (8.58 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
8349/B00G/R0005/Floor Coverings Res/Textile/S7					No Asbestos Detected	

B00G - R0008 - Sport Equipment Store (12.04 m2)

No Asbestos

B00G - R0009 - Chair Store (44.84 m2)

No Asbestos

B00G - R0010 - Main Switchroom (3.01 m2)

No Asbestos

B00G - R0011 - Movement (2.85 m2)

No Asbestos

B00G - R0012 - Toilets-Boys (14.56 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00G/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00G/R0001/Wall Linings Internal/S6					Chrysotile (white asbestos)	
B00G - R0013 - Shower/Change (32.31 m2)						
Wall Linings Internal	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00G/R0001/Wall Linings Internal/S6					Chrysotile (white asbestos)	
B00G - R0014 - Movement (58.8 m2)						
No Asbestos						
B00G - R0015 - Stage (66.86 m2)						
No Asbestos						
B00G - R0016 - Multi-Purpose Space (455.54 m2)						
No Asbestos						
B00G - R0017 - External Movement (185.66 m2)						
No Asbestos						
B00G - R0018 - Plant (8.28 m2)						
No Asbestos						
B00G - R0019 - Plant (8.4 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Agricultural Science - 1979 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Electrical Backing Board	Resinous Board 8349/B00H/Electrical Backing Board/S24					No Asbestos Detected

Interior

B00H - R0001 - Class Tools Storage (34.69 m2)

Wall Linings Internal	Flat AC Sheeting	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00H/R0001/Wall Linings Internal/S8					Chrysotile (white asbestos)	

B00H - R0002 - Animal Space (8.4 m2)

Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00H/R0001/Wall Linings Internal/S8					Chrysotile (white asbestos)	

B00H - R0003 - External Movement (20.58 m2)

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00H/R0001/Wall Linings Internal/S8					Chrysotile (white asbestos)	

B00H - R0004 - Plant Space (6.79 m2)

Wall Linings Internal	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00H/R0001/Wall Linings Internal/S8					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library/Science Learning - 1970 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00L - R0001 - Laboratory L.S. (91.4 m2)**

Floor Coverings Res/Textile Vinyl Tiles 92m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8349/B00L/R0008/Floor Coverings Res/Textile/S9 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Vermiculite 8349/B00L/R0007/Ceiling Structures/Linings/S11 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00L - R0002 - Laboratory L.S. (91.4 m2)

Floor Coverings Res/Textile Vinyl Tiles 92m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8349/B00L/R0008/Floor Coverings Res/Textile/S9 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Vermiculite 8349/B00L/R0007/Ceiling Structures/Linings/S11 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00L - R0003 - General Learning Space (58.77 m2)

Ceiling Structures/Linings Vermiculite 8349/B00L/R0007/Ceiling Structures/Linings/S11 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00L - R0004 - Preparation (43.33 m2)

Floor Coverings Res/Textile Vinyl Tiles 44m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8349/B00L/R0008/Floor Coverings Res/Textile/S9 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Vermiculite 8349/B00L/R0007/Ceiling Structures/Linings/S11 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00L - R0005 - Distribution Board Cupboard (0.71 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Vermiculite 8349/B00L/R0007/Ceiling Structures/Linings/S11 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00L - R0006 - Cleaning Store - Distributed (0.52 m2)

Ceiling Structures/Linings Vermiculite 8349/B00L/R0007/Ceiling Structures/Linings/S11 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00L - R0008 - Movement (3.79 m2)

Floor Coverings Res/Textile Vinyl Tiles 4m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8349/B00L/R0008/Floor Coverings Res/Textile/S9 **Chrysotile (white asbestos)**

B00L - R0009 - Bulk Store (23.8 m2)

No Asbestos

B00L - R0010 - Staff - Toilet (2.96 m2)

Partition Walls (Cubicles) Compressed AC Sheet 2m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8349/B00L/R0010/Partition Walls (Cubicles)/S10 **Chrysotile (white asbestos)**

B00L - R0011 - Staff - Toilet (2.97 m2)

Partition Walls (Cubicles) Compressed AC Sheet 2m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
8349/B00L/R0010/Partition Walls (Cubicles)/S10 **Chrysotile (white asbestos)**

B00L - R0012 - External Movement (150.87 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00L - R0013 - Chemical Store (4.27 m2)						
Ceiling Structures/Linings	Vermiculite	8349/B00L/R0014/Ceiling Structures/Linings/S26				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8349/B00L/R0014/Floor Coverings Res/Textile/S27				No Asbestos Detected
B00L - R0014 - Movement (2.75 m2)						
Ceiling Structures/Linings	Vermiculite	8349/B00L/R0014/Ceiling Structures/Linings/S26				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8349/B00L/R0014/Floor Coverings Res/Textile/S27				No Asbestos Detected
B00L - R1001 - Main Area (241.55 m2)						
No Asbestos						
B00L - R1002 - Librarian (5.83 m2)						
No Asbestos						
B00L - R1003 - Workroom (7.85 m2)						
No Asbestos						
B00L - R1004 - Resources Store (11.3 m2)						
No Asbestos						
B00L - R1005 - Staff Study (12.75 m2)						
No Asbestos						
B00L - R1006 - Staff Study (12.75 m2)						
No Asbestos						
B00L - R1007 - Audio Visual Workroom (12.85 m2)						
No Asbestos						
B00L - R1008 - Staff - Toilet (2.98 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00L/R0010/Partition Walls (Cubicles)/S10						Chrysotile (white asbestos)
B00L - R1009 - Cleaning Store - Distributed (2.56 m2)						
No Asbestos						
B00L - R1010 - Distribution Board Cupboard (0.58 m2)						
						Note: No inspection of live electrical installation.
No Asbestos						
B00L - R1011 - Staff - Toilet (3.05 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8349/B00L/R0010/Partition Walls (Cubicles)/S10						Chrysotile (white asbestos)
B00L - R1012 - Movement (18.57 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8349/B00L/R1012/Ceiling Structures/Linings/S12				No Asbestos Detected
B00L - R1013 - Audio Visual Workroom (12.96 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other - 2007 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00M - R0001 - No Access (35.6 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00N - R0001 - Computer Learning Space (91.97 m2)

No Asbestos

B00N - R0002 - Seminar - Type 1 (19.12 m2)

No Asbestos

B00N - R0003 - Resources Store (10.08 m2)

No Asbestos

B00N - R0004 - Computer Store (9 m2)

No Asbestos

B00N - R0005 - External Movement (28.51 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+1 - Added Building

Exterior

No Asbestos

Interior

Build+1 - Room+1 - Added Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 340 - D15518 - Handicap Toilet/Shower : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Disabled Shower

No Asbestos Found.

NS 100 - D15911 - Learning Unit - Single Primary/PAA : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017