


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Great Lakes College Forster Campus (8534)
Region : North Coast
State Electorate : Myall Lakes
Local Government Area : Great Lakes

Initial Survey : Noel Arnold & Associates : 16 - Apr - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Multi Purpose Facilities - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Multi-Purpose Space**

No Asbestos

B00A - R0002 - Plant

No Asbestos

B00A - R0003 - Shower/Change

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Movement

No Asbestos

B00A - R0006 - Stage

No Asbestos

B00A - R0007 - Control Room

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Shower/Change

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Toilets-Girls

No Asbestos

B00A - R0012 - Cleaning Store - Distributed

No Asbestos

B00A - R0013 - Staff Shower

No Asbestos

B00A - R0014 - Staff - Toilet

No Asbestos

B00A - R0015 - Toilets-Boys

No Asbestos

B00A - R0016 - Sport Equipment Store

No Asbestos

B00A - R0018 - Staff StudyVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0019 - Chair Store**

No Asbestos

B00A - R0020 - Plant

No Asbestos

B00A - R0021 - Sport Equipment Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Art - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Art Learning Space

No Asbestos

B00B - R0003 - Workshop

No Asbestos

B00B - R0004 - Darkroom Space

No Asbestos

B00B - R0005 - Art Entry/Display

No Asbestos

B00B - R0006 - Resources Store

No Asbestos

B00B - R0007 - Resources SpaceVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0008 - Plant**

No Asbestos

B00B - R0009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0010 - Art Learning Space

No Asbestos

B00B - R0011 - Art Learning Space

No Asbestos

B00B - R0012 - Art Learning Space

No Asbestos

B00B - R0013 - Staff StudyVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0016 - Resources Store**

No Asbestos

B00B - R0017 - Cleaning Store - Distributed

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Music/Science - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Laboratory L.S.**

No Asbestos

B00C - R0002 - Laboratory L.S.

No Asbestos

B00C - R0003 - Laboratory L.S.

No Asbestos

B00C - R0004 - Laboratory L.S.

No Asbestos

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Laboratory L.S.

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Music Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0011 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Cleaning Supplies Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0013 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0014 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0015 - Cleaning Store - Distributed

No Asbestos

B00C - R0016 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00C - R0017 - Plant

No Asbestos

B00C - R0018 - Laboratory L.S.

No Asbestos

B00C - R0019 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0020 - Chemical Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0021 - Cleaning Store - Distributed						
No Asbestos						
B00C - R0022 - Preparation						
No Asbestos						
B00C - R0023 - Apparatus Store						
No Asbestos						
B00C - R0024 - Plant						
No Asbestos						
B00C - R0025 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00C - R0027 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0003 - Teachers Aides

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - Cleaning Store - Distributed

No Asbestos

B00D - R0005 - Ancillary Staff

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - Staff - Toilet

No Asbestos

B00D - R0007 - Clinic - Girls

No Asbestos

B00D - R0008 - Clinic-Toilets

No Asbestos

B00D - R0009 - Clinic-Toilets

No Asbestos

B00D - R0010 - Clinic - Boys

No Asbestos

B00D - R0011 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0012 - Movement

No Asbestos

B00D - R0013 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0015 - Duplicating Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0016 - Plant

No Asbestos

B00D - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0018 - Security Store

No Asbestos

B00D - R0019 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0020 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0022 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Technological & Applied Studies - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - Materials Technology L.S.**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0002 - Food Technology L.S.

No Asbestos

B00E - R0003 - Food/Research Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - Pantry

No Asbestos

B00E - R0005 - Food Technology L.S.

No Asbestos

B00E - R0006 - Materials Technology L.S.

No Asbestos

B00E - R0007 - Wood Technology Bay

No Asbestos

B00E - R0008 - Dust Extraction Space

No Asbestos

B00E - R0009 - Materials Technology L.S.

No Asbestos

B00E - R0010 - Bulk Store

No Asbestos

B00E - R0011 - Materials Technology L.S.

No Asbestos

B00E - R0012 - Metal Technology Bay

No Asbestos

B00E - R0013 - Materials Technology L.S.

No Asbestos

B00E - R0014 - Materials Store

No Asbestos

B00E - R0015 - Welding Area

No Asbestos

B00E - R0016 - Plant

No Asbestos

B00E - R0017 - Chemical Store

No Asbestos

B00E - R0019 - T.A.S. Entry/Display

No Asbestos

B00E - R0020 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0021 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0022 - Plant

No Asbestos

B00E - R0023 - Design L.S.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R0024 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0025 - Seminar/Technology Space

No Asbestos

B00E - R0026 - Design L.S.

No Asbestos

B00E - R0027 - Materials Technology L.S.

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00E - R0028 - T.A.S. Entry/Display

No Asbestos

B00E - R0029 - Laundry

No Asbestos

B00E - R0030 - Cleaning Store - Distributed

No Asbestos

B00E - R0031 - Plant

No Asbestos

B00E - R0032 - Materials Store

No Asbestos

B00E - R0033 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0034 - Staff Study

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B00E - R0035 - Movement

No Asbestos

B00E - R0036 - Materials Store

No Asbestos

B00E - R0037 - Materials Store

No Asbestos

B00E - R0038 - Metal Technology Bay

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library - 1992 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Movement**

No Asbestos

B00F - R0002 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0003 - Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0004 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0007 - Staff - Toilet

No Asbestos

B00F - R0008 - Plant

No Asbestos

B00F - R0009 - Cleaning Store - Distributed

No Asbestos

B00F - R0010 - Entry

No Asbestos

B00F - R0011 - Entry

No Asbestos

B00F - R0012 - Movement

No Asbestos

B00F - R0013 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0014 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0015 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0016 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0017 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0018 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0019 - Stairs

No Asbestos

B00F - R1001 - Interview/Office - Type 1

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1002 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1003 - Movement						
No Asbestos						
B00F - R1004 - Commonroom						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1005 - Staff - Toilet						
No Asbestos						
B00F - R1006 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Computer Learning - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0003 - Movement

No Asbestos

B00G - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0006 - General Storeroom

No Asbestos

B00G - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0008 - Entry

No Asbestos

B00G - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0010 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0011 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0012 - General Storeroom

No Asbestos

B00G - R0013 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0014 - Staff - Toilet

No Asbestos

B00G - R0015 - Cleaning Store - Distributed

No Asbestos

B00G - R0016 - Plant

No Asbestos

B00G - R0017 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0019 - Plant

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0020 - Lift						
No Asbestos						
B00G - R0021 - Entry						
No Asbestos						
B00G - R0022 - Tiered Learning Area						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0023 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0024 - Tiered Learning Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0025 - General Storeroom						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0026 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0027 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0028 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0029 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0030 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0031 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0032 - Distribution Board Cupboard						
No Asbestos					Note: No inspection of live electrical installation.	
B00G - R0033 - Cleaning Store - Distributed						
No Asbestos						
B00G - R0034 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0035 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0036 - Plant						
No Asbestos						
B00G - R0037 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0038 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R0039 - General Learning Space						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R0040 - General Learning Space						
No Asbestos						
B00G - R0041 - Toilets-Boys						
No Asbestos						
B00G - R0042 - Toilets-Girls						
No Asbestos						
B00G - R0043 - Toilets-Disabled						
No Asbestos						
B00G - R0045 - Movement						
No Asbestos						
B00G - R0046 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00G - R0047 - Stairs						
No Asbestos						
B00G - R0048 - Stairs						
No Asbestos						
B00G - R0049 - Stairs						
No Asbestos						
B00G - R0050 - Stairs						
No Asbestos						
B00G - R1001 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1002 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1004 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1005 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1006 - Cleaning Store - Distributed						
No Asbestos						
B00G - R1007 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1008 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1010 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1011 - General Storeroom						
No Asbestos						
B00G - R1012 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R1013 - Plant						
No Asbestos						
B00G - R1014 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1015 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1016 - Movement						
No Asbestos						
B00G - R1017 - Entry						
No Asbestos						
B00G - R1018 - Lift						
No Asbestos						
B00G - R1019 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1020 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1021 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1022 - General Storeroom						
No Asbestos						
B00G - R1023 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1024 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1025 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1026 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1027 - Cleaning Store - Distributed						
No Asbestos						
B00G - R1028 - Distribution Board Cupboard						
No Asbestos						
B00G - R1029 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1030 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1031 - Plant						
No Asbestos						
B00G - R1032 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1033 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R1034 - Computer Resource						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00G - R1035 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00G - R1036 - General Storeroom						
No Asbestos						
B00G - R1037 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00G - R1038 - Stairs						
No Asbestos						
B00G - R1039 - Stairs						
No Asbestos						
B00G - R1040 - Stairs						
No Asbestos						
B00G - R1041 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Agricultural Science - 1992 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Machine Storage

No Asbestos

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - General Learning Space

No Asbestos

B00H - R0004 - Staff Shower

No Asbestos

B00H - R0005 - Staff - Toilet

No Asbestos

B00H - R0006 - Garden Store Room

No Asbestos

B00H - R0007 - Class Tools Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Pupil Facilities - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0002 - Student Canteen

No Asbestos

B00I - R0003 - Office/Store

No Asbestos

B00I - R0004 - Maintenance Bulk Store

No Asbestos

B00I - R0005 - Toilets-Disabled

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Movement

No Asbestos

B00J - R0002 - Toilets-Girls

No Asbestos

B00J - R0003 - Toilets-Boys

No Asbestos

B00J - R0004 - Staff - Toilet

No Asbestos

B00J - R0005 - General Storeroom

No Asbestos

B00J - R0006 - Main Switchroom

No Asbestos

B00J - R0007 - Cleaning Supplies Store

No Asbestos

B00J - R0008 - General Assistants

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 971 - D80089 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017