

# Asbestos Register

(Hazardous Materials and Risk Assessment)



**School :** Georges River College Hurstville Boys Campus (8813)  
**Region :** Sydney  
**State Electorate :** Kogarah  
**Local Government Area :** Hurstville

**Initial Survey :** Noel Arnold & Associates : 17 - Mar - 2008  
**Reviewed By :** AECOM : 30 - Oct - 2014



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Various - 1928 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00A - M0001 - General Storeroom (14.4 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				Chrysotile (white asbestos)	

**B00A - M0002 - Stairs (2.4 m2)**

No Asbestos

**B00A - R0001 - General Learning Space (47.23 m2)**

No Asbestos

**B00A - R0002 - General Learning Space (47.23 m2)**

No Asbestos

**B00A - R0003 - General Learning Space (47.83 m2)**

No Asbestos

**B00A - R0004 - Computer Store (9.19 m2)**

No Asbestos

**B00A - R0005 - Principal Office (15.73 m2)**

No Asbestos

**B00A - R0006 - Staff - Toilet (1.59 m2)**

No Asbestos

**B00A - R0007 - Ancillary Staff (28.05 m2)**

No Asbestos

**B00A - R0010 - General Learning Space (47.24 m2)**

No Asbestos

**B00A - R0013 - Staff - Toilet (3.93 m2)**

No Asbestos

**B00A - R0014 - General Storeroom (9.17 m2)**

No Asbestos

**B00A - R0015 - General Storeroom (18.8 m2)**

No Asbestos

**B00A - R0022 - Commonroom (27.99 m2)**

No Asbestos

**B00A - R0023 - Leading Teacher (14.01 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				Chrysotile (white asbestos)	

**B00A - R0024 - General Learning Space (47.23 m2)**

No Asbestos

**B00A - R0025 - General Storeroom (15.74 m2)**

Floor Coverings Res/Textile	Vinyl Sheet					
	8813/B00A/R1007/Floor Coverings Res/Textile/S25				No Asbestos Detected	

**B00A - R0026 - General Storeroom (9.07 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Sheet					
	8813/B00A/R1007/Floor Coverings Res/Textile/S25				<b>No Asbestos Detected</b>	
<b>B00A - R0028 - Movement (18.76 m2)</b>						
No Asbestos						
<b>B00A - R0029 - Cleaning Supplies Store (10.73 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0030 - Computer Learning Space (60.5 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	61m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0031 - Computer Store (10.75 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0032 - Computer Learning Space (60.4 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	61m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0034 - Resources Store (16.92 m2)</b>						
No Asbestos						
<b>B00A - R0038 - General Storeroom (13.35 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0039 - Welding Store (18.15 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0040 - Resource/Project Store (18.18 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0044 - Staff Study (5.86 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0045 - General Storeroom (4.09 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0046 - Wood Technology L.S. (166.96 m2)</b>						
No Asbestos						
<b>B00A - R0047 - Staff Study (7.52 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0048 - Dust Extraction Space (39.72 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00A/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0049 - Wood Technology Bay (74.19 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0050 - Wood Technology L.S. (167.51 m2)</b>						
No Asbestos						
<b>B00A - R0052 - Materials Store (19.41 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0053 - Dust Extraction Space (19.41 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0055 - Design L.S. (55.02 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0056 - Design L.S. (54.93 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0057 - Staff Study (7.34 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0058 - Commonroom (123.14 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
8813/B00A/R0058/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>	
Ceiling Structures/Linings	Flat AC Sheeting	124m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0059 - Ancillary Staff (10.77 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	North facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0060 - Staff Study (6.61 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0061 - External Movement (30.25 m2)</b>						
No Asbestos						
<b>B00A - R0062 - External Movement (4.41 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0063 - Stairs (5.72 m2)</b>						
No Asbestos						
<b>B00A - R0064 - External Movement (2.11 m2)</b>						
No Asbestos						
<b>B00A - R0065 - External Movement (4.36 m2)</b>						
No Asbestos						
<b>B00A - R0066 - External Movement (1.72 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	1.72m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0067 - External Movement (1.72 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0068 - Stairs (8.58 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8.58m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R0069 - External Movement (1.71 m2)</b>						
No Asbestos						
<b>B00A - R0070 - External Movement (1.74 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R0072 - Stairs (0.14 m2)</b>						
No Asbestos						
<b>B00A - R0073 - Stairs (6.81 m2)</b>						
No Asbestos						
<b>B00A - R0074 - External Movement (1.72 m2)</b>						
No Asbestos						
<b>B00A - R0075 - Movement (6.3 m2)</b>						
No Asbestos						
<b>B00A - R0076 - Lift (1.82 m2)</b>						
No Asbestos						
<b>B00A - R0077 - External Movement (6.33 m2)</b>						
No Asbestos						
<b>B00A - R0078 - General Learning Space (47.39 m2)</b>						
No Asbestos						
<b>B00A - R0079 - General Learning Space (47.39 m2)</b>						
No Asbestos						
<b>B00A - R0080 - Movement (77.83 m2)</b>						
No Asbestos						
<b>B00A - R0081 - Movement (206.95 m2)</b>						
No Asbestos						
<b>B00A - R0082 - Interview/Office - Type 1 (37.92 m2)</b>						
No Asbestos						
<b>B00A - R0083 - Shared Learning Space (69.42 m2)</b>						
No Asbestos						
<b>B00A - R0084 - Staff Study (19.98 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R0085 - Movement (119.48 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R0086 - Distribution Board Cupboard (0.57 m2)</b>						
No Asbestos						
<b>B00A - R0087 - General Storeroom (5.74 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R0088 - Staff - Toilet (5.76 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0089 - Staff - Toilet (8.09 m2)</b>						
No Asbestos						
<b>B00A - R0090 - Metal Technology L.S. (151.79 m2)</b>						
No Asbestos						
<b>B00A - R0091 - Welding Area (7.65 m2)</b>						
No Asbestos						
<b>B00A - R0092 - Welding Area (7.56 m2)</b>						
No Asbestos						
<b>B00A - R0093 - Art Learning Space (61.71 m2)</b>						
No Asbestos						
<b>B00A - R0094 - Art Learning Space (65.33 m2)</b>						
No Asbestos						
<b>B00A - R0095 - Movement (35.67 m2)</b>						
No Asbestos						
<b>B00A - R0096 - Staff Kitchen (2.72 m2)</b>						
No Asbestos						
<b>B00A - R0097 - Student Kitchen (13.2 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0098/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0098 - Special Learning Space (53.29 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0098/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1006 - General Learning Space (49.72 m2)</b>						
No Asbestos						
<b>B00A - R1011 - General Learning Space (49.36 m2)</b>						
No Asbestos						
<b>B00A - R1013 - General Learning Space (49.08 m2)</b>						
No Asbestos						
<b>B00A - R1014 - General Storeroom (9.42 m2)</b>						
No Asbestos						
<b>B00A - R1015 - Cleaning Store - Distributed (13.34 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0036/Floor Coverings Res/Textile/S23					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1017 - Stairs (13 m2)</b>						
No Asbestos						
<b>B00A - R1018 - Stairs (16.25 m2)</b>						
No Asbestos						
<b>B00A - R1019 - Movement (5.71 m2)</b>						
No Asbestos						
<b>B00A - R1020 - Movement (5.76 m2)</b>						
No Asbestos						
<b>B00A - R1021 - General Storeroom (8.62 m2)</b>						
No Asbestos						
<b>B00A - R1022 - Isolation Space (7.63 m2)</b>						
No Asbestos						
<b>B00A - R1023 - General Learning Space (48.7 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1024 - Movement (162.2 m2)</b>						
No Asbestos						
<b>B00A - R1025 - General Learning Space (49.83 m2)</b>						
No Asbestos						
<b>B00A - R1026 - General Storeroom (10.68 m2)</b>						
No Asbestos						
<b>B00A - R1027 - Staff Study (15.34 m2)</b>						
No Asbestos						
<b>B00A - R1028 - Student Lounge (21.82 m2)</b>						
No Asbestos						
<b>B00A - R1029 - Gymnasium (77.05 m2)</b>						
No Asbestos						
<b>B00A - R1030 - Isolation Space (21.88 m2)</b>						
No Asbestos						
<b>B00A - R1031 - Fitness Store (10.48 m2)</b>						
No Asbestos						
<b>B00A - R1032 - Staff Study (15.34 m2)</b>						
No Asbestos						
<b>B00A - R1033 - General Storeroom (1.64 m2)</b>						
No Asbestos						
<b>B00A - R1034 - Distribution Board Cupboard (0.72 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R9001 - General Storeroom (6.99 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R9002 - General Storeroom (6.26 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R9003 - General Storeroom (6.24 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R9004 - Multi-Purpose Space (161.97 m2)</b>						
No Asbestos						
<b>B00A - R9008 - Movement (9.75 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00A/R0027/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
<b>B00A - R9009 - General Assistant/Bulk Store (54.5 m2)</b>						
No Asbestos						
<b>B00A - R9010 - Stairs (2.15 m2)</b>						
No Asbestos						
<b>B00A - R9011 - General Assistant/Bulk Store (34.42 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
8813/B00A/R9011/Ceiling Structures/Linings/S26					No Asbestos Detected	
<b>B00A - R9012 - Movement (6.25 m2)</b>						
No Asbestos						
<b>B00A - R9013 - External Movement (6.34 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R9014 - Toilets-Boys (48.67 m2)</b>						
No Asbestos						
<b>B00A - R9015 - Plant (13.17 m2)</b>						
No Asbestos						
<b>B00A - R9016 - Movement (25.91 m2)</b>						
No Asbestos						
<b>B00A - R9017 - Staff Shower (5.6 m2)</b>						
No Asbestos						
<b>B00A - R9018 - Sport Equipment Store (11.63 m2)</b>						
No Asbestos						
<b>B00A - R9019 - Staff Kitchen (1.72 m2)</b>						
No Asbestos						
<b>B00A - R9020 - Staff Study (15.74 m2)</b>						
No Asbestos						

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1964 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00C/R1016/Ceiling Structures/Linings/S27			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00C - R0001 - General Learning Space (53.46 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8813/B00C/R0011/Ceiling Structures/Linings/S18					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00C - R0002 - General Learning Space (52.73 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8813/B00C/R0011/Ceiling Structures/Linings/S18					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00C - R0003 - General Learning Space (52.79 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8813/B00C/R0011/Ceiling Structures/Linings/S18					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00C - R0004 - General Learning Space (53.46 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8813/B00C/R0011/Ceiling Structures/Linings/S18					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00C - R0005 - Staff - Toilet (3.64 m2)**

No Asbestos

**B00C - R0006 - Staff - Toilet (3.72 m2)**

No Asbestos

**B00C - R0007 - Cleaning Store - Distributed (3.71 m2)**

No Asbestos

**B00C - R0011 - Laboratory L.S. (86.23 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8813/B00C/R0011/Ceiling Structures/Linings/S18					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00C - R0012 - Distribution Board Cupboard (0.62 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0013 - Cleaning Store - Distributed (3.69 m2)**

No Asbestos

**B00C - R0014 - Movement (120.15 m2)**

No Asbestos

**B00C - R0015 - Stairs (10.79 m2)**

No Asbestos

**B00C - R0017 - Stairs (10.79 m2)**

No Asbestos

**B00C - R0018 - Staff Kitchen (25.89 m2)**

No Asbestos

**B00C - R0019 - General Storeroom (38.74 m2)**

No Asbestos

**B00C - R0020 - Staff Kitchen (6.45 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0021 - Performance Workspace (53.67 m2)</b>						
No Asbestos						
<b>B00C - R1001 - General Learning Space (53.6 m2)</b>						
No Asbestos						
<b>B00C - R1002 - General Learning Space (52.73 m2)</b>						
No Asbestos						
<b>B00C - R1003 - General Learning Space (52.79 m2)</b>						
No Asbestos						
<b>B00C - R1004 - General Learning Space (53.6 m2)</b>						
No Asbestos						
<b>B00C - R1010 - Staff Kitchen (25.93 m2)</b>						
No Asbestos						
<b>B00C - R1011 - Distribution Board Cupboard (0.49 m2)</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00C - R1012 - Cleaning Store - Distributed (3.21 m2)</b>						
No Asbestos						
<b>B00C - R1013 - General Storeroom (7.17 m2)</b>						
No Asbestos						
<b>B00C - R1014 - General Learning Space (60.4 m2)</b>						
No Asbestos						
<b>B00C - R1015 - Movement (120.86 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	118m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00C/R1016/Ceiling Structures/Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00C - R1016 - Stairs (15.74 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00C/R1016/Ceiling Structures/Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00C - R1017 - Stairs (15.74 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15.7m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00C/R1016/Ceiling Structures/Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00C - R1018 - General Learning Space (53.23 m2)</b>						
No Asbestos						
<b>B00C - R1019 - Staff Kitchen (6.19 m2)</b>						
No Asbestos						
<b>B00C - R1020 - General Learning Space (48.39 m2)</b>						
No Asbestos						
<b>B00C - R1021 - Staff Kitchen (5.04 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1964 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00D/R1011/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Staff - Toilet (5.17 m2)**

No Asbestos

**B00D - R0002 - General Storeroom (1.6 m2)**

No Asbestos

**B00D - R0003 - Movement (12.61 m2)**

No Asbestos

**B00D - R0008 - Darkroom Space (19.18 m2)**

Ceiling Structures/Linings	Vermiculite	8813/B00D/R0007/Ceiling Structures/Linings/S8		<b>Limited Samples Taken</b>		
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00D - R0009 - Staff Study (25.18 m2)**

Ceiling Structures/Linings	Vermiculite	8813/B00D/R0007/Ceiling Structures/Linings/S8		<b>Limited Samples Taken</b>		
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00D - R0010 - Distribution Board Cupboard (0.7 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0011 - Movement (7.41 m2)**

No Asbestos

**B00D - R0012 - External Movement (84.3 m2)**

No Asbestos

**B00D - R0013 - Stairs (13.2 m2)**

No Asbestos

**B00D - R0014 - Stairs (3.73 m2)**

No Asbestos

**B00D - R0015 - Music Learning Space (59.6 m2)**

No Asbestos

**B00D - R0016 - Practice/Seminar (26.07 m2)**

No Asbestos

**B00D - R0017 - Music Store (26.15 m2)**

No Asbestos

**B00D - R0018 - Music Learning Space (53.01 m2)**

No Asbestos

**B00D - R0019 - Music Learning Space (53.31 m2)**

No Asbestos

**B00D - R1001 - Art Learning Space (52.79 m2)**

No Asbestos

**B00D - R1002 - Resources Store (6.15 m2)**

Floor Coverings Res/Textile	Vinyl Sheet	8813/B00D/R1003/Floor Coverings Res/Textile/S13		<b>No Asbestos Detected</b>		
-----------------------------	-------------	-------------------------------------------------	--	-----------------------------	--	--

**B00D - R1003 - Resources Space (6.14 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
8813/B00D/R1003/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>	
<b>B00D - R1004 - Art Learning Space (59.23 m2)</b>						
No Asbestos						
<b>B00D - R1005 - Art Learning Space (52.87 m2)</b>						
No Asbestos						
<b>B00D - R1006 - Kiln Space (20.93 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00D/R1006/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R1007 - Resources Store (10.91 m2)</b>						
No Asbestos						
<b>B00D - R1008 - General Learning Space (52.36 m2)</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
8813/B00D/R1008/Floor Coverings Res/Textile/S11					<b>No Asbestos Detected</b>	
<b>B00D - R1009 - Distribution Board Cupboard (0.39 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00D - R1010 - External Movement (98.74 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	99m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00D/R1011/Ceiling Structures/Linings/S28					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R1011 - Stairs (16.23 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00D/R1011/Ceiling Structures/Linings/S28					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R1012 - Stairs (15.28 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Medium (2)	Low Priority (2-3)
8813/B00D/R1011/Ceiling Structures/Linings/S28					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R9001 - General Storeroom (6.47 m2)</b>						
No Asbestos						
<b>B00D - R9002 - Toilets-Boys (30.35 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
8813/B00D/R0007/Ceiling Structures/Linings/S8					<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00D - R9003 - Cleaning Store - Distributed (2.3 m2)</b>						
No Asbestos						
<b>B00D - R9004 - Staff - Toilet (6.97 m2)</b>						
No Asbestos						
<b>B00D - R9005 - Cleaning Supplies Store (30.82 m2)</b>						
No Asbestos						
<b>B00D - R9006 - Movement (8.69 m2)</b>						
No Asbestos						
<b>B00D - R9007 - General Storeroom (3.26 m2)</b>						
No Asbestos						
<b>B00D - R9008 - Stairs (10.79 m2)</b>						
No Asbestos						
<b>B00D - R9009 - External Movement (7.67 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Physical Education - 1978 - Concrete (Concrete)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00E - R0001 - Movement (2.79 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00E - R0002 - Shower/Change (31.97 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00E/R0021/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>

**B00E - R0003 - Movement (16.14 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00E - R0004 - Shower/Change (32.33 m2)**

No Asbestos

**B00E - R0005 - Movement (2.77 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00E - R0006 - Stage (60.27 m2)**

No Asbestos

**B00E - R0007 - Toilets-Boys (19.37 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00E/R0021/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>

**B00E - R0008 - Staff Study (9.76 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00E/R0021/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>

**B00E - R0009 - Plant (5.61 m2)**

No Asbestos

**B00E - R0010 - Sport Equipment Store (12.94 m2)**

No Asbestos

**B00E - R0011 - Cleaning Store - Distributed (3.1 m2)**

No Asbestos

**B00E - R0012 - Sport Equipment Store (23.96 m2)**

No Asbestos

**B00E - R0013 - Chair Store (12.03 m2)**

No Asbestos

**B00E - R0014 - Student Canteen (61.65 m2)**

Floor Coverings Res/Textile	Vinyl Sheet					
	8813/B00E/R0014/Floor Coverings Res/Textile/S3					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0015 - Movement (12.24 m2)</b>						
No Asbestos						
<b>B00E - R0016 - Distribution Board Cupboard (1.07 m2)</b>						
No Asbestos						
Note: No inspection of live electrical installation.						
<b>B00E - R0017 - Cleaning Store - Distributed (6.02 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
<b>B00E - R0018 - General Storeroom (4.7 m2)</b>						
No Asbestos						
<b>B00E - R0019 - Chair Store (33.16 m2)</b>						
No Asbestos						
<b>B00E - R0020 - Staff Study (9.91 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00E/R0021/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>
<b>B00E - R0021 - Toilets-Girls (18.23 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00E/R0021/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>
<b>B00E - R0022 - Multi-Purpose Space (568.16 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8813/B00E/R0022/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Vermiculite					
	8813/B00E/R0022/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Library/Science Learning - 1980 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00F/R0023/Ceiling Structures/Linings/S29					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00F - R0005 - Distribution Board Cupboard (0.46 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0008 - General Learning Space (51.33 m2)**

Ceiling Structures/Linings	Vermiculite					
	8813/B00F/R0013/Ceiling Structures/Linings/S14					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0009 - General Learning Space (50.33 m2)**

Ceiling Structures/Linings	Vermiculite					
	8813/B00F/R0013/Ceiling Structures/Linings/S14					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0010 - Apparatus Store (39.26 m2)**

No Asbestos

**B00F - R0011 - Chemical Store (10.25 m2)**

Bench	Compressed AC Sheet	2Unit(s)	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8813/B00F/R0011/Bench/S16					<b>Chrysotile (white asbestos)</b>

**B00F - R0012 - Cleaning Store - Distributed (1.02 m2)**

No Asbestos

**B00F - R0013 - Laboratory L.S. (80.58 m2)**

Ceiling Structures/Linings	Vermiculite					
	8813/B00F/R0013/Ceiling Structures/Linings/S14					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0014 - Preparation (51.14 m2)**

Ceiling Structures/Linings	Vermiculite					
	8813/B00F/R0013/Ceiling Structures/Linings/S14					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0015 - Laboratory L.S. (81.47 m2)**

Ceiling Structures/Linings	Vermiculite					
	8813/B00F/R0013/Ceiling Structures/Linings/S14					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0017 - Movement (65.08 m2)**

No Asbestos

**B00F - R0018 - External Movement (20.22 m2)**

No Asbestos

**B00F - R0019 - Stairs (5.65 m2)**

No Asbestos

**B00F - R0020 - External Stairs (4.63 m2)**

No Asbestos

**B00F - R0021 - Garden Store Room (10.64 m2)**

No Asbestos

**B00F - R0022 - Movement (86.53 m2)**

No Asbestos

**B00F - R0023 - Cleaning Supplies Store (5.59 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	5.5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00F/R0023/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)	
<b>B00F - R0025 - Toilets-Girls (61.7 m2)</b>						
No Asbestos						
<b>B00F - R0026 - General Learning Space - Type 3 (50.4 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
8813/B00F/R0027/Ceiling Structures/Linings/S31					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R0027 - Garden Store Room (4.77 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
8813/B00F/R0027/Ceiling Structures/Linings/S31					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1001 - Interview/Office - Type 1 (11.95 m2)</b>						
No Asbestos						
<b>B00F - R1002 - Distribution Board Cupboard (0.54 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00F - R1003 - Staff - Toilet (10.68 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00F/R0002/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)	
<b>B00F - R1004 - Staff - Toilet (7.26 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00F/R0002/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)	
<b>B00F - R1008 - Workroom (44.63 m2)</b>						
No Asbestos						
<b>B00F - R1009 - Seminar (11.24 m2)</b>						
No Asbestos						
<b>B00F - R1010 - Seminar (11.05 m2)</b>						
No Asbestos						
<b>B00F - R1011 - Seminar (11.27 m2)</b>						
No Asbestos						
<b>B00F - R1012 - Cleaning Store - Distributed (1.02 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00F/R0023/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)	
<b>B00F - R1013 - Movement (48.16 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00F/R0023/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)	
<b>B00F - R1014 - External Movement (19.69 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00F/R0023/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)	
<b>B00F - R1015 - Stairs (21.04 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8813/B00F/R0023/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)	
<b>B00F - R1016 - System Administrators Office (20.12 m2)</b>						
No Asbestos						
<b>B00F - R1017 - Main Area (341.71 m2)</b>						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00F - R1018 - Staff Study (23.14 m2)</b>						
No Asbestos						
<b>B00F - R1019 - Computer Store (18.16 m2)</b>						
No Asbestos						
<b>B00F - R1020 - Seminar (74.06 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0II - Administration/Pupil Facilities - 2012 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

**Interior**

**B0II - R0001 - Covered Area (195.59 m2)**

No Asbestos

**B0II - R0002 - Movement (47.92 m2)**

No Asbestos

**B0II - R0003 - Deputy Principal Office (12.22 m2)**

No Asbestos

**B0II - R0004 - Cleaning Store - Distributed (3.94 m2)**

No Asbestos

**B0II - R0005 - Tea Room (6.25 m2)**

No Asbestos

**B0II - R0006 - Staff - Toilet (4.71 m2)**

No Asbestos

**B0II - R0007 - Staff - Toilet (4.71 m2)**

No Asbestos

**B0II - R0008 - Interview/Meeting (12.53 m2)**

No Asbestos

**B0II - R0009 - Interview/Meeting (13.07 m2)**

No Asbestos

**B0II - R0010 - Store (11.78 m2)**

No Asbestos

**B0II - R0011 - Distribution Board Cupboard (0.92 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B0II - R0012 - Principal Office (20.02 m2)**

No Asbestos

**B0II - R0013 - Principal Office (20.32 m2)**

No Asbestos

**B0II - R0014 - Public Reception (23.85 m2)**

No Asbestos

**B0II - R0015 - Secure Storeroom (12.14 m2)**

No Asbestos

**B0II - R0016 - Interview/Meeting (12.78 m2)**

No Asbestos

**B0II - R0017 - Deputy Principal Office (11.97 m2)**

No Asbestos

**B0II - R0018 - Movement (28.06 m2)**

No Asbestos

**B0II - R0019 - External Movement (126.54 m2)**

No Asbestos

**B0II - R0020 - Interview/Office - Type 1 (16.77 m2)**

No Asbestos

**B0II - R0021 - Store (1.05 m2)**

No Asbestos

**B0II - R0022 - Access Staff Shower/Toilet (5.74 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0II - R0023 - First Aid (11.06 m2)</b>						
No Asbestos						
<b>B0II - R0024 - Administration - Clerical (100.49 m2)</b>						
No Asbestos						
<b>B0II - R0025 - Student Reception (21.35 m2)</b>						
No Asbestos						
<b>B0II - R0026 - Clinic (12.25 m2)</b>						
No Asbestos						
<b>B0II - R0027 - Access Staff Shower/Toilet (5.14 m2)</b>						
No Asbestos						
<b>B0II - R0028 - Visitors Office (13.53 m2)</b>						
No Asbestos						
<b>B0II - R0029 - Interview/Office - Type 1 (12.46 m2)</b>						
No Asbestos						
<b>B0II - R0030 - Toilets-Boys (42.66 m2)</b>						
No Asbestos						
<b>B0II - R0031 - Movement (5.83 m2)</b>						
No Asbestos						
<b>B0II - R0032 - Lift (1.82 m2)</b>						
No Asbestos						
<b>B0II - R0033 - External Stairs (5.47 m2)</b>						
No Asbestos						
<b>B0II - R9001 - Laboratory L.S. (5.5 m2)</b>						
No Asbestos						
<b>B0II - R9002 - External Movement (26.52 m2)</b>						
No Asbestos						
<b>B0II - R9003 - External Stairs (16.3 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

8813\_ASB\_150514\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017