


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Georges River College Penshurst Girls Campus (8857)  
**Region :** Sydney  
**State Electorate :** Oatley  
**Local Government Area :** Hurstville

**Initial Survey :** Noel Arnold & Associates : 04 - Apr - 2008  
**Reviewed By :** Parsons Brinckerhoff : 28 - Jul - 2015



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
|         | Sample No            |        |                    |                    |             | Test Result      |

**B00A - Administration/General Learning - 1954 - Brick/Block (Brick/Block)****Exterior**

|                  |                                                            |
|------------------|------------------------------------------------------------|
| Ceiling Voids    | Non Accessible Area<br>- no access hatches, solid ceilings |
| Underfloor Voids | No Asbestos Found                                          |

**Interior****B00A - R0001 - Staff - Toilet (8.19 m2)**

No Asbestos

**B00A - R0002 - Administration - Clerical (33.62 m2)**

No Asbestos

**B00A - R0003 - Public Entry (72.75 m2)**

No Asbestos

**B00A - R0004 - General Storeroom (2.51 m2)**

No Asbestos

**B00A - R0005 - General Storeroom (3.07 m2)**

No Asbestos

**B00A - R0006 - Principal Office (25.92 m2)**

No Asbestos

**B00A - R0007 - Staff - Toilet (8.77 m2)**

No Asbestos

**B00A - R0008 - General Learning Space (51.34 m2)**

No Asbestos

**B00A - R0009 - General Learning Space (51.32 m2)**

No Asbestos

**B00A - R0011 - Pantry (13.24 m2)**

No Asbestos

**B00A - R0017 - Distribution Board Cupboard (0.63 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0019 - Cleaning Store - Distributed (5.98 m2)**

No Asbestos

**B00A - R0023 - Commonroom (91.21 m2)**

No Asbestos

**B00A - R0026 - General Learning Space (49.94 m2)**

No Asbestos

**B00A - R0027 - Clinic - Girls (19.15 m2)**

No Asbestos

**B00A - R0028 - General Storeroom (3.97 m2)**

No Asbestos

**B00A - R0029 - Interview/Office - Type 1 (13.98 m2)**

No Asbestos

**B00A - R0030 - Deputy Principal Office (16.82 m2)**

No Asbestos

**B00A - R0031 - Movement (27.08 m2)**

No Asbestos

**B00A - R0032 - Movement (33.28 m2)**

No Asbestos

**B00A - R0033 - Movement (1.99 m2)**

No Asbestos

| Product                                                       | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority                                              |
|---------------------------------------------------------------|----------------------|--------|--------------------|--------------------|-------------|---------------------------------------------------------------|
| Sample No                                                     |                      |        |                    |                    |             | Test Result                                                   |
| <b>B00A - R0034 - Movement (134.91 m2)</b>                    |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0035 - Movement (1.91 m2)</b>                      |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0036 - Movement (19.9 m2)</b>                      |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0037 - Interview/Office - Type 1 (12.46 m2)</b>    |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0038 - Textiles Technology L.S. (81.62 m2)</b>     |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0040 - Food Technology L.S. (93.86 m2)</b>         |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0041 - Food/Research Space (26.71 m2)</b>          |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0042 - Food Technology L.S. (99.29 m2)</b>         |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0043 - Movement (1.55 m2)</b>                      |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0044 - Cleaning Supplies Store (2.12 m2)</b>       |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0045 - Stairs (5.81 m2)</b>                        |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0046 - Printing/Photocopying (15.78 m2)</b>        |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R0047 - Stairs (8.68 m2)</b>                        |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R1001 - Staff - Toilet (8.25 m2)</b>                |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R1002 - Administration - Clerical (24.8 m2)</b>     |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R1003 - General Storeroom (8.78 m2)</b>             |                      |        |                    |                    |             |                                                               |
| Floor Coverings Res/Textile                                   | Vinyl Tiles          | 8m2    | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)                                            |
| 8857/B00B/R1015/Floor Coverings Res/Textile/S4                |                      |        |                    |                    |             | <b>Chrysotile (white asbestos)</b>                            |
| Floor Coverings Res/Textile                                   | Bitumen adhesive     |        |                    |                    |             |                                                               |
| 8857/B00A/R1003/Floor Coverings Res/Textile/S12               |                      |        |                    |                    |             | <b>No Asbestos Detected</b>                                   |
| <b>B00A - R1004 - General Storeroom (3.35 m2)</b>             |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R1005 - General Storeroom (3.64 m2)</b>             |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |
| <b>B00A - R1006 - Cleaning Store - Distributed (19.99 m2)</b> |                      |        |                    |                    |             |                                                               |
| Ceiling Structures/Linings                                    | Flat AC Sheeting     | 20m2   | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)                                            |
| 8857/B00A/R1006/Ceiling Structures/Linings/S13                |                      |        |                    |                    |             | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |
| Air conditioning unit - Flange Gaskets                        | Fibrous Putty        | 10m    | Throughout         | Good Condition (1) | Low (1)     | Low Priority (2-3)                                            |
| 8857/B00A/R1006/Air conditioning unit - Flange Gaskets/S14    |                      |        |                    |                    |             | <b>Chrysotile (white asbestos)</b>                            |
| <b>B00A - R1007 - General Storeroom (4.06 m2)</b>             |                      |        |                    |                    |             |                                                               |
| No Asbestos                                                   |                      |        |                    |                    |             |                                                               |

| Product                                                  | Material Description | Extent | Location Reference                             | Material Condition | Risk Status | Control Priority                   |
|----------------------------------------------------------|----------------------|--------|------------------------------------------------|--------------------|-------------|------------------------------------|
| Sample No                                                |                      |        |                                                |                    | Test Result |                                    |
| <b>B00A - R1008 - General Storeroom (4.4 m2)</b>         |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1009 - Cleaning Supplies Store (7.75 m2)</b>  |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1010 - General Learning Space (25.92 m2)</b>  |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1011 - General Storeroom (1.01 m2)</b>        |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1012 - Staff Study (11.99 m2)</b>             |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1013 - General Storeroom (4.86 m2)</b>        |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1014 - Staff Study (13.28 m2)</b>             |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1015 - Staff - Toilet (8.87 m2)</b>           |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1016 - Movement (7.16 m2)</b>                 |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1017 - General Learning Space (51.32 m2)</b>  |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1018 - General Learning Space (51.55 m2)</b>  |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1019 - General Storeroom (16.85 m2)</b>       |                      |        |                                                |                    |             |                                    |
| Floor Coverings Res/Textile                              | Vinyl Tiles          |        |                                                |                    |             |                                    |
|                                                          |                      |        | 8857/B00A/R1019/Floor Coverings Res/Textile/S6 |                    |             | <b>No Asbestos Detected</b>        |
| <b>B00A - R1020 - General Learning Space (19.21 m2)</b>  |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1021 - General Storeroom (3.98 m2)</b>        |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1022 - General Storeroom (17.83 m2)</b>       |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1023 - Leading Teacher (10.71 m2)</b>         |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1024 - General Learning Space (70.55 m2)</b>  |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1025 - Movement (3.4 m2)</b>                  |                      |        |                                                |                    |             |                                    |
| Floor Coverings Res/Textile                              | Vinyl Tiles          | 4m2    | All surfaces                                   | Good Condition (1) | Low (1)     | Low Priority (2-3)                 |
|                                                          |                      |        | 8857/B00B/R1015/Floor Coverings Res/Textile/S4 |                    |             | <b>Chrysotile (white asbestos)</b> |
| <b>B00A - R1026 - Computer Learning Space (52.68 m2)</b> |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1027 - General Storeroom (4.04 m2)</b>        |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1028 - General Storeroom (2.93 m2)</b>        |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1033 - Commonroom (7.31 m2)</b>               |                      |        |                                                |                    |             |                                    |
| No Asbestos                                              |                      |        |                                                |                    |             |                                    |
| <b>B00A - R1034 - Staff - Toilet (4.89 m2)</b>           |                      |        |                                                |                    |             |                                    |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

No Asbestos

**B00A - R1036 - Design L.S. (57.82 m2)**

No Asbestos

**B00A - R1037 - Materials Store (8.02 m2)**

No Asbestos

**B00A - R1038 - Materials Store (9.03 m2)**

|                                                |             |      |              |                    |                                    |                    |
|------------------------------------------------|-------------|------|--------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                    | Vinyl Tiles | 10m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5 |             |      |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00A - R1039 - Design L.S. (56.28 m2)**

No Asbestos

**B00A - R1040 - Materials Store (9.28 m2)**

No Asbestos

**B00A - R1041 - Computer Store (12.63 m2)**

|                                                |             |      |              |                    |                                    |                    |
|------------------------------------------------|-------------|------|--------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                    | Vinyl Tiles | 13m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5 |             |      |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00A - R1042 - Computer Learning Space (60.09 m2)**

No Asbestos

**B00A - R1043 - Distribution Board Cupboard (0.57 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R1044 - Movement (182.15 m2)**

|                                                |             |       |              |                    |                                    |                    |
|------------------------------------------------|-------------|-------|--------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                    | Vinyl Tiles | 183m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1015/Floor Coverings Res/Textile/S4 |             |       |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00A - R1045 - Movement (20.53 m2)**

|                                                |             |      |              |                    |                                    |                    |
|------------------------------------------------|-------------|------|--------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                    | Vinyl Tiles | 21m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1015/Floor Coverings Res/Textile/S4 |             |      |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00A - R1046 - Movement (3.57 m2)**

No Asbestos

**B00A - R1047 - Staff Study (32.03 m2)**

No Asbestos

**B00A - R1048 - Careers Advisers Office (34.51 m2)**

No Asbestos

**B00A - R1049 - Stairs (14.55 m2)**

No Asbestos

**B00A - R1050 - Stairs (12.05 m2)**

No Asbestos

**B00A - R1051 - Plant (2.09 m2)**

No Asbestos



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    | Test Result        |             |                  |

**B00B - Pupil Facilities/General Learning - 1954 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                                                                                              |      |                                        |                                                               |         |                    |
|------------------|----------------------------------------------------------------------------------------------|------|----------------------------------------|---------------------------------------------------------------|---------|--------------------|
| Ceiling Voids    | Non Accessible Area<br>- solid ceilings throughout, no access to ceiling cavities if present |      |                                        |                                                               |         |                    |
| Eaves Linings    | Flat AC Sheeting                                                                             | 35m2 | North and south facing to western wing | Good Condition (1)                                            | Low (1) | Low Priority (2-3) |
|                  | 8857/B00B/Eaves Linings/S16                                                                  |      |                                        | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |         |                    |
| Underfloor Voids | Non Accessible Area<br>- no access to underfloor void, no access hatches available           |      |                                        |                                                               |         |                    |

**Interior**

**B00B - R0002 - Student Canteen (7.55 m2)**

|                             |                                                |     |              |                                    |         |                    |
|-----------------------------|------------------------------------------------|-----|--------------|------------------------------------|---------|--------------------|
| Floor Coverings Res/Textile | Vinyl Tiles                                    | 8m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                             | 8857/B00B/R0001/Floor Coverings Res/Textile/S3 |     |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B00B - R0006 - Gymnasium (22.99 m2)**

No Asbestos

**B00B - R0007 - Garden Store Room (8.08 m2)**

No Asbestos

**B00B - R0008 - Movement (17.37 m2)**

No Asbestos

**B00B - R0009 - External Movement (31.46 m2)**

No Asbestos

**B00B - R0010 - Movement (1.55 m2)**

No Asbestos

**B00B - R0011 - Senior Study (93.51 m2)**

No Asbestos

**B00B - R0012 - Toilets-Girls (135.97 m2)**

|                            |                                               |       |              |                                                               |         |                    |
|----------------------------|-----------------------------------------------|-------|--------------|---------------------------------------------------------------|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                              | 136m2 | All surfaces | Good Condition (1)                                            | Low (1) | Low Priority (2-3) |
|                            | 8857/B00B/R0012/Ceiling Structures/Linings/S7 |       |              | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |         |                    |

**B00B - R0013 - Distribution Board Cupboard (2.03 m2)**

Note: No inspection of live electrical installation.

|                            |                                               |     |              |                                                               |         |                    |
|----------------------------|-----------------------------------------------|-----|--------------|---------------------------------------------------------------|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                              | 3m2 | All surfaces | Good Condition (1)                                            | Low (1) | Low Priority (2-3) |
|                            | 8857/B00B/R0012/Ceiling Structures/Linings/S7 |     |              | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |         |                    |

**B00B - R0014 - Garden Store Room (7 m2)**

|                            |                             |     |            |                                                               |         |                    |
|----------------------------|-----------------------------|-----|------------|---------------------------------------------------------------|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting            | 7m2 | Throughout | Good Condition (1)                                            | Low (1) | Low Priority (2-3) |
|                            | 8857/B00B/Eaves Linings/S16 |     |            | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |         |                    |

**B00B - R0015 - Movement (74.74 m2)**

No Asbestos

**B00B - R0016 - Movement (16.97 m2)**

No Asbestos

**B00B - R0017 - General Storeroom (2.86 m2)**

No Asbestos

**B00B - R0019 - Sport Equipment Store (15.24 m2)**

No Asbestos

**B00B - R0020 - Sport Equipment Store (18.43 m2)**

| Product                                                      | Material Description | Extent | Location Reference | Material Condition | Risk Status                        | Control Priority            |
|--------------------------------------------------------------|----------------------|--------|--------------------|--------------------|------------------------------------|-----------------------------|
| Sample No                                                    |                      |        |                    |                    | Test Result                        |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R0022 - Movement (22.26 m2)</b>                    |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R0023 - Staff - Toilet (3.38 m2)</b>               |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R0024 - Handwashing Facilities (2.97 m2)</b>       |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R0025 - Student Canteen (61.69 m2)</b>             |                      |        |                    |                    |                                    |                             |
| Wall Linings Internal                                        | Compressed AC Sheet  | 20m2   | South              | Good Condition (1) | Low (1)                            | Low Priority (2-3)          |
| 8857/B00B/R0025/Ceiling Structures/Linings/S20               |                      |        |                    |                    | <b>Invalid Sample</b>              |                             |
| Wall Linings Internal                                        | Compressed AC Sheet  |        |                    |                    |                                    | <b>No Asbestos Detected</b> |
| 8857/B00B/R0025/Wall Linings Internal/S21                    |                      |        |                    |                    |                                    |                             |
| Infill Panels                                                | Compressed AC Sheet  |        |                    |                    |                                    | <b>No Asbestos Detected</b> |
| 8857/B00B/R0025/Wall Linings Internal/S21                    |                      |        |                    |                    |                                    |                             |
| <b>B00B - R0026 - Movement (284 m2)</b>                      |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R0028 - Stairs (6.52 m2)</b>                       |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R0029 - Stairs (3.86 m2)</b>                       |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R1001 - Cleaning Store - Distributed (0.88 m2)</b> |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R1002 - Cleaning Store - Distributed (0.7 m2)</b>  |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R1003 - General Storeroom (11.26 m2)</b>           |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R1004 - General Learning Space (49.63 m2)</b>      |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R1005 - General Learning Space (49.5 m2)</b>       |                      |        |                    |                    |                                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3)          |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                             |
| <b>B00B - R1006 - General Learning Space (49.63 m2)</b>      |                      |        |                    |                    |                                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3)          |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                             |
| <b>B00B - R1007 - General Learning Space (49.7 m2)</b>       |                      |        |                    |                    |                                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3)          |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                             |
| <b>B00B - R1008 - General Learning Space (49.82 m2)</b>      |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R1009 - General Learning Space (49.63 m2)</b>      |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |
| <b>B00B - R1010 - General Storeroom (7.35 m2)</b>            |                      |        |                    |                    |                                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 8m2    | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3)          |
| 8857/B00B/R1015/Floor Coverings Res/Textile/S4               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                             |
| <b>B00B - R1011 - Staff Study (41.76 m2)</b>                 |                      |        |                    |                    |                                    |                             |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                             |

| Product                                                      | Material Description | Extent | Location Reference | Material Condition | Risk Status                        | Control Priority   |
|--------------------------------------------------------------|----------------------|--------|--------------------|--------------------|------------------------------------|--------------------|
| Sample No                                                    |                      |        |                    |                    | Test Result                        |                    |
| <b>B00B - R1012 - General Storeroom (28.28 m2)</b>           |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R1013 - Staff Study (42.53 m2)</b>                 |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R1014 - General Storeroom (27.44 m2)</b>           |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R1015 - Movement (141.69 m2)</b>                   |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 142m2  | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1015/Floor Coverings Res/Textile/S4               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R1016 - Movement (14.97 m2)</b>                    |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R1017 - Stairs (10.06 m2)</b>                      |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R1018 - Stairs (15.41 m2)</b>                      |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R1019 - Stairs (1.7 m2)</b>                        |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R2001 - Cleaning Store - Distributed (0.89 m2)</b> |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R2002 - Cleaning Store - Distributed (0.7 m2)</b>  |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R2003 - General Storeroom (11.38 m2)</b>           |                      |        |                    |                    |                                    |                    |
| No Asbestos                                                  |                      |        |                    |                    |                                    |                    |
| <b>B00B - R2004 - General Learning Space (49.82 m2)</b>      |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2005 - General Learning Space (49.69 m2)</b>      |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2006 - General Learning Space (49.62 m2)</b>      |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2007 - General Learning Space (49.62 m2)</b>      |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2008 - General Learning Space (49.62 m2)</b>      |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2009 - General Learning Space (49.62 m2)</b>      |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 50m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1005/Floor Coverings Res/Textile/S5               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2010 - Movement (149.42 m2)</b>                   |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 150m2  | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8857/B00B/R1015/Floor Coverings Res/Textile/S4               |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2011 - Interview/Office - Type 1 (14.81 m2)</b>   |                      |        |                    |                    |                                    |                    |



| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
|         | Sample No            |        |                    |                    |             | Test Result      |

No Asbestos

**B00B - R2012 - Interview/Office - Type 1 (13.92 m2)**

No Asbestos

**B00B - R2013 - Staff Study (35.81 m2)**

No Asbestos

**B00B - R2014 - General Storeroom (20.02 m2)**

No Asbestos

**B00B - R2015 - Interview/Office - Type 1 (15.89 m2)**

No Asbestos

**B00B - R2016 - Staff Study (14.99 m2)**

No Asbestos

**B00B - R2017 - Stairs (22.8 m2)**

No Asbestos

**B00B - R2018 - Stairs (8.48 m2)**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00C - Art/Music - 1954 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                                                                                       |      |                                                                         |                    |         |                                    |
|------------------|---------------------------------------------------------------------------------------|------|-------------------------------------------------------------------------|--------------------|---------|------------------------------------|
| Eaves Linings    | Flat AC Sheeting                                                                      | 28m2 | North facing,<br>South facing,<br>East facing,<br>Variable<br>positions | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                  | 8857/B00C/Eaves Linings/S15                                                           |      |                                                                         |                    |         | <b>Chrysotile (white asbestos)</b> |
| Ceiling Voids    | Non Accessible Area<br>- ceiling lining flush with roof, no access hatches to cavity. |      |                                                                         |                    |         |                                    |
| Underfloor Voids | Vinyl Tile Debris                                                                     |      |                                                                         |                    |         | <b>No Asbestos Detected</b>        |
|                  | 8857/B00C/Underfloor Voids/S19                                                        |      |                                                                         |                    |         |                                    |

**Interior**

**B00C - R0002 - Cleaning Store - Distributed (2.55 m2)**

No Asbestos

**B00C - R0003 - Darkroom Space (25.1 m2)**

No Asbestos

**B00C - R0005 - Music Learning Space (52.06 m2)**

No Asbestos

**B00C - R0006 - Music Store (23.66 m2)**

No Asbestos

**B00C - R0007 - Music Learning Space (91.39 m2)**

No Asbestos

**B00C - R0008 - Music Store (14.66 m2)**

No Asbestos

**B00C - R0009 - Movement (36.91 m2)**

No Asbestos

**B00C - R0010 - Movement (21.55 m2)**

No Asbestos

**B00C - R0012 - General Storeroom (0.95 m2)**

No Asbestos

**B00C - R0013 - Movement (3.44 m2)**

No Asbestos

**B00C - R0014 - Handwashing Facilities (2.12 m2)**

No Asbestos

**B00C - R0015 - Staff - Toilet (1.49 m2)**

No Asbestos

**B00C - R0016 - Stairs (13.23 m2)**

No Asbestos

**B00C - R0017 - Staff Study (47.73 m2)**

No Asbestos

**B00C - R0018 - Movement (2.01 m2)**

No Asbestos

**B00C - R0019 - External Movement (6.12 m2)**

No Asbestos

**B00C - R0020 - Movement (4.84 m2)**

No Asbestos

**B00C - R1003 - Cleaning Store - Distributed (2.82 m2)**

No Asbestos

**B00C - R1004 - Art Learning Space (64.82 m2)**

| Product                                                  | Material Description | Extent | Location Reference | Material Condition | Risk Status                 | Control Priority |
|----------------------------------------------------------|----------------------|--------|--------------------|--------------------|-----------------------------|------------------|
| Sample No                                                |                      |        |                    |                    | Test Result                 |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1005 - General Storeroom (6.14 m2)</b>        |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1006 - Kiln Space (6.1 m2)</b>                |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1007 - General Storeroom (1.49 m2)</b>        |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1008 - Resources Store (17.09 m2)</b>         |                      |        |                    |                    |                             |                  |
| Floor Coverings Res/Textile                              | Vinyl Tiles          |        |                    |                    |                             |                  |
| 8857/B00C/R1008/Floor Coverings Res/Textile/S2           |                      |        |                    |                    | <b>No Asbestos Detected</b> |                  |
| <b>B00C - R1009 - Resources Store (8.47 m2)</b>          |                      |        |                    |                    |                             |                  |
| Floor Coverings Res/Textile                              | Vinyl Tiles          |        |                    |                    |                             |                  |
| 8857/B00C/R1008/Floor Coverings Res/Textile/S2           |                      |        |                    |                    | <b>No Asbestos Detected</b> |                  |
| <b>B00C - R1010 - Art Learning Space (78.59 m2)</b>      |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1011 - Movement (74.46 m2)</b>                |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1012 - General Learning Space (63.03 m2)</b>  |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1015 - Stairs (13.21 m2)</b>                  |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R1016 - Movement (11.28 m2)</b>                |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9003 - Staff - Toilet (1.84 m2)</b>           |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9007 - Movement (6.65 m2)</b>                 |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9008 - Art Learning Space (66.8 m2)</b>       |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9009 - Kiln Space (9.07 m2)</b>               |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9010 - General Assistants (25.42 m2)</b>      |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9011 - Cleaning Supplies Store (24.29 m2)</b> |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9012 - Movement (67.5 m2)</b>                 |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |
| <b>B00C - R9013 - Stairs (5.85 m2)</b>                   |                      |        |                    |                    |                             |                  |
| No Asbestos                                              |                      |        |                    |                    |                             |                  |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00D - Multi Purpose Facilities - 1954 - Brick/Block (Brick/Block)**

**Exterior**

|                                                 |                                                            |     |                                                     |                    |                                    |                    |
|-------------------------------------------------|------------------------------------------------------------|-----|-----------------------------------------------------|--------------------|------------------------------------|--------------------|
| Ceiling void - Above hall (accessed via AR1006) | Fibrous Putty                                              | 40m | Throughout air conditioning ductwork flange gaskets | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
|                                                 | 8857/B00A/R1006/Air conditioning unit - Flange Gaskets/S14 |     |                                                     |                    | <b>Chrysotile (white asbestos)</b> |                    |
| Underfloor Voids                                | No Asbestos Found                                          |     |                                                     |                    |                                    |                    |

**Interior**

**B00D - R0001 - General Storeroom (8.81 m2)**

No Asbestos

**B00D - R0002 - Cleaning Supplies Store (7.09 m2)**

No Asbestos

**B00D - R0003 - General Storeroom (0.87 m2)**

No Asbestos

**B00D - R0004 - Shower/Change (34.4 m2)**

No Asbestos

**B00D - R0005 - Shower/Change (16.61 m2)**

No Asbestos

**B00D - R0006 - Toilets-Girls (1.27 m2)**

No Asbestos

**B00D - R0007 - Stage (78.82 m2)**

No Asbestos

**B00D - R0008 - Movement (24.02 m2)**

No Asbestos

**B00D - R0009 - Multi-Purpose Space (290.16 m2)**

No Asbestos

**B00D - R0010 - General Storeroom (7.42 m2)**

No Asbestos

**B00D - R0011 - Movement (15.99 m2)**

No Asbestos

**B00D - R0012 - Security Store (7.36 m2)**

No Asbestos

**B00D - R0013 - Stairs (5.76 m2)**

No Asbestos

**B00D - R9001 - General Storeroom (9.67 m2)**

No Asbestos

**B00D - R9002 - General Storeroom (2.03 m2)**

No Asbestos

**B00D - R9003 - Sport Equipment Store (0.97 m2)**

No Asbestos

**B00D - R9004 - Staff Study (30.72 m2)**

No Asbestos

**B00D - R9005 - Shower/Change (16.45 m2)**

No Asbestos

**B00D - R9006 - Staff - Toilet (1.4 m2)**

No Asbestos

**B00D - R9008 - Sport Equipment Store (6.37 m2)**

No Asbestos

| Product                                            | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|----------------------------------------------------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No                                          |                      |        |                    |                    | Test Result |                  |
| <b>B00D - R9009 - Movement (17.66 m2)</b>          |                      |        |                    |                    |             |                  |
| No Asbestos                                        |                      |        |                    |                    |             |                  |
| <b>B00D - R9010 - Shower/Change (45.55 m2)</b>     |                      |        |                    |                    |             |                  |
| No Asbestos                                        |                      |        |                    |                    |             |                  |
| <b>B00D - R9011 - General Storeroom (25.02 m2)</b> |                      |        |                    |                    |             |                  |
| No Asbestos                                        |                      |        |                    |                    |             |                  |
| <b>B00D - R9012 - Stairs (5.84 m2)</b>             |                      |        |                    |                    |             |                  |
| No Asbestos                                        |                      |        |                    |                    |             |                  |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00E - Performing Arts - 1954 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |                   |
|-----------------------------------|-------------------|
| Ceiling Voids                     | No Asbestos Found |
| Underfloor Voids - Slab on Ground | No Asbestos Found |

**Interior**

**B00E - R0001 - General Storeroom (31.4 m2)**

No Asbestos

**B00E - R0002 - General Storeroom (7.78 m2)**

No Asbestos

**B00E - R0003 - Distribution Board Cupboard (0.94 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0005 - Control Room (9.68 m2)**

No Asbestos

**B00E - R0006 - Performing Arts Chair Store (19.81 m2)**

No Asbestos

**B00E - R0007 - Movement (16.09 m2)**

No Asbestos

**B00E - R0008 - Movement Studio (120.46 m2)**

No Asbestos

**B00E - R0009 - Stage (36.91 m2)**

No Asbestos

**B00E - R1001 - Sport Equipment Store (31.51 m2)**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00F - Library/Science Learning - 1970 - Brick/Block (Brick/Block)****Exterior**

|                                   |                                                                                                                                                   |
|-----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found                                                                                                                                 |
| Ceiling Voids - Raked Ceiling     | Non Accessible Area<br>- no access withing ceiling cavities flush with roof. Mezzanine level rooms enter ceiling cativity and surveyed separately |

**Interior****B00F - M1001 - Plant (24.63 m2)**

No Asbestos

**B00F - M1002 - Seminar (14.89 m2)**

|                                                                                                                     |                                                              |                       |
|---------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|-----------------------|
| Ceiling Structures/Linings                                                                                          | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8 | Limited Samples Taken |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                                              |                       |

**B00F - M1003 - Plant (23.65 m2)**

No Asbestos

**B00F - M1004 - Main Area (68.23 m2)**

No Asbestos

**B00F - M1005 - Senior Study (37.33 m2)**

|                                                                                                                     |                                                              |                       |
|---------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|-----------------------|
| Ceiling Structures/Linings                                                                                          | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8 | Limited Samples Taken |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                                              |                       |

**B00F - M1006 - Plant (54.32 m2)**

No Asbestos

**B00F - M1007 - Plant (8.48 m2)**

|                                                                                                                     |                                                              |                       |
|---------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|-----------------------|
| Ceiling Structures/Linings                                                                                          | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8 | Limited Samples Taken |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                                              |                       |

**B00F - R0001 - Laboratory L.S. (91.1 m2)**

|                                                                                                                     |                                                                |                       |              |                    |         |                    |
|---------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|-----------------------|--------------|--------------------|---------|--------------------|
| Floor Coverings Res/Textile                                                                                         | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 92m2                  | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3) |
| <b>Chrysotile (white asbestos)</b>                                                                                  |                                                                |                       |              |                    |         |                    |
| Ceiling Structures/Linings                                                                                          | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   | Limited Samples Taken |              |                    |         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                                                |                       |              |                    |         |                    |

**B00F - R0002 - Preparation (44.68 m2)**

|                                                                                                                     |                                                                |                       |              |                    |         |                    |
|---------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|-----------------------|--------------|--------------------|---------|--------------------|
| Floor Coverings Res/Textile                                                                                         | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 45m2                  | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3) |
| <b>Chrysotile (white asbestos)</b>                                                                                  |                                                                |                       |              |                    |         |                    |
| Ceiling Structures/Linings                                                                                          | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   | Limited Samples Taken |              |                    |         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                                                |                       |              |                    |         |                    |

**B00F - R0003 - General Storeroom (3.2 m2)**

|                                                                                                                     |                                                                |                       |              |                    |         |                    |
|---------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|-----------------------|--------------|--------------------|---------|--------------------|
| Floor Coverings Res/Textile                                                                                         | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 4m2                   | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3) |
| <b>Chrysotile (white asbestos)</b>                                                                                  |                                                                |                       |              |                    |         |                    |
| Ceiling Structures/Linings                                                                                          | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   | Limited Samples Taken |              |                    |         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                                                |                       |              |                    |         |                    |

**B00F - R0004 - Laboratory L.S. (91.19 m2)**

|                                    |                                                                |      |              |                    |         |                    |
|------------------------------------|----------------------------------------------------------------|------|--------------|--------------------|---------|--------------------|
| Floor Coverings Res/Textile        | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 92m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3) |
| <b>Chrysotile (white asbestos)</b> |                                                                |      |              |                    |         |                    |

| Product                                                      | Material Description                                           | Extent | Location Reference | Material Condition | Risk Status | Control Priority                                                                                                                             |
|--------------------------------------------------------------|----------------------------------------------------------------|--------|--------------------|--------------------|-------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| Sample No                                                    |                                                                |        |                    |                    | Test Result |                                                                                                                                              |
| Ceiling Structures/Linings                                   | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   |        |                    |                    |             | Limited Samples Taken<br><i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |
| <b>B00F - R0006 - Staff Study (41.1 m2)</b>                  |                                                                |        |                    |                    |             |                                                                                                                                              |
| No Asbestos                                                  |                                                                |        |                    |                    |             |                                                                                                                                              |
| <b>B00F - R0007 - Cleaning Store - Distributed (8.01 m2)</b> |                                                                |        |                    |                    |             |                                                                                                                                              |
| Window In-fill Panel                                         | Flat AC Sheeting<br>8857/B00F/R1019/Window In-fill Panel/S10   |        |                    |                    |             | No Asbestos Detected                                                                                                                         |
| <b>B00F - R0008 - Chemical Store (9.19 m2)</b>               |                                                                |        |                    |                    |             |                                                                                                                                              |
| No Asbestos                                                  |                                                                |        |                    |                    |             |                                                                                                                                              |
| <b>B00F - R0009 - Laboratory L.S. (91.19 m2)</b>             |                                                                |        |                    |                    |             |                                                                                                                                              |
| Floor Coverings Res/Textile                                  | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 92m2   | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)<br>Chrysotile (white asbestos)                                                                                            |
| Ceiling Structures/Linings                                   | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   |        |                    |                    |             | Limited Samples Taken<br><i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |
| <b>B00F - R0010 - Preparation (44.85 m2)</b>                 |                                                                |        |                    |                    |             |                                                                                                                                              |
| Floor Coverings Res/Textile                                  | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 45m2   | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)<br>Chrysotile (white asbestos)                                                                                            |
| Ceiling Structures/Linings                                   | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   |        |                    |                    |             | Limited Samples Taken<br><i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |
| <b>B00F - R0011 - General Storeroom (3.21 m2)</b>            |                                                                |        |                    |                    |             |                                                                                                                                              |
| Floor Coverings Res/Textile                                  | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 4m2    | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)<br>Chrysotile (white asbestos)                                                                                            |
| Ceiling Structures/Linings                                   | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   |        |                    |                    |             | Limited Samples Taken<br><i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |
| <b>B00F - R0012 - Laboratory L.S. (90.82 m2)</b>             |                                                                |        |                    |                    |             |                                                                                                                                              |
| Floor Coverings Res/Textile                                  | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 91m2   | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)<br>Chrysotile (white asbestos)                                                                                            |
| Ceiling Structures/Linings                                   | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   |        |                    |                    |             | Limited Samples Taken<br><i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |
| <b>B00F - R0013 - Main Switchroom (0.83 m2)</b>              |                                                                |        |                    |                    |             |                                                                                                                                              |
| No Asbestos                                                  |                                                                |        |                    |                    |             |                                                                                                                                              |
| <b>B00F - R0014 - Apparatus Store (16.68 m2)</b>             |                                                                |        |                    |                    |             |                                                                                                                                              |
| Ceiling Structures/Linings                                   | Vermiculite<br>8857/B00F/M1002/Ceiling Structures/Linings/S8   |        |                    |                    |             | Limited Samples Taken<br><i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |
| <b>B00F - R0015 - Movement (40.67 m2)</b>                    |                                                                |        |                    |                    |             |                                                                                                                                              |
| Floor Coverings Res/Textile                                  | Vinyl Tiles<br>8857/B00F/R0001/Floor Coverings Res/Textile/S11 | 41m2   | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)<br>Chrysotile (white asbestos)                                                                                            |
| <b>B00F - R0016 - Movement (54.26 m2)</b>                    |                                                                |        |                    |                    |             |                                                                                                                                              |
| No Asbestos                                                  |                                                                |        |                    |                    |             |                                                                                                                                              |
| <b>B00F - R0018 - Plant (10.68 m2)</b>                       |                                                                |        |                    |                    |             |                                                                                                                                              |
| No Asbestos                                                  |                                                                |        |                    |                    |             |                                                                                                                                              |
| <b>B00F - R0019 - Laboratory L.S. (74.92 m2)</b>             |                                                                |        |                    |                    |             |                                                                                                                                              |
| No Asbestos                                                  |                                                                |        |                    |                    |             |                                                                                                                                              |



| Product                                                                                                             | Material Description                          | Extent | Location Reference                   | Material Condition | Risk Status | Control Priority                   |
|---------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|--------|--------------------------------------|--------------------|-------------|------------------------------------|
| Sample No                                                                                                           |                                               |        |                                      |                    | Test Result |                                    |
| <b>B00F - R0020 - Stairs (8.11 m2)</b>                                                                              |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R0021 - External Movement (13.19 m2)</b>                                                                  |                                               |        |                                      |                    |             |                                    |
| Window Infill Panels                                                                                                | Compressed AC Sheet                           |        |                                      |                    |             |                                    |
|                                                                                                                     | 8857/B00F/R1019/Window In-fill Panel/S10      |        |                                      |                    |             | <b>No Asbestos Detected</b>        |
| <b>B00F - R0022 - Computer Room (23.48 m2)</b>                                                                      |                                               |        |                                      |                    |             |                                    |
| Wall Linings Internal                                                                                               | Compressed AC Sheet                           |        |                                      |                    |             |                                    |
|                                                                                                                     | 8857/B00F/R1019/Ceiling Structures/Linings/S9 |        |                                      |                    |             | <b>No Asbestos Detected</b>        |
| <b>B00F - R1001 - Careers Advisers Office (25.33 m2)</b>                                                            |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1002 - Plant (6.37 m2)</b>                                                                               |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1003 - Plant (5.41 m2)</b>                                                                               |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1004 - Movement (4.64 m2)</b>                                                                            |                                               |        |                                      |                    |             |                                    |
| Electrical Mounting Board                                                                                           | Resinous Board                                | 1Unit  | East facing                          | Good Condition (1) | Low (1)     | Low Priority (2-3)                 |
|                                                                                                                     | 8857/B00F/R1004/Electrical Mounting Board/S18 |        |                                      |                    |             | <b>Chrysotile (white asbestos)</b> |
| <b>B00F - R1005 - Cleaning Store - Distributed (0.37 m2)</b>                                                        |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1006 - Distribution Board Cupboard (0.32 m2)</b>                                                         |                                               |        |                                      |                    |             |                                    |
| Note: No inspection of live electrical installation.                                                                |                                               |        |                                      |                    |             |                                    |
| Electrical Mounting Board                                                                                           | Resinous Board                                | 2m2    | Within electrical distribution board | Good Condition (1) | Low (1)     | Low Priority (2-3)                 |
| <b>Assumed Asbestos - no access within electrical distribution board to confirm due to electrical hazard.</b>       |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1007 - Seminar (25.33 m2)</b>                                                                            |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1008 - Main Area (328.36 m2)</b>                                                                         |                                               |        |                                      |                    |             |                                    |
| Ceiling Structures/Linings                                                                                          | Vermiculite                                   |        |                                      |                    |             |                                    |
|                                                                                                                     | 8857/B00F/M1002/Ceiling Structures/Linings/S8 |        |                                      |                    |             | <b>Limited Samples Taken</b>       |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1009 - Audio Visual Workroom (28.59 m2)</b>                                                              |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1010 - Audio Visual Workroom (12.86 m2)</b>                                                              |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1011 - Workroom (18.01 m2)</b>                                                                           |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1012 - Librarian (11.51 m2)</b>                                                                          |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1013 - Staff - Toilet (2.94 m2)</b>                                                                      |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1014 - Staff - Toilet (2.96 m2)</b>                                                                      |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1015 - Seminar (72.03 m2)</b>                                                                            |                                               |        |                                      |                    |             |                                    |
| Ceiling Structures/Linings                                                                                          | Vermiculite                                   |        |                                      |                    |             |                                    |
|                                                                                                                     | 8857/B00F/M1002/Ceiling Structures/Linings/S8 |        |                                      |                    |             | <b>Limited Samples Taken</b>       |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                                               |        |                                      |                    |             |                                    |
| <b>B00F - R1016 - Computer Learning Space (49.17 m2)</b>                                                            |                                               |        |                                      |                    |             |                                    |
| No Asbestos                                                                                                         |                                               |        |                                      |                    |             |                                    |

| Product                                                 | Material Description | Extent | Location Reference                            | Material Condition | Risk Status | Control Priority            |
|---------------------------------------------------------|----------------------|--------|-----------------------------------------------|--------------------|-------------|-----------------------------|
| Sample No                                               |                      |        |                                               |                    | Test Result |                             |
| <b>B00F - R1017 - General Learning Space (49.02 m2)</b> |                      |        |                                               |                    |             |                             |
| No Asbestos                                             |                      |        |                                               |                    |             |                             |
| <b>B00F - R1018 - Movement (51.53 m2)</b>               |                      |        |                                               |                    |             |                             |
| No Asbestos                                             |                      |        |                                               |                    |             |                             |
| <b>B00F - R1020 - Stairs (8.03 m2)</b>                  |                      |        |                                               |                    |             |                             |
| No Asbestos                                             |                      |        |                                               |                    |             |                             |
| <b>B00F - R1021 - External Movement (13.2 m2)</b>       |                      |        |                                               |                    |             |                             |
| Window Infill Panels                                    | Compressed AC Sheet  |        |                                               |                    |             | <b>No Asbestos Detected</b> |
|                                                         |                      |        | 8857/B00F/R1019/Window In-fill Panel/S10      |                    |             |                             |
| Ceiling Structures/Linings                              | Compressed AC Sheet  |        |                                               |                    |             | <b>No Asbestos Detected</b> |
|                                                         |                      |        | 8857/B00F/R1019/Ceiling Structures/Linings/S9 |                    |             |                             |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00G - Building Services - 1995 - Steel (Steel)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00G - R0001 - Materials Store (40.71 m2)**

No Asbestos

**B00G - R0002 - Movement (10.98 m2)**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    | Test Result        |             |                  |

**B00H - Building Services - 2008 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |                                                                                    |     |            |                                                                                             |         |                    |
|-----------------------------------|------------------------------------------------------------------------------------|-----|------------|---------------------------------------------------------------------------------------------|---------|--------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found                                                                  |     |            |                                                                                             |         |                    |
| Ceiling Voids - Flat Roof         | Non Accessible Area<br>- asbestos ceiling flush with metal roof, no cavity present |     |            |                                                                                             |         |                    |
| Eaves Linings                     | Flat AC Sheeting                                                                   | 4m2 | Throughout | Good Condition (1)                                                                          | Low (1) | Low Priority (2-3) |
|                                   | 8857/B00H/Eaves Linings/S17                                                        |     |            | <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b> |         |                    |

**Interior**

**B00H - R0001 - Sport Equipment Store (14.11 m2)**

|                            |                             |      |            |                                                                                             |         |                    |
|----------------------------|-----------------------------|------|------------|---------------------------------------------------------------------------------------------|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting            | 15m2 | Throughout | Good Condition (1)                                                                          | Low (1) | Low Priority (2-3) |
|                            | 8857/B00H/Eaves Linings/S17 |      |            | <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b> |         |                    |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017