


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kangaroo Valley Public School (2256)
Region : Illawarra and South East
State Electorate : Kiama
Local Government Area : Shoalhaven

Initial Survey : Noel Arnold & Associates : 04 - May - 2008
Reviewed By : Greencap-NAA : 02 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1885 - Sandstone (Sandstone)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					
	2256/B00A/Eaves Linings/S3					No Asbestos Detected

Interior

B00A - R0001 - Special Programs Room

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Cleaning Distributed Store

No Asbestos

B00A - R0005 - Personal Effects Storage

No Asbestos

B00A - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2256/B00A/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected

B00A - R0007 - Staff Kitchen

No Asbestos

B00A - R0008 - Staff Room

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Duplicating Workroom

No Asbestos

B00A - R0011 - Principal

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Clerical Office

No Asbestos

B00A - R0014 - Movement

No Asbestos

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Cleaning Supplies

No Asbestos

B00A - R0017 - Disabled Toilet

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1984 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2256/B00B/Eaves Linings/S2					No Asbestos Detected

Interior**B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2256/B00A/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0002 - Sick Bay

No Asbestos

B00B - R0003 - Home Base Store

No Asbestos

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2256/B00A/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0006 - Withdrawal Space - 1hb

No Asbestos

B00B - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2256/B00A/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - Home Base Store

No Asbestos

B00B - R0010 - Main Switch Board

Ceiling Structures/Linings	Flat AC Sheeting 2256/B00A/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0011 - Personal Effects Storage

No Asbestos

B00B - R0012 - Practical Activities - 1hb

No Asbestos

B00B - R0013 - Kiln Room

No Asbestos

B00B - R0014 - Sports Store

No Asbestos

B00B - R0015 - Movement

No Asbestos

B00B - R0016 - Movement

No Asbestos

B00B - R0017 - Toilets - Boys

No Asbestos

B00B - R0018 - Toilets - Girls

No Asbestos

B00B - R0019 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2256/B00A/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - R0020 - Access Shower/Toilet/Change

No Asbestos

B00B - R0021 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2256/B00C/Eaves Linings/S4					No Asbestos Detected

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Practical Activities - 1hb

No Asbestos

B00C - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pre-School Facilities - 1885 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00D - R0002 - Toilets - Boys/Girls - Pre**

No Asbestos

B00D - R0003 - Staff Toilet

No Asbestos

B00D - R0004 - Home Base - Pre

No Asbestos

B00D - R0005 - General Storeroom - Pre

No Asbestos

B00D - R0006 - Withdrawal - Pre

No Asbestos

B00D - R0007 - Staff Kitchen

No Asbestos

B00D - R0008 - Covered Outdoor Learning Area - Pre

No Asbestos

B00D - R0009 - Movement

No Asbestos

B00D - R0010 - Practical Activities - Pre

No Asbestos

B00D - R0011 - Movement

No Asbestos

B00D - R0012 - Clerical Office

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1924 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00E - R0001 - Toilets - Girls

No Asbestos

B00E - R0002 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1985 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00G - R0001 - Other-Vacant

No Asbestos

B00G - R0002 - Other-Vacant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pre-School Facilities - 1985 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00H - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Shed - 1985 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Packing to Floor Joists	No Asbestos Found

Interior

B001 - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pre-School Facilities - 1985 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00J - R0001 - General Storeroom - Pre

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - Reading Area

No Asbestos

B00K - R0002 - Communications Room

No Asbestos

B00K - R0003 - K.L.A. Store

No Asbestos

B00K - R0004 - Library Office/Workroom

No Asbestos

B00K - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - General Assistant/Bulk Store

No Asbestos

B00L - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 801 - D15961 - FSU : Placement Date - 8/08/1997

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		8.64 m2

Interior

R1 - Canteen

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		45 m2

R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017