


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Karangi Public School (2260)
Region : North Coast
State Electorate : Coffs Harbour
Local Government Area : Coffs Harbour

Initial Survey : Noel Arnold & Associates : 09 - May - 2008
Reviewed By : Greencap-NAA : 05 - May - 2016

2260 - Karangi Public School
Site Plan (12961)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1986 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 2260/B00A/Eaves Linings/S14					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 2260/B00A/In-fill-panel/S2					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0011 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2260/B00A/R0011/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00A - R0012 - Staff Room

Wall Linings Internal	Flat AC Sheeting 2260/B00A/R0012/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00A - R0013 - Staff Kitchen

No Asbestos

B00A - R0014 - Sick Bay

No Asbestos

B00A - R0015 - Entry Vestibule

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - Staff Toilet

No Asbestos

B00A - R0018 - Staff Shower/Change

Wall Linings Internal	Flat AC Sheeting 2260/B00A/R0018/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00A - R0019 - Movement

No Asbestos

B00A - R0020 - Clerical Office

No Asbestos

B00A - R0021 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1955 - Timber (Timber)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	15m2	East West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00C/Eaves Linings/S13					Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Personal Effects Storage**

Wall Linings Internal	Flat AC Sheeting					
	2260/B00A/R0012/Wall Linings Internal/S3					No Asbestos Detected

B00C - R0002 - Withdrawal Space - 1hb

Wall Linings Internal	Flat AC Sheeting					
	2260/B00A/R0012/Wall Linings Internal/S3					No Asbestos Detected

B00C - R0003 - Home Base

No Asbestos

B00C - R0004 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	2260/B00C/R0004/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00C - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration/General Learning - 1919 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction 3m height					
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/Eaves Linings/S12					Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/Eaves Linings/S12					Chrysotile (white asbestos)

B00D - R0004 - Clerical Office

Wall Linings Internal	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/R0007/Wall Linings Internal/S8					Chrysotile (white asbestos)

B00D - R0006 - Staff Kitchen

Wall Linings Internal	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/R0007/Wall Linings Internal/S8					Chrysotile (white asbestos)

B00D - R0007 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/R0007/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/R0007/Wall Linings Internal/S8					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	2260/B00D/R0008/Floor Coverings Res/Textile/S10					

B00D - R0008 - Home Base

Wall Linings Internal	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/R0007/Wall Linings Internal/S8					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2260/B00D/R0007/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	2260/B00D/R0008/Floor Coverings Res/Textile/S10					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - Pupil Facilities - 1970 - Brick/Block (Brick/Block)						
Exterior						
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2260/B00E/Eaves Linings/S11	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Downpipes	Fibre Cement Pipe 2260/B00E/Downpipes/S9	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Interior						
B00E - R0001 - Drinking Facilities						
Ceiling Structures/Linings	Flat AC Sheeting 2260/B00E/Eaves Linings/S11	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0002 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting 2260/B00E/Eaves Linings/S11	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet 2260/B00E/R0002/Partition Walls (Cubicles)/S6	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
B00E - R0003 - Drinking Facilities						
Ceiling Structures/Linings	Flat AC Sheeting 2260/B00E/Eaves Linings/S11	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0004 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting 2260/B00E/Eaves Linings/S11	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet 2260/B00E/R0002/Partition Walls (Cubicles)/S6	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
B00E - R0005 - Toilets - Boys/Girls						
Ceiling Structures/Linings	Flat AC Sheeting 2260/B00E/Eaves Linings/S11	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0006 - Toilets - Boys/Girls						
Ceiling Structures/Linings	Flat AC Sheeting 2260/B00E/Eaves Linings/S11	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Shed - 1986 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Shed - 2004 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00G - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 2003 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Plant

No Asbestos

B00H - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00I - R0001 - Reading Area

No Asbestos

B00I - R0002 - Library Office/Workroom

No Asbestos

B00I - R0003 - Communications Room

No Asbestos

B00I - R0004 - K.L.A. Store

No Asbestos

B00I - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 2014 - Steel (Steel)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00J - R0001 - Canteen Covered Area

No Asbestos

B00J - R0002 - Canteen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D10038 - Learning Unit - Standard/Withdrawal : Placement Date - 11/10/1993

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 602 - D10560 - Learning Unit - Standard With P.A.A. : Placement Date - 26/03/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11617 - Learning Unit - Standard With P.A.A. : Placement Date - 28/01/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 840 - D15286 - Girls Toilet : Placement Date - 18/01/2002

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

OS 601 - D16810 - Learning Unit - Standard/Withdrawal : Placement Date - 11/01/2000

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2260_ASB_270816_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017