

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kempsey East Public School (2278)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Kempsey

**Initial Survey :** Noel Arnold & Associates : 24 - Apr - 2008  
**Reviewed By :** Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1977 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible. Ceiling space partially visible from access hatch, no safe access in ceiling space (3.6m)					
Eaves Linings	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/Eaves Linings/S3					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B00A - R0001 - Home Base (51.01 m2)**

Access Hatch Cover	Flat AC Sheeting	1m2	Adjacent Door	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0001/Access Hatch Cover/S31					<b>Chrysotile (white asbestos)</b>

**B00A - R0002 - Practical Activities - 1hb (18.78 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0003 - External Movement (18.97 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0003/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>

**B00A - R9001 - General Assistant/Bulk Store (70.32 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00B - General Learning - 1979 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/Eaves Linings/S3				<b>Chrysotile (white asbestos)</b>	
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible. No access to area at the time of inspection					

**Interior****B00B - R0001 - Practical Activities - 1hb (22.15 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0001/Ceiling Structures/Linings/S5				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0002/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0003/Ceiling Structures/Linings/S34				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

**B00B - R0002 - Home Base (48.82 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0001/Ceiling Structures/Linings/S5				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Adjacent door	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0002/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0003/Ceiling Structures/Linings/S34				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

**B00B - R0003 - Home Base (48.66 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0001/Ceiling Structures/Linings/S5				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Adjacent door	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0002/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0003/Ceiling Structures/Linings/S34				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

**B00B - R0004 - Practical Activities - 1hb (22.63 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0002/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0001/Ceiling Structures/Linings/S5				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2278/B00B/R0003/Ceiling Structures/Linings/S34				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

**B00B - R0005 - Home Base Store (13.49 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00A/R0002/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0006 - Distribution Board (1.02 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00B - R0007 - External Movement (43.99 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00B/R1001/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0008 - Stairs (19.45 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00B/R1001/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1001 - Movement (42.88 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00B/R1001/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1002 - Practical Activities - 1hb (22.36 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00A/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1003 - Home Base (48 m2)</b>						
No Asbestos						
<b>B00B - R1004 - Home Base (48.15 m2)</b>						
No Asbestos						
<b>B00B - R1005 - Practical Activities - 1hb (22.36 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00A/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1006 - Home Base Store (13.49 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00A/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
Access Hatch Cover	Flat AC Sheeting	1m2	Adjacent Door	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00B/R1006/Access Hatch Cover/S32					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1007 - Stairs (20.65 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00B/R1001/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R9001 - General Storeroom (11.67 m2)</b>						
No Asbestos						
<b>B00B - R9002 - General Storeroom (16.52 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 1949 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground  
Non Accessible Area  
- Area inaccessible

Ceiling Voids - Flat Roof  
Non Accessible Area  
- Access hatch above toilet, no safe access

**Interior****B00C - R0001 - External Movement (37.38 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00C/R0001/Ceiling Structures/Linings/S20					<b>Chrysotile (white asbestos)</b>	

**B00C - R0002 - Toilets - Girls (49.42 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	14m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
2278/B00C/R0002/Partition Walls (Cubicles)/S19					<b>Chrysotile (white asbestos)</b>	

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00D/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B00C - R0003 - Cleaning Distributed Store (5.79 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00D/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B00C - R0004 - Cleaning Distributed Store (2.24 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00D/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B00C - R0005 - Toilets - Boys (52.04 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00C/R0002/Partition Walls (Cubicles)/S19					<b>Chrysotile (white asbestos)</b>	

Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00D/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

**B00C - R0006 - Plant (1.68 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00D/R0002/Ceiling Structures/Linings/S6					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1977 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2278/B00F/Eaves Linings/S16	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Gable Verge Lining	Flat AC Sheeting 2278/B00D/Gable Verge Lining/S33	12m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**Interior****B00D - R0001 - Movement (97.47 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	------	------------	--------------------	---------	--

**B00D - R0004 - Canteen (18.6 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting 2278/B00D/R0004/Wall Linings Internal/S21	3m2	West, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Bulkhead	Flat AC Sheeting 2278/B00D/R0004/Roller Door Bulkhead/S22	2m2	Above Roller Shutter Door	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

Wall Linings External	Compressed AC Sheet 2278/B00D/R0004/Wall Linings External/S25					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

**B00D - R0005 - Canteen Office/Store (2.87 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	------------	--------------------	---------	--

**B00D - R0006 - Canteen Office/Store (3.03 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	------------	--------------------	---------	--

**B00D - R0007 - Kiln Room (3.06 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	------------	--------------------	---------	--

**B00D - R0008 - Toilet - Lobby (3.55 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	------------	--------------------	---------	--

**B00D - R0009 - Toilet - Lobby (3.08 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	------------	--------------------	---------	--

**B00D - R0010 - Staff Toilet (2.38 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2278/B00D/R0002/Ceiling Structures/Linings/S6	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	------------	--------------------	---------	--

**B00D - R0011 - Staff Toilet (2.09 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2278/B00D/R0002/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00E - Administration/General Learning - 1883 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible. Area partially visible through access hatch, no safe access to ceiling space (3.8m)					
Eaves Linings	Flat AC Sheeting	40m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Height Restriction (4m+)</b>					
Underfloor Voids	Compressed AC Sheet 2278/B00E/Underfloor Voids/S26					<b>No Asbestos Detected</b>
Underfloor Voids - Packing to Floor Joists	Fibrous Membrane 2278/B00E/Underfloor Voids - Packing to Floor Joists/S27					<b>No Asbestos Detected</b>

**Interior****B00E - R0001 - External Movement (19.97 m2)**

No Asbestos

**B00E - R0002 - Staff Room (45.47 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 2278/B00E/R0002/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive 2278/B00E/R0024/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>

**B00E - R0003 - External Movement (11.51 m2)**

No Asbestos

**B00E - R0004 - Sick Bay (8 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 2278/B00E/R0002/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>
-----------------------------	--	--	--	--	--	-----------------------------

**B00E - R0005 - Entry Vestibule (15.39 m2)**

No Asbestos

**B00E - R0006 - Withdrawal Space - 1hb (15.54 m2)**

No Asbestos

**B00E - R0009 - Principal (17.87 m2)**

No Asbestos

**B00E - R0012 - Home Base (56.89 m2)**

No Asbestos

**B00E - R0013 - Home Base (56.89 m2)**

Chalk Board	Compressed AC Sheet 2278/B00E/R0013/Chalk Board/S23					<b>No Asbestos Detected</b>
-------------	--	--	--	--	--	-----------------------------

**B00E - R0015 - General Storeroom (43.72 m2)**

No Asbestos

**B00E - R0016 - Main Switch Board (7.42 m2)**

No Asbestos

**B00E - R0018 - External Movement (46.73 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	East, Central and West (above Entrances)	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00E/R0018/Ceiling Structures/Linings/S18					<b>Chrysotile (white asbestos)</b>

**B00E - R0019 - Entry Vestibule (8.07 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0020 - Clerical Office (29.24 m2)</b>						
Safe (tag 'Lord')	Encapsulated Insulation material within unit	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Safe in good condition</b>						
<b>B00E - R0021 - Practical Activities/Movement - 2hb (38.35 m2)</b>						
No Asbestos						
<b>B00E - R0022 - Clerical/Printing (20.38 m2)</b>						
No Asbestos						
<b>B00E - R0023 - Movement (7.43 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	2278/B00E/R0024/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	2278/B00E/R0002/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>
<b>B00E - R0024 - General Storeroom (4.94 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	2278/B00E/R0024/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	2278/B00E/R0002/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>
<b>B00E - R0025 - Cleaning Supplies (3.28 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	2278/B00E/R0024/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	2278/B00E/R0002/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>
<b>B00E - R0026 - Disabled Shower/Toilet (7.74 m2)</b>						
No Asbestos						
<b>B00E - R9001 - Sports Store (43.89 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1977 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00F/Eaves Linings/S16					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area - No access hatch identified					

**Interior**

**B00F - R0001 - Toilets - Boys/Girls (3.43 m2)**

Wall Linings Internal	Flat AC Sheeting	12m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00F/R0001/Wall Linings Internal/S13					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	4m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00F/R0001/Wall Linings Internal/S14					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00F/R0001/Wall Linings Internal/S14					<b>Chrysotile (white asbestos)</b>

**B00F - R0002 - External Movement (5.51 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00F/R0002/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B00F - R0003 - Home Base Store (4.19 m2)**

No Asbestos

**B00F - R0004 - Movement (2.19 m2)**

No Asbestos

**B00F - R0006 - Home Base (86.39 m2)**

No Asbestos

**B00F - R0007 - Personal Effects Storage (14.35 m2)**

Wall Linings Internal	Flat AC Sheeting	10m2	Along Western wall, lower portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2278/B00F/R0001/Wall Linings Internal/S13					<b>Chrysotile (white asbestos)</b>

**B00F - R0008 - External Movement (65.6 m2)**

No Asbestos

**B00F - R0009 - External Movement (4.04 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00F/R0002/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B00F - R0010 - Deputy Principal (4.91 m2)**

No Asbestos

**B00F - R0011 - Interview (16.48 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1949 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00G/Eaves Linings/S35					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	Flat AC Sheeting	10m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	2278/B00G/Underfloor Voids/S28					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible. Ceiling space visible only through access hatch. No safe access to ceiling space					

**Interior****B00G - R0001 - Communications Room (103.56 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	30m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00G/R0001/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>

**B00G - R0002 - External Movement (2.23 m2)**

Wall Linings Internal	Flat AC Sheeting					<b>No Asbestos Detected</b>
	2278/B00G/R0002/Wall Linings Internal/S11					

**B00G - R0003 - General Storeroom (12.46 m2)**

Wall Linings Internal	Flat AC Sheeting	12m2	North, East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00G/R0004/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00G/R0003/Ceiling Structures/Linings/S29					<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>

**B00G - R0004 - Home Base Store (3.42 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	2278/B00G/R0004/Floor Coverings Res/Textile/S7					
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00G/R0004/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>
Flooring	Compressed AC Sheet	1m2	West	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2278/B00G/R0004/Floor/S9					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2278/B00G/R0003/Ceiling Structures/Linings/S29					<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	2278/B00G/R0004/Floor Coverings Res/Textile/S30					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Library - 1977 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids - Raked Ceiling      No Asbestos Found

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

**Interior**

**B00H - R0001 - Communal Space (13.99 m2)**

No Asbestos

**B00H - R0002 - Library Office/Workroom (23.46 m2)**

No Asbestos

**B00H - R0003 - Reading Area (163.68 m2)**

No Asbestos

**B00H - R0004 - External Movement (39.32 m2)**

No Asbestos

**B00H - R9001 - General Assistant/Bulk Store (212.64 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00I - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior****B00I - R0001 - Communal Space (145.5 m2)**

No Asbestos

**B00I - R0002 - Raised Platform (60.15 m2)**

No Asbestos

**B00I - R0003 - Hall Chair Store (9.61 m2)**

No Asbestos

**B00I - R0004 - Communal/Performance Store (9.61 m2)**

No Asbestos

**B00I - R0005 - P.E. Store (13 m2)**

No Asbestos

**B00I - R0006 - Toilet - Lobby (2.37 m2)**

No Asbestos

**B00I - R0007 - Toilets - Girls (7.32 m2)**

No Asbestos

**B00I - R0008 - Sound Cupboard (2.07 m2)**

No Asbestos

**B00I - R0009 - Toilet - Lobby (3.31 m2)**

No Asbestos

**B00I - R0010 - Toilets - Boys (5.72 m2)**

No Asbestos

**B00I - R0011 - Cleaning Distributed Store (3.51 m2)**

No Asbestos

**B00I - R0012 - Plant (1.6 m2)**

No Asbestos

**B00I - R0013 - Main Switch Board (3.24 m2)**

No Asbestos

**B00I - R0014 - Access Shower/Toilet (6.88 m2)**

No Asbestos

**B00I - R0015 - Covered Outdoor Learning Area (152.34 m2)**

No Asbestos

**B00I - R0016 - Movement (6.18 m2)**

No Asbestos

**B00I - R0017 - Ramp (12.45 m2)**

No Asbestos

**B00I - R0018 - Movement (13.01 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Storage - 2014 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00J - R0001 - Sports Store (33.17 m2)**

No Asbestos

**B00J - R0002 - External Movement (16.39 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 603 - D12738 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 10/11/2003**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017