


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kensington Public School (2283)
Region : Sydney
State Electorate : Heffron
Local Government Area : Randwick

Initial Survey : Noel Arnold & Associates : 11 - Feb - 2008
Reviewed By : AECOM : 26 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Library/General Learning - 1900 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2283/B001/R0005/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction - Access to ceiling greater than 5m					
Underfloor Voids	Non Accessible Area - Area inaccessible - no access could be found.					

Interior**B001 - R0001 - Movement (13.61 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2283/B001/R0005/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B001 - R0002 - Canteen Office/Store (3.11 m2)

No Asbestos

B001 - R0003 - Canteen Office/Store (2.94 m2)

No Asbestos

B001 - R0004 - Canteen (17.55 m2)

No Asbestos

B001 - R0005 - Movement (37.88 m2)

Ceiling Structures/Linings	Flat AC Sheeting	38m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2283/B001/R0005/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B001 - R0006 - Home Base (55.08 m2)

No Asbestos

B001 - R0007 - Home Base (53.08 m2)

No Asbestos

B001 - R0008 - Home Base (52.09 m2)

No Asbestos

B001 - R0009 - Home Base (52.61 m2)

No Asbestos

B001 - R0010 - Security Store (22.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles				
	2283/B001/R0010/Floor Coverings Res/Textile/S7				

No Asbestos Detected**B001 - R0011 - General Storeroom (11.46 m2)**

No Asbestos

B001 - R0012 - K.L.A. Store (25.53 m2)

No Asbestos

B001 - R0013 - Reading Area (133.76 m2)

No Asbestos

B001 - R0014 - Movement (29 m2)

No Asbestos

B001 - R0015 - Movement (61.81 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2283/B001/R0015/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)

B001 - R0016 - Clerical Office/Workroom (14.05 m2)

Floor Coverings Res/Textile	Vinyl Tiles				
	2283/B001/R0010/Floor Coverings Res/Textile/S7				

No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B001 - R0017 - Clerical Office (31.13 m2)						
No Asbestos						
B001 - R0018 - Staff Toilet (9.9 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
2283/B001/R0018/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)	
B001 - R0019 - Staff Toilet (9.9 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
2283/B001/R0018/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)	
B001 - R0020 - Deputy Principal (11.07 m2)						
No Asbestos						
B001 - R0021 - Sick Bay (8.95 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2283/B001/R0015/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
B001 - R0022 - Principal (22.49 m2)						
No Asbestos						
B001 - R0023 - Home Base (62.59 m2)						
No Asbestos						
B001 - R0024 - Movement (7.96 m2)						
No Asbestos						
B001 - R0025 - Movement (43.58 m2)						
Ceiling Structures/Linings	Vermiculite					
2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0026 - Cleaning Distributed Store (4.38 m2)						
No Asbestos						
B001 - R0027 - Toilets - Girls (38.76 m2)						
Ceiling Structures/Linings	Vermiculite					
2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Partition Walls (Cubicles)	Compressed AC Sheet	21m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
2283/B001/R0027/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	
B001 - R0028 - Drinking Facilities (43.71 m2)						
Ceiling Structures/Linings	Vermiculite					
2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0029 - Toilets - Boys (38.76 m2)						
Ceiling Structures/Linings	Vermiculite					
2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
2283/B001/R0027/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	
B001 - R0030 - General Storeroom (4.3 m2)						
Ceiling Structures/Linings	Vermiculite					
2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R0031 - General Storeroom (4.26 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Ceiling Structures/Linings	Vermiculite 2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R0032 - Craft Store (4.67 m2)						
Ceiling Structures/Linings	Vermiculite 2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 2283/B001/R0032/Floor Coverings Res/Textile/S8	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0033 - Special Programs Room (31.46 m2)						
Ceiling Structures/Linings	Vermiculite 2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R0034 - Staff Room (62.83 m2)						
Ceiling Structures/Linings	Vermiculite 2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B001 - R0035 - Movement (4.17 m2)						
No Asbestos						
B001 - R0036 - Toilets - Girls (30.46 m2)						
Ceiling Structures/Linings	Vermiculite 2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Partition Walls (Cubicles)	Compressed AC Sheet 2283/B001/R0027/Partition Walls (Cubicles)/S2	15m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0037 - Toilets - Boys (30.49 m2)						
Ceiling Structures/Linings	Vermiculite 2283/B001/R0027/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Partition Walls (Cubicles)	Compressed AC Sheet 2283/B001/R0027/Partition Walls (Cubicles)/S2	9m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R0038 - Drinking Facilities (19.34 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 2283/B001/R0038/Ceiling Structures/Linings/S3					No Asbestos Detected
B001 - R0039 - Movement (7.03 m2)						
No Asbestos						
B001 - R0040 - General Storeroom (2.32 m2)						
No Asbestos						
B001 - R0041 - Sports Store (14.1 m2)						
No Asbestos						
B001 - R0042 - General Assistant/Bulk Store (8.12 m2)						
No Asbestos						
B001 - R0043 - Movement (67.28 m2)						
No Asbestos						
B001 - R1001 - Home Base (62.9 m2)						
No Asbestos						
B001 - R1002 - Movement (47.29 m2)						
No Asbestos						
B001 - R1006 - Cleaning Distributed Store (2.36 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B001 - R1007 - Home Base (62.83 m2)						
No Asbestos						
B001 - R1008 - Distribution Board (0.51 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B001 - R1009 - Withdrawal Space - 1hb (32.95 m2)						
No Asbestos						
B001 - R1011 - Movement (9.53 m2)						
No Asbestos						
B001 - R1012 - Home Base (32.88 m2)						
Recently Modified Space Requires Inspection						
B001 - R1013 - Home Base (67.08 m2)						
Recently Modified Space Requires Inspection						
B001 - R1014 - Home Base (91.56 m2)						
Recently Modified Space Requires Inspection						
B001 - R1015 - Staff Room (12.99 m2)						
Recently Modified Space Requires Inspection						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B005 - General Learning - 1924 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2283/B005/R1007/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction Area inaccessible					
Underfloor Voids	Non Accessible Area - Area inaccessible - access could not be found.					

Interior

B005 - R0001 - Home Base (84.06 m2)

Ceiling Structures/Linings	Flat AC Sheeting					
	2283/B001/R0027/Ceiling Structures/Linings/S1			No Asbestos Detected		

B005 - R0002 - Practical Activities - 1hb (18.52 m2)

Ceiling Structures/Linings	Vermiculite					
	2283/B001/R0027/Ceiling Structures/Linings/S1			Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Floor Coverings Res/Textile	Vinyl Tiles	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2283/B005/R0002/Floor Coverings Res/Textile/S4			Chrysotile (white asbestos)		

B005 - R0003 - Movement (87.21 m2)

No Asbestos

B005 - R0004 - Movement (1.73 m2)

No Asbestos

B005 - R0005 - Staff Toilet (5.15 m2)

Ceiling Structures/Linings	Vermiculite					
	2283/B001/R0027/Ceiling Structures/Linings/S1			Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B005 - R0006 - Movement (3.09 m2)

No Asbestos

B005 - R0007 - Movement (36.53 m2)

No Asbestos

B005 - R0008 - Movement (5.08 m2)

No Asbestos

B005 - R0009 - General Storeroom (3 m2)

No Asbestos

B005 - R0010 - Movement (20.77 m2)

No Asbestos

B005 - R0011 - Cleaning Distributed Store (4.58 m2)

No Asbestos

B005 - R0012 - Movement (2.64 m2)

No Asbestos

B005 - R0013 - General Storeroom (16.55 m2)

No Asbestos

B005 - R0014 - Home Base (46.6 m2)

No Asbestos

B005 - R0015 - Home Base (47.32 m2)

No Asbestos

B005 - R0016 - Home Base (47.8 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B005 - R0017 - Distribution Board (1.82 m2)				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board	1m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

B005 - R1001 - Practical Activities - 1hb (20.79 m2)

No Asbestos

B005 - R1002 - Home Base (68.71 m2)

No Asbestos

B005 - R1003 - Toilets - Boys/Girls (3.62 m2)

No Asbestos

B005 - R1004 - Security Store (7.58 m2)

No Asbestos

B005 - R1005 - Personal Effects Storage (5.69 m2)

No Asbestos

B005 - R1006 - Movement (5.2 m2)

Ceiling Structures/Linings No Asbestos Found

B005 - R1007 - Movement (91.52 m2)

Ceiling Structures/Linings	Flat AC Sheeting	92m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

2283/B005/R1007/Ceiling Structures/Linings/S11

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B005 - R1008 - Home Base (49.77 m2)

No Asbestos

B005 - R1009 - Home Base (49.83 m2)

No Asbestos

B005 - R1010 - Home Base (49.83 m2)

No Asbestos

B005 - R1011 - Deputy Principal (13.99 m2)

No Asbestos

B005 - R1012 - Staff Room Annexe (18.8 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B006 - Building Services - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B006 - R0001 - General Storeroom (10.88 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B007 - Library/General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B007 - R0001 - Movement (2.94 m2)**

No Asbestos

B007 - R0002 - Staff Toilet (4.97 m2)

No Asbestos

B007 - R0003 - Distribution Board (0.49 m2)

Note: No inspection of live electrical installation.

No Asbestos

B007 - R0004 - Cleaning Distributed Store (3.91 m2)

No Asbestos

B007 - R0005 - K.L.A. Store (19.45 m2)

No Asbestos

B007 - R0006 - Communications Room (7.82 m2)

No Asbestos

B007 - R0007 - Library Office/Workroom (25.73 m2)

No Asbestos

B007 - R0008 - Reading Area (232.05 m2)

No Asbestos

B007 - R0009 - External Movement (90.88 m2)

No Asbestos

B007 - R1001 - Home Base (60.81 m2)

No Asbestos

B007 - R1002 - General Storeroom (6.19 m2)

No Asbestos

B007 - R1003 - Practical Activities - 1hb (18.8 m2)

No Asbestos

B007 - R1004 - Withdrawal Space - 2hb (11.87 m2)

No Asbestos

B007 - R1005 - Home Base (60.52 m2)

No Asbestos

B007 - R1006 - General Storeroom (5.96 m2)

No Asbestos

B007 - R1007 - Practical Activities - 1hb (18.66 m2)

No Asbestos

B007 - R1008 - External Movement (87.99 m2)

No Asbestos

B007 - R1009 - Home Base (59.53 m2)

No Asbestos

B007 - R1010 - General Storeroom (5.71 m2)

No Asbestos

B007 - R1011 - Practical Activities - 1hb (18.69 m2)

No Asbestos

B007 - R1012 - Withdrawal Space - 1hb (9.06 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B007 - R1013 - Toilets - Girls (7.53 m2)

No Asbestos

B007 - R1014 - Toilets - Boys (7.9 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017