

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kinchela Public School (2303)
Region : North Coast
State Electorate : Oxley
Local Government Area : Kempsey

Initial Survey : Noel Arnold & Associates : 01 - May - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Staff Facilities/Library - 1921 - Timber (Timber)**Exterior**

Wall Cladding	Flat AC Sheeting	40m2	North, South, East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/Wall Cladding/S1					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/Eaves Linings/S15					Chrysotile (white asbestos)
Downpipes	Fibre Cement Casting (Monocrete)	10m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/Downpipes/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2303/B00A/R0001/Ceiling Structures/Linings/S2					
Electrical Mounting Board	Resinous Board	2Unit	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/R0001/Electrical Mounting Board/S21					Chrysotile (white asbestos)

B00A - R0002 - Reading Area

Wall Linings Internal	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/R0014/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00A - R0003 - Movement

Manhole Hatch	Flat AC Sheeting	1m2	Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2303/B00A/R0003/Manhole Hatch/S22					Chrysotile (white asbestos)
Ceiling Void	AC Fragments/Debris	1m2	Adjacent Manhole above Room R0003	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	2303/B00A/R0003/Ceiling Void/S23					Chrysotile (white asbestos)

B00A - R0004 - K.L.A. Store

No Asbestos

B00A - R0005 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/R0009/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0006 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/R0009/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00A - R0007 - General Storeroom

No Asbestos

B00A - R0008 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	2303/B00A/R0008/Floor Coverings Res/Textile/S6					

B00A - R0009 - Staff Shower/Change

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00A/R0009/Wall Linings Internal/S4					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2303/B00A/R0001/Ceiling Structures/Linings/S2					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2303/B00A/R0009/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R0010 - Staff Kitchen						
No Asbestos						
B00A - R0011 - Library Office/Workroom						
No Asbestos						
B00A - R0012 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
2303/B00A/R0001/Ceiling Structures/Linings/S2					No Asbestos Detected	
B00A - R0013 - General Storeroom						
No Asbestos						
B00A - R0014 - Reading Area						
Ceiling Structures/Linings	Flat AC Sheeting					
2303/B00A/R0001/Ceiling Structures/Linings/S2					No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2303/B00A/R0014/Wall Linings Internal/S3					Chrysotile (white asbestos)	
B00A - R0015 - Plant						
Wall Linings Internal	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2303/B00A/R0014/Wall Linings Internal/S3					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting					
2303/B00A/R0001/Ceiling Structures/Linings/S2					No Asbestos Detected	
B00A - R0016 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
2303/B00A/R0001/Ceiling Structures/Linings/S2					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Staff Facilities - 1978 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 2303/B00B/Eaves Linings/S16	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting 2303/B00B/Wall Cladding/S10					No Asbestos Detected
Underfloor Void	No Asbestos Found					
Ceiling Void	AC Fragments/Debris 2303/B00B/Ceiling Void/S24	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00B - R0001 - Cleaning Distributed Store**

Wall Linings Internal	Flat AC Sheeting 2303/B00B/R0001/Wall Linings Internal/S11					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00B - R0002 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 2303/B00B/R0001/Wall Linings Internal/S11					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00B - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 2303/B00B/R0003/Floor Coverings Res/Textile/S12					No Asbestos Detected
--------------------------------	--	--	--	--	--	-----------------------------

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 2303/B00B/R0001/Wall Linings Internal/S11					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00B - R0006 - Home Base

Wall Linings Internal	Flat AC Sheeting 2303/B00B/R0001/Wall Linings Internal/S11					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00B - R0007 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 2303/B00B/R0003/Floor Coverings Res/Textile/S12					No Asbestos Detected
--------------------------------	--	--	--	--	--	-----------------------------

Wall Linings Internal	Flat AC Sheeting 2303/B00B/R0001/Wall Linings Internal/S11					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00B - R0008 - Staff Room

No Asbestos

B00B - R0009 - Staff Room Annexe

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Administration/General Learning - 1978 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00C/Gable Verge Lining/S19				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00C/Eaves Linings/S17				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Void	No Asbestos Found					

Interior

B00C - R0001 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2303/B00C/R0001/Ceiling Structures/Linings/S13				Chrysotile (white asbestos)	

B00C - R0002 - Clerical Office

No Asbestos

B00C - R0003 - Principal

No Asbestos

B00C - R0004 - Entry Vestibule

No Asbestos

B00C - R0005 - Home Base Store

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	2303/B00C/R0008/Floor Coverings Res/Textile/S14				No Asbestos Detected	

B00C - R0008 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles					
	2303/B00C/R0008/Floor Coverings Res/Textile/S14				No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1974 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2303/B00D/Eaves Linings/S18	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Crocidolite (blue asbestos)
Downpipes	Fibre Cement Casting (Monocrete) 2303/B00A/Downpipes/S7	20m	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Void	AC Fragments/Debris 2303/B00D/Ceiling Void/S25					No Asbestos Detected

Interior**B00D - R0001 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting 2303/B00D/R0001/Ceiling Structures/Linings/S20	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Crocidolite (blue asbestos)
----------------------------	--	------	------------	--------------------	---------	--

B00D - R0002 - External Movement

No Asbestos

B00D - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 2303/B00D/R0003/Partition Walls (Cubicles)/S8	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

B00D - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 2303/B00D/R0003/Partition Walls (Cubicles)/S8	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

B00D - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1952 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00E - R0001 - External Movement

No Asbestos

B00E - R0002 - External Movement

No Asbestos

B00E - R0003 - Canteen

Wall Linings Internal	Flat AC Sheeting 2303/B00E/R0003/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Shed - 1978 - Timber Shed (Timber Shed)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00F - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Shed

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0001 - Shed

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017