

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kirkton Public School (2314)
Region : Hunter/Central Coast
State Electorate : Upper Hunter
Local Government Area : Singleton

Initial Survey : Noel Arnold & Associates : 27 - May - 2008
Reviewed By : AECOM : 29 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Library - 1920 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction 3.98m, access point in AR0004.					
Eaves Linings	Flat AC Sheeting 2314/B00A/Eaves Linings/S1					No Asbestos Detected
Underfloor Voids	Loose FC sheets stored under AR0004. 2314/B00A/Underfloor Voids/S2					No Asbestos Detected

Interior

B00A - R0001 - Clerical Office

No Asbestos

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Reading Area

No Asbestos

B00A - R0005 - Staff Room

No Asbestos

B00A - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2314/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1925 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Height Restriction 3.89m BR0004

Underfloor Voids - Packing to Floor Joists
 No Asbestos Found

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - General Storeroom

No Asbestos

B00B - R0003 - Home Base

No Asbestos

B00B - R0004 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1960 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible Slab on ground no access point					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible Flat roof no access point					
Eaves Linings	Flat AC Sheeting	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2314/B00C/R0004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

Interior

B00C - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2314/B00C/R0004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00C - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2314/B00C/R0004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00C - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2314/B00C/R0004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00C - R0004 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2314/B00C/R0004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1920 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Slab on ground no access point

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00D - R0001 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 1920 - Steel (Steel)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Slab on ground no access point

Interior

B00E - R0001 - Cleaning Distributed Store

No Asbestos

B00E - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Communal Facilities - 1920 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Slab on ground no access point

Interior

B00F - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00G - R0001 - External Movement**

No Asbestos

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - Home Base Store

No Asbestos

B00G - R0005 - Withdrawal Space - 2hb

No Asbestos

B00G - R0006 - Practical Activities - 1hb

No Asbestos

B00G - R0007 - Home Base

No Asbestos

B00G - R0008 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Storage - 2008 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Slab on ground no access point

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Administration - 1950 - Timber (Timber)

Exterior

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

Interior

B00I - R0001 - External Movement

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0002 - Entry Vestibule

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0003 - External Movement

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0004 - Toilets-Unisex

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0005 - Toilet - Lobby

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0006 - Staff Toilet

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0007 - External Movement

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0008 - Staff Kitchen

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0009 - Staff Room

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0010 - General Storeroom

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0011 - General Storeroom

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0012 - Clerical Office

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0013 - Interview

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0014 - Principal

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00I - R0015 - Movement

Recently Modified Space	Requires Inspection
-------------------------	---------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017