

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kitchener Public School (2315)
Region : Hunter/Central Coast
State Electorate : Cessnock
Local Government Area : Cessnock

Initial Survey : Noel Arnold & Associates : 15 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Library - 1920 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - General Storeroom

No Asbestos

B00A - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2315/B00A/R0009/Ceiling Structures/Linings/S1					No Asbestos Detected

B00A - R0003 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2315/B00A/R0003/Floor Coverings Res/Textile/S2					Chrysotile (White asbestos)

B00A - R0004 - Reading Area

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Clerical Office

No Asbestos

B00A - R0007 - Home Base

No Asbestos

B00A - R0008 - Principal

No Asbestos

B00A - R0009 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2315/B00A/R0009/Ceiling Structures/Linings/S1					No Asbestos Detected

B00A - R0010 - Clerical Office

No Asbestos

B00A - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2315/B00A/R0009/Ceiling Structures/Linings/S1					No Asbestos Detected

B00A - R0012 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1950 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00B - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2315/B00B/R0001/Ceiling Structures/Linings/S3					
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2315/B00B/R0001/Partition Walls (Cubicles)/S4					
	Chrysotile (White asbestos) , Amosite (Brown asbestos)					

B00B - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2315/B00B/R0001/Ceiling Structures/Linings/S3					
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2315/B00B/R0001/Partition Walls (Cubicles)/S4					
	Chrysotile (White asbestos) , Amosite (Brown asbestos)					

B00B - R0003 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2315/B00B/R0001/Ceiling Structures/Linings/S3					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Other-Community Use - 1950 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00C - R0001 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	2315/B00C/R0003/Ceiling Structures/Linings/S5			No Asbestos Detected
----------------------------	------------------	---	--	--	-----------------------------

B00C - R0002 - Staff Kitchen

Ceiling Structures/Linings	Flat AC Sheeting	2315/B00C/R0003/Ceiling Structures/Linings/S5			No Asbestos Detected
----------------------------	------------------	---	--	--	-----------------------------

B00C - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	2315/B00C/R0003/Ceiling Structures/Linings/S5			No Asbestos Detected
----------------------------	------------------	---	--	--	-----------------------------

B00C - R0004 - Other-Community Use

Ceiling Structures/Linings	Flat AC Sheeting	2315/B00C/R0003/Ceiling Structures/Linings/S5			No Asbestos Detected
----------------------------	------------------	---	--	--	-----------------------------

B00C - R0005 - Raised Platform

Ceiling Structures/Linings	Flat AC Sheeting	2315/B00C/R0003/Ceiling Structures/Linings/S5			No Asbestos Detected
----------------------------	------------------	---	--	--	-----------------------------

B00C - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2315/B00C/R0003/Ceiling Structures/Linings/S5			No Asbestos Detected
----------------------------	------------------	---	--	--	-----------------------------

B00C - R0007 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2315/B00C/R0003/Ceiling Structures/Linings/S5			No Asbestos Detected
----------------------------	------------------	---	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Special Purpose (Craft Art Science Tas Etc) - 2008 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - External Movement

No Asbestos

B00E - R0002 - Practical Activities - 1hb

No Asbestos

B00E - R0003 - Home Base Store

No Asbestos

B00E - R0004 - Home Base

No Asbestos

B00E - R0005 - Withdrawal Space - 2hb

No Asbestos

B00E - R0006 - Home Base

No Asbestos

B00E - R0007 - Home Base Store

No Asbestos

B00E - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 505 - D13484 - Admin Staff/Principal/Secure Store : Placement Date - 10/10/2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Principal

No Asbestos Found.

R3 - Staff Room

No Asbestos Found.

R4 - Security Store

No Asbestos Found.

R5 - Clerical Office

No Asbestos Found.

OS 844 - D16341 - Country Toilet - Reltc - Boys/Girls : Placement Date - 2/05/1997

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

Interior

R1 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

R2 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017