

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kurmond Public School (2340)  
**Region :** Western Sydney  
**State Electorate :** Hawkesbury  
**Local Government Area :** Hawkesbury

**Initial Survey :** Noel Arnold & Associates : 12 - Jun - 2008  
**Reviewed By :** Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00A - R0001 - Movement**

No Asbestos

**B00A - R0002 - Practical Activities - 1hb**

No Asbestos

**B00A - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0005 - Movement**

No Asbestos

**B00A - R0006 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0007 - Movement**

No Asbestos

**B00A - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0010 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1920 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 2340/B00B/Eaves Linings/S5					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00B - R0001 - Staff Room Annexe**

Wall Linings Internal	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>

**B00B - R0002 - Withdrawal Space - 1hb**

In-fill-panel	Flat AC Sheeting 2340/B00B/R0002/In-fill-panel/S2					<b>No Asbestos Detected</b>
---------------	--	--	--	--	--	-----------------------------

**B00B - R0003 - Withdrawal Space - 1hb**

No Asbestos

**B00B - R0004 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	22m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>

**B00B - R0005 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	14m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles 2340/B00B/R0005/Floor Coverings Res/Textile/S3	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>

**B00B - R0006 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	14m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>

**B00B - R0007 - Movement**

Wall Linings Internal	Flat AC Sheeting 2340/B00B/R0007/Wall Linings Internal/S1	14m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (White asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1976 - Timber (Timber)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00C - R0001 - Home Base**

No Asbestos

**B00C - R0002 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1976 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Flat Roof	No Asbestos Found

**Interior**

**B00D - R0001 - Canteen**

Floor Coverings Res/Textile	Vinyl Tiles					
		2340/B00D/R0001/Floor Coverings Res/Textile/S11				<b>No Asbestos Detected</b>

**B00D - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
		2340/B00D/R0002/Ceiling Structures/Linings/S12				<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1976 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	16m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00E/Eaves Linings/S6				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00E/Gable Verge Lining/S7				Chrysotile (white asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00E - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00E/R0001/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

**B00E - R0002 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00E/R0006/Floor Coverings Res/Textile/S4				Chrysotile (White asbestos)	

**B00E - R0003 - Toilets - Boys/Girls**

No Asbestos

**B00E - R0004 - Home Base**

No Asbestos

**B00E - R0005 - Home Base**

No Asbestos

**B00E - R0006 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00E/R0006/Floor Coverings Res/Textile/S4				Chrysotile (White asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Pupil Facilities - 1976 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00E/Eaves Linings/S6				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00E/Gable Verge Lining/S7				Chrysotile (white asbestos)	
Ceiling Void	No Asbestos Found					

**Interior**

**B00F - R0005 - Toilets - Girls**

No Asbestos

**B00F - R0006 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00F/R0008/Ceiling Structures/Linings/S10				Chrysotile (white asbestos)	

**B00F - R0007 - Access Shower/Toilet**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2340/B00F/R0007/Ceiling Structures/Linings/S9					

**B00F - R0008 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2340/B00F/R0008/Ceiling Structures/Linings/S10				Chrysotile (white asbestos)	

**B00F - R0009 - Cleaning Distributed Store**

No Asbestos

**B00F - R0010 - Staff Toilet**

No Asbestos

**B00F - R0011 - Toilets - Boys**

No Asbestos

**B00F - R0012 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Shed - 1976 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Void      No Asbestos Found

**Interior**

**B00G - R0001 - Sports Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Other - 2008 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00H - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Library - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Reading Area**

No Asbestos

**B00J - R0002 - Library Office/Workroom**

No Asbestos

**B00J - R0003 - Communications Room**

No Asbestos

**B00J - R0004 - K.L.A. Store**

No Asbestos

**B00J - R0005 - External Movement**

No Asbestos

**B00J - R0006 - Main Switch Board**

No Asbestos

**B00J - R0007 - Movement**

No Asbestos

**B00J - R0008 - Staff Toilet**

No Asbestos

**B00J - R0009 - Cleaning Distributed Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 603 - D10160 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 19/11/2011**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D11659 - Learning Unit - Standard With P.A.A. : Placement Date - 16/06/2009**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 810 - D13024 - FSU/Shelter/Stores : Placement Date - 16/02/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Canteen**

No Asbestos Found.

**R2 - Covered Area**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**R4 - Sports Store**

No Asbestos Found.

**R5 - Garden Store**

No Asbestos Found.

**R6 - Change Room**

No Asbestos Found.

**R7 - Store**

No Asbestos Found.

**OS 601 - D14314 - Learning Unit - Standard/Withdrawal : Placement Date - 8/01/1996**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 503 - D14331 - Admin Lib Staff/Principal/Clerk/Store : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				23.04 m2
<b>Interior</b>						
<b>R1 - Clerical Office</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				24 m2
<b>R2 - Principal</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
<b>R3 - Staff Toilet</b>						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
<b>R4 - Staff Toilet</b>						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
<b>R5 - Reading Area</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R6 - Security Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R7 - Staff Room</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				27 m2
<b>R8 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				6 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

2340\_ASB\_270513\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017