

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kurnell Public School (2341)
Region : Sydney
State Electorate : Cronulla
Local Government Area : Sutherland

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00A - R0001 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0002 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0004 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0006 - Sick Bay

No Asbestos

B00A - R0007 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - External Movement

No Asbestos

B00A - R0009 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0010 - External Movement

No Asbestos

B00A - R0011 - Duplicating Workroom

No Asbestos

B00A - R0012 - Security Store

No Asbestos

B00A - R0013 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Main Switch Board

No Asbestos

B00A - R0015 - Cleaning Distributed Store

No Asbestos

B00A - R0016 - Staff Toilet

No Asbestos

B00A - R0017 - Staff Toilet

No Asbestos

B00A - R0018 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1956 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 2341/B00B/Eaves Linings/S5	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	Vinyl Tile debris 2341/B00B/Underfloor Voids/S15					No Asbestos Detected

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Home Base

No Asbestos

B00B - R0004 - Home Base Store

No Asbestos

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0007 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Library - 1956 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 2341/B00C/Eaves Linings/S6	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting 2341/B00C/Gable Verge Lining/S10	30m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access - No Manhole located in Building					

Interior**B00C - R0001 - General Storeroom**

No Asbestos

B00C - R0002 - Reading Area

No Asbestos

B00C - R0003 - Library Office/Workroom

No Asbestos

B00C - R0004 - Home Base Store

No Asbestos

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1994 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2341/B00D/Eaves Linings/S7					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - External Movement	No Asbestos					
B00D - R0002 - Toilets - Boys	No Asbestos					
B00D - R0003 - Sports Store	No Asbestos					
B00D - R0004 - Plant	No Asbestos					
B00D - R0005 - P.E. Store	No Asbestos					
B00D - R0006 - Hall Chair Store	No Asbestos					
B00D - R0007 - Disabled Toilet	No Asbestos					
B00D - R0008 - General Storeroom	No Asbestos					
B00D - R0009 - Communal Space	No Asbestos					
B00D - R0010 - Raised Platform	No Asbestos					
B00D - R0011 - Distribution Board	No Asbestos					Note: No inspection of live electrical installation.
B00D - R0012 - Plant	No Asbestos					
B00D - R0013 - General Assistant/Bulk Store	No Asbestos					
B00D - R0014 - Cleaning Supplies	No Asbestos					
B00D - R0015 - Cleaning Supplies	No Asbestos					
B00D - R0016 - General Storeroom	No Asbestos					
B00D - R0017 - Movement	No Asbestos					
B00D - R0018 - Toilets - Girls	No Asbestos					
B00D - R0019 - Shower/Change	No Asbestos					
B00D - R0020 - External Movement	No Asbestos					
B00D - R0021 - External Movement	No Asbestos					
B00D - R0022 - Canteen						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R0023 - Canteen Office/Store

No Asbestos

B00D - R0024 - Canteen Office/Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1956 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2341/B00E/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access - Manhole has been screwed shut with special screws - No access possible					

Interior

B00E - R0001 - Home Base

No Asbestos

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Home Base Store

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2341/B00E/R0005/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0006 - Home Base Store

No Asbestos

B00E - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0008 - Home Base Store

No Asbestos

B00E - R0009 - Home Base

No Asbestos

B00E - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2341/B00E/R0010/Ceiling Structures/Linings/S13				No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1976 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2341/B00F/Eaves Linings/S9				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	30m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2341/B00F/Gable Verge Lining/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access - Manhole has been screwed shut with special screws - unable to open manhole for inspection					

Interior

B00F - R0001 - Home Base

No Asbestos

B00F - R0002 - Home Base Store

No Asbestos

B00F - R0003 - Special Programs Room

No Asbestos

B00F - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0005 - Movement

No Asbestos

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Home Base Store

No Asbestos

B00F - R0009 - Withdrawal Space - 1hb

No Asbestos

B00F - R0010 - Home Base

No Asbestos

B00F - R0011 - Movement

No Asbestos

B00F - R0012 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2341/B00F/R0012/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	

B00F - R0013 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2341/B00F/R0013/Ceiling Structures/Linings/S3					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1956 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00G - R0001 - Cleaning Supplies

No Asbestos

B00G - R0002 - Toilets - Girls

No Asbestos

B00G - R0003 - Toilets - Girls

No Asbestos

B00G - R0004 - General Storeroom

No Asbestos

B00G - R0005 - Toilets - Boys

No Asbestos

B00G - R0006 - Toilets - Boys

No Asbestos

B00G - R0007 - Garden Store

No Asbestos

B00G - R0008 - General Storeroom

No Asbestos

B00G - R0009 - Craft Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - Reading Area

No Asbestos

B00H - R0002 - Library Office/Workroom

No Asbestos

B00H - R0003 - K.L.A. Store

No Asbestos

B00H - R0004 - Main Switch Board Cupboard

No Asbestos

B00H - R0005 - Cleaning Distributed Store

No Asbestos

B00H - R0006 - Toilet - Lobby

No Asbestos

B00H - R0007 - Staff Toilet

No Asbestos

B00H - R0008 - General Storeroom

No Asbestos

B00H - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Play Shed

Exterior

Underfloor Void	AC Fragments/Debris 2341/B001/Underfloor Void/S12					No Asbestos Detected
Ceiling Void	No Asbestos Found 2341/B001/Underfloor Void/S12					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 2341/B001/Wall Cladding/S14					No Asbestos Detected

Interior

B001 - R0001 - Play Shed

Wall Linings Internal	Flat AC Sheeting 2341/B001/Wall Cladding/S14					No Asbestos Detected
-----------------------	---	--	--	--	--	----------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2341_ASB_261112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017