


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kemp's Creek Public School (3615)  
**Region :** South Western Sydney  
**State Electorate :** Mulgoa  
**Local Government Area :** Liverpool

**Initial Survey :** Noel Arnold & Associates : 19 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Library - 1981 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Gable Verge Lining	Flat AC Sheeting	25m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
3615/B00A/Gable Verge Lining/S7					Chrysotile (white asbestos)	

**Interior****B00A - R0001 - Staff Room**

No Asbestos

**B00A - R0002 - Movement**

No Asbestos

**B00A - R0003 - Staff Toilet**

No Asbestos

**B00A - R0004 - Staff Toilet**

No Asbestos

**B00A - R0005 - Principal**

No Asbestos

**B00A - R0006 - Cleaning Distributed Store**

Floor Coverings Res/Textile	Vinyl Tiles					
3615/B00A/R0006/Floor Coverings Res/Textile/S1					No Asbestos Detected	

**B00A - R0007 - Entry Vestibule**

No Asbestos

**B00A - R0008 - Clerical Office**

No Asbestos

**B00A - R0009 - Duplicating Workroom**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3615/B00A/R0009/Ceiling Structures/Linings/S2					Chrysotile (White asbestos)	

**B00A - R0010 - Community Clinic**

Floor Coverings Res/Textile	Vinyl Tiles					
3615/B00A/R0006/Floor Coverings Res/Textile/S1					No Asbestos Detected	

**B00A - R0011 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles					
3615/B00A/R0006/Floor Coverings Res/Textile/S1					No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3615/B00A/R0009/Ceiling Structures/Linings/S2					Chrysotile (White asbestos)	

**B00A - R0012 - Main Switch Board**

No Asbestos

**B00A - R0013 - Movement**

No Asbestos

**B00A - R0014 - Movement**

No Asbestos

**B00A - R0015 - Library Office/Workroom**

No Asbestos

**B00A - R0016 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0017 - Deputy Principal</b>						
No Asbestos						
<b>B00A - R0018 - Security Store</b>						
No Asbestos						
<b>B00A - R0019 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0020 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0021 - Reading Area</b>						
No Asbestos						
<b>B00A - R0022 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities/Pupil Facilities - 1981 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00B/Gable Verge Lining/S8					<b>Chrysotile (white asbestos)</b>

**Interior****B00B - R0001 - Canteen Office/Store**

Electrical Backing Board No Asbestos Found

**B00B - R0002 - Staff Toilet**

No Asbestos

**B00B - R0003 - Canteen Office/Store**

No Asbestos

**B00B - R0004 - Canteen**

No Asbestos

**B00B - R0005 - Movement**

No Asbestos

**B00B - R0006 - Garden Store**

Wall Linings Internal	Flat AC Sheeting	40m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00B/R0006/Wall Linings Internal/S3					<b>Chrysotile (White asbestos)</b>

**B00B - R0007 - Garden Store**

Wall Linings Internal	Flat AC Sheeting	20m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00B/R0006/Wall Linings Internal/S3					<b>Chrysotile (White asbestos)</b>

**B00B - R0008 - Movement**

No Asbestos

**B00B - R0009 - Movement**

No Asbestos

**B00B - R0015 - Hall Chair Store**

Floor Coverings Res/Textile	Vinyl Tiles					
	3615/B00A/R0006/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00B - R0016 - Toilets - Boys**

No Asbestos

**B00B - R0017 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Backing Board No Asbestos Found

**B00B - R0018 - Entry Vestibule**

No Asbestos

**B00B - R0019 - Cleaning Distributed Store**

No Asbestos

**B00B - R0020 - Toilets - Girls**

No Asbestos

**B00B - R0021 - Lift**

No Asbestos

**B00B - R0023 - Raised Platform**

No Asbestos

**B00B - R0024 - Access Shower/Toilet**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0025 - Communal Space</b>						
No Asbestos						
<b>B00B - R0026 - External Movement</b>						
No Asbestos						
<b>B00B - R0027 - External Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1981 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Gable Verge Lining	Flat AC Sheeting	40m2	East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
3615/B00C/Gable Verge Lining/S9					<b>Chrysotile (white asbestos)</b>	

**Interior**

**B00C - R0001 - Home Base**

No Asbestos

**B00C - R0002 - Toilets - Boys/Girls**

No Asbestos

**B00C - R0003 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0004 - Toilets - Boys/Girls**

No Asbestos

**B00C - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	6m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
3615/B00C/R0005/Wall Linings Internal/S6					<b>Chrysotile (White asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
3615/B00C/R0005/Wall Linings Internal/S6					<b>Chrysotile (White asbestos)</b>	

Electrical Mounting Board No Asbestos Found

**B00C - R0006 - Movement**

No Asbestos

**B00C - R0007 - Home Base**

No Asbestos

**B00C - R0008 - Movement**

No Asbestos

**B00C - R0009 - Practical Activities - 1hb**

No Asbestos

**B00C - R0010 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning/Building Services - 1981 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area					
	- No Voids					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	30m2	East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00D/Gable Verge Lining/S10					<b>Chrysotile (white asbestos)</b>

**Interior**

**B00D - R0001 - Sports Store**

Floor Coverings Res/Textile	Vinyl Tiles					
	3615/B00A/R0006/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00D - R0002 - External Movement**

No Asbestos

**B00D - R0003 - Home Base**

No Asbestos

**B00D - R0004 - Withdrawal Space - 1hb**

No Asbestos

**B00D - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00C/R0005/Wall Linings Internal/S6					<b>Chrysotile (White asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	6m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00C/R0005/Wall Linings Internal/S6					<b>Chrysotile (White asbestos)</b>

Electrical Backing Board No Asbestos Found

**B00D - R0006 - Movement**

No Asbestos

**B00D - R0007 - Home Base**

No Asbestos

**B00D - R0008 - Movement**

No Asbestos

**B00D - R0009 - Practical Activities - 1hb**

No Asbestos

**B00D - R0010 - Cleaning Distributed Store**

Floor Coverings Res/Textile	Vinyl Tiles					
	3615/B00A/R0006/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00D - R0011 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles					
	3615/B00A/R0006/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00D/R0011/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Pupil Facilities - 1981 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	40m2	East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00E/Gable Verge Lining/S12					<b>Chrysotile (white asbestos)</b>

**Interior**

**B00E - R0001 - Movement**

No Asbestos

**B00E - R0002 - Toilets - Boys**

No Asbestos

**B00E - R0003 - Toilets - Girls**

No Asbestos

**B00E - R0004 - Movement**

No Asbestos

**B00E - R0005 - Home Base**

No Asbestos

**B00E - R0006 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0007 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00C/R0005/Wall Linings Internal/S6					<b>Chrysotile (White asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	6m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3615/B00C/R0005/Wall Linings Internal/S6					<b>Chrysotile (White asbestos)</b>

Electrical Backing Board No Asbestos Found

**B00E - R0008 - Movement**

No Asbestos

**B00E - R0009 - Home Base**

No Asbestos

**B00E - R0010 - Movement**

No Asbestos

**B00E - R0011 - Practical Activities - 1hb**

No Asbestos





Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Library - 1998 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Eaves Linings	Flat AC Sheeting 3615/Build+1/Room+1/Ceiling Structures/Linings/S5					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					

**Interior**

**B00F - R0001 - Reading Area**

No Asbestos

**B00F - R0002 - Library Office/Workroom**

No Asbestos

**B00F - R0003 - Communications Room**

No Asbestos

**B00F - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 3615/Build+1/Room+1/Ceiling Structures/Linings/S5					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

**Interior**

**B00G - R0001 - External Movement**

No Asbestos

**B00G - R0002 - Canteen**

No Asbestos

**B00G - R0003 - Canteen Office/Store**

No Asbestos

**B00G - R0004 - Practical Activities**

No Asbestos

**B00G - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00G - R0006 - Home Base Store**

No Asbestos

**B00G - R0007 - Home Base**

No Asbestos

**B00G - R0008 - Main Switch Board**

No Asbestos

**B00G - R0009 - Movement**

No Asbestos

**B00G - R0010 - Special Programs Room**

No Asbestos

**B00G - R0011 - Special Programs Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017