


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Killara Public School (3918)
Region : Northern Sydney
State Electorate : Ku-ring-gai
Local Government Area : Ku-Ring-Gai

Initial Survey : Noel Arnold & Associates : 23 - Jan - 2008
Reviewed By : Parsons Brinckerhoff : 16 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1954 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids	Fibre Cement Pipe 3918/B00A/Underfloor Voids/S6	8Unit	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00A - R0001 - Toilets - Boys/Girls**

No Asbestos

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Movement

Wall Linings Internal	Flat AC Sheeting 3918/B00A/R0004/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Personal Effects Storage

No Asbestos

B00A - R0007 - Personal Effects Storage

No Asbestos

B00A - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction >3m.**B00A - R0011 - Security Store**

No Asbestos

B00A - R0012 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles 3918/B00A/R0012/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00A - R0013 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	-------------	--------------------	---------	--------------------

3918/B00A/R0013/Ceiling Structures/Linings/S4

Chrysotile (white asbestos)**B00A - R0014 - Principal**

No Asbestos

B00A - R0019 - Movement

No Asbestos

B00A - R0021 - Home Base

No Asbestos

B00A - R0022 - Sick Bay

No Asbestos

B00A - R0023 - General Storeroom

No Asbestos

B00A - R0024 - Clerical Office

No Asbestos

B00A - R0025 - Entry Vestibule

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0026 - Interview						
No Asbestos						
B00A - R0027 - Communications Cupboard						
No Asbestos						
B00A - R0028 - Clerical Office/Workroom						
No Asbestos						
B00A - R0029 - Movement						
No Asbestos						
B00A - R0030 - External Movement						
No Asbestos						
B00A - R0031 - External Movement						
No Asbestos						
B00A - R9001 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities/Special Purpose - 1954 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					

Interior

B00B - R0001 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3918/B00B/R0004/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	

B00B - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3918/B00B/R0004/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	

B00B - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3918/B00B/R0004/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
3918/B00B/R0003/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	

B00B - R0004 - Special Programs Room

Ceiling Structures/Linings	Flat AC Sheeting	39m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3918/B00B/R0004/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Other-Non-Govt Pre-School - 1954 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Height Restriction >3m.

Underfloor Voids - Slab on Ground
No Asbestos Found

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Other-Non Government Pre-Sch

No Asbestos

B00C - R0003 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0004 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0005 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0006 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0007 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0008 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0009 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0010 - Other-Non Government Pre-Sch

No Asbestos

B00C - R0011 - Other-Non Government Pre-Sch

No Asbestos

B00C - R0012 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0013 - Other-Non Government Pre-Sch

No Asbestos

B00C - R0014 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile Vinyl Sheet
3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00C - R0015 - Other-Non Government Pre-Sch

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings
Res/Textile

Vinyl Sheet

3918/B00C/R0014/Floor Coverings Res/Textile/S10

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Other-Non-Govt Pre-School - 1954 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Height Restriction >3m.

Underfloor Voids - Slab on Ground
 No Asbestos Found

Interior

B00D - R0001 - Other-Non Government Pre-Sch

Ceiling Structures/Linings
 Flat AC Sheeting
 3918/B00D/R0001/Ceiling Structures/Linings/S11
No Asbestos Detected

B00D - R0002 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile
 Vinyl Sheet
 3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00D - R0003 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile
 Vinyl Sheet
 3918/B00C/R0014/Floor Coverings Res/Textile/S10
No Asbestos Detected

B00D - R0004 - Other-Non Government Pre-Sch

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Communal Facilities - 1954 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Height Restriction >3m.

Underfloor Voids - Packing to Floor Joists
 No Asbestos Found

Interior

B00E - R0001 - Canteen

No Asbestos

B00E - R0002 - Raised Platform

No Asbestos

B00E - R0003 - Home Base

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Home Base

No Asbestos

B00E - R0006 - Practical Activities - 1hb

Hot Metal Workbench	Compressed AC Sheet	6m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------	---------------------	-----	--------------	--------------------	---------	--------------------

3918/B00E/R0006/Hot Metal Workbench/S3

Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - Home Base Store

No Asbestos

B00F - R0002 - Practical Activities

No Asbestos

B00F - R0003 - Home Base

No Asbestos

B00F - R0004 - Withdrawal Space - 2hb

No Asbestos

B00F - R0005 - Home Base

No Asbestos

B00F - R0006 - Practical Activities

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Home Base Store

No Asbestos

B00F - R0009 - Practical Activities - S - 1hb

No Asbestos

B00F - R0010 - Special Programs Room - Type 1

No Asbestos

B00F - R0011 - Access Shower/Toilet

No Asbestos

B00F - R0012 - Toilets - Girls

No Asbestos

B00F - R0013 - Toilets - Boys

No Asbestos

B00F - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - General Learning/Pupil Facilities - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00G - R0001 - Home Base Store

No Asbestos

B00G - R0002 - Home Base

No Asbestos

B00G - R0003 - Practical Activities

No Asbestos

B00G - R0004 - Withdrawal Space - 2hb

No Asbestos

B00G - R0005 - Practical Activities

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Home Base Store

No Asbestos

B00G - R0009 - Practical Activities

No Asbestos

B00G - R0010 - Home Base

No Asbestos

B00G - R0011 - Withdrawal Space - 2hb

No Asbestos

B00G - R0012 - Practical Activities

No Asbestos

B00G - R0013 - Home Base

No Asbestos

B00G - R0014 - Home Base Store

No Asbestos

B00G - R0015 - Home Base Store

No Asbestos

B00G - R0016 - Practical Activities

No Asbestos

B00G - R0017 - Home Base

No Asbestos

B00G - R0018 - Canteen Office/Store

No Asbestos

B00G - R0019 - Canteen

No Asbestos

B00G - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library/Staff Facilities - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - Library Office/Workroom

No Asbestos

B00H - R0002 - K.L.A. Store

No Asbestos

B00H - R0003 - Reading Area

No Asbestos

B00H - R0004 - Staff Room

No Asbestos

B00H - R0005 - General Storeroom

No Asbestos

B00H - R0006 - Access Shower/Toilet

No Asbestos

B00H - R0007 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00I - R0001 - Covered Outdoor Learning Area**

No Asbestos

B00I - R0002 - Communal Space

No Asbestos

B00I - R0003 - Raised Platform

No Asbestos

B00I - R0004 - Chair Storeroom

No Asbestos

B00I - R0005 - Communal/Performance Store

No Asbestos

B00I - R0006 - P.E. Store

No Asbestos

B00I - R0007 - Toilet - Lobby

No Asbestos

B00I - R0008 - Toilets - Girls

No Asbestos

B00I - R0009 - Sound Cupboard

No Asbestos

B00I - R0010 - Toilets - Boys

No Asbestos

B00I - R0011 - Toilet - Lobby

No Asbestos

B00I - R0012 - Cleaning Distributed Store

No Asbestos

B00I - R0013 - Main Switch Board

No Asbestos

B00I - R0014 - Toilet - P

No Asbestos

B00I - R0015 - Plant

No Asbestos

B00I - R0016 - Movement

No Asbestos

B00I - R0017 - Movement

No Asbestos

B00I - R0018 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10004 - Learning Unit - Standard With P.A.A. : Placement Date - 17/12/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11587 - Learning Unit - Standard With P.A.A. : Placement Date - 24/11/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11799 - Learning Unit - Standard With P.A.A. : Placement Date - 13/10/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 840 - D12400 - Girls Toilet : Placement Date - 1/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

OS 841 - D13390 - Boys Toilet : Placement Date - 1/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Boys

No Asbestos Found.

OS 602 - D14013 - Learning Unit - Standard With P.A.A. : Placement Date - 29/03/2012

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14186 - Learning Unit - Standard With P.A.A. : Placement Date - 18/06/2010						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14869 - Learning Unit - Standard With P.A.A. : Placement Date - 1/12/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16806 - Learning Unit - Standard With P.A.A. : Placement Date - 1/12/2016						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017