


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Katoomba North Public School (3987)
Region : Western Sydney
State Electorate : Blue Mountains
Local Government Area : Blue Mountains

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Reviewed By : Parsons Brinckerhoff : 14 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1980 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
		3987/B00A/R0001/Floor Coverings Res/Textile/S1				No Asbestos Detected

B00A - R0002 - Main Switch Board

No Asbestos

B00A - R0003 - Principal

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles					
		3987/B00A/R0001/Floor Coverings Res/Textile/S1				No Asbestos Detected

B00A - R0006 - Staff Toilet

No Asbestos

B00A - R0007 - Staff Toilet

No Asbestos

B00A - R0008 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Clerical Office/Workroom

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Duplicating Workroom

No Asbestos

B00A - R0012 - Clerical Office

No Asbestos

B00A - R0013 - Entry Vestibule

No Asbestos

B00A - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
		3987/B00D/R0009/Ceiling Structures/Linings/S17				

B00A - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
		3987/B00D/R0009/Ceiling Structures/Linings/S17				

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Communal Facilities - 1993 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00B - R0001 - Cleaning Supplies**

No Asbestos

B00B - R0002 - General Storeroom

No Asbestos

B00B - R0003 - Disabled Toilet

No Asbestos

B00B - R0004 - Toilets - Girls

No Asbestos

B00B - R0005 - Plant

No Asbestos

B00B - R0006 - P.E. Store

No Asbestos

B00B - R0007 - Hall Chair Store

No Asbestos

B00B - R0008 - Toilets - Boys

No Asbestos

B00B - R0009 - Movement

No Asbestos

B00B - R0010 - Shower/Change

No Asbestos

B00B - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0012 - Communal Space

No Asbestos

B00B - R0013 - Raised Platform

No Asbestos

B00B - R0014 - Movement

No Asbestos

B00B - R0015 - Movement

No Asbestos

B00B - R0016 - Canteen

No Asbestos

B00B - R0017 - Canteen Office/Store

No Asbestos

B00B - R0018 - Cleaning Distributed Store

No Asbestos

B00B - R0019 - Movement

No Asbestos

B00B - R0020 - Sports Store

No Asbestos

B00B - R0021 - General Assistant/Bulk Store

No Asbestos

B00B - R0022 - Garden Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1968 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00C/Eaves Linings/S4					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	5m2	East & West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3987/B00C/Gable Verge Lining/S5					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00C/R0001/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Withdrawal Space - 1hb

No Asbestos

B00C - R0004 - Home Base Store

Ceiling Hatch	Flat AC Sheeting	1m2	Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3987/B00C/R0004/Ceiling Hatch/S20					Chrysotile (white asbestos)

B00C - R0005 - Toilets - Boys/Girls

No Asbestos

B00C - R0006 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00C/R0006/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

B00C - R0007 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00C/R0006/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

B00C - R0008 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00C/R0006/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

B00C - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	10m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00C/R0006/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1980 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00D/Eaves Linings/S6					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00D/R0009/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)

B00D - R0002 - Home Base

No Asbestos

B00D - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00D/R0009/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)

B00D - R0004 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3987/B00A/R0001/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00D - R0005 - Withdrawal Space - 1hb

No Asbestos

B00D - R0006 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3987/B00A/R0001/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00D - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00D/R0009/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)

B00D - R0008 - Home Base

No Asbestos

B00D - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00D/R0009/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)

B00D - R0010 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles					
	3987/B00A/R0001/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00D - R0011 - Practical Activities - 1hb

No Asbestos

B00D - R0012 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	3987/B00A/R0001/Floor Coverings Res/Textile/S1					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Music - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00E/Eaves Linings/S7					Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting	8m2	North (Variable)	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00E/Gable Ends/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Fibre Cement Pipe	1m	Adjacent Manhole hatch from R0002	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	3987/B00E/Ceiling Voids/S9					Chrysotile (white asbestos)

Interior

B00E - R0001 - Practical Activities - 1hb

No Asbestos

B00E - R0002 - Music Store

No Asbestos

B00E - R0003 - General Storeroom

No Asbestos

B00E - R0004 - Craft Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Administration - 1956 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting	40m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3987/B00F/Wall Cladding/S11				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00F/Eaves Linings/S10				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Ramp	Compressed AC Sheet					No Asbestos Detected
	3987/B00F/Ramp/S14					

Interior

B00F - R0001 - Community Clinic

Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00F/R0002/Wall Linings Internal/S19				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00F/R0001/Ceiling Structures/Linings/S18				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	3987/B00F/R0001/Floor Coverings Res/Textile/S2					

B00F - R0002 - Community Clinic

Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00F/R0002/Wall Linings Internal/S19				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00F/R0001/Ceiling Structures/Linings/S18				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	3987/B00F/R0001/Floor Coverings Res/Textile/S2					

B00F - R0003 - Community Clinic

Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00F/R0002/Wall Linings Internal/S19				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00F/R0001/Ceiling Structures/Linings/S18				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	3987/B00F/R0001/Floor Coverings Res/Textile/S2					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Staff Facilities - 1956 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/Eaves Linings/S12					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00G - R0001 - Cleaning Supplies**

No Asbestos

B00G - R0002 - General Storeroom

No Asbestos

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - Home Base

No Asbestos

B00G - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/R0005/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/R0005/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0007 - General Storeroom

No Asbestos

B00G - R0008 - Home Base Store

No Asbestos

B00G - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/R0005/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0012 - Cleaning Distributed Store

No Asbestos

B00G - R0013 - Staff Room

No Asbestos

B00G - R0014 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/R0005/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/R0014/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0015 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/R0005/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3987/B00G/R0014/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0016 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00G - R0017 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3987/B00G/R0005/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0018 - Special Programs Room

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	50m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
3987/B00G/R0019/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)		

B00G - R0019 - Special Programs Room

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	50m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
3987/B00G/R0019/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)		

B00G - R0020 - Special Programs Store

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
3987/B00G/R0019/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-Non-Govt Pre-School - 1933 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Other-Non Government Pre-Sch

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0003 - Other-Non Government Pre-Sch

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0004 - Other-Non Government Pre-Sch

No Asbestos

B00H - R0005 - Kitchen - Pre

No Asbestos

B00H - R0006 - General Storeroom - Pre

No Asbestos

B00H - R0007 - Covered Outdoor Learning Area - Pre

No Asbestos

B00H - R0008 - Practical Activities - Pre

No Asbestos

B00H - R0009 - Practical Activities - Pre

No Asbestos

B00H - R0010 - Toilets - Boys/Girls - Pre

No Asbestos

B00H - R0011 - General Storeroom - Pre

No Asbestos

B00H - R0012 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Library - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B001 - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B001 - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B001 - R0003 - Communications Room

No Asbestos

B001 - R0004 - K.L.A. Store

No Asbestos

B001 - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B001 - R0006 - Cleaning Distributed Store

No Asbestos

B001 - R0007 - Staff Toilet

No Asbestos

B001 - R0008 - Movement

No Asbestos

B001 - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids

Underfloor Voids No Asbestos Found

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - Practical Activities - 1hb

No Asbestos

B00J - R0003 - Home Base Store

No Asbestos

B00J - R0004 - Home Base

No Asbestos

B00J - R0005 - Withdrawal Space - 2hb

No Asbestos

B00J - R0006 - Home Base

No Asbestos

B00J - R0007 - Home Base Store

No Asbestos

B00J - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017