


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kotara South Public School (4203)  
**Region :** Hunter/Central Coast  
**State Electorate :** Charlestown  
**Local Government Area :** Newcastle

**Initial Survey :** Noel Arnold & Associates : 14 - Jan - 2010  
**Reviewed By :** Greencap-NAA : 10 - Feb - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00A - Administration/General Learning - 1969 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
In-fill-panel	Flat AC Sheeting	80m2	South, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00B/In-fill-panel/S14			<b>Chrysotile (white asbestos)</b>		
Ceiling Voids	AC Fragments/Debris	20m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00A - R0001 - Duplicating Workroom (11.77 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00A - R0002 - Movement (46.49 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00A - R0003 - Principal (17.31 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00A - R0004 - Staff Room (38.46 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00A - R0005 - Staff Toilet (4.96 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00A - R0006 - Staff Toilet (4.88 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
<b>B00A - R0007 - Sick Bay (8.47 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
<b>B00A - R0008 - Staff Toilet (2.99 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
<b>B00A - R0009 - Clerical Office (21.25 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0010 - Entry Vestibule (13.86 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0011 - Deputy Principal (13.79 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0012 - Movement (15.35 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4203/B00A/R0012/Ceiling Structures/Linings/S2				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00A - R0013 - General Storeroom (6.69 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4203/B00A/R0012/Ceiling Structures/Linings/S2				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00A - R0014 - Main Switch Board (3.88 m2)</b>						
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Electrical Hazard</b>					
<b>B00A - R0015 - Cleaning Supplies (10.93 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4203/B00A/R0012/Ceiling Structures/Linings/S2				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00A - R0016 - Movement (105.44 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	4203/B00A/R0012/Ceiling Structures/Linings/S2				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00A - R0017 - Home Base (59.43 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0018 - General Storeroom (4.38 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0019 - Movement (21.19 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0020 - Home Base Store (4.31 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0021 - Home Base (59.65 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0022 - Home Base (57.67 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0023 - Home Base Store (9.06 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0024 - Practical Activities - 1hb (7.76 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0025 - Movement (7.81 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0026 - Practical Activities - 1hb (9 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0027 - Home Base (59.11 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0028 - Distribution Board (0.54 m2)</b>						
Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00A - R0029 - Home Base Store (4.91 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0030 - Movement (7.99 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00A - R0031 - Home Base (58.78 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0032 - Movement (8.1 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 4203/B00A/R0001/Ceiling Structures/Linings/S8	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R0033 - Stairs (6.53 m2)</b>						
Ceiling Structures/Linings	Vermiculite 4203/B00A/R0012/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00A - R0034 - Stairs (4.98 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 4203/B00A/R0001/Ceiling Structures/Linings/S8	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R1001 - General Storeroom (17.85 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 4203/B00A/R0001/Ceiling Structures/Linings/S8	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R1002 - Movement (10.76 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 4203/B00A/R0001/Ceiling Structures/Linings/S8	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R1003 - Movement (105.7 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 4203/B00A/R0001/Ceiling Structures/Linings/S8	106m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R1004 - Home Base (59.62 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1005 - Home Base Store (4.46 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1006 - Movement (20.94 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1007 - Home Base Store (4.44 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 4203/B00A/R0001/Floor Coverings Res/Textile/S1	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1008 - Home Base (59.62 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1009 - Home Base (58.96 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4203/B00A/R0001/Floor Coverings Res/Textile/S1	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1010 - Home Base Store (8.98 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1011 - Practical Activities - 1hb (7.65 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1012 - Home Base Store - P (9.1 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1013 - Movement (7.74 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1014 - Home Base - P (58.94 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1015 - Distribution Board (0.57 m2)</b>				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00A - R1016 - Home Base Store (5.07 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1017 - Movement (7.79 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1018 - Home Base (58.31 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1019 - Stairs (18.82 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Ceiling Structures/Linings/S8					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library - 1966 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
In-fill-panel	Flat AC Sheeting	50m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00B/In-fill-panel/S14			<b>Chrysotile (white asbestos)</b>		
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior**

**B00B - R0001 - Reading Area (214.92 m2)**

No Asbestos

**B00B - R0002 - Toilets - Girls (4.21 m2)**

No Asbestos

**B00B - R0003 - Toilets - Boys (4.26 m2)**

No Asbestos

**B00B - R0004 - Movement (2.51 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00B - R0005 - Movement (10.43 m2)**

No Asbestos

**B00B - R0006 - Cleaning Distributed Store (1.85 m2)**

Floor Coverings Res/Textile	Vinyl Sheet					
	4203/B00B/R0006/Floor Coverings Res/Textile/S10				<b>No Asbestos Detected</b>	

**B00B - R0007 - K.L.A. Store (12.91 m2)**

No Asbestos

**B00B - R0008 - Library Office/Workroom (9.46 m2)**

No Asbestos

**B00B - R0009 - Library Office/Workroom (23.35 m2)**

No Asbestos

**B00B - R0010 - Seminar/Study (15.56 m2)**

No Asbestos

**B00B - R0011 - Seminar/Study (15.49 m2)**

No Asbestos

**B00B - R9001 - General Storeroom (41.64 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1976 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00C/R0004/Ceiling Structures/Linings/S16				<b>Chrysotile (white asbestos)</b>	
In-fill-panel	Flat AC Sheeting	30m2	East, West, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00B/In-fill-panel/S14				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B00C - R0001 - Toilets - Boys/Girls (2.96 m2)**

No Asbestos

**B00C - R0002 - Practical Activities - 1hb (14.33 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00C/R0002/Floor Coverings Res/Textile/S15				<b>Chrysotile (white asbestos)</b>	

**B00C - R0003 - Home Base (79.08 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00C/R0002/Floor Coverings Res/Textile/S15				<b>Chrysotile (white asbestos)</b>	

**B00C - R0004 - Movement (7.59 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00C/R0004/Ceiling Structures/Linings/S16				<b>Chrysotile (white asbestos)</b>	
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)

**Assumed Asbestos - Electrical Hazard**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities/General Learning - 1962 - Concrete (Concrete)****Exterior**

Eaves Linings	Flat AC Sheeting	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Gable Verge Lining	Flat AC Sheeting	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00F/Gable Verge Lining/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00D - R0001 - Home Base Store (4.78 m2)**

No Asbestos

**B00D - R0002 - General Storeroom (7.64 m2)**

Wall Linings Internal	Flat AC Sheeting	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00D/R0002/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>

**B00D - R0003 - Movement (3.88 m2)**

No Asbestos

**B00D - R0004 - Movement (3.88 m2)**

No Asbestos

**B00D - R0005 - Home Base (66.02 m2)**

No Asbestos

**B00D - R0006 - Home Base (65.86 m2)**

No Asbestos

**B00D - R0007 - Home Base Store (7.21 m2)**

No Asbestos

**B00D - R0008 - Personal Effects Storage (11.58 m2)**

No Asbestos

**B00D - R0009 - Movement (9.07 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	4203/B00D/R0009/Floor Coverings Res/Textile/S11					<b>No Asbestos Detected</b>

**B00D - R0010 - Staff Toilet (2.19 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	4203/B00D/R0009/Floor Coverings Res/Textile/S11					<b>No Asbestos Detected</b>

**B00D - R0011 - Raised Platform (13.95 m2)**

No Asbestos

**B00D - R0012 - Communal Space (145.79 m2)**

No Asbestos

**B00D - R0013 - General Storeroom (4.75 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00D/R0013/Floor Coverings Res/Textile/S17					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	4203/B00D/R0013/Floor Coverings Res/Textile/S18					<b>No Asbestos Detected</b>

**B00D - R0014 - Sports Store (6.99 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00D/R0013/Floor Coverings Res/Textile/S17					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive					
4203/B00D/R0013/Floor Coverings Res/Textile/S18					<b>No Asbestos Detected</b>	
<b>B00D - R0015 - Movement (19.58 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00D/R0015/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R0016 - Seminar/Study (18.54 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00D/R0015/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R0017 - Cleaning Distributed Store (2.16 m2)</b>						
No Asbestos						
<b>B00D - R0018 - Staff Room Annexe (22.18 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00D/R0015/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R0019 - General Storeroom (6.91 m2)</b>						
No Asbestos						
<b>B00D - R0020 - Movement (3.86 m2)</b>						
No Asbestos						
<b>B00D - R0021 - Movement (3.92 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Support Unit - 1962 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00F/Gable Verge Lining/S13			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
In-fill-panel	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00B/In-fill-panel/S14			<b>Chrysotile (white asbestos)</b>		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00E - R0001 - Practical Activities - E (28.01 m2)**

No Asbestos

**B00E - R0002 - Movement (1.37 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00E - R0003 - Shower/Change (6.03 m2)**

No Asbestos

**B00E - R0004 - Home Base - E (46.24 m2)**

No Asbestos

**B00E - R0005 - Practical Activities - E (16.92 m2)**

No Asbestos

**B00E - R0006 - Home Base Store - E (4.76 m2)**

No Asbestos

**B00E - R0007 - Personal Effects - E (13.18 m2)**

No Asbestos

**B00E - R0008 - General Storeroom (7.69 m2)**

No Asbestos

**B00E - R0009 - General Storeroom (25.5 m2)**

No Asbestos

**B00E - R0010 - General Storeroom (7.62 m2)**

No Asbestos

**B00E - R0011 - Home Base Store - P (4.73 m2)**

No Asbestos

**B00E - R0012 - Home Base - P (65.84 m2)**

No Asbestos

**B00E - R0013 - Movement (3.59 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00E - R9001 - General Storeroom (22.82 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Other-After School Care/Support Unit - 1956 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00F/Gable Verge Lining/S13				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00F/Gable Verge Lining/S13				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					

**Interior****B00F - R0001 - Out Of School Hours Care Centre (51.8 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	

**B00F - R0002 - Out Of School Hours Care Centre (3.96 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	

**B00F - R0003 - Out Of School Hours Care Centre (18.29 m2)**

No Asbestos

**B00F - R0004 - Movement (3.74 m2)**

No Asbestos

**B00F - R0005 - Movement (3.26 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					
	4203/B00F/R0006/Wall Linings Internal/S5				<b>No Asbestos Detected</b>	

**B00F - R0006 - Toilets - Boys/Girls (1.87 m2)**

Wall Linings Internal	Flat AC Sheeting					
	4203/B00F/R0006/Wall Linings Internal/S5				<b>No Asbestos Detected</b>	

**B00F - R0007 - Home Base - P (52.02 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	3m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	

**B00F - R0008 - Home Base Store - P (3.95 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Floor Coverings Res/Textile/S1				<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00G - Pupil Facilities/Building Services - 1962 - Concrete (Concrete)****Exterior**

Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Gable Verge Lining	Flat AC Sheeting	8m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00F/Gable Verge Lining/S13			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	AC Fragments/Debris	2m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00G - R0001 - Movement (21.88 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0002 - Cleaning Distributed Store (1.54 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0003 - Toilets - Boys (20.9 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0004 - Toilets - Girls (19.18 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0005 - Cleaning Distributed Store (1.55 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0006 - Cleaning Distributed Store (1.52 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0007 - Movement (21.78 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00H - Pupil Facilities/Building Services - 1966 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/Eaves Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	AC Fragments/Debris	2m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00H - R0001 - Sports Store (10.29 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0002 - Movement (236.06 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Perimeter	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Wall Linings Internal	Flat AC Sheeting	50m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00D/R0002/Wall Linings Internal/S4			<b>Chrysotile (white asbestos)</b>		

**B00H - R0003 - Canteen Office/Store (3.54 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00H/R0006/Floor Coverings Res/Textile/S6			<b>Chrysotile (white asbestos)</b>		

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0004 - Canteen (19.64 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00H/R0006/Floor Coverings Res/Textile/S6			<b>Chrysotile (white asbestos)</b>		

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0005 - Canteen Office/Store (2.44 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00H/R0006/Floor Coverings Res/Textile/S6			<b>Chrysotile (white asbestos)</b>		

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0006 - Canteen Office/Store (9.45 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00H/R0006/Floor Coverings Res/Textile/S6			<b>Chrysotile (white asbestos)</b>		

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4203/B00A/R0001/Ceiling Structures/Linings/S8			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - R0007 - Uniform Shop (10.25 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R9001 - General Assistant/Bulk Store (10.96 m2)**

No Asbestos

**B00H - R9002 - Garden Store (10.54 m2)**

No Asbestos

**B00H - R9003 - Garden Store (12.51 m2)**

No Asbestos

**B00H - R9004 - General Storeroom (9.87 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Pupil Facilities - 1959 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Flat Roof No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

**Interior****B00I - R0001 - Movement (7.96 m2)**

Ceiling Structures/Linings Flat AC Sheeting 8m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4203/B00A/R0001/Ceiling Structures/Linings/S8

**Chrysotile (white asbestos) , Amosite (brown asbestos)****B00I - R0002 - Movement (34.58 m2)**

Ceiling Structures/Linings Flat AC Sheeting 35m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4203/B00A/R0001/Ceiling Structures/Linings/S8

**Chrysotile (white asbestos) , Amosite (brown asbestos)****B00I - R0003 - Toilets - Boys (43.72 m2)**

Ceiling Structures/Linings Flat AC Sheeting 44m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4203/B00A/R0001/Ceiling Structures/Linings/S8

**Chrysotile (white asbestos) , Amosite (brown asbestos)****B00I - R0004 - Movement (7.69 m2)**

Ceiling Structures/Linings Flat AC Sheeting 8m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4203/B00A/R0001/Ceiling Structures/Linings/S8

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1966 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00J - R0001 - Movement (7.82 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00J - R0002 - Movement (34.63 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00J - R0003 - Toilets - Girls (43.77 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00J - R0004 - Movement (7.8 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4203/B00A/R0001/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00K - R0001 - Covered Outdoor Learning Area (145.56 m2)**

No Asbestos

**B00K - R0002 - Communal Space (143.97 m2)**

No Asbestos

**B00K - R0003 - Movement (5.54 m2)**

No Asbestos

**B00K - R0004 - Raised Platform (62.08 m2)**

No Asbestos

**B00K - R0005 - Ramp (11.28 m2)**

No Asbestos

**B00K - R0006 - Movement (13.51 m2)**

No Asbestos

**B00K - R0007 - Hall Chair Store (9.23 m2)**

No Asbestos

**B00K - R0008 - Communal/Performance Store (9.3 m2)**

No Asbestos

**B00K - R0009 - P.E. Store (12.95 m2)**

No Asbestos

**B00K - R0010 - Toilet - Lobby (2.42 m2)**

No Asbestos

**B00K - R0011 - Toilets - Girls (7.38 m2)**

No Asbestos

**B00K - R0012 - Sound Cupboard (2.03 m2)**

No Asbestos

**B00K - R0013 - Toilet - Lobby (3.37 m2)**

No Asbestos

**B00K - R0014 - Toilets - Boys (5.71 m2)**

No Asbestos

**B00K - R0015 - Cleaning Distributed Store (3.51 m2)**

No Asbestos

**B00K - R0016 - General Storeroom (1.6 m2)**

No Asbestos

**B00K - R0017 - Main Switch Board (3.35 m2)**

No Asbestos

**B00K - R0018 - Access Shower/Toilet (6.87 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017