

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kingswood South Public School (4339)
Region : Western Sydney
State Electorate : Penrith
Local Government Area : Penrith

Initial Survey : Noel Arnold & Associates : 21 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 09 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1970 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - Community Clinic

No Asbestos

B00A - R0002 - Community Clinic

No Asbestos

B00A - R0003 - Community Clinic

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Other-Community Use - 1934 - Brick/Block (Brick/Block)**Exterior**

Gable Verge Lining	Flat AC Sheeting 4339/B00B/Gable Verge Lining/S19					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 4339/B00B/Eaves Linings/S18	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	Fibre Cement Pipe 4339/B00B/Ceiling Voids/S17	0.5m	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Packing 4339/B00B/Ceiling Voids/S16					No Asbestos Detected
Underfloor Voids	Fibre Cement Pipe 4339/B00B/Underfloor Voids/S21	NA	East	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	AC Fragments/Debris 4339/B00B/Underfloor Voids/S20	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	Packing 4339/B00B/Underfloor Voids/S22	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - General Storeroom

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Movement

In-fill-panel	Flat AC Sheeting 4339/B00E/R0005/In-fill-panel/S3	1m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 4339/B00E/R0005/Ceiling Structures/Linings/S2	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0005 - Home Base

Heater Surround	Flat AC Sheeting 4339/B00B/R0006/Panel behind heater/S14	1Unit(s)	South	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00B - R0006 - Home Base

Heater Surround	Flat AC Sheeting 4339/B00B/R0006/Panel behind heater/S14	1Unit(s)	North	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00B - R0007 - Personal Effects Storage

No Asbestos

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - Cleaning Distributed Store

No Asbestos

B00B - R0010 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00E/R0005/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	1m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00E/R0005/In-fill-panel/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00B - R0011 - Cleaning Distributed Store						
No Asbestos						
B00B - R0012 - Personal Effects Storage						
No Asbestos						
B00B - R0013 - Home Base						
Heater Surround	Flat AC Sheeting	1Unit(s)	South	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00B/R0006/Panel behind heater/S14				Chrysotile (white asbestos)		
B00B - R0014 - Home Base						
No Asbestos						
B00B - R0015 - Movement						
In-fill-panel	Flat AC Sheeting	1m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00E/R0005/In-fill-panel/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00B - R0016 - Personal Effects Storage						
No Asbestos						
B00B - R0017 - Movement						
In-fill-panel	Flat AC Sheeting	1m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00E/R0005/In-fill-panel/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00E/R0005/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00B - R0018 - Toilets - Boys/Girls						
Wall Linings Internal	Flat AC Sheeting	16m2	North, East, South, and Partition walls	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4339/B00B/R0018/Wall Linings Internal/S58				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00B/R0018/Ceiling Structures/Linings/S57				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00C/Eaves Linings/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Eaves Linings	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00C/Eaves Linings/S59				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00C - R0001 - Drinking Facilities

No Asbestos

B00C - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

B00C - R0003 - Cleaning Distributed Store

No Asbestos

B00C - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

B00C - R0005 - Drinking Facilities

No Asbestos

B00C - R0006 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Support Unit - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 4339/B00D/Eaves Linings/S60	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 4339/B00D/Gable Verge Lining/S27					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 4339/B001/R0001/In-fill-panel/S9					No Asbestos Detected
Ceiling Voids	Internal gable end wall cladding	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Ceiling Voids	Internal gable end wall cladding	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Ceiling Voids	Internal gable end wall cladding 4339/B00D/Ceiling Voids/S24					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Area inaccessible					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 4339/B00D/Eaves Linings/S25					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 4339/B00D/Eaves Linings/S26	14m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Infill panels under windows	Flat AC Sheeting 4339/B00D/Infill panels under windows/S62	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior

B00D - R0018 - External Movement

No Asbestos

B00D - R0019 - Entry Vestibule

No Asbestos

B00D - R0020 - Practical Activities - Pre

No Asbestos

B00D - R0021 - Home Base - Pre

No Asbestos

B00D - R0022 - Kitchen - Pre

No Asbestos

B00D - R0023 - Toilets - Boys/Girls - Pre

No Asbestos

B00D - R0024 - Laundry - Pre

No Asbestos

B00D - R0025 - General Storeroom

No Asbestos

B00D - R0026 - Clerical Office - Pre

No Asbestos

B00D - R0027 - Practical Activities - Pre

No Asbestos

B00D - R0028 - Practical Activities - Pre

No Asbestos

B00D - R0029 - Toilet - Lobby

No Asbestos

B00D - R0030 - Staff Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R0031 - General Storeroom - Pre

No Asbestos

B00D - R0032 - Toilets - Boys/Girls - Pre

No Asbestos

B00D - R0033 - Ramp

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Building Services - 1970 - Brick/Veneer (Brick/Veneer)**Exterior**

Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/Gable Verge Lining/S30				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/Eaves Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Flat AC Sheeting				No Asbestos Detected	
	4339/B00E/Ceiling Voids/S28					
Underfloor Voids	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00E/Underfloor Voids/S32				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00E/Underfloor Voids/S31				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

Interior**B00E - R0001 - Home Base**

No Asbestos

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Personal Effects Storage

No Asbestos

B00E - R0004 - Movement

Splashback lining	Flat AC Sheeting	1m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0004/Panel above Sink/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Flat AC Sheeting	1m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/In-fill-panel/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0006 - Home Base

No Asbestos

B00E - R0013 - External Movement

No Asbestos

B00E - R0014 - External Movement

No Asbestos

B00E - R0015 - Library Office/Workroom

No Asbestos

B00E - R0016 - Staff Toilet

No Asbestos

B00E - R0017 - K.L.A. Store

No Asbestos

B00E - R0018 - Reading Area

No Asbestos

B00E - R0019 - Staff Kitchen

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R9001 - General Assistant/Bulk Store

No Asbestos

B00E - R9002 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

4339/B00E/R0005/Ceiling Structures/Linings/S2

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R9003 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/Eaves Linings/S33				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00F - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	16m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Pupil Facilities - 1972 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00G/Gable Verge Lining/S35				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00G/Eaves Linings/S34				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00G/Underfloor Voids/S36				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00G - R0001 - Movement

No Asbestos

B00G - R0002 - Home Base

No Asbestos

B00G - R0003 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00G/R1004/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	

B00G - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00G/R1010/Partition Walls (Cubicles)/S8				Chrysotile (white asbestos)	

B00G - R0005 - Movement

No Asbestos

B00G - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0007 - General Storeroom

No Asbestos

B00G - R0008 - Stairs

No Asbestos

B00G - R1001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	74m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00G/R0001/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)	

B00G - R1002 - Home Base

No Asbestos

B00G - R1003 - Practical Activities - 1hb

No Asbestos

B00G - R1004 - Craft Store

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00G/R1004/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	

B00G - R1005 - Cleaning Distributed Store

No Asbestos

B00G - R1006 - Home Base

No Asbestos

B00G - R1007 - Home Base

No Asbestos

B00G - R1008 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00G/R1004/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)	
B00G - R1009 - Sports Store						
No Asbestos						
B00G - R1010 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00G/R1010/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)	
B00G - R1011 - Practical Activities - 1hb						
No Asbestos						
B00G - R1012 - Practical Activities - 1hb						
No Asbestos						
B00G - R1013 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00H/Eaves Linings/S37				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

B00H - R0003 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0005 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0006 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00F/R0002/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Other-D.E.C. Admin/Communal Facilities - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00I/Gable Verge Lining/S39					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00I/Eaves Linings/S38					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	4339/B00I/R0001/In-fill-panel/S9					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00I/Underfloor Voids/S41					Chrysotile (white asbestos)
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00I/Underfloor Voids/S40					Chrysotile (white asbestos)

Interior

B00I - R0005 - Other - Regional Use

No Asbestos

B00I - R0007 - Other - Regional Use

No Asbestos

B00I - R0015 - Home Base - P

No Asbestos

B00I - R0016 - Home Base Store - P

No Asbestos

B00I - R0017 - Personal Effects Storage

No Asbestos

B00I - R0018 - Movement

No Asbestos

B00I - R0019 - General Storeroom

No Asbestos

B00I - R0020 - Special Programs Room

No Asbestos

B00I - R0027 - Toilet - Lobby

No Asbestos

B00I - R0028 - Staff Toilet

No Asbestos

B00I - R0029 - Staff Toilet

No Asbestos

B00I - R0030 - Toilet - Lobby

No Asbestos

B00I - R0031 - Principal

No Asbestos

B00I - R0032 - Deputy Principal

No Asbestos

B00I - R0033 - Interview

No Asbestos

B00I - R0034 - Movement

No Asbestos

B00I - R0035 - Sick Bay

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - R0036 - Staff Kitchen						
No Asbestos						
B00I - R0037 - Clerical Office/Workroom						
No Asbestos						
B00I - R0038 - Clerical Office						
No Asbestos						
B00I - R0039 - Entry Vestibule						
No Asbestos						
B00I - R0040 - Communal Space						
No Asbestos						
B00I - R0041 - Communal Space						
No Asbestos						
B00I - R0042 - Raised Platform						
No Asbestos						
B00I - R0043 - Uniform Shop						
No Asbestos						
B00I - R0044 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00J - Staff Facilities/Pupil Facilities - 1964 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00J/Gable Verge Lining/S43					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00J/Eaves Linings/S42					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00J/Underfloor Voids/S45					Chrysotile (white asbestos)
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00J/Underfloor Voids/S44					Chrysotile (white asbestos)

Interior

B00J - R0001 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00I/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00J/R0003/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)

B00J - R0002 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00I/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00J/R0003/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)

B00J - R0003 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00I/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00J/R0003/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)

B00J - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00I/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00I/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0006 - Staff Room

No Asbestos

B00J - R0007 - Staff Room Annexe

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Building Services - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00K/Eaves Linings/S47				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
BBQ	Packing					
	4339/B00K/BBQ/S46					No Asbestos Detected

Interior

B00K - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00L - General Learning - 1964 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00L/Gable Verge Lining/S50					Chrysotile (white asbestos) , Amosite (brown asbestos)
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00L/Eaves Linings/S49					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
	4339/B00D/Eaves Linings/S60					Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
	4339/B00L/Ceiling Voids/S48					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Non Accessible Area					
	4339/B00D/Gable Verge Lining/S61 - Area inaccessible					No Asbestos Detected

Interior

B00L - R0001 - Home Base

Heater Surround	Flat AC Sheeting	1Unit(s)	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00B/R0006/Panel behind heater/S14					Chrysotile (white asbestos)

B00L - R0002 - Movement

In-fill-panel	Flat AC Sheeting	1m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/In-fill-panel/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/Ceiling Structures/Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0003 - Movement

No Asbestos

B00L - R0004 - Personal Effects Storage

No Asbestos

B00L - R0005 - Personal Effects Storage

No Asbestos

B00L - R0006 - Home Base

Heater Surround	Flat AC Sheeting	1Unit(s)	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00B/R0006/Panel behind heater/S14					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Administration - 1970 - Brick/Veneer (Brick/Veneer)**Exterior**

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00M/Gable Verge Lining/S53				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00M/Eaves Linings/S51				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00M/Underfloor Voids/S55				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	4339/B00M/Underfloor Voids/S54				Chrysotile (white asbestos)	
Underfloor Voids	Lagging				No Asbestos Detected	
	4339/B00M/Underfloor Voids/S56					
Gable Ends	Flat AC Sheeting	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00M/Gable Ends/S52				Chrysotile (white asbestos)	

Interior**B00M - R0001 - Interview**

No Asbestos

B00M - R0002 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00M/R0010/Wall Linings Internal/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00M - R0003 - General Storeroom

No Asbestos

B00M - R0004 - Movement

In-fill-panel	Flat AC Sheeting	1m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/In-fill-panel/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00M - R0005 - Movement

No Asbestos

B00M - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Flat AC Sheeting	1m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/In-fill-panel/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00M - R0007 - Entry Vestibule

No Asbestos

B00M - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4339/B00E/R0005/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00M - R0009 - Principal

No Asbestos

B00M - R0010 - Staff Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4339/B00M/R0010/Wall Linings Internal/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00M - R0011 - Movement

No Asbestos

B00M - R0012 - General Storeroom

No Asbestos

B00M - R0013 - Main Switch Board

No Asbestos

B00M - R0014 - Clerical Office

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Pupil Facilities - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00N - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B000 - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior**B000 - R0001 - Communal Space**

No Asbestos

B000 - R0002 - Raised Platform

No Asbestos

B000 - R0003 - Movement

No Asbestos

B000 - R0004 - Movement

No Asbestos

B000 - R0005 - Ramp

No Asbestos

B000 - R0006 - Hall Chair Store

No Asbestos

B000 - R0007 - Communal/Performance Store

No Asbestos

B000 - R0008 - P.E. Store

No Asbestos

B000 - R0009 - Toilet - Lobby

No Asbestos

B000 - R0010 - Toilets - Girls

No Asbestos

B000 - R0011 - Sound Cupboard

No Asbestos

B000 - R0012 - Toilet - Lobby

No Asbestos

B000 - R0013 - Toilets - Boys

No Asbestos

B000 - R0014 - Cleaning Distributed Store

No Asbestos

B000 - R0015 - Disabled Shower/Toilet

No Asbestos

B000 - R0016 - Main Switch Board

No Asbestos

B000 - R0017 - Covered Outdoor Learning Area

No Asbestos

B000 - R0018 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11030 - Learning Unit - Standard With P.A.A. : Placement Date - 3/12/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12665 - Learning Unit - Standard With P.A.A. : Placement Date - 4/01/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13518 - Learning Unit - Standard With P.A.A. : Placement Date - 10/11/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

NS 120 - D15919 - Learning Unit - Single Primary H/Cap PAA : Placement Date - 13/01/2010

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Home Base Store-I.O.

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Entry

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017