

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Killarney Vale Public School (4426)
Region : Hunter/Central Coast
State Electorate : The Entrance
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 14 - Mar - 2008
Reviewed By : Grencap-NAA : 20 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1973 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Gable Verge Lining/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Compressed AC Sheet	21m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/In-fill-panel/S13				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00A - R0001 - Movement (6.4 m2)**

No Asbestos

B00A - R0002 - General Storeroom (4.21 m2)

No Asbestos

B00A - R0003 - Movement (45.15 m2)

No Asbestos

B00A - R0004 - Principal (17.06 m2)

Ceiling Structures/Linings	Vermiculite					
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00A - R0005 - Entry Vestibule (8.48 m2)

Ceiling Structures/Linings	Vermiculite					
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1005/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)	

B00A - R0006 - Clerical Office (12.66 m2)

Ceiling Structures/Linings	Vermiculite					
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00A - R0007 - Sick Bay (9.34 m2)

Heater Bank	Encapsulated Insulation material within unit	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
					Assumed Asbestos - Electrical Hazard	

Ceiling Structures/Linings	Vermiculite					
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00A/R0008/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)	

B00A - R0008 - Duplicating Workroom (33.04 m2)

Heater Bank	Encapsulated Insulation material within unit	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
					Assumed Asbestos - Electrical Hazard	

Ceiling Structures/Linings	Vermiculite					
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00A/R0008/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)		
B00A - R0009 - Interview (8.58 m2)						
Ceiling Structures/Linings	Vermiculite					
4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0012 - Staff Toilet (4.27 m2)						
Ceiling Structures/Linings	Vermiculite					
4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0013 - General Storeroom (5.12 m2)						
Ceiling Structures/Linings	Vermiculite					
4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1005/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0014 - Staff Room Annexe (13.22 m2)						
Ceiling Structures/Linings	Vermiculite					
4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0015 - Deputy Principal (14.6 m2)						
Ceiling Structures/Linings	Vermiculite					
4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0016 - Movement (24.55 m2)						
Ceiling Structures/Linings	Vermiculite					
4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1005/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0017 - Distribution Board (0.28 m2)						
				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00A - R0018 - Stairs (12.31 m2)						
No Asbestos						
B00A - R0019 - Access Shower/Toilet (6.13 m2)						
No Asbestos						
B00A - R0020 - Cleaning Distributed Store (0.96 m2)						
No Asbestos						
B00A - R1001 - Practical Activities - 1hb (14.04 m2)						
Ceiling Structures/Linings	Vermiculite					
4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1005/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R1002 - Home Base (61 m2)						
Heater Bank	Encapsulated Insulation material within unit	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Vinyl Tiles 4426/B00B/R1005/Floor Coverings Res/Textile/S2	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
B00A - R1003 - Home Base (61 m2)						
Heater Bank	Encapsulated Insulation material within unit Assumed Asbestos - Electrical Hazard	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Ceiling Structures/Linings	Vermiculite 4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Vinyl Tiles 4426/B00B/R1005/Floor Coverings Res/Textile/S2	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
B00A - R1004 - Practical Activities - 1hb (14.04 m2)						
Ceiling Structures/Linings	Vermiculite 4426/B00B/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Vinyl Tiles 4426/B00B/R1005/Floor Coverings Res/Textile/S2	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
B00A - R1005 - Movement (45.65 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4426/B00L/Eaves Linings/S26	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
B00A - R1006 - Stairs (17.01 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4426/B00L/Eaves Linings/S26	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1969 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/Eaves Linings/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	40m	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/Gable Verge Lining/S10				Chrysotile (white asbestos)	
In-fill-panel	Compressed AC Sheet	33m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/In-fill-panel/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00B - M0001 - Movement (7.07 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

B00B - M0002 - Cleaning Supplies (9.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1005/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)	

B00B - R0001 - Cleaning Distributed Store (3.92 m2)

No Asbestos

B00B - R0002 - Practical Activities - 1hb (13.98 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00B - R0003 - Home Base (60.14 m2)

Heater Bank	Encapsulated Insulation material within unit	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00B - R0004 - Distribution Board (0.33 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00B - R0005 - Home Base - M (62.41 m2)

Heater Bank	Encapsulated Insulation material within unit	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00B - R0006 - Practical Activities - 1hb (12.34 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0007 - Toilets - Boys (12.57 m2)						
No Asbestos						
B00B - R0008 - Toilets - Girls (11.07 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet					
	4426/B00B/R1007/Partition Walls (Cubicles)/S3					No Asbestos Detected
B00B - R0009 - Movement (73.66 m2)						
No Asbestos						
B00B - R0010 - Movement (7.01 m2)						
No Asbestos						
B00B - R0011 - General Storeroom (5.36 m2)						
No Asbestos						
B00B - R0012 - Stairs (0.7 m2)						
No Asbestos						
B00B - R0013 - Stairs (6.16 m2)						
No Asbestos						
B00B - R0014 - Stairs (4.36 m2)						
No Asbestos						
B00B - R1001 - Movement (72.8 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00B - R1002 - Practical Activities - 1hb (13.99 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1005/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1003 - Home Base (60.04 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1005/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1004 - Home Base (59.97 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1005/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1005 - Practical Activities - 1hb (13.99 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4426/B00B/R0003/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1005/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R1006 - Toilets - Boys (12.67 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1007/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)
B00B - R1007 - Toilets - Girls (11.1 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1007/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet					
4426/B00B/R1007/Partition Walls (Cubicles)/S3					No Asbestos Detected	
B00B - R1008 - Movement (9.62 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	
B00B - R1009 - Stairs (5.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	
B00B - R1010 - Stairs (16.96 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	
B00B - R1011 - Stairs (3.74 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00B/R1001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1973 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/R1008/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	40m	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/Gable Verge Lining/S14				Chrysotile (white asbestos)	
In-fill-panel	Compressed AC Sheet	32m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/In-fill-panel/S13				Chrysotile (white asbestos)	
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00C - R0001 - Practical Activities - 1hb (14.36 m2)

Ceiling Structures/Linings	Vermiculite					
	4426/B00C/R1006/Ceiling Structures/Linings/S16					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00C - R0003 - Distribution Board (0.32 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00C - R0005 - Practical Activities - 1hb (13.13 m2)

Ceiling Structures/Linings	Vermiculite					
	4426/B00C/R1006/Ceiling Structures/Linings/S16					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00B/R1005/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)	

B00C - R0006 - Movement (34.32 m2)

No Asbestos

B00C - R0007 - Movement (24.48 m2)

No Asbestos

B00C - R0008 - General Storeroom (5.36 m2)

No Asbestos

B00C - R0009 - Practical Activities - 1hb (14.02 m2)

Ceiling Structures/Linings	Vermiculite					
	4426/B00C/R1006/Ceiling Structures/Linings/S16					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00C - R0010 - Home Base (59.69 m2)

Heater Bank	Encapsulated Insulation material within unit	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

Ceiling Structures/Linings	Vermiculite					
	4426/B00C/R1006/Ceiling Structures/Linings/S16					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00C - R0011 - Stairs (6.15 m2)

No Asbestos

B00C - R0012 - Stairs (0.69 m2)

No Asbestos

B00C - R0013 - Home Base (48.53 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4426/B00C/R0013/Ceiling Structures/Linings/S30				Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4426/B00C/R0013/Floor Coverings Res/Textile/S31	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4426/B00C/R0013/Floor Coverings Res/Textile/S32	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R0014 - Toilet - E (20.58 m2)						
Ceiling Structures/Linings	Vermiculite 4426/B00C/R0013/Ceiling Structures/Linings/S30				Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00C - R0015 - Home Base (50.26 m2)						
Ceiling Structures/Linings	Vermiculite 4426/B00C/R0013/Ceiling Structures/Linings/S30				Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4426/B00C/R0013/Floor Coverings Res/Textile/S31	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4426/B00C/R0013/Floor Coverings Res/Textile/S31	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1001 - Movement (34.33 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4426/B00C/R1008/Ceiling Structures/Linings/S15	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R1002 - Practical Activities - 1hb (14.35 m2)						
Ceiling Structures/Linings	Vermiculite 4426/B00C/R1006/Ceiling Structures/Linings/S16				Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles 4426/B00B/R1005/Floor Coverings Res/Textile/S2	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1003 - Home Base (59.07 m2)						
Heater Bank	Encapsulated Insulation material within unit Assumed Asbestos - Electrical Hazard	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Ceiling Structures/Linings	Vermiculite 4426/B00C/R1006/Ceiling Structures/Linings/S16				Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles 4426/B00B/R1005/Floor Coverings Res/Textile/S2	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1004 - Home Base (60.96 m2)						
Heater Bank	Encapsulated Insulation material within unit Assumed Asbestos - Electrical Hazard	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Ceiling Structures/Linings	Vermiculite 4426/B00C/R1006/Ceiling Structures/Linings/S16				Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles 4426/B00B/R1005/Floor Coverings Res/Textile/S2	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1005 - Practical Activities - 1hb (13.12 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4426/B00C/R1006/Ceiling Structures/Linings/S16					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4426/B00B/R1005/Floor Coverings Res/Textile/S2	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1006 - Practical Activities - 1hb (14.01 m2)						
Ceiling Structures/Linings	Vermiculite 4426/B00C/R1006/Ceiling Structures/Linings/S16					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00C - R1007 - Home Base (59.69 m2)						
Ceiling Structures/Linings	Vermiculite 4426/B00C/R1006/Ceiling Structures/Linings/S16					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00C - R1008 - Movement (24.48 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4426/B00C/R1008/Ceiling Structures/Linings/S15	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R1009 - Stairs (6.19 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4426/B00C/R1008/Ceiling Structures/Linings/S15	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R1010 - Stairs (5.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4426/B00C/R1008/Ceiling Structures/Linings/S15	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library/Multi Purpose Facilities - 1980 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	East/West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/Eaves Linings/S30					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	60m	North/South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/Gable Verge Lining/S14					Chrysotile (white asbestos)

Interior

B00E - M9001 - General Assistant/Bulk Store (7.14 m2)

No Asbestos

B00E - R0001 - Staff Toilet (3.02 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R0007/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)

B00E - R0002 - Movement (1.39 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R0007/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)

B00E - R0003 - Seminar/Study (14.49 m2)

No Asbestos

B00E - R0004 - Movement (10.41 m2)

No Asbestos

B00E - R0005 - Library Office/Workroom (7.56 m2)

No Asbestos

B00E - R0006 - Library Office/Workroom (19.48 m2)

No Asbestos

B00E - R0007 - Security Store (11.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R0007/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)

B00E - R0008 - Reading Area (252.84 m2)

No Asbestos

B00E - R0009 - Movement (12.44 m2)

No Asbestos

B00E - R0010 - Communications Room (41.16 m2)

No Asbestos

B00E - R0011 - Plant (1.66 m2)

No Asbestos

B00E - R0012 - Cleaning Distributed Store (2.2 m2)

Ceiling Structures/Linings	Fibrous Membrane					No Asbestos Detected
	4426/B00E/R0012/Ceiling Structures/Linings/S17					
Wall & Floor lining	Resinous Membrane	6m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4426/B00E/R0012/Wall & Floor lining/S18					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0013 - Seminar/Study (14.48 m2)

No Asbestos

B00E - R0014 - Stairs (2.11 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R0007/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
B00E - R9001 - Sports Store (20.81 m2)						
No Asbestos						
B00E - R9002 - General Storeroom (4.63 m2)						
No Asbestos						
B00E - R9003 - Toilets - Boys (10.74 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R0007/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R9003/Partition Walls (Cubicles)/S21					Chrysotile (white asbestos)	
B00E - R9004 - Toilets - Girls (10.82 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R0007/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R9003/Partition Walls (Cubicles)/S21					Chrysotile (white asbestos)	
B00E - R9005 - Movement (10.17 m2)						
No Asbestos						
B00E - R9006 - Communal Space (227.5 m2)						
No Asbestos						
B00E - R9007 - Movement (1.66 m2)						
No Asbestos						
B00E - R9008 - Movement (1.66 m2)						
No Asbestos						
B00E - R9009 - Movement (1.66 m2)						
No Asbestos						
B00E - R9010 - Distribution Board (1.22 m2)						
Note: No inspection of live electrical installation.						
Door lining	Flat AC Sheeting	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R9010/Door lining/S20					Chrysotile (white asbestos)	
B00E - R9011 - Movement (5.27 m2)						
No Asbestos						
B00E - R9012 - Raised Platform (40.26 m2)						
No Asbestos						
B00E - R9013 - Plant (3.83 m2)						
No Asbestos						
B00E - R9014 - P.E. Store (11.98 m2)						
No Asbestos						
B00E - R9015 - Cleaning Distributed Store (16.05 m2)						
No Asbestos						
B00E - R9016 - Disabled Toilet (2.88 m2)						
No Asbestos						
B00E - R9018 - Cleaning Distributed Store (2.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R0007/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
B00E - R9020 - Movement (1.66 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R9021 - Movement (1.66 m2)

No Asbestos

B00E - R9022 - Chair Storeroom (17.61 m2)

Recently Modified Space Requires Inspection

B00E - R9023 - Cleaning Supplies (2.9 m2)

Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1973 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Gable Verge Lining/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - M9001 - Movement (2.42 m2)

No Asbestos

B00F - R0001 - Movement (121.26 m2)

Ceiling Structures/Linings	Flat AC Sheeting	118m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0002 - Toilets - Boys (19.23 m2)

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R9003/Partition Walls (Cubicles)/S21				Chrysotile (white asbestos)	

B00F - R0003 - Toilets - Girls (18.31 m2)

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R9003/Partition Walls (Cubicles)/S21				Chrysotile (white asbestos)	

B00F - R0004 - Interview (22.62 m2)

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0005 - Staff Toilet (2.67 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0006 - Movement (3.75 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0007 - Security Store (25.71 m2)

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0008 - Canteen (53.11 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00F - R0009 - Distribution Board (0.29 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00F - R0010 - Staff Toilet (3.83 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00F - R0011 - Canteen Office/Store (4.75 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00F - R0012 - Canteen Office/Store (3.56 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00F - R0013 - Stairs (10.06 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00F - R0014 - Stairs (9.26 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00F - R9001 - General Assistant/Bulk Store (18.27 m2)						
No Asbestos						
B00F - R9002 - Garden Store (8.02 m2)						
No Asbestos						
B00F - R9003 - Movement (33.47 m2)						
No Asbestos						
B00F - R9004 - Stairs (9.26 m2)						
No Asbestos						
B00F - R9005 - Stairs (2.3 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Gable Verge Lining/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Compressed AC Sheet	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/In-fill-panel/S13				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0002 - Home Base Store (6.61 m2)

Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00G/R0002/Wall Linings Internal/S6				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00G/R0002/Wall Linings Internal/S6				Chrysotile (white asbestos)	

B00G - R0005 - Home Base Store (2.72 m2)

Wall Linings Internal	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00G/R0002/Wall Linings Internal/S6				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00G/R0002/Wall Linings Internal/S6				Chrysotile (white asbestos)	

B00G - R0006 - Movement (10.78 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0007 - Movement (11.26 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0008 - Movement (71.5 m2)

Ceiling Structures/Linings	Flat AC Sheeting	72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0009 - Movement (9 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0010 - Practical Activities - 1hb (10.18 m2)

No Asbestos

B00G - R0011 - Home Base (47 m2)

No Asbestos

B00G - R0012 - Practical Activities - 1hb (13.67 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - R0013 - Home Base (51.12 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/Gable Verge Lining/S25					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/Gable Verge Lining/S25					Chrysotile (white asbestos)
In-fill-panel	Compressed AC Sheet	19m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/In-fill-panel/S13					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0002 - Home Base Store (6.48 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00H - R0006 - Toilets - Boys/Girls (4.07 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0007/Wall Linings Internal/S23					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0007/Wall Linings Internal/S23					Chrysotile (white asbestos)
Wall Linings Internal	Vinyl Tiles					No Asbestos Detected
	4426/B00M/R0004/Wall Linings Internal/S5					

B00H - R0007 - Movement (10.71 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	North/South/East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0007/Wall Linings Internal/S23					Chrysotile (white asbestos)

B00H - R0008 - Movement (42.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00H - R0009 - Movement (9.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00H - R0010 - Movement (6.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00H - R0011 - Home Base (58.93 m2)

No Asbestos

B00H - R0012 - Practical Activities - 1hb (13.81 m2)

No Asbestos

B00H - R0013 - Home Base (55.81 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - R0014 - Practical Activities - 1hb (20.83 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/Gable Verge Lining/S25				Chrysotile (white asbestos)	
In-fill-panel	Compressed AC Sheet	21m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/In-fill-panel/S13				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00J - R0002 - Home Base Store (4.01 m2)

No Asbestos

B00J - R0003 - Toilets - Boys/Girls (3.06 m2)

Wall Linings Internal	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0007/Wall Linings Internal/S23				Chrysotile (white asbestos)	

B00J - R0006 - Home Base Store (7.3 m2)

No Asbestos

B00J - R0009 - Movement (41.4 m2)

Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24				Chrysotile (white asbestos)	

B00J - R0010 - Practical Activities - 1hb (16.61 m2)

No Asbestos

B00J - R0011 - Home Base (71.74 m2)

No Asbestos

B00J - R0012 - Practical Activities - 1hb (16.96 m2)

No Asbestos

B00J - R0013 - Home Base (51.16 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities/Other - 1969 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/Gable Verge Lining/S25					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00K - R0001 - Home Base Store (3.27 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00K - R0005 - Drinking Facilities (8.19 m2)

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00K - R0006 - Toilets - Boys (29.59 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	16m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R9003/Partition Walls (Cubicles)/S21					Chrysotile (white asbestos)

B00K - R0007 - Movement (27.13 m2)

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00K - R0008 - Garden Store (13.51 m2)

No Asbestos

B00K - R0009 - Toilets - Girls (26.36 m2)

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R9003/Partition Walls (Cubicles)/S21					Chrysotile (white asbestos)

B00K - R0010 - Other-Community Use (3.69 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0007/Wall Linings Internal/S23					Chrysotile (white asbestos)

B00K - R0011 - Other-Community Use (10.17 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00K - R0012 - Other-Community Use (38.22 m2)

Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00K - R0013 - Other-Community Use (41.27 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)	
B00K - R0014 - Other-Community Use (11.66 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00H/R0008/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 1973 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26					Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Gable Verge Lining/S27					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00L - R0001 - Home Base Store (12.68 m2)**

No Asbestos

B00L - R0002 - Staff Room Annexe (12.81 m2)

No Asbestos

B00L - R0003 - Movement (29.74 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0004 - Home Base (66.1 m2)

No Asbestos

B00L - R0005 - Withdrawal Space - 1hb (11.74 m2)

No Asbestos

B00L - R0006 - Home Base (61.93 m2)

No Asbestos

B00L - R0009 - Craft Store (4.63 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0010 - Sports Store (4.17 m2)

No Asbestos

B00L - R0011 - Distribution Board (0.85 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0012 - Movement (40.86 m2)

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0013 - Communications Room (49.73 m2)

No Asbestos

B00L - R0014 - General Storeroom (4.33 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0015 - Toilets - Boys (8.72 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00E/R9003/Partition Walls (Cubicles)/S21					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00L - R0016 - Cleaning Distributed Store (2.2 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00L - R0017 - Toilets - Girls (8.83 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00E/R9003/Partition Walls (Cubicles)/S21				Chrysotile (white asbestos)		
B00L - R0018 - General Storeroom (1.62 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00L - R0019 - Practical Activities (52.28 m2)						
No Asbestos						
B00L - R0020 - External Movement (58.3 m2)						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Staff Facilities - 1970 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00L/Gable Verge Lining/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Compressed AC Sheet	8m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00C/In-fill-panel/S13				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00M - R0001 - Staff Room (63.66 m2)**

No Asbestos

B00M - R0002 - K.L.A. Store (0.72 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	

B00M - R0003 - Staff Toilet (4.28 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	

B00M - R0004 - No Access (1.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	
Wall Linings Internal	Vinyl Tiles				No Asbestos Detected	
	4426/B00M/R0004/Wall Linings Internal/S29					
Wall Linings Internal	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	

B00M - R0005 - Staff Toilet (4.91 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	

B00M - R0006 - Staff Room Annexe (17.05 m2)

No Asbestos

B00M - R0007 - Main Switch Board (5.45 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4426/B00M/R0002/Ceiling Structures/Linings/S28				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00M/R0002/Ceiling Structures/Linings/S28					Chrysotile (white asbestos)	
Electrical Backing Board	Resinous Board	3Unit	North/South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00M - R0008 - Movement (35.05 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4426/B00L/Eaves Linings/S26					Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10008 - Learning Unit - Standard With P.A.A. : Placement Date - 17/08/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017