


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kambora Public School (4515)  
**Region :** Northern Sydney  
**State Electorate :** Davidson  
**Local Government Area :** Warringah

**Initial Survey :** Noel Arnold & Associates : 25 - Jan - 2008  
**Reviewed By :** AECOM : 28 - Jun - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/General Learning - 1979 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible, no manhole / no access points.					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.					
Eaves Linings	Flat AC Sheeting 4515/B00A/Eaves Linings/S16	500m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Gable Ends	Flat AC Sheeting 4515/B00A/Gable Ends/S17	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**Interior****B00A - M0001 - Withdrawal Space - 1hb**

No Asbestos

**B00A - M0002 - Communications Room**

No Asbestos

**B00A - M0003 - Staff Room**

No Asbestos

**B00A - M0004 - Distribution Board**

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 4515/B00A/M0004/Wall Linings Internal/S14	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - M0005 - Plant**

No Asbestos

**B00A - M0006 - Movement**

No Asbestos

**B00A - M0007 - Communications Room**

No Asbestos

**B00A - M0008 - Stairs**

No Asbestos

**B00A - M0009 - Stairs**

No Asbestos

**B00A - M0010 - Stairs**

No Asbestos

**B00A - R0001 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet 4515/B00A/R0019/Partition Walls (Cubicles)/S15	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0002 - Personal Effects Storage**

No Asbestos

**B00A - R0003 - Main Switch Board**

Wall Linings Internal	Flat AC Sheeting 4515/B00A/M0004/Wall Linings Internal/S14	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Electrical Mounting Board	Resinous Board	1Unit	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)

**Assumed Asbestos - Electrical Hazard**

Floor Coverings Res/Textile	Compressed AC Sheet 4515/B00A/R0003/Floor Coverings Res/Textile/S20	1.5m2	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0004 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0105/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00A - R0005 - Kiln Room</b>						
Workbench	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0021/Workbench/S6					Chrysotile (white asbestos)	
<b>B00A - R0006 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0007 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0008 - Seminar/Study</b>						
No Asbestos						
<b>B00A - R0009 - K.L.A. Store</b>						
No Asbestos						
<b>B00A - R0010 - Library Office/Workroom</b>						
No Asbestos						
<b>B00A - R0011 - Communications Room</b>						
No Asbestos						
<b>B00A - R0012 - Distribution Board</b> <span style="float: right;">Note: No inspection of live electrical installation.</span>						
Wall Linings Internal	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/M0004/Wall Linings Internal/S14					Chrysotile (white asbestos)	
<b>B00A - R0013 - Library Office/Workroom</b>						
No Asbestos						
<b>B00A - R0014 - Movement</b>						
No Asbestos						
<b>B00A - R0015 - Movement</b>						
No Asbestos						
<b>B00A - R0016 - Reading Area</b>						
No Asbestos						
<b>B00A - R0017 - Craft Store</b>						
No Asbestos						
<b>B00A - R0018 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R0019 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0019/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)	
<b>B00A - R0020 - Distribution Board</b> <span style="float: right;">Note: No inspection of live electrical installation.</span>						
Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/M0004/Wall Linings Internal/S14					Chrysotile (white asbestos)	
<b>B00A - R0021 - Kiln Room</b>						
Workbench	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0021/Workbench/S6					Chrysotile (white asbestos)	
<b>B00A - R0022 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0023 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0024 - Craft Store</b>						
No Asbestos						
<b>B00A - R0025 - Home Base</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0026 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
4515/B00A/R0105/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00A - R0027 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0028 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0105/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00A - R0029 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0105/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00A - R0030 - Movement</b>						
No Asbestos						
<b>B00A - R0031 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0105/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00A - R0032 - Toilets - Boys</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0019/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)	
<b>B00A - R0033 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R0034 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0035 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0036 - Craft Store</b>						
No Asbestos						
<b>B00A - R0037 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	37m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4515/B00A/R0037/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	
<b>B00A - R0038 - Home Base</b>						
No Asbestos						
<b>B00A - R0039 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0040 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0041 - Movement</b>						
No Asbestos						
<b>B00A - R0043 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0044 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0045 - Cleaning Supplies</b>						
No Asbestos						
<b>B00A - R0046 - Raised Platform</b>						
No Asbestos						
<b>B00A - R0047 - Communal Space</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0048 - Hall Chair Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4515/B00A/R0048/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
<b>B00A - R0049 - Cleaning Supplies</b>						
No Asbestos						
<b>B00A - R0050 - Toilets - Girls</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0052/Wall Linings Internal/S5					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0051 - Toilets - Boys</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0052/Wall Linings Internal/S5					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0052 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0052/Wall Linings Internal/S5					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0053 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0037/Ceiling Structures/Linings/S12					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0054 - Canteen</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4515/B00A/R0054/Floor Coverings Res/Textile/S10					<b>No Asbestos Detected</b>
<b>B00A - R0055 - Canteen Office/Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4515/B00A/R0054/Floor Coverings Res/Textile/S10					<b>No Asbestos Detected</b>
<b>B00A - R0056 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0075/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0057 - Canteen Office/Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4515/B00A/R0054/Floor Coverings Res/Textile/S10					<b>No Asbestos Detected</b>
<b>B00A - R0059 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0037/Ceiling Structures/Linings/S12					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0060 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4515/B00A/R0060/Floor Coverings Res/Textile/S18					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting	9.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0061/Wall Linings Internal/S19					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	33.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4515/B00A/R0061/Wall Linings Internal/S19					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0061 - General Assistant/Bulk Store</b>						
Wall Linings Internal	Flat AC Sheeting	45.8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4515/B00A/R0061/Wall Linings Internal/S19					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	9.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0061/Wall Linings Internal/S19					Chrysotile (white asbestos)	
<b>B00A - R0062 - Garden Store</b>						
Wall Linings Internal	Encapsulated Insulation material within unit	36.5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4515/B00A/R0061/Wall Linings Internal/S19					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	12.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0061/Wall Linings Internal/S19					Chrysotile (white asbestos)	
<b>B00A - R0063 - Communications Room</b>						
No Asbestos						
<b>B00A - R0064 - General Assistant/Bulk Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4515/B00A/R0064/Floor Coverings Res/Textile/S4					No Asbestos Detected	
<b>B00A - R0065 - Deputy Principal</b>						
No Asbestos						
<b>B00A - R0066 - Clerical Office</b>						
No Asbestos						
<b>B00A - R0067 - Sick Bay</b>						
No Asbestos						
<b>B00A - R0068 - Duplicating Workroom</b>						
No Asbestos						
<b>B00A - R0069 - Movement</b>						
No Asbestos						
<b>B00A - R0070 - Entry Vestibule</b>						
No Asbestos						
<b>B00A - R0071 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0037/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	
<b>B00A - R0072 - Principal</b>						
No Asbestos						
<b>B00A - R0073 - Movement</b>						
No Asbestos						
<b>B00A - R0074 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0074/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
<b>B00A - R0075 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0075/Wall Linings Internal/S8					Chrysotile (white asbestos)	
<b>B00A - R0076 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0075/Wall Linings Internal/S8					Chrysotile (white asbestos)	
<b>B00A - R0077 - Movement</b>						
No Asbestos						
<b>B00A - R0078 - Deputy Principal</b>						
No Asbestos						
<b>B00A - R0079 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0080 - Toilets - Boys</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet 4515/B00A/R0080/Partition Walls (Cubicles)/S9					No Asbestos Detected
<b>B00A - R0081 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet 4515/B00A/R0080/Partition Walls (Cubicles)/S9					No Asbestos Detected
<b>B00A - R0082 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet 4515/B00A/R0080/Partition Walls (Cubicles)/S9					No Asbestos Detected
<b>B00A - R0083 - Disabled Toilet</b>						
Partition Walls (Cubicles)	Compressed AC Sheet 4515/B00A/R0080/Partition Walls (Cubicles)/S9					No Asbestos Detected
<b>B00A - R0084 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R0085 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0087 - Uniform Shop</b>						
No Asbestos						
<b>B00A - R0088 - Uniform Shop</b>						
No Asbestos						
<b>B00A - R0089 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0075/Wall Linings Internal/S8					Chrysotile (white asbestos)	
<b>B00A - R0090 - Toilets - Boys/Girls</b>						
No Asbestos						
<b>B00A - R0091 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0092 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0074/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
<b>B00A - R0093 - Home Base</b>						
No Asbestos						
<b>B00A - R0094 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0095 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0096 - Home Base</b>						
No Asbestos						
<b>B00A - R0097 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0098 - Movement</b>						
No Asbestos						
<b>B00A - R0099 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0100 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0101 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0102 - Home Base</b>						
No Asbestos						
<b>B00A - R0103 - Withdrawal Space - 1hb</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0104 - Home Base</b>						
No Asbestos						
<b>B00A - R0105 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0105/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00A - R0106 - Disabled Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0106/Wall Linings Internal/S1					Chrysotile (white asbestos)	
<b>B00A - R0107 - Toilets - Girls</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0106/Wall Linings Internal/S1					Chrysotile (white asbestos)	
<b>B00A - R0108 - Toilets - Girls</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0106/Wall Linings Internal/S1					Chrysotile (white asbestos)	
<b>B00A - R0109 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R0111 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0112 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0113 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0114 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0115 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0116 - Home Base</b>						
No Asbestos						
<b>B00A - R0117 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0117/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	
<b>B00A - R0118 - Home Base</b>						
No Asbestos						
<b>B00A - R0119 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0120 - Movement</b>						
No Asbestos						
<b>B00A - R0121 - Movement</b>						
No Asbestos						
<b>B00A - R0122 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4515/B00A/R0037/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	
<b>B00A - R0123 - Stairs</b>						
No Asbestos						
<b>B00A - R0124 - Stairs</b>						
No Asbestos						
<b>B00A - R0125 - Stairs</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Other-After School Care - 1996 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.					
Eaves Linings	Flat AC Sheeting 4515/B00B/Eaves Linings/S22					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					

**Interior**

**B00B - R0001 - Out Of School Hours Care Centre**

No Asbestos

**B00B - R0002 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4515/B00B/R0003/Ceiling Structures/Linings/S11					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00B - R0004 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Railway Carriage - 1989 - Steel (Steel)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Entryway - Floor covering	Flat AC Sheeting					
	4515/B00C/Entryway - Floor covering/S21					<b>No Asbestos Detected</b>

**Interior**

**B00C - R0001 - Railway Carriage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - School could not locate keys, assumed no asbestos.

**Interior**

**B00D - R0001 - Home Base**

No Asbestos

**B00D - R0002 - Home Base**

No Asbestos

**B00D - R0003 - Home Base Store**

No Asbestos

**B00D - R0004 - Toilets - Girls**

No Asbestos

**B00D - R0005 - Access Shower/Toilet/Change**

No Asbestos

**B00D - R0006 - Toilets - Boys**

No Asbestos

**B00D - R0007 - Practical Activities - 1hb**

No Asbestos

**B00D - R0008 - Withdrawal Space - 2hb**

No Asbestos

**B00D - R0009 - Practical Activities - 1hb**

No Asbestos

**B00D - R0010 - Home Base Store**

No Asbestos

**B00D - R0011 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017