


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kings Langley Public School (4528)  
**Region :** Western Sydney  
**State Electorate :** Seven Hills  
**Local Government Area :** Blacktown

**Initial Survey :** Noel Arnold & Associates : 30 - Mar - 2008  
**Register Issue Date :** 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - General Learning/Tiered Learning - 1981 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B001 - R0001 - External Movement**

No Asbestos

**B001 - R0002 - Plant**

No Asbestos

**B001 - R0003 - Special Programs Room**

No Asbestos

**B001 - R0004 - External Movement**

No Asbestos

**B001 - R0005 - Special Programs Store**

No Asbestos

**B001 - R0006 - Withdrawal Space - 1hb**

No Asbestos

**B001 - R0007 - Home Base**

No Asbestos

**B001 - R0008 - External Movement**

No Asbestos

**B001 - R0009 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Backing Board Resinous Board  
4528/B004/R0008/Electrical Backing Board/S1

**No Asbestos Detected**

**B001 - R0010 - Home Base Store**

No Asbestos

**B001 - R0011 - Home Base Store**

No Asbestos

**B001 - R0012 - Home Base**

No Asbestos

**B001 - R0013 - Withdrawal Space - 1hb**

No Asbestos

**B001 - R0014 - Movement**

No Asbestos

**B001 - R0015 - Home Base**

No Asbestos

**B001 - R0016 - Home Base Store**

No Asbestos

**B001 - R0017 - Security Store**

No Asbestos

**B001 - R0018 - Practical Activities - 1hb**

No Asbestos

**B001 - R0019 - External Movement**

No Asbestos

**B001 - R0020 - Practical Activities - 1hb**

No Asbestos

**B001 - R0021 - Security Store**

No Asbestos

**B001 - R0022 - Cleaning Distributed Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B002 - General Learning - 1981 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B002 - R0001 - External Movement**

No Asbestos

**B002 - R0002 - Home Base**

No Asbestos

**B002 - R0003 - Home Base Store**

No Asbestos

**B002 - R0004 - Security Store**

No Asbestos

**B002 - R0005 - Practical Activities - 1hb**

No Asbestos

**B002 - R0006 - External Movement**

No Asbestos

**B002 - R0007 - Practical Activities - 1hb**

No Asbestos

**B002 - R0008 - Security Store**

No Asbestos

**B002 - R0009 - Home Base Store**

No Asbestos

**B002 - R0010 - Home Base**

No Asbestos

**B002 - R0011 - External Movement**

No Asbestos

**B002 - R0012 - Withdrawal Space - 1hb**

No Asbestos

**B002 - R0013 - Home Base**

No Asbestos

**B002 - R0014 - External Movement**

No Asbestos

**B002 - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board
	4528/B004/R0008/Electrical Backing Board/S1

**No Asbestos Detected**

**B002 - R0016 - Home Base Store**

No Asbestos

**B002 - R0017 - General Storeroom**

No Asbestos

**B002 - R0018 - Cleaning Distributed Store**

No Asbestos

**B002 - R0019 - Home Base**

No Asbestos

**B002 - R0020 - Withdrawal Space - 1hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B003 - General Learning - 1981 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B003 - R0001 - External Movement**

No Asbestos

**B003 - R0002 - Home Base**

No Asbestos

**B003 - R0003 - Home Base Store**

No Asbestos

**B003 - R0004 - Security Store**

No Asbestos

**B003 - R0005 - Practical Activities - 1hb**

No Asbestos

**B003 - R0006 - External Movement**

No Asbestos

**B003 - R0007 - Cleaning Distributed Store**

No Asbestos

**B003 - R0008 - Kiln Room**

No Asbestos

**B003 - R0009 - Security Store**

No Asbestos

**B003 - R0010 - Home Base Store**

No Asbestos

**B003 - R0011 - Home Base**

No Asbestos

**B003 - R0012 - External Movement**

No Asbestos

**B003 - R0013 - Withdrawal Space - 1hb**

No Asbestos

**B003 - R0014 - Home Base**

No Asbestos

**B003 - R0015 - External Movement**

No Asbestos

**B003 - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board
	4528/B004/R0008/Electrical Backing Board/S1

**No Asbestos Detected****B003 - R0017 - Home Base Store**

No Asbestos

**B003 - R0018 - Home Base Store**

No Asbestos

**B003 - R0019 - Home Base**

No Asbestos

**B003 - R0020 - Withdrawal Space - 1hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B004 - General Learning/Pupil Facilities - 1981 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B004 - R0001 - Security Store**

No Asbestos

**B004 - R0002 - General Storeroom**

No Asbestos

**B004 - R0003 - Home Base**

No Asbestos

**B004 - R0004 - Movement**

No Asbestos

**B004 - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B004 - R0006 - Home Base**

No Asbestos

**B004 - R0007 - External Movement**

No Asbestos

**B004 - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board
4528/B004/R0008/Electrical Backing Board/S1	

**No Asbestos Detected**

**B004 - R0009 - Home Base**

No Asbestos

**B004 - R0010 - Withdrawal Space - 1hb**

No Asbestos

**B004 - R0011 - External Movement**

No Asbestos

**B004 - R0012 - Toilets - Boys**

No Asbestos

**B004 - R0013 - General Storeroom**

No Asbestos

**B004 - R0014 - Toilets - Girls**

No Asbestos

**B004 - R0015 - Disabled Toilet**

No Asbestos

**B004 - R0016 - Security Store**

No Asbestos

**B004 - R0017 - Practical Activities - 1hb**

No Asbestos

**B004 - R0018 - External Movement**

No Asbestos

**B004 - R0019 - Cleaning Distributed Store**

No Asbestos

**B004 - R0020 - Home Base Store**

No Asbestos

**B004 - R0021 - Home Base Store**

No Asbestos

**B004 - R0022 - Practical Activities - 1hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B005 - Library/Building Services - 1981 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	North, South, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos</b>					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B005 - R0001 - Reading Area**

No Asbestos

**B005 - R0002 - Cleaning Distributed Store**

No Asbestos

**B005 - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board					<b>No Asbestos Detected</b>
		4528/B005/R0003/Electrical Backing Board/S2				

**B005 - R0004 - External Movement**

No Asbestos

**B005 - R0005 - K.L.A. Store**

No Asbestos

**B005 - R0006 - Cleaning Supplies**

Non Accessible

**B005 - R0007 - Reading Area**

No Asbestos

**B005 - R0008 - Library Office/Workroom**

No Asbestos

**B005 - R0010 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B006 - Administration - 1981 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------	--------------------	---------	--------------------

**Assumed Asbestos**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

**Interior****B006 - R0001 - Staff Room Annexe**

No Asbestos

**B006 - R0002 - Staff Room**

No Asbestos

**B006 - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

Loose panel on ground	Flat AC Sheeting	4528/B006/R0003/loose panel on ground/S3	<b>No Asbestos Detected</b>
-----------------------	------------------	--	-----------------------------

**B006 - R0004 - Duplicating Workroom**

No Asbestos

**B006 - R0005 - Security Store**

No Asbestos

**B006 - R0006 - Staff Room Annexe**

No Asbestos

**B006 - R0007 - Entry Vestibule**

No Asbestos

**B006 - R0008 - External Movement**

No Asbestos

**B006 - R0009 - Staff Room Annexe**

No Asbestos

**B006 - R0010 - Sick Bay**

No Asbestos

**B006 - R0011 - Security Store**

No Asbestos

**B006 - R0012 - Principal**

No Asbestos

**B006 - R0013 - Clerical Office/Workroom**

No Asbestos

**B006 - R0014 - Cleaning Distributed Store**

No Asbestos

**B006 - R0015 - Staff Toilet**

No Asbestos

**B006 - R0016 - Staff Toilet**

No Asbestos

**B006 - R0017 - Movement**

No Asbestos

**B006 - R0018 - Clerical Office**

No Asbestos

**B006 - R0019 - External Movement**

No Asbestos

**B006 - R0020 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B007 - Communal Facilities - 1981 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos</b>					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior****B007 - R0001 - External Movement**

No Asbestos

**B007 - R0002 - Disabled Toilet**

No Asbestos

**B007 - R0003 - Music Store**

No Asbestos

**B007 - R0004 - Entry Vestibule**

No Asbestos

**B007 - R0005 - Hall Chair Store**

No Asbestos

**B007 - R0006 - Communal Space**

No Asbestos

**B007 - R0007 - Cleaning Distributed Store**

No Asbestos

**B007 - R0008 - Cleaning Supplies**

No Asbestos

**B007 - R0009 - Raised Platform**

No Asbestos

**B007 - R0010 - Movement**

No Asbestos

**B007 - R0011 - General Assistant/Bulk Store**

No Asbestos

**B007 - R0012 - Toilets - Girls**

No Asbestos

**B007 - R0013 - Main Switch Board**

Electrical Backing Board	Resinous Board
4528/B005/R0003/Electrical Backing Board/S2	

**No Asbestos Detected****B007 - R0014 - Toilets - Boys**

No Asbestos

**B007 - R0015 - Movement**

No Asbestos

**B007 - R0016 - General Assistant/Bulk Store**

No Asbestos

**B007 - R0017 - P.E. Store**

No Asbestos

**B007 - R0018 - Canteen Office/Store**

No Asbestos

**B007 - R0019 - Canteen**

No Asbestos

**B007 - R0020 - Canteen Office/Store**

No Asbestos

**B007 - R0021 - Plant**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B007 - R0022 - Cleaning Distributed Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B008 - Pupil Facilities - 1981 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B008 - R0001 - Toilets - Girls**

No Asbestos

**B008 - R0002 - Drinking Facilities**

No Asbestos

**B008 - R0003 - Toilets - Boys**

No Asbestos

**B008 - R0004 - Cleaning Distributed Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B009 - Pupil Facilities - 1981 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B009 - R0001 - Toilets - Girls**

No Asbestos

**B009 - R0002 - Drinking Facilities**

No Asbestos

**B009 - R0003 - Toilets - Boys**

No Asbestos

**B009 - R0004 - Cleaning Distributed Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B010 - General Learning - 2005 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B010 - R0001 - External Movement**

No Asbestos

**B010 - R0002 - Practical Activities - 1hb**

No Asbestos

**B010 - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B010 - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B010 - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B010 - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B010 - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B010 - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B011 - General Learning - 2007 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B011 - R0001 - Special Programs Room**

No Asbestos

**B011 - R0002 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B012 - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B012 - R0001 - External Movement**

No Asbestos

**B012 - R0002 - Home Base Store**

No Asbestos

**B012 - R0003 - Home Base**

No Asbestos

**B012 - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B012 - R0005 - Home Base**

No Asbestos

**B012 - R0006 - Home Base Store**

No Asbestos

**B012 - R0007 - Home Base Store**

No Asbestos

**B012 - R0008 - Home Base**

No Asbestos

**B012 - R0009 - Withdrawal Space - 2hb**

No Asbestos

**B012 - R0010 - Home Base**

No Asbestos

**B012 - R0011 - Home Base Store**

No Asbestos

**B012 - R0012 - Practical Activities - 1hb**

No Asbestos

**B012 - R0013 - Practical Activities - 1hb**

No Asbestos

**B012 - R0014 - Practical Activities - 1hb**

No Asbestos

**B012 - R0015 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B013 - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B013 - R0001 - External Movement**

No Asbestos

**B013 - R0002 - Home Base Store**

No Asbestos

**B013 - R0003 - Home Base**

No Asbestos

**B013 - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B013 - R0005 - Home Base**

No Asbestos

**B013 - R0006 - Home Base Store**

No Asbestos

**B013 - R0007 - Practical Activities - 1hb**

No Asbestos

**B013 - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B014 - Pre-School Facilities - 2010 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B014 - R0001 - External Movement**

No Asbestos

**B014 - R0002 - Movement**

No Asbestos

**B014 - R0003 - Clerical Office - Pre**

No Asbestos

**B014 - R0004 - Other-Non Government Pre-Sch**

No Asbestos

**B014 - R0005 - Practical Activities - Pre**

No Asbestos

**B014 - R0006 - Kitchen - Pre**

No Asbestos

**B014 - R0007 - General Storeroom - Pre**

No Asbestos

**B014 - R0008 - Practical Activities - Pre**

No Asbestos

**B014 - R0009 - Toilets - Boys/Girls - Pre**

No Asbestos

**B014 - R0010 - Cleaning Distributed Store**

No Asbestos

**B014 - R0011 - Laundry - Pre**

No Asbestos

**B014 - R0012 - Toilets - Boys**

No Asbestos

**B014 - R0013 - Toilets - Girls**

No Asbestos

**B014 - R0014 - Toilets - Boys/Girls - Pre**

No Asbestos

**B014 - R0015 - Practical Activities - Pre**

No Asbestos

**B014 - R0016 - Other-Non Government Pre-Sch**

No Asbestos

**B014 - R0017 - Other-Non Government Pre-Sch**

No Asbestos

**B014 - R0018 - Practical Activities - Pre**

No Asbestos

**B014 - R0019 - General Storeroom - Pre**

No Asbestos

**B014 - R0020 - Child Care Centre**

No Asbestos

**B014 - R0021 - Disabled Shower/Toilet**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

**OS 602 - D10311 - Learning Unit - Standard With P.A.A. : Placement Date - 27/05/1994**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

#### R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

**OS 602 - D10666 - Learning Unit - Standard With P.A.A. : Placement Date - 2/01/2009**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 602 - D11146 - Learning Unit - Standard With P.A.A. : Placement Date - 20/12/2012**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

#### R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

**OS 750 - D11879 - Learning Unit - ESL : Placement Date - 18/03/2015**

### Exterior

No Asbestos Found.

### Interior

#### R1 - EsL

No Asbestos Found.

**OS 602 - D13547 - Learning Unit - Standard With P.A.A. : Placement Date - 20/12/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14322 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

**Interior**

**R1 - Learning space/withdrawal/entry**

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

**R2 - Home Base Store**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

**OS 602 - D14328 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

**Interior**

**R1 - Learning space/withdrawal/entry**

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

**R2 - Home Base Store**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017