

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kariong Public School (4580)
Region : Hunter/Central Coast
State Electorate : Gosford
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 21 - Mar - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	16m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0005 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - Security Store

No Asbestos

B00A - R0007 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	4580/B00A/R0019/Wall Linings Internal/S12				No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	4580/B00A/R0019/Ceiling Structures/Linings/S13				No Asbestos Detected

B00A - R0008 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	4580/B00A/R0019/Wall Linings Internal/S12				No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	4580/B00A/R0019/Ceiling Structures/Linings/S13				No Asbestos Detected

B00A - R0009 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	4580/B00A/R0019/Wall Linings Internal/S12				No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	4580/B00A/R0019/Ceiling Structures/Linings/S13				No Asbestos Detected

B00A - R0011 - Seminar/Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0015 - Cleaning Distributed Store

No Asbestos

B00A - R0016 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0018 - Sick Bay

No Asbestos

B00A - R0019 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	4580/B00A/R0019/Wall Linings Internal/S12				No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	4580/B00A/R0019/Ceiling Structures/Linings/S13				No Asbestos Detected

B00A - R0021 - Kiln Room

Wall Linings Internal	Flat AC Sheeting	4580/B00A/R0019/Wall Linings Internal/S12				No Asbestos Detected
-----------------------	------------------	---	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4580/B00A/R0019/Ceiling Structures/Linings/S13				No Asbestos Detected
Floor Coverings Res/Textile	Compressed AC Sheet	4580/B00A/R0021/Floor Coverings Res/Textile/S17				No Asbestos Detected
B00A - R0023 - Movement						
Wall Linings Internal	Flat AC Sheeting	4580/B00A/R1013/Wall Linings Internal/S11				No Asbestos Detected
B00A - R0024 - Entry Vestibule						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0025 - Clerical Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0026 - Duplicating Workroom						
No Asbestos						
B00A - R0027 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0028 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0029 - Stairs						
Wall Linings Internal	Flat AC Sheeting	4580/B00A/R1013/Wall Linings Internal/S11				No Asbestos Detected
B00A - R1001 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1002 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1003 - Practical Activities - 1hb						
No Asbestos						
B00A - R1004 - Communications Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1005 - Practical Activities - 1hb						
No Asbestos						
B00A - R1006 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1007 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1008 - Cleaning Distributed Store						
No Asbestos						
B00A - R1009 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1013 - Movement						
Wall Linings Internal	Flat AC Sheeting	4580/B00A/R1013/Wall Linings Internal/S11				No Asbestos Detected
B00A - R1014 - Home Base Store						
No Asbestos						
B00A - R1015 - Practical Activities - 1hb						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1016 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1017 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1018 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1019 - Practical Activities - 1hb						
No Asbestos						
B00A - R1020 - Interview						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1021 - Home Base Store						
No Asbestos						
B00A - R1022 - Stairs						
Wall Linings Internal	Flat AC Sheeting		4580/B00A/R1013/Wall Linings Internal/S11			No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1988 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Wall Cladding	Flat AC Sheeting 4580/B00B/Wall Cladding/S10					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior**B00B - R0001 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0002 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0003 - Toilets - Boys/Girls

Ceiling Structures/Linings Flat AC Sheeting
4580/B00B/R0003/Ceiling Structures/Linings/S16 **No Asbestos Detected**

Wall Linings Internal Flat AC Sheeting
4580/B00B/R1001/Wall Linings Internal/S14 **No Asbestos Detected**

B00B - R0004 - Toilets - Boys/Girls

Ceiling Structures/Linings Flat AC Sheeting
4580/B00B/R0003/Ceiling Structures/Linings/S16 **No Asbestos Detected**

Wall Linings Internal Flat AC Sheeting
4580/B00B/R1001/Wall Linings Internal/S14 **No Asbestos Detected**

B00B - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0012 - Main Switch Board

Floor Coverings Res/Textile Compressed AC Sheet
4580/B00B/R0012/Floor Coverings Res/Textile/S15 **No Asbestos Detected**

B00B - R0013 - Cleaning Distributed Store

No Asbestos

B00B - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0015 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0016 - Practical Activities - 1hb						
No Asbestos						
B00B - R0017 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0018 - Practical Activities - 1hb						
No Asbestos						
B00B - R0019 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0020 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0021 - Movement						
Wall Linings Internal	Flat AC Sheeting					
	4580/B00B/Wall Cladding/S10					No Asbestos Detected
B00B - R1001 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting					
	4580/B00B/R0003/Ceiling Structures/Linings/S16					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	4580/B00B/R1001/Wall Linings Internal/S14					No Asbestos Detected
B00B - R1002 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting					
	4580/B00B/R0003/Ceiling Structures/Linings/S16					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	4580/B00B/R1001/Wall Linings Internal/S14					No Asbestos Detected
B00B - R1003 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1004 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1005 - Practical Activities - 1hb						
No Asbestos						
B00B - R1006 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1007 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1008 - Practical Activities - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1009 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1010 - Plant						
Non Accessible						
B00B - R1011 - General Storeroom						
No Asbestos						
B00B - R1012 - Distribution Board						
No Asbestos					Note: No inspection of live electrical installation.	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1013 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1014 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1015 - Practical Activities - 1hb						
No Asbestos						
B00B - R1016 - Communications Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1017 - Practical Activities - 1hb						
No Asbestos						
B00B - R1018 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1019 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1020 - Movement						
Wall Linings Internal	Flat AC Sheeting		4580/B00B/Wall Cladding/S10			No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1988 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Hall Chair Store

Wall Linings Internal	Flat AC Sheeting 4580/B00C/R0015/Wall Linings Internal/S2	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 4580/B00C/R0015/Ceiling Structures/Linings/S3	No Asbestos Detected

B00C - R0003 - P.E. Store

Wall Linings Internal	Flat AC Sheeting 4580/B00C/R0015/Wall Linings Internal/S2	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 4580/B00C/R0015/Ceiling Structures/Linings/S3	No Asbestos Detected

B00C - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0006 - Plant

No Asbestos

B00C - R0007 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting 4580/B00C/R0015/Ceiling Structures/Linings/S3	No Asbestos Detected
----------------------------	---	----------------------

B00C - R0008 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting 4580/B00C/R0015/Ceiling Structures/Linings/S3	No Asbestos Detected
----------------------------	---	----------------------

B00C - R0009 - General Assistant/Bulk Store

No Asbestos

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - Movement

No Asbestos

B00C - R0012 - Communal Space

No Asbestos

B00C - R0013 - Raised Platform

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - General Storeroom

Wall Linings Internal	Flat AC Sheeting 4580/B00C/R0015/Wall Linings Internal/S2	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 4580/B00C/R0015/Ceiling Structures/Linings/S3	No Asbestos Detected

B00C - R0016 - Movement

No Asbestos

B00C - R0017 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00D - R0001 - Uniform Shop

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4580/B00D/R0001/Wall Linings Internal/S1					

B00D - R0002 - Canteen Office/Store

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4580/B00D/R0001/Wall Linings Internal/S1					

B00D - R0003 - Canteen

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4580/B00D/R0001/Wall Linings Internal/S1					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00E - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting					
	4580/B00E/R0004/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0002 - Disabled Shower/Toilet

Ceiling Structures/Linings	Flat AC Sheeting					
	4580/B00E/R0004/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0003 - Shower/Change

Ceiling Structures/Linings	Flat AC Sheeting					
	4580/B00E/R0004/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting					
	4580/B00E/R0004/Ceiling Structures/Linings/S4					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00F - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - General Storeroom

Wall Linings Internal Flat AC Sheeting
4580/B00F/R1009/Wall Linings Internal/S9 **No Asbestos Detected**

B00F - R0010 - Movement

Wall Linings Internal Flat AC Sheeting
4580/B00F/R1009/Wall Linings Internal/S9 **No Asbestos Detected**

B00F - R0011 - Stairs

Wall Linings Internal Flat AC Sheeting
4580/B00F/R1010/Wall Linings Internal/S8 **No Asbestos Detected**

Ceiling Structures/Linings Flat AC Sheeting
4580/B00F/R1010/Wall Linings Internal/S8 **No Asbestos Detected**

B00F - R1001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00F - R1002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1003 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1004 - Home Base

No Asbestos

B00F - R1005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1006 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1007 - Home Base						
No Asbestos						
B00F - R1008 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1009 - Movement						
Wall Linings Internal	Flat AC Sheeting					
	4580/B00F/R1009/Wall Linings Internal/S9					No Asbestos Detected
B00F - R1010 - Stairs						
Wall Linings Internal	Flat AC Sheeting					
	4580/B00F/R1010/Wall Linings Internal/S8					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Practical Activities - 1hb

No Asbestos

B00G - R0002 - Personal Effects Storage

No Asbestos

B00G - R0003 - Home Base Store

No Asbestos

B00G - R0004 - Home Base

No Asbestos

B00G - R0005 - Withdrawal Space - 2hb

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Personal Effects Storage

No Asbestos

B00G - R0009 - Practical Activities - 1hb

No Asbestos

B00G - R0010 - Withdrawal Space - 1hb

No Asbestos

B00G - R0011 - Home Base Store

No Asbestos

B00G - R0012 - Home Base

No Asbestos

B00G - R0013 - Personal Effects Storage

No Asbestos

B00G - R0014 - Practical Activities - 1hb

No Asbestos

B00G - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0016 - General Storeroom

No Asbestos

B00G - R0017 - General Storeroom

No Asbestos

B00G - R0018 - External Movement

No Asbestos

B00G - R0019 - External Stairs

No Asbestos

B00G - R0020 - External Stairs

No Asbestos

B00G - R1001 - Practical Activities - 1hb

No Asbestos

B00G - R1002 - Personal Effects Storage

No Asbestos

B00G - R1003 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00G - R1004 - Home Base					
	No Asbestos					
	B00G - R1005 - Withdrawal Space - 2hb					
	No Asbestos					
	B00G - R1006 - Home Base					
	No Asbestos					
	B00G - R1007 - Home Base Store					
	No Asbestos					
	B00G - R1008 - Personal Effects Storage					
	No Asbestos					
	B00G - R1009 - Practical Activities - 1hb					
	No Asbestos					
	B00G - R1010 - Practical Activities - 1hb					
	No Asbestos					
	B00G - R1011 - Home Base Store					
	No Asbestos					
	B00G - R1012 - Withdrawal Space - 1hb					
	No Asbestos					
	B00G - R1013 - Home Base					
	No Asbestos					
	B00G - R1014 - Personal Effects Storage					
	No Asbestos					
	B00G - R1015 - Distribution Board				Note: No inspection of live electrical installation.	
	No Asbestos					
	B00G - R1016 - External Movement					
	No Asbestos					
	B00G - R1017 - External Stairs					
	No Asbestos					
	B00G - R1018 - External Stairs					
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00H - R0001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0002 - Practical Activities - 1hb

No Asbestos

B00H - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0005 - Movement

Wall Linings Internal Flat AC Sheeting
4580/B00H/R0005/Wall Linings Internal/S7 **No Asbestos Detected**

B00H - R1001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R1002 - Practical Activities - 1hb

No Asbestos

B00H - R1003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R1004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R1005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R1006 - Movement

Wall Linings Internal Flat AC Sheeting
4580/B00H/R0005/Wall Linings Internal/S7 **No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Wall Cladding	Flat AC Sheeting 4580/B00L/Wall Cladding/S6					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00L - R0001 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0002 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0004 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0005 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0006 - Toilets - Boys

No Asbestos

B00L - R0007 - Toilets - Girls

No Asbestos

B00L - R0008 - Movement

Wall Linings Internal	Flat AC Sheeting 4580/B00L/R0008/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00L - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017