

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kearns Public School (4593)  
**Region :** South Western Sydney  
**State Electorate :** Macquarie Fields  
**Local Government Area :** Campbelltown

**Initial Survey :** Noel Arnold & Associates : 22 - May - 2008  
**Register Issue Date :** 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1992 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00A - R0001 - Personal Effects Storage**

No Asbestos

**B00A - R0002 - Practical Activities - 1hb**

No Asbestos

**B00A - R0003 - Home Base**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0004 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0005 - Home Base Store**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0006 - Personal Effects Storage**

No Asbestos

**B00A - R0007 - Practical Activities - 1hb**

No Asbestos

**B00A - R0008 - Home Base**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0009 - Movement**

No Asbestos

**B00A - R0010 - Cleaning Distributed Store**

No Asbestos

**B00A - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0012 - Home Base Store**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0013 - Home Base Store**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0014 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0015 - Home Base**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0016 - Practical Activities - 1hb**

No Asbestos

**B00A - R0017 - Personal Effects Storage**

No Asbestos

**B00A - R0018 - Movement**

No Asbestos

**B00A - R0019 - Staff Room**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0020 - Staff Room Annexe**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0021 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0022 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0023 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0024 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0025 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0026 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0027 - Security Store</b>						
No Asbestos						
<b>B00A - R0028 - Movement</b>						
No Asbestos						
<b>B00A - R0029 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0030 - Staff Shower/Change</b>						
No Asbestos						
<b>B00A - R0031 - Sick Bay</b>						
No Asbestos						
<b>B00A - R0032 - Duplicating Workroom</b>						
No Asbestos						
<b>B00A - R0033 - Clerical Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0034 - Interview</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0035 - Staff Room Annexe</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0036 - Principal</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0037 - Staff Room Annexe</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0038 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0039 - Entry Vestibule</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0040 - Movement</b>						
No Asbestos						
<b>B00A - R0041 - Movement</b>						
No Asbestos						
<b>B00A - R0042 - Movement</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00B - R0002 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0003 - K.L.A. Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0004 - Drinking Facilities**

No Asbestos

**B00B - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0007 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0008 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0002 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0004 - Practical Activities - 1hb**

No Asbestos

**B00C - R0005 - Personal Effects Storage**

No Asbestos

**B00C - R0006 - Personal Effects Storage**

No Asbestos

**B00C - R0007 - Practical Activities - 1hb**

No Asbestos

**B00C - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0010 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0011 - Movement**

No Asbestos

**B00C - R0012 - Toilets - Girls**

No Asbestos

**B00C - R0013 - Cleaning Distributed Store**

No Asbestos

**B00C - R0014 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0015 - Toilets - Boys**

No Asbestos

**B00C - R0016 - Movement**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library/Pupil Facilities - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00D - R0001 - Garden Store**

No Asbestos

**B00D - R0002 - General Storeroom**

No Asbestos

**B00D - R0003 - General Assistant/Bulk Store**

No Asbestos

**B00D - R0004 - Canteen Office/Store**

No Asbestos

**B00D - R0005 - Canteen**

No Asbestos

**B00D - R0006 - Communal/Performance Store**

No Asbestos

**B00D - R0007 - Cleaning Supplies**

No Asbestos

**B00D - R0008 - Main Switch Board**

No Asbestos

**B00D - R0009 - Security Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0010 - Bulk Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0011 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0012 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0013 - General Storeroom**

No Asbestos

**B00D - R0014 - Plant**

No Asbestos

**B00D - R0015 - Disabled Toilet**

No Asbestos

**B00D - R0016 - Staff Shower/Change**

No Asbestos

**B00D - R0017 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0018 - Drinking Facilities**

No Asbestos

**B00D - R0021 - Movement**

No Asbestos

**B00D - R0022 - Movement**

No Asbestos

**B00D - R0023 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - R0024 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - Communal Space**

No Asbestos

**B00E - R0002 - Raised Platform**

No Asbestos

**B00E - R0003 - Hall Chair Store**

No Asbestos

**B00E - R0004 - Communal/Performance Store**

No Asbestos

**B00E - R0005 - P.E. Store**

No Asbestos

**B00E - R0006 - Toilet - Lobby**

No Asbestos

**B00E - R0007 - Toilets - Girls**

No Asbestos

**B00E - R0008 - Sound Cupboard**

No Asbestos

**B00E - R0009 - Toilet - Lobby**

No Asbestos

**B00E - R0010 - Toilets - Boys**

No Asbestos

**B00E - R0011 - Cleaning Distributed Store**

No Asbestos

**B00E - R0012 - General Storeroom**

No Asbestos

**B00E - R0013 - Main Switch Board**

No Asbestos

**B00E - R0014 - Access Shower/Toilet**

No Asbestos

**B00E - R0015 - Movement**

No Asbestos

**B00E - R0016 - Movement**

No Asbestos

**B00E - R0017 - Ramp**

No Asbestos

**B00E - R0018 - Covered Outdoor Learning Area**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D10700 - Learning Unit - Standard With P.A.A. : Placement Date - 12/09/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D11393 - Learning Unit - Standard With P.A.A. : Placement Date - 5/02/1997**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

**Interior**

**R1 - Learning space/withdrawal/entry**

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

**R2 - Home Base Store**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

**OS 602 - D12417 - Learning Unit - Standard With P.A.A. : Placement Date - 5/03/2010**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D13655 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 19/06/2008**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.


**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017