


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kellyville Ridge Public School (4639)  
**Region :** Western Sydney  
**State Electorate :** Riverstone  
**Local Government Area :** Blacktown

**Initial Survey :** Noel Arnold & Associates : 23 - May - 2008  
**Register Issue Date :** 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00A - R0001 - Movement**

No Asbestos

**B00A - R0002 - Staff Room Annexe**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0003 - Staff Room**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0004 - Staff Kitchen**

No Asbestos

**B00A - R0005 - Deputy Principal**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0006 - Deputy Principal**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0007 - Security Store**

No Asbestos

**B00A - R0008 - Principal**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0009 - Clerical Office/Workroom**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0010 - Movement**

No Asbestos

**B00A - R0011 - Entry Vestibule**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0012 - Interview**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0013 - Sick Bay**

No Asbestos

**B00A - R0014 - Access Shower/Toilet**

No Asbestos

**B00A - R0015 - Interview**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0016 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0017 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0018 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0019 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0020 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0021 - Movement</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00B - R0002 - Sports Store**

No Asbestos

**B00B - R0003 - Movement**

No Asbestos

**B00B - R0004 - Raised Platform**

No Asbestos

**B00B - R0005 - Movement**

No Asbestos

**B00B - R0006 - Main Switch Board**

No Asbestos

**B00B - R0007 - Communal/Performance Store**

No Asbestos

**B00B - R0008 - General Assistant/Bulk Store**

No Asbestos

**B00B - R0009 - General Assistant/Bulk Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0010 - Community Clinic**

No Asbestos

**B00B - R0011 - Toilets - Boys**

No Asbestos

**B00B - R0012 - Access Shower/Toilet**

No Asbestos

**B00B - R0013 - Staff Kitchen**

No Asbestos

**B00B - R0014 - Canteen**

No Asbestos

**B00B - R0015 - Canteen Office/Store**

No Asbestos

**B00B - R0016 - Toilets - Girls**

No Asbestos

**B00B - R0017 - Communications Cupboard**

No Asbestos

**B00B - R0018 - Garden Store**

No Asbestos

**B00B - R0019 - Cleaning Supplies**

No Asbestos

**B00B - R0020 - P.E. Store**

No Asbestos

**B00B - R0021 - Hall Chair Store**

No Asbestos

**B00B - R0022 - Communal Space**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - R0023 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00D - R0002 - Staff Toilet**

No Asbestos

**B00D - R0003 - Special Programs Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0004 - Special Programs Room**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0005 - K.L.A. Store**

No Asbestos

**B00D - R0006 - Cleaning Distributed Store**

No Asbestos

**B00D - R0007 - Reading Area**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0008 - Communications Room**

No Asbestos

**B00D - R0009 - Library Office/Workroom**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0011 - Seminar/Study**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0012 - Special Programs Room**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0013 - Special Programs Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0014 - Special Programs Room - Type 1**

No Asbestos

**B00D - R0015 - Special Programs Store**

No Asbestos

**B00D - R0016 - General Storeroom**

No Asbestos

**B00D - R0017 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00E - R0001 - Movement**

No Asbestos

**B00E - R0002 - Toilets - Boys**

No Asbestos

**B00E - R0003 - General Storeroom**

No Asbestos

**B00E - R0004 - Toilets - Girls**

No Asbestos

**B00E - R0005 - Practical Activities - 1hb**

No Asbestos

**B00E - R0006 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0007 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0008 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0009 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0010 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0011 - Practical Activities - 1hb**

No Asbestos

**B00E - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0013 - Practical Activities - 1hb**

No Asbestos

**B00E - R0014 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0015 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0016 - Withdrawal Space - 2hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0017 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0018 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0019 - Practical Activities - 1hb**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00F - R0001 - Movement**

No Asbestos

**B00F - R0002 - Toilets - Boys**

No Asbestos

**B00F - R0003 - Cleaning Distributed Store**

No Asbestos

**B00F - R0004 - Toilets - Girls**

No Asbestos

**B00F - R0005 - Practical Activities - 1hb**

No Asbestos

**B00F - R0006 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0007 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0008 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0009 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0010 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0011 - Practical Activities - 1hb**

No Asbestos

**B00F - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0013 - Laundry - Type 2**

No Asbestos

**B00F - R0014 - Access Shower/Toilet - Type 2**

No Asbestos

**B00F - R0015 - Home Base**

No Asbestos

**B00F - R0016 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0017 - Practical Activities - 1hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00F - R0018 - Withdrawal Space - 2hb</b>						
No Asbestos						
<b>B00F - R0019 - Home Base</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
<b>B00F - R0020 - Home Base Store</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
<b>B00F - R0021 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00F - R0022 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00G - R0001 - Movement**

No Asbestos

**B00G - R0002 - Practical Activities - 1hb**

No Asbestos

**B00G - R0003 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0004 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0005 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0006 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0007 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0008 - Practical Activities - 1hb**

No Asbestos

**B00G - R0009 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0010 - Practical Activities - 1hb**

No Asbestos

**B00G - R0011 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0012 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0013 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0014 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0015 - Home Base Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0016 - Practical Activities - 1hb**

No Asbestos

**B00G - R0017 - Distribution Board** Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0018 - Practical Activities - 1hb**

No Asbestos

**B00G - R0019 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0020 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0021 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0022 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0023 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0024 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Other - Non-Govt Pre-School - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00H - R0001 - No Access**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D10218 - Learning Unit - Standard With P.A.A. : Placement Date - 5/11/2008**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D10809 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 5/01/2007**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D11103 - Learning Unit - Standard With P.A.A. : Placement Date - 9/01/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D11281 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 28/11/2007**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D11428 - Learning Unit - Standard With P.A.A. : Placement Date - 26/11/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D11531 - Learning Unit - Standard With P.A.A. : Placement Date - 9/12/2009</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D11710 - Learning Unit - Standard With P.A.A. : Placement Date - 11/01/2012</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D12286 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 28/11/2007</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D12295 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 8/01/2007</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D12516 - Learning Unit - Standard With P.A.A. : Placement Date - 3/07/2008</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D12636 - Learning Unit - Standard With P.A.A. : Placement Date - 23/01/2010</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D12708 - Learning Unit - Standard With P.A.A. : Placement Date - 11/01/2012</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D12879 - Learning Unit - Standard With P.A.A. : Placement Date - 9/12/2009</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D13502 - Learning Unit - Standard With P.A.A. : Placement Date - 12/01/2012</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D13744 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 5/11/2008</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14100 - Learning Unit - Standard With P.A.A. : Placement Date - 26/11/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14573 - Learning Unit - Standard With P.A.A. : Placement Date - 20/01/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 840 - D15038 - Girls Toilet : Placement Date - 23/01/2010**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Toilets-Girls**

No Asbestos Found.

**OS 603 - D15273 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 22/02/2006**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D15709 - Learning Unit - Standard With P.A.A. : Placement Date - 11/01/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D16091 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 18/07/2007</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D17452 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 5/01/2007</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017